

Lew W. Myers
Senior Vice President724-682-5234
Fax: 724-643-8069

August 2, 2000

L-00-102

Beaver Valley Power Station, Unit No. 1
Docket No. 50-334 License No. DPR-66
LER 2000-006-00

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

In accordance with Appendix A, Beaver Valley Technical Specifications, the following
Licensee Event Report is submitted:

LER 2000-006-00, 10 CFR 50.73(a)(2)(iv), "Reactor Trip/Turbine Trip Due to
Turbine EH Loss of Control Power."



Lew W. Myers

Attachment

IE 22

cc: Mr. H. J. Miller, Regional Administrator
United States Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, PA 19406

Mr. D. S. Collins
BVPS Project Manager
United States Nuclear Regulatory Commission
Washington, DC 20555

Mr. David M. Kern
BVPS Senior Resident Inspector
United States Nuclear Regulatory Commission

Mr. J. A. Hultz
Ohio Edison Company
76 S. Main Street
Akron, OH 44308

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Mr. L. E. Ryan
Bureau of Radiation Protection
Department of Environmental Protection
RCSOB-13th Floor
P.O. Box 8469
Harrisburg, PA 17105-8469

Manager, Nuclear Licensing and
Operations Support
Virginia Electric & Power Company
5000 Dominion Blvd.
Innsbrook Tech. Center
Glen Allen, VA 23060

LICENSEE EVENT REPORT (LER)

(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Forward comments regarding burden estimate to the Records Management Branch (T-6 F33), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, and to the Paperwork Reduction Project (3150-0104), Office of Management and Budget, Washington, DC 20503. If an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

FACILITY NAME (1) Beaver Valley Power Station Unit 1	DOCKET NUMBER (2) 05000334	PAGE (3) 1 OF 4
--	--------------------------------------	---------------------------

TITLE (4)
Reactor Trip / Turbine Trip Due to Turbine EH Loss of Control Power

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
07	05	2000	2000	-- 006	-- 00	08	02	2000	None	
									FACILITY NAME	DOCKET NUMBER
									FACILITY NAME	DOCKET NUMBER

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)				
POWER LEVEL (10) 100 %	20.2201(b)	20.2203(a)(2)(v)	50.73(a)(2)(i)	50.73(a)(2)(viii)	
	20.2203(a)(1)	20.2203(a)(3)(i)	50.73(a)(2)(ii)	50.73(a)(2)(x)	
	20.2203(a)(2)(i)	20.2203(a)(3)(ii)	50.73(a)(2)(iii)	73.71	
	20.2203(a)(2)(ii)	20.2203(a)(4)	X 50.73(a)(2)(iv)	OTHER	
	20.2203(a)(2)(iii)	50.36(c)(1)	50.73(a)(2)(v)		
	20.2203(a)(2)(iv)	50.36(c)(2)	50.73(a)(2)(vii)		

LICENSEE CONTACT FOR THIS LER (12)

NAME T. S. Cosgrove, Manager Licensing	TELEPHONE NUMBER (Include Area Code) (724) 682-5203
--	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
X	TG	JX	W120	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE).	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
X					

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

At 1305 on July 5, 2000, Beaver Valley Power Station (BVPS) Unit 1 experienced a reactor trip from 100% power due to the four (4) Main Turbine throttle valves going closed. There were no turbine related activities ongoing at the time. The Sequence of Events recorder indicated a momentary loss of DC control power (18 milliseconds) to the Analog Electrohydraulic (AEH) control system associated with the Main Turbine. One second later, a computer point indicated that a Throttle Valve/Governor Valve transfer had occurred. All four Main Turbine throttle valves closed between 10 and 13 seconds after the momentary loss of DC power. Following initiation of the automatic reactor trip signal, all control rods fully inserted and the Unit was stabilized in Mode 3 with decay heat being removed via the normal post-reactor trip method of using the steam bypass system into the Main Condenser. There were no radiological releases.

The throttle valve mixing amp 3 card was the only failed component found in the AEH control cabinet. It affected both the primary and secondary power supply output. The apparent root cause is that a solid state component on the mixing amp 3 card failed to ground. A new mixing amp 3 card was installed and tested satisfactorily. As a precautionary measure, the primary power supply was replaced.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
Beaver Valley Power Station Unit 1	05000334	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 4
		2000	- 006	- 00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

PLANT AND SYSTEM IDENTIFICATION

Westinghouse-Pressurized Water Reactor System
Westinghouse Main Turbine (TA)
Main Turbine Control Fluid System (TG)

CONDITIONS PRIOR TO OCCURRENCE

Unit 1: Mode 1 at 100 % power

There were no systems, structures, or components that were inoperable that contributed to the event.

DESCRIPTION OF EVENT

At 1305 on July 5, 2000, Beaver Valley Power Station (BVPS) Unit 1 experienced a reactor trip from 100% power due to the four (4) Main Turbine throttle valves going closed. There were no turbine related activities ongoing at the time. The Sequence of Events recorder indicated a momentary loss of DC control power (18 milliseconds) to the Analog Electrohydraulic (AEH) control system associated with the Main Turbine. One second later, a computer point indicated that a Throttle Valve/Governor Valve transfer had occurred. The momentary power loss caused the AEH to reset in the condition of Throttle Valve Control. The AEH is not designed to be in Throttle Valve Control when the Main Generator breaker is closed. With the AEH in Throttle Valve Control, the desired position for the Throttle Valves was zero (0) percent. All four Main Turbine throttle valves closed between 10 and 13 seconds after the momentary loss of DC power. The four throttle valves closing initiated an automatic reactor trip.

Following initiation of the automatic reactor trip signal, all control rods fully inserted and no Pressurizer or Steam Generator relief valves lifted or ECCS equipment actuated. The Unit was stabilized in Mode 3 with decay heat being removed via the normal post-reactor trip method of using the steam bypass system into the Main Condenser. The Auxiliary Feedwater System automatically started as designed and supplied make-up water to the Steam Generators. There were no radiological releases. Reactor Coolant System temperature and pressure and Steam Generator temperature, level and pressure exhibited normally expected post-trip responses.

The only failed component found during troubleshooting was the throttle valve mixing amp 3 card (Westinghouse, Model Number 3-398621/G). A new mixing amp 3 card was installed and tested. The apparent root cause is that a solid state component on the mixing amp 3 card failed to ground.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Beaver Valley Power Station Unit 1	05000334	2000	- 006	- 00	3 OF 4

REPORTABILITY

The automatic initiation of the Reactor Trip System constitutes an automatic actuation of an engineered safety feature as described in 10 CFR 50.73(a)(2)(iv). This requires NRC reporting within four hours of the occurrence, pursuant to the reporting criteria of 10 CFR 50.72(b)(2)(ii), and LER reporting within 30 days of the occurrence, pursuant to the reporting criteria of 10 CFR 50.73(a)(2)(iv). At 1417 hours on July 5, 2000, a 4-hour notification (Report # 37145) was made to the NRC in accordance with 10 CFR 50.72(b)(2)(ii).

CAUSE OF EVENT

Unexpected Failure:

The throttle valve mixing amp 3 card was the only failed device found in the AEH control cabinet. A solid state component on the mixing amp card 3 failed to ground and thus caused the +15 Vdc bus to go to ground, which affected both the primary and secondary power supply output. The specific cause of the mixing amp card 3 failure was not determined.

SAFETY IMPLICATIONS

Following initiation of the automatic reactor trip signal, all control rods fully inserted, no Pressurizer or Steam Generator relief valves lifted, and no ECCS equipment actuated. The Unit was stabilized in Mode 3 with decay heat being removed via the normal post-reactor trip method of using the steam bypass system into the Main Condenser. The Auxiliary Feedwater System automatically started as designed and supplied make-up water to the Steam Generators. The unit was stabilized and station recovery was satisfactorily completed. There were no radiological releases. Reactor Coolant System temperature and pressure and Steam Generator temperature, level and pressure exhibited normally expected post-trip responses.

At the time of the BVPS Unit 1 reactor trip, no components modeled in the Unit 1 Probabilistic Risk Analysis were unavailable. The calculated risk associated with this event is small.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Beaver Valley Power Station Unit 1	05000334	2000	- 006	- 00	4 OF 4

CORRECTIVE ACTIONS

1. The failed mixing amp 3 card which caused the +15 Vdc bus to go to ground was replaced and will be sent to an offsite facility for testing. Any follow-up corrective action will be based upon the as-found test results.
2. As a precautionary measure, the AEH control cabinet +15Vdc primary power supply was replaced. The removed power supply will be sent to the vendor to perform as-found testing. Any follow-up corrective action will be based upon the as-found test results.
3. Additional evaluation of vendor and industry information will be performed to determine if additional actions should be performed.

Corrective action completion is being tracked through the corrective action program.

PREVIOUS SIMILAR EVENTS

A review of the BVPS Corrective Action program documents and Licensee Event Reports found two similar events involving turbine trip or EHC Power supply within the last four years:

Condition Report 992408, Loss Of Turbine EH DC Power Supply. The primary power supply failed; however, the secondary power supply continued to provide power to the EH control system.

BVPS Unit 1 LER 96-008, "Reactor Trip During Solid State Protection System Turbine Testing."