



South Texas Project Electric Generating Station P.O. Box 289 Wadsworth, Texas 77483

March 5, 2001
NOC-AE-01001012
File No.: G09.16
10CFR50.55a

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555-0001


South Texas Project
Unit 1
Docket No. STN 50-498
Request for Relief from ASME Boiler and Pressure Vessel Code,
Section XI Requirements (RR-ENG-2-24)

In accordance with the provisions of 10CFR50.55a(g)(5)(iii), the South Texas Project requests relief from the requirements of IWA-5250 of Section XI of the ASME Boiler and Pressure Vessel Code. Approval will allow deferral of code repair of a flaw recently identified in service water Class 3 piping. Repair of the flaw with a code repair at this time is impractical. In accordance with the guidance provided in Generic Letter 90-05 and subject to Nuclear Regulatory Commission approval of this request, code repairs will be implemented no later than the next Unit 1 refueling outage, which is scheduled to begin October 3, 2001.

The flaw is a discoloration at a single point on the exterior of a 30-inch by 30-inch by 14-inch tee located in the Unit 1 Mechanical Auxiliary Building. The tee is part of the Essential Cooling Water supply to essential chiller train 1A. The discoloration is due to dealloying that has propagated from an interior weld defect. There is currently no visible leakage. Operability and functionality of the system have been maintained, and deferring repair of the flaw will not affect the health and safety of the public.

The attached relief request includes an evaluation of the present condition of the tee, compensatory actions, and opportunities for effecting code repairs in accordance with the guidelines provided in Generic Letter 90-05.

If there are any questions, please contact either Mr. P. L. Walker at (361) 972-8392 or me at (361) 972-7902.


T. J. Jordan
Manager,
Nuclear Engineering

KRC/PLW

Attachment: Request for Relief from ASME Boiler and Pressure Vessel Code, Section XI Requirements (RR-ENG-2-24)

Project Manager on Behalf of the Participants in the South Texas Project

A047

cc:

Ellis W. Merschoff
Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, Texas 76011-8064

John A. Nakoski
Addressee Only
U. S. Nuclear Regulatory Commission
Project Manager, Mail Stop OWFN/7-D-1
Washington, DC 20555-0001

Mohan C. Thadani
Addressee Only
U. S. Nuclear Regulatory Commission
Project Manager, Mail Stop OWFN/7-D-1
Washington, DC 20555

Cornelius F. O'Keefe
c/o U. S. Nuclear Regulatory Commission
P. O. Box 910
Bay City, TX 77404-0910

A. H. Gutterman, Esquire
Morgan, Lewis & Bockius
1800 M. Street, N.W.
Washington, DC 20036-5869

M. T. Hardt/W. C. Gunst
City Public Service
P. O. Box 1771
San Antonio, TX 78296

A. Ramirez/C. M. Canady
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, TX 78704

Jon C. Wood
Matthews & Branscomb
112 East Pecan, Suite 1100
San Antonio, Texas 78205-3692

Institute of Nuclear Power
Operations - Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Richard A. Ratliff
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

R. L. Balcom/D. G. Tees
Houston Lighting & Power Co.
P. O. Box 1700
Houston, TX 77251

C. A. Johnson/R. P. Powers
AEP - Central Power and Light Company
P. O. Box 289, Mail Code: N5012
Wadsworth, TX 77483

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555-0001

**SOUTH TEXAS PROJECT
UNIT 1
REQUEST FOR RELIEF FROM ASME BOILER AND PRESSURE
VESSEL CODE SECTION XI REQUIREMENTS
(RELIEF REQUEST RR-ENG-2-24)**

References

1. Leakage of Aluminum-Bronze Essential Cooling Water System, S. L. Rosen to NRC Document Control Desk, dated May 12, 1988 (ST-HL-AE-2652)
2. Supplement to Request for Relief from ASME Boiler and Pressure Vessel Code, Section XI Requirements, Relief Request RR-ENG-10, S. L. Rosen to NRC Document Control Desk, dated May 12, 1988, dated April 30, 1992 (ST-HL-AE-4075)
3. Letter from the NRC dated April 12, 1993, "Relief Request for Repair of Essential Cooling Water Piping, South Texas Project, Units 1 and 2 (TAC Nos. M82646 and M82647)"

Reference Code: ASME Boiler and Pressure Vessel Code, Section XI, 1989 Edition, no Addenda

A. Introduction

A1. Component for which Relief is Requested

- (a) Identification: Unit 1 Essential Cooling Water System, Train 1A Essential Chiller Supply, 30" x 30" x 14" tee, Spool EW-1102-AP, line EW1102WT3, ISO 3M361PEW229, Sheet 19.
- (b) Function: The Essential Cooling Water System is designed to supply cooling water to various safety-related systems for normal plant operation, normal shutdown, and during and after postulated design-basis accidents. The subject tee provides Essential Cooling Water to Train A Chillers 11A and 12A.
- (c) Class: ASME Code Class 3
- (d) Description of the flaw: An area of recurring discoloration has been found on the bottom of the 14-inch portion of the tee. Discoloration of aluminum-bronze indicates a dealloyed through-wall defect. However, the small size of the discolored area indicates the dealloying is relatively minor. There is currently no leakage or surface accumulation of moisture at this location.

A2. Code Requirements From Which Relief is Requested

Relief is requested from the requirements of IWA-5250(a)(3) of ASME Section XI so that code repair of the through-wall flaw in Essential Cooling Water piping may be deferred until the next Unit 1 outage of sufficient duration.

A3. Basis for Relief Request

As stated in Generic Letter 90-05, a repair is considered to be impractical if the flaw detected during plant operation is in a section of Class 3 piping that cannot be isolated for completing a code repair within the time period permitted by the limiting condition for operation of the affected system as specified in the plant Technical Specifications, and performance of code repair necessitates a plant shutdown. Performance of code repairs within the allowed outage time for the Essential Cooling Water System at the South Texas Project, as permitted by the limiting condition for operation, may be impractical due to the potential for fit-up problems during repair. Therefore, the South Texas Project requests this relief on the basis of impracticality.

B. Scope, Limitations, and Specific Considerations

B1. Scope

This relief request covers a dealloyed spot on a 30" x 30" x 14" tee in the Unit 1 Essential Cooling Water system. The tee is part of the supply line to Train 1A Essential Chiller. The through-wall flaw discovered is the result of a previously analyzed dealloying process that can occur in aluminum-bronze components.

B2. Limitations

Repair of the flaw is to be deferred until adequate time is available for the repair, but no later than the next Unit 1 refueling outage, providing the condition meets the acceptance criteria of Generic Letter 90-05 and is enveloped by previous studies as described in C3 of this relief request. Compensatory action has been implemented to detect any changes in the condition of the flaw. The next Unit 1 refueling outage is currently scheduled to start October 3, 2001.

B3. Specific Considerations

Consequences of potential system interactions, including flooding, spray on equipment, and loss of flow to the system, have been evaluated and are bounded by Appendix 9A of the South Texas Project Updated Final Safety Analysis Report.

The structural integrity of piping with dealloying has been evaluated for all design loading conditions including dead weight, pressure, thermal expansion, and seismic loads. Flaw evaluation is addressed in paragraph C3.

The structural integrity is monitored by the following methods:

- Monthly monitoring for qualitative assessment of leakage (quantitative if measurable leaks are observed). Currently there is no measurable leakage.

- Continuation of Essential Cooling Water System large bore piping periodic walkdowns. This walkdown is a regularly scheduled VT-2 examination. The inspection technique has proven to be an effective means of identifying dealloyed/cracked components prior to deterioration of structural integrity margins below ASME Section XI requirements.

Structural integrity and the monitoring frequency will be reviewed if significant changes are found during this monitoring.

The Essential Cooling Water System is a low-pressure system with normal operating pressure of approximately 50 psig and a design pressure of 120 psig. The consequences associated with failure of high-energy lines are not applicable to the Essential Cooling Water System.

The corrective action is to repair the identified flaw when the system can be taken out of service for an adequate time, but no later than the next Unit 1 refueling outage currently scheduled for October 3, 2001, subject to augmented monitoring meeting the criteria for consequences, and meeting structural integrity requirements.

C. Evaluation

C1. Flaw Detection During Plant Operation and Impracticality of Code Replacement

The flaw was identified on July 24, 2000, during normal Unit 1 plant operations. The subject flaw was discovered during periodic examination of Essential Cooling Water large bore piping.

Performance of code repairs prior to an extended allowed outage time or refueling outage as permitted by the limiting condition for operation may not be practical due to the time required to complete repair. The South Texas Project prefers to perform the code repair under controlled conditions during a scheduled outage that is long enough for the necessary repairs to be made as long as the specific considerations listed above are met.

C2. Root Cause Determination and Flaw Characterization

The root cause of dealloying flaws is a combination of corrosion and stress. The dealloying process normally initiates from a crevice such as the area behind a backing ring, a fabrication-induced flaw, or a casting flaw. Dealloying in this case is believed to be the result of susceptible material associated with a weld repair of an extruded tee.

Presence of a flaw is indicated by an area of recurring discoloration that has been found on the bottom of the 14-inch portion of the tee. Discoloration of aluminum-bronze indicates a dealloyed through-wall defect. However, the small size of the discolored area indicates the dealloying is relatively minor. There is currently no leakage or surface accumulation of moisture at this location.

C3. Flaw Evaluation

The South Texas Project has performed laboratory analyses, calculations, and proof-testing on welded aluminum-bronze material to address dealloying and cracking in dealloyed material. The process of dealloying of aluminum-bronze has been described in previous communications with the NRC (Reference 1).

The South Texas Project has analyzed through-wall flaws in Essential Cooling Water piping and found that degradation progresses slowly. Rapid or catastrophic failure due to dealloying defects is not a concern. Dealloying produces detectable leakage before flaws reach a limiting size that would affect the operability of the Essential Cooling Water System. The flaws are monitored and inspected to ensure detection of leakage. Compensatory actions taken following discovery of this condition provide assurance that changes in the condition will be monitored and analyzed for further action as needed.

The subject flaw is identical to a flaw previously identified in the Unit 1 Train B tee (EW 1202-AQ) serving the same function and specified in a supplement to relief request RR-ENG-10 (reference 2). The two flaws were found on identical tees in the same general location and are of about the same magnitude. Therefore, the justification for relief previously accepted by the NRC in reference 3 is applicable to the subject flaw.

C4. Augmented Inspection

Augmented monthly inspections have been implemented to detect any changes in the size of the discolored area or leakage. A significant change in the flaw will require additional engineering attention to confirm that the technical justification of this relief request remains valid.