



Monticello Nuclear Generating Plant
2807 West County Road 75
Monticello, MN 55362-9637

Operated by Nuclear Management
Company LLC

April 16, 2001

US Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

LER 2001-004
Testing of Recombiner Space Heaters Not
Performed Due to Inadequate Procedures

A Licensee Event Report for this occurrence is attached. This report contains no new NRC commitments.

Contact Sam Shirey, Senior Production Engineer, at (763) 295-1449 if you require further information.

Byron Day
Plant Manager
Monticello Nuclear Generating Plant

c: Regional Administrator - III NRC
NRR Project Manager, NRC

Sr. Resident Inspector, NRC
Minnesota Department of Commerce

Attachment

IE22

NRC FORM 366 (1-2001)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB NO. 3150-0104 EXPIRES 6-30-2001							
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)						Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bis1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the					
FACILITY NAME (1) Monticello Nuclear Generating Plant				DOCKET NUMBER (2) 05000263		PAGE (3) 1 OF 4					
TITLE (4) Testing of Recombiner Space Heaters Not Performed Due to Inadequate Procedures											
EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
02	16	2001	2001 - 004 - 00			04	17	2001	FACILITY NAME	DOCKET NUMBER	
									05000	05000	
OPERATING MODE (9)		POWER LEVEL (10)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply) (11)							
N		100		20.2201(b)		20.2203(a)(3)(ii)		50.73(a)(2)(ii)(B)		50.73(a)(2)(ix)(A)	
				20.2201(d)		20.2203(a)(4)		50.73(a)(2)(iii)		50.73(a)(2)(x)	
				20.2203(a)(1)		50.36(c)(1)(i)(A)		50.73(a)(2)(iv)(A)		73.71(a)(4)	
				20.2203(a)(2)(i)		50.36(c)(1)(ii)(A)		50.73(a)(2)(v)(A)		73.71(a)(5)	
				20.2203(a)(2)(ii)		50.36(c)(2)		50.73(a)(2)(v)(B)		OTHER Specify in Abstract below or in NRC Form 366A	
				20.2203(a)(2)(iii)		50.46(a)(3)(ii)		50.73(a)(2)(v)(C)			
				20.2203(a)(2)(iv)		50.73(a)(2)(i)(A)		50.73(a)(2)(v)(D)			
				20.2203(a)(2)(v)		X	50.73(a)(2)(i)(B)		50.73(a)(2)(vii)		
				20.2203(a)(2)(vi)		50.73(a)(2)(i)(C)		50.73(a)(2)(viii)(A)			
				20.2203(a)(3)(i)		50.73(a)(2)(ii)(A)		50.73(a)(2)(viii)(B)			
LICENSEE CONTACT FOR THIS LER (12)											
NAME Sam Shirey						TELEPHONE NUMBER (Include Area Code) (763) 295-1449					
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX		
SUPPLEMENTAL REPORT EXPECTED (14)						EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR	
YES (If yes, complete EXPECTED SUBMISSION DATE).				X	NO						
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16) During review of an operations manual change, the system engineer recognized space heaters for the Combustible Gas Control (CGC) System recombinder reaction chamber and the recombinder blower motor had not been tested as required by plant Technical Specifications. It was concluded this condition does not meet the requirements of the Technical Specification 4.7.E.1.b which is to perform a resistance to ground test on all heater electrical circuits.											

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME(1)	DOCKET	LER NUMBER (6)			PAGE (3)
MONTICELLO NUCLEAR GENERATING PLANT	05000263	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 of 4
		01	-- 04 --	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Description

On February 16, 2001, while operating at 100% power and during review of an operations manual change, the system engineer recognized space heaters¹ for the Combustible Gas Control (CGC)² System recombiner³ reaction chamber and the recombiner blower⁴ motor⁵ had not been tested as required by plant Technical Specifications.

Both trains of CGC Systems were declared inoperable on February 16, 2001 due to a failure to comply with the surveillance requirements of Technical Specification 4.7.E.1.b to perform a resistance to ground test on all heater electrical circuits. A 30-day LCO was entered per Technical Specification 3.7.E.3.

This check had been performed, as specified, for the recombiner main heater circuits, but not for the space heaters in the recombiner enclosure or in the blower motor.

The primary purpose of the space heaters is to prevent excessive moisture buildup in these components. The space heaters are not required for operability, however, they should have been tested based on the Technical Specification requirement (i.e. "all heaters").

Failure to perform the resistance to ground checks of the space heaters did not affect CGC functionality based on the following:

A trickle heater "power on" light on the recombiner provided assurance the space heaters were operating properly.

Cyclic megger checks of the CGC recombiner main heaters and blower motors have shown acceptable results. This demonstrates no excessive degradation of these components.

Semi-annual and cyclic surveillance tests of the CGC Systems have not shown a problem with these components.

The heater circuit resistance to ground surveillance procedures were revised to include the space heaters and were issued on February 22, 2001. These procedures were successfully run on February 23, 2001. Both trains of CGC were declared operable, and the 30-day LCO was exited.

¹ EIIS Component Code: EHTR

² EIIS System Code: BB

³ EIIS Component Code: RCB

⁴ EIIS Component Code: BLO

⁵ EIIS Component Code: MO

NRC FORM 366A (6-1998)		U.S. NUCLEAR REGULATORY COMMISSION		
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				
FACILITY NAME(1)	DOCKET	LER NUMBER (6)		PAGE (3)
MONTICELLO NUCLEAR GENERATING PLANT	05000263	YEAR 01	SEQUENTIAL NUMBER -- 04 --	REVISION NUMBER 00
				3 of 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Event Analysis

Analysis of Reportability

This event was determined to be reportable as a condition prohibited by the Technical Specifications in accordance with 10 CFR 50.73(a)(2)(i)(B). Technical Surveillance requirement 4.7.E.1.b requires performance of a resistance to ground test on all heater electrical circuits. Contrary to this, only the safety related primary heater elements had been tested.

Safety Significance

The safety significance to this event was low. The safety related primary recombiner heater elements had been tested as required. The space heaters for the recombiner reaction chamber and for the recombiner blower motor had not been tested. At time of discovery, indicator lights on the CGC system control panel indicated the heaters were operating properly. The surveillance test procedures were revised to include the additional heaters, and were successfully run. This event had no impact on the health and safety of the public.

Cause

The cause of this event is a failure to realize that the supporting surveillance procedures did not meet the Technical Specification requirements. The condition is due to a lack of awareness and is cognitive in nature.

Corrective Actions

The heater circuit resistance to ground surveillance procedures were revised to include the space heaters and were issued on February 22, 2001. These procedures were successfully run on February 23, 2001. Both trains of CGC were declared operable at 1539, and the 30-day LCO was exited.

This event and the lessons learned will be the subject of training for the MNGP Engineering Technical staff.

Failed Component Identification

None

NRC FORM 366A (6-1998)		U.S. NUCLEAR REGULATORY COMMISSION			
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION					
FACILITY NAME(1) MONTICELLO NUCLEAR GENERATING PLANT	DOCKET 05000263	YEAR 01	LER NUMBER (6) SEQUENTIAL NUMBER -- 04 --	REVISION NUMBER 00	PAGE (3) 4 of 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Similar Events

Monticello LER 92-005: Failure to Complete Control Rod Drive Surveillance Caused by Inadequate Administrative Controls

Monticello LER 96-013: Failure to Comply with Tech Spec Requirement to Verify that the Control Room Ventilation System Maintains a Positive Pressure with Respect to Adjacent Area

Monticello LER 2000-014: Missed Standby Liquid Control System (SLC) Test