

WINSTON & STRAWN

35 WEST WACKER DRIVE
CHICAGO, ILLINOIS 60601-9703

43 RUE DU RHONE
1204 GENEVA, SWITZERLAND

444 SOUTH FLOWER STREET
LOS ANGELES, CALIFORNIA 90071-2911

THOMAS C. POINDEXTER

(202) 371-5748

tpoindex@winston.com

1400 L STREET, N.W.
WASHINGTON, D.C. 20005-3502

(202) 371-5700

FACSIMILE (202) 371-5922
FACSIMILE (202) 371-5950

www.winston.com

May 9, 2001

200 PARK AVENUE
NEW YORK, NEW YORK 10166-4193

21 AVENUE VICTOR HUGO
75116 PARIS, FRANCE

FOIA/PA REQUEST

Case No:

2001-0256

Date Rec'd:

5-10-2001

Action Off:

BROWN

Related Cases:

Ms. Natalie Brown
Freedom of Information Office
U.S. Nuclear Regulatory Commission
11555 Rockville Pike
Rockville, MD 20852

Re: Freedom of Information Act Request

Dear Ms. Brown:

Winston & Strawn respectfully submits this Freedom of Information Act (FOIA) request on behalf of our client, Consolidated Edison Company of New York, Inc. ("ConEdison"), pursuant to the Freedom of Information Act (5 U.S.C. Sec. 552) and to the Nuclear Regulatory Commission's (NRC) policies and regulations (10 C.F.R. Part 9, Subpart A). Specifically, this second party FOIA requests the documents described in the attached list.

We would appreciate your prompt response within ten (10) working days of the receipt of this request, as provided by the Code and the NRC's policies. We agree to pay such fees as required under 10 C.F.R. § 9.33 et seq., without further authorization. However, please call if the fees exceed \$1,000.00. In addition, please send the response only to me, rather than making it available at the NRC's Public Document Room or on the ADAMS system. Please call me at (202) 371-5748 if you have questions.

Sincerely,



Thomas C. Poindexter, Esq.
Winston & Strawn

Enclosures

DOCUMENTS REQUESTED

Note 1: Please interpret the word "documents" to include written and electronic documents and all drafts and copies with notations or amendments.

Note 2: Please interpret the word "concerning" to mean relating to, referring to, describing, evidencing, or constituting.

1. All documents prepared by the NRC (including its consultants) beginning in 1995, concerning Con Edison's 1995 in-service inspection (hereafter, "ISI") of steam generators, including (i) documents created prior to the start of the ISI concerning the NRC's review of the procedures and plan of the ISI and documents concerning any meeting between Con Edison and the NRC to discuss the ISI or related issues; (ii) documents created during the ISI, including but not limited to, trip reports, and all other documents created by the NRC (including consultants) that was on site during the ISI; and (iii) documents created after the ISI, including but not limited to, documents concerning Con Edison's report to the NRC on the results of the ISI.

2. All documents prepared by the NRC (including consultants) *circa* 1997 concerning Con Edison's 1997 in-service inspection of steam generators including (i) documents created prior to the start of the ISI concerning the NRC's review of the procedures and plan of the ISI, and documents concerning any meetings between Con Edison and the NRC *circa* 1997 to discuss the ISI; (ii) documents created during the ISI, including but not limited to, trip reports and all other documents created by NRC personnel (including consultants) who were on site during the ISI; and (iii) documents created after the ISI, including but not limited to, documents concerning Con Edison's report to the NRC on the results of the ISI.

3. All documents prepared by the NRC (including consultants) in 2000 concerning the NRC's "Special Inspection" concerning the February 15, 2000 leak at Indian Point 2 (the Special inspection began in or about May 2000; the team manager was Dave Lew of Region 1; and the on-site team leader was Wayne Schmidt) and Notice of Violation ("NOV") to Con Edison dated November 20, 2000. (Please note that the NRC does not have to provide (i) documents already provided to the NRC by Con Edison pursuant to the Special Inspection or (ii) documents provided to the NRC by Con Edison in response to the NOV.)

4. All documents prepared by the NRC (including consultants) concerning Con Edison's December 7, 1998 request for an extension of the tube in-service inspection interval and the NRC's June 9, 1999 decision granting the request.

5. All documents prepared by the NRC (including consultants) concerning lessons learned from the February 15, 2000 leak at Indian point 2, including but not limited to, drafts of the Lessons Learned Report dated October 23, 2000, documents concerning the preparation of that Report, and all documents concerning communications to and from licensees concerning lessons learned from the February 15, 2000 leak at Indian Point.

6. All documents prepared by the NRC (including consultants) concerning the Inspector General's investigation and report concerning the February 15, 2000 leak at Indian Point 2, including but not limited to, drafts of the Inspector Generals' Report, 2000 and documents concerning the preparation of that Report.

7. All documents concerning the use of probes with frequencies above 700 kHz to test for PWSCC in the u-bends of steam generator tubes, including but not limited to,

documents prepared by Cass Dodd in 1999-2000 concerning such probes and documents concerning the first use of such probes to test for PWSCC in u-bends.

8. All documents concerning the probability of detection ("POD") for PWSCC in u-bends using a plus point probe with a frequency of 300-400 kHz and/or a probe using a frequency above 700 kHz.

9. All documents prepared by or for the NRC concerning profiling analysis to determine the depth that a crack had to penetrate a tube's wall before a plus point probe would detect the crack (see transcript of conference held on May 3, 2000, pages 93-94 (Emmett Murphy speaking) (copy attached).

10. The report prepared by or for the NRC concerning the depth that a crack had to penetrate a tube's wall before a plus point probe would detect the crack (see transcript of the May 3, 2000, meeting between the NRC and ConEdison, pages 89-93 (Emmett Murphy speaking) (copy attached).

11. The review prepared by a consultant for the NRC that is mentioned by Mr. Emmett Murphy at page 132 of the transcript of a May 3, 2000 meeting between the NRC and ConEdison (copy attached).

12. All documents prepared by Cais Dodd concerning (i) the ISI of the steam generators at Indian Point in 1997, (ii) the ISI of the steam generators at Indian Point in 2000, and (iii) the detection of PWSCC in u-bends (including but not limited to issues related to "noise," outer diameter deposits, and the operating frequency of the probes).

13. All documents concerning industry conferences in 1996-2000 that concerned detecting indications in tubes, "noise" in tubes that might mask indications, probability of detection of indications, outer diameter deposits on tubes, and probes operating at a frequency above 700 kHz to detect PWSCC in u-bends, including but not limited to, (i)

trip reports prepared by NRC employees or consultants, (ii) materials received at such conferences, and (iii) materials used at the hearing by the NRC or its consultants in making presentations.

14. All documents comparing the use of rotating pancake coils to bobbin coils for detecting PWSCC in u-bends.

15. . All documents prepared by the NRC (including its consultants) concerning Con Edison's request in 2000 to restart the Indian Point 2 plant without replacing the steam generators, including but not limited to, documents concerning the NRC's review of the request, the NRC's decisions to ask for more information from Con Edison, all documents concerning communications within the NRC (including with consultants), which involve whether to grant the request to restart, any drafts of documents granting and/or denying permission to restart, and any memoranda concerning such decisions or decision-making.

16. All documents concerning industry practices at any time between January 1, 1993 and December 31, 1998 for foreign material exclusion in the secondary side of nuclear power plants, including but not limited to, documents concerning (i) foreign materials causing forced outages or deratings at plants, (ii) foreign materials being found inside components in plants, (iii) the use of duct tape as a foreign material barrier, (iv) lessons learned from inadequate root cause evaluations, and (v) sandblasting or grit-blasting projects that caused forced outages or deratings at nuclear plants.

17. All documents concerning industry-wide standards and practices for root cause evaluations in the period 1993 through 1998.

18. All documents concerning industry practices at any time between 1995 and 1998 for root cause evaluations, including but not limited to, documents concerning

lessons learned from inadequate root cause evaluations and documents concerning industry-wide standards and practices for root cause evaluations.

19. All documents prepared by the NRC or its consultants concerning the NRC's review and consideration of the use of plus point probes to test for the presence of PWSCC in u-bends. This request includes, but is not limited to, documents comparing the detection abilities of plus point probes to other types of probes, documents concerning communications between the NRC and licensees concerning the appropriateness of using plus point probes to detect for PWSCC in u-bends, and documents concerning the frequency at which the plus point probe should be operated.

20. All documents prepared by the NRC or its consultants concerning the NRC's review, consideration, and comments concerning EPRI's Steam Generator Examination Guidelines: Revision 4 (dated June 1996).

21. All documents prepared by the NRC or its consultants concerning the NRC's review, consideration, and comments concerning EPRI's Steam Generator Examination Guidelines: Revision 5 (dated September 1997).

22. All documents prepared by the NRC or its consultants concerning the NRC's review, consideration, and comments concerning EPRI's Steam Generator Examination Guidelines: Revision 6 (at the time of this submittal, Revision 6 is currently in draft only and is dated April 24, 2001).

23. All documents prepared by the NRC or its consultants concerning the NRC's review, consideration, or comments concerning NEI 97-06 (dated April 1998).

1 address all degradation. Here I have highlighted what we
 2 believe to be the two, although we do need to look at all
 3 the degradation, but the two key elements are the low row
 4 U-bends PWSCC, the cracking mechanism for row two, column
 5 five, that led to the leakage, PWSCC at dented support
 6 plates is -- well, no indications, confirmed indications.7 found in this particular
 outage.
 8 The sludge pile, a lot of effort went into the
 9 inspection to look at, in considerable depth, the sludge
 10 pile assessment will be performed as a part of this effort.
 11 And there is the area above, if we call the sludge pile ten
 12 inches, above the sludge pile, those two, sludge pile and
 13 free span above the sludge pile are OD degradation, and then
 14 areas that have to be addressed in the tube sheet.
 15 There is denting at the top of the tube sheet, can
 16 cause some indication in those dents. Crevice region ODSCC,
 17 the tubes in the Indian Point units are fully expanded for
 18 the first two and a half inches or so at the bottom of the
 19 tube sheet. They're not expanded the rest of the way in the
 20 tube sheet and you get deposits on the tubes and you can get
 21 OD cracking inside.
 22 And then in the role transition, a couple inches
 23 from above the top of the tube -- the bottom of the tube
 24 sheet, there is a PWSCC indication. These will all be
 25 addressed in the final CMOA.

1 We focus more of this discussion today on the low
 2 row U-bends and then come back and more briefly address the
 3 other degradation mechanisms again.
 4 We've, I think, pretty much covered these first
 5 couple topics, 2-5 would not have been called in 1997. We
 6 believe and very strongly believe that the improvements in
 7 going to the 800 kilohertz high frequency probe, we would
 8 not be leaving any indications of that size in service as a
 9 result of the 2000 inspection.
 10 So the POD has been improved by probe,
 11 improvements in the analysis, guidelines and training. The
 12 high frequency probe, which improved the signal-to-noise
 13 ratio. Clear indication is one of the 2-4 type, row 2,
 14 column 4 indication, shown earlier. We can really begin to
 15 see a lot of the very small indications relatively clearly
 16 with the high frequency probe.
 17 And a very important element, no indications found
 18 in rows three and four and all the indications have been in
 19 row two. We will discuss the PODs that we are planning to
 20 apply in the assessment for the U-bend and compare basically
 21 based on the extreme case of industry experience.
 22 MR. MURPHY: I take it you're going to -- go
 23 ahead, go ahead.
 24 MR. PITTERLE: This represents, in searching back
 25 through PODs that have been developed for PWSCC, this

1 represents kind of the range of PODs that have been found
 2 for a +Point coil. Now, applying this here specifically to.3 the 800 kilohertz probe,
 I'm not trying to draw conclusions
 4 on the 400 kilohertz, where the issues of bad data come into
 5 play.
 6 But as far as looking forward from this inspection
 7 on, showing what has been one of the better PODs found for
 8 +Point for PWSCC has been for denting at tube support
 9 plates. In this condition, the dents are relatively
 10 symmetric. The +Point probe tends to cancel out a lot of
 11 the denting effects and detection with the +Point probe is
 12 very good.
 13 And we see that developed through a combination of
 14 pulled tubes and extensive laboratory testing is shown the
 15 +Point POD here, lost call rates for that particular exam
 16 were very, very low, a few percent, and it represents
 17 considerable effort in training, procedures, went into that
 18 program.
 19 MR. MURPHY: Tom, you're not suggesting that these
 20 PODs here on this chart are representative of those in the
 21 U-bend, even with the +Point.
 22 MR. PITTERLE: I believe that this POD is
 23 representative, the lower one, representing the lower band
 24 of indications of +Point detection is typical of what we can
 25 expect for the 800 kilohertz probe, not for the 400

1 kilohertz.
 2 MR. MURPHY: I guess based on the information on
 3 the table, we wouldn't agree with that. It would seem to us
 4 that one is not going to detect a significant fraction of
 5 these until the max depth is on the order of 70 percent
 6 thruwall.
 7 Be that as it may, there's no -- you don't have it
 8 with the surface deposits.
 9 MR. PITTERLE: I agree we do not have a
 10 performance demonstration set, but I think I disagree with
 11 the first statement that if you look at the depths that we
 12 found, the average depth, this is average depth, the max
 13 depth shifts approximately 30 percent to the right, we found
 14 an indication in this range, two indications in this range.
 15 Let me get the numbers straight.
 16 I don't have a full set of numbers, but there's
 17 two indications, one around 14, one about 20. A large group
 18 of indications found in this range of average depth.
 19 MR. MURPHY: Those are square with the experience.
 20 The seven or eight U-bend indications found at Indian Point.
 21 MR. PITTERLE: This is Indian Point.
 22 MR. MURPHY: I'm talking about the U-bend
 23 indications.
 24 MR. PITTERLE: Yes.
 25 MR. MURPHY: Our assessment is these indications.90

1 don't become visible to the +Point until you have about a
 2 one volt response from the flaw and taking the +Point depth
 3 measurements at face value, the depths have to penetrate on
 4 the order of 60 to 70 percent thruwall before you get
 5 anything approaching a one volt response from the law.
 6 So that would seem to be roughly the detection
 7 threshold for cracks in the U-bend.
 8 MR. PITTERLE: I don't know the basis for that
 9 statement. We sized these indications and as I will go
 10 through a little bit, the sizing of the indications, when we
 11 do benchmark calculations, demonstrates that we are being
 12 pretty conservative with these indications.
 13 And when we evaluate the data, 400 kilohertz data,
 14 which is the basis for sizing, because that's the one that's
 15 been developed, and the techniques that we're applying were
 16 developed for 400 kilohertz, there is a 14.4 average percent
 17 depth indication, a 23 percent average depth indication,
 18 large group between 38.9 to 45, 55, the 64.
 19 MR. MURPHY: This is for axial dents, though.
 20 MR. PITTERLE: The technique is derived from axial
 21 dents, but the sizes of these particular indications found
 22 in the U-bend.
 23 MR. MURPHY: But I guess the question that arises
 24 is where is the evidence that this kind of information
 25 applies to cracks in the U-bend.

1 MR. PITTERLE: Don't have any direct indication, I
 2 concede, because there has not been an equivalent
 3 demonstration program. But the coils from the indications
 4 are riding the surface quite well, and certainly at the
 5 apex, where these indications are located, that the basic
 6 technique should be reasonable accurate.
 7 We've increased the uncertainty by 25 percent to
 8 cover the differences between the support plates, the
 9 standard deviation. When we do the tube integrity, we
 10 increase the uncertainty by 25 percent.
 11 But there's no good reason to expect that it's
 12 going to be radically different in the U-bend. We've looked
 13 at it for the same techniques, for example, against pulled
 14 tubes and role transitions. They work quite well. I agree
 15 there's going to be and we felt it also necessary to
 16 increase the uncertainty treatment for it, but I believe
 17 we're certainly of the right magnitude.
 18 But increase in deviation, we're looking at maybe
 19 plus or minus ten percent average depth, a little bit more,
 20 12 percent. And there is nothing to indicate that these
 21 tubes are all -- that we found are all up here.
 22 MR. MURPHY: Well, I explained how we came to our 23 conclusion and I think to
 23 support a different conclusion is
 24 going to take a heck of a lot more supporting information
 25 than has thus far been presented.

1 MR. PITTERLE: Well, I don't think I understood
 2 how you came to a conclusion that all these indications are
 3 70 percent.
 4 MR. MURPHY: It appears that that is the threshold
 5 at which flaws are being detected, that's correct.
 6 MR. PITTERLE: But I don't see any data that says
 7 that.
 8 MR. MURPHY: The decision was made not to pull
 9 tubes, so we don't have any supporting tube information,
 10 pulled tube information to help resolve this issue.
 11 Certainly pulled tubes from Indian Point would be
 12 very helpful, but it was decided not to do that.
 13 MR. PITTERLE: I think we'll need to certainly
 14 cover that one in more detail and I do believe that the
 15 sizing is reasonable, if I'm looking at 12 percentage
 16 average depth, that's a lot of difference in an average
 17 depth of the flaw, size in error, the large error that we've
 18 encompassed, and I cannot believe that something more sizing
 19 that 20 percent is 70 percent average depth. It just --
 20 MR. MURPHY: Well, you're not sizing the U-bend
 21 flaws at 20 percent.
 22 MR. PITTERLE: Yes.
 23 MR. MURPHY: Okay. I see the source of our
 24 discrepancy then, because our profiling analysis, by our
 25 consultants, indicates that these depths, when they're being

1 detected, are on the order of 70 percent thruwall.
 2 MR. PITTERLE: I think we'll need to sit down very
 3 carefully with the consultants and see how --
 4 MR. MURPHY: I understand. Once you have a 70
 5 percent thruwall penetration that produces at least a one
 6 volt response, making it detectable, now, with the ability
 7 of hindsight, you can go in and you can pick out lower
 8 percentage thruwall components of the crack below the noise.
 9 You can dig those out.
 10 But unless you have a segment of the crack that's
 11 producing at least a one volt signal, by which time it's
 12 about 70 percent thruwall, unless you have that situation,
 13 you're just not going to pick out a lesser crack from the
 14 noise. It's just not going to have the voltage amplitude.
 15 MR. PITTERLE: I think we're different already at
 16 the voltage dependence on depth. These flaws that we're
 17 sizing at 23 percent, for example, is .86 volts. No reason,
 18 on an ID flaw, we believe that a one volt ID flaw is 70.19 percent deep. It doesn't
 19 jive. The ID voltages are much
 20 higher than you can anticipate seeing an OD flaw.
 21 But it's something I think we're going to have to
 22 come across the table in detail to --
 23 MR. MURPHY: We've done a lot of profiling
 24 analyses on our end of the table and it may be that there
 25 are some -- a conciliation process that needs to be gone

1 probe versus the other that's going to detect some of these
 2 small indications and the other one won't.
 3 This is really -- I would argue it actually
 4 supports CECCO, but I'm not trying to make any point of one
 5 probe or the other, other than this certainly is a good
 6 over-check on the inspection, the detection in the sludge
 7 pile region. That's the main point.
 8 Again, as I talked about before, we did the U-tech
 9 inspection of 23 tubes. That confirmed the CECCO call.
 10 All of this was basically done, this additional
 11 testing was done to make sure that we had done everything
 12 practical, possible, debate between those two adjectives, to
 13 identify any of the indications in the first pass above the
 14 top of the tube sheet.
 15 In addition, since we basically made the decision,
 16 we're going to basically in situ test everything in the
 17 sludge pile region just to make sure that we did not have
 18 sizing problems. Thirty-one tubes were in situ tested. All
 19 met the 9706 or the burst criteria, the leakage criteria,
 20 basically none leaked, steam line break.
 21 The only one that leaked at all in the full test
 22 pressure of 5500 psi cold was 3451. And this, the peak test.23 pressure reached was
 4985 and I'm just going to -- I'm used
 24 to working with hot, it's 4591 psi into a hot condition.
 25 Well, you talked about how close together one was,

1 to address that question. We have the same question.
 2 MR. PITTERLE: The bottom line is that the tube
 3 and looking at that, it didn't even open up the length of
 4 the crack, it probably did not burst either, it's a ligament
 5 tear, but in either case, just met the three delta P
 6 criteria.
 7 In the cold leg program, the initial inspection
 8 with CECCO and bobbin probe, then followed by 20 percent of
 9 one steam generator with +Point from the cold to just above
 10 the first tube support plate.
 11 Inspected 20 percent of each of the other three
 12 steam generators to the tube end cold to 24 inches above the
 13 tube sheet, but, again, an over-check with +Point to assure
 14 that we've picked up any significant indications.
 15 No crack-like indications were found in any of
 16 these inspections, were found to varying degrees of pits,
 17 and as a result of finding some pit-like indications, 23 and
 18 24 were expanded to 40 percent of the tubes..19 And that, in fact, is all pit-like
 indications
 20 have been plugged and no cracking was found by any of this
 21 extended inspection on the cold leg.
 22 The cold leg is basically pits and tend to be
 23 small, from all indications, negligible growth, but as a
 24 conservative element, they have been repaired. See really
 25 no anticipation of this being an issue in the operational

1 it's at three delta P. You take the 4591, divide it by the
 2 4985, 4591 psi hot, divide it by the 1539 normal operating
 3 delta P, the burst margin is 2.98, bounds to three.
 4 MR. MURPHY: Perhaps you can clarify something.
 5 Am I correct in recalling that this tube was detected by one
 6 of two analysts?
 7 MR. ADANONIS: That's correct.
 8 MR. MURPHY: Here we have a tube that, at this
 9 point in time, is marginal with respect to meeting NRC
 10 performance criteria and was only detected by one of two
 11 analysts? I believe that five -- only five of the eight
 12 actual indications were detected by both analysts and the
 13 review conducted by our consultant indicated that this
 14 indication certainly was one that should have been detected
 15 by both analysts.
 16 I think as we indicated to you last week, I guess
 17 this is a source of concern for us and certainly I think we
 18 need to understand a little bit better why this type of
 19 indication, which includes one that was quite marginal in
 20 terms of its burst pressure capability, why there isn't
 21 better performance in the field in picking up this kind of
 22 indication.
 23 MR. ADANONIS: And we are in the process of going
 24 back and pulling together those statistics and looking at
 25 these particular indications in detail to be in a position

1 assessment.
 2 MS. KAUFMANN: Tom, when you talked about the
 3 comparison between CECCO and +Point for the sludge pile, did
 4 you do a similar comparison for the cold leg inspection
 5 between +Point calls and CECCO calls?
 6 MR. PITTERLE: I think the only difference was a
 7 couple pit calls.
 8 MR. ADANONIS: There were a number of pits. I
 9 don't have the statistics with me, but there were pits
 10 identified with the bobbin or identified with the +Point.
 11 MR. PITTERLE: The point is when you take a +Point
 12 to something like the pits, even if you inspect, say, new
 13 steam generator tubing, you get what's sometimes called a
 14 lap indication, you can see those with +Point, down to two
 15 or three percent depth. You see in some of these it may
 16 well be a manufacturing defect, there is no way of
 17 separating them in this vintage of a plant.
 18 Tube sheet region, then the tube sheet burst is
 19 not an issue, the restraint of the tube sheet prevents the
 20 tube from bursting, so it's really just the -- not just, but
 21 is a leakage related question.
 22 Again, CECCO and +Point correlation as far as
 23 confirmation with CECCO was similar to that of the
 24 qualification. There appears to be less of an influence of
 25 copper within the tube sheet crevice.