

Steam Generator Issues

Generic Implications of TMI Tube
Sever Event

January 31, 2002

1/31/2002

1



Presentation Outline

- Update TMI and Oconee Inspection Results
- Industry Assessment
- Industry Actions to Date
- Industry Action Plan
- Response to NRC Questions
- Conclusions
- Next Meeting

1/31/2002

2



TMI Results

■ Inspection Results

- 870 tubes de-plugged
- 263 tubes contained water
- No tubes with original Alloy 690 plugs (87) contained water or any evidence of swelling
- 29 tubes have swelling present:
 - ◆ Westinghouse Alloy 600 re-rolled plugs (23) top and bottom
 - ◆ Framatome Alloy 600 rolled plugs (6) replaced with Framatome Alloy 690 rolled plugs on top and Framatome ribbed plugs bottom

1/31/2002

3



TMI Results

■ Two severed tubes

- B66-130, Severed at UTSF
 - ◆ Impacted 4 surrounding tubes
 - ◆ Original UTS Alloy 600 rolled plug replaced in 1997 with Alloy 690 (ribbed A-600 at bottom)
- A2-24, Severed at 15th TSP
 - ◆ No impact on surrounding tubes
 - ◆ Westinghouse Alloy 600 rolled plugs top and bottom, re-rolled after hot functional testing

■ One axial burst


- B150-14, Opening in Top Span
 - ◆ Original UTS Alloy 600 rolled plug replaced in 1997 with Alloy 690 (ribbed A-600 at bottom)

1/31/2002

4



Tubes With Damage Surrounding B66-130



1/31/2002

5

NEI

TMI Root Cause Assessment

■ Failure scenario for B66-130

- Tube swelled during heatup due to trapped water
- Tube became restrained at top TSP and UTS
- Restraint isolated top span & decreased damping
- Tube severed due to high cycle fatigue caused by flow-induced vibration at area of high cross flow
 - ◆ Initiated at shallow OD IGA patch

■ Populations with observed swelling at TMI

- Locations where plugs were repaired without de-watering
 - ◆ Westinghouse A-600 roll plugs re-rolled in place
 - ◆ Framatome A-600 UTS roll plugs removed & replaced

1/31/2002

6

NEI

ONS-3 Plugged Tube Inspection

- 108 UTS rolled plugs removed, tube inspected
 - All locations (73) where either UTS or LTS plugs were removed and replaced
 - Older Alloy 600 plug locations (35)
- Results
 - 22 tubes contained water
 - ◆ One through-wall leak at site of original tube defect
 - 8 tubes >50% filled with water (6 tubes > 70%)
 - No swollen, severed, or burst tubes

1/31/2002

7



Comparison of TMI-1 and Oconee-3 Results

- Difference can be explained by relative numbers of plugged tubes most susceptible to swelling:
 - Westinghouse re-rolled A-600 plugs
 - ◆ TMI - 484 tubes, 23 were swollen (5%)
 - ◆ ONS - 0 tubes
 - Removed / replaced UTS Framatome A-600 rolled plugs
 - ◆ TMI - 248 tubes, 6 were swollen (2%)
 - ◆ ONS - 37 tubes, 0 swollen
 - Would expect <1 swollen tube based on percent affected at TMI-1

1/31/2002

8



Comparison of TMI-1 and Oconee-3 Results

- TMI had a larger population of the plugged tubes susceptible to severance from swelling:
 - 546 total at OTSGs
 - ◆ 492 inspected at TMI-1
 - ◆ 11 inspected at ONS-3
 - ◆ 43 elsewhere:

ANO-1, 8 (Fall 2002)	ONS-1, 18 (Spring 2002)
CR-3, 1 (Fall 2003)	ONS-2, 11 (Fall 2002)
Davis Besse, 1 (Spring 2002)	ONS-3, 4 (Spring 2003)

1/31/2002

9



Industry Actions to Date

- Senior management meeting with NRC on 11/29
- Communicated event to the industry
 - BWOOG meeting week of 12/3
 - SGMP TAG meeting week of 12/10
- Developed initial assessment and submitted to NRC on December 21, 2001
- Numerous industry meetings and telecons including a meeting at NEI on January 10th

1/31/2002

10



OTSG Initial Assessment

- Time is available to take action on the susceptible plugged tubes:
 - Based on the rate of wear at TMI and the time that an affected tube could be expected to be in service in a condition that it may fail under MSLB conditions, the changes in CDF and LERF for the remaining plants would be in Region III of RG 1.174
 - The risk attributable to other plug types is inconsequential to the short term operation of the plants

1/31/2002

11



RSG Initial Assessment

- Time is available to study the issue:
 - Three potential areas of high flow concern in RSGs:
 - ◆ U-bends
 - Response to NRC Bulletin 88-02 on rapidly propagating fatigue cracks in U-bends
 - ◆ Top of tube sheet
 - Operating experience and/or analysis for plants with locked tubes has identified no fluid-elastic instability problems
 - ◆ Pre-heater
 - Encompassed by actions taken in response to stability analyses performed in the early 80s
 - CE system 80 plants stabilize degraded tubes in the pre-heater region with high flow velocities

1/31/2002

12



RSG Initial Assessment

- Operating experience shows that among the plug diode effects observed, only axial failures occurred which caused no damage to in-service tubes
- Unplugged hundreds of tubes – no known severed tubes
- Thousands of locked / dented tubes in the areas of highest cross flow velocity with no fatigue failures confirms analysis results
- No locations of fluid-structure coupling where fatigue failure of swollen tubes is expected



1/31/2002

13

Current Status

- BWOOG developed recommendations for addressing susceptible plug types to be implemented during next scheduled outage
 - May be revised based on experience and longer term study
- SGMP taking lead to address generic implications
 - Received proposals and directed scope of initial tasks
 - Developing long term plan



1/31/2002

14

Initial Tasks

- Identify potential damage mechanisms that would cause plugged tubes to damage adjacent tubes
 - Include interaction effects
- Evaluate the existing level of analytical and empirical data to ensure it is sufficient to support conclusions
- Evaluate the probability of occurrence of each mechanism
- Rank mechanisms in order of importance
- Determine need and priority of additional action



1/31/2002

15

Action Plan Scheduling

- Time is available to study the significance of the issue and determine appropriate actions
 - Complete initial tasks in 5 months
 - If safety significant issues are identified, follow up action will be initiated immediately and communicated to the NRC
 - Longer term actions will be addressed through the SGMP process



1/31/2002

16

Response to NRC Questions

- 1) RSG operating experience on swelled and ruptured tubes
 - Visual inspections have identified ruptured tubes in row 1 and peripheral tubes
 - ◆ These are the most limiting locations from a FIV perspective
 - Frequent visual inspections of the interior are performed, but not for the purpose of identifying swelled tubes
 - Numerous interior tubes have been returned to service
 - no swollen or ruptured tubes have been identified
 - ◆ Sample size is comparable to TMI's unplugging campaign

1/31/2002

17



Response to NRC Questions

- 2) Probability that a plugged RSG tube may sever over the long term
 - Analyses have been performed on tubes locked at the most limiting locations from a FIV (turbulence and fluid elastic) perspective
 - ◆ Fatigue evaluations consider the maximum effect of mean stress
 - ◆ Existing analyses indicate that a significant pre-existing crack must be present to exceed the threshold for fatigue crack growth
 - Initial tasks of industry action plan will address this item further

1/31/2002

18



Response to NRC Questions

- 3) Basis for limiting OTSG tube plug types susceptible to swelling / burst
 - 12/01 letter stated that all plugged tubes are potentially susceptible to swelling
 - Short term actions focused on most susceptible tube populations
 - ◆ Joint repaired such that existing water trapped inside
 - ◆ Supported by OTSG field experience to date
 - 31 of 31 known observations fall in this category
 - Many locations in other categories inspected with no swollen tubes
 - All plug types will be evaluated as part of long term plan

1/31/2002

19



Response to NRC Questions

- 4) Total Number of Tubes Plugged in OTSGs

Plant	Number of Tubes Plugged
ANO-1	1274
CR-3	947
DB-1	540
ONS-1	2429
ONS-2	1998
ONS-3	1980
TMI-1	2064

1/31/2002

20



Response to NRC Questions

Types of Plugs Installed in OTSGs

Plug Type	Mfg	Matl	Dates Plugs Installed			Total Installed	Total Removed / Repaired	Current Pressure Boundary
Ribbed	FRA-ANP	I600	Oct-83	To	Oct-88	998	205	793
	WEST	I600	Jun-83	To	Oct-84	190	119	71
Roll Tube Plug	FRA-ANP	I600	Feb-85	To	Mar-90	974	555	419
	FRA-ANP	I690	Feb-90	To	Present	17967	471	17496
	WEST	I600	Mar-82	To	Nov-84	1021	478	543
	CE	I690	Sep-91	To	Sep-91	56		56
Roll Sleeve Plug	FRA-ANP	I600 & I690	Apr-90	To	Present	213	1	212
Explosive Welded	FRA-ANP	I600	Jan-71	To	Oct-84	1431	1117	314
Tig Welded	FRA-ANP	I600 & I690	Jan-70	To	Present	2602	43	2559
	CE	I690	Sep-91	To	Sep-91	1		1
						Total	22464	

1/31/2002

21



Response to NRC Questions

■ 5) Basis for OTSG 50% fill information

- TMI-1 Tubes de-watered by inserting eddy current sheath into tube
 - ◆ Displaced approximately 1/2 of tube volume
 - ◆ Displacement of water onto tubesheet indicates tube >50% full
 - Actual volume of water not recorded
- Pressurization can occur during heatup when tube >70% full at room temperature
 - ◆ Based on ratio of specific volume of water at hot conditions to cold conditions

1/31/2002

22



Response to NRC Questions

- 6) Basis for OTSG not de-plugging and inspecting A-690 rolled plugs
 - Initial focus on most susceptible locations, as determined by field observations
 - ◆ Locations where plugs repaired w/o de-watering
 - UTS plug removed / replaced
 - Plugs re-rolled after pressurization cycle
 - Alloy 690 roll plugs benefit from improved installation techniques
 - ◆ Much better control of installation torque
 - ◆ Better sealing at temperature (up to factor of 10)
 - ◆ Field observations at TMI and Oconee-3 show that originally installed A-600 and A-690 roll plugs generally have low leakage in service

1/31/2002

23



Response to NRC Questions

- 7a) Flow stability margin at TMI tubes B66-130 and A2-24
 - These tubes are less than 1" from periphery.
 - Difference in T/H parameters between the outermost tubes and these tubes is insignificant
 - ◆ Therefore FSM = 1.1 applies to these tubes as well

1/31/2002

24



Response to NRC Questions

■ 7.a.1) OTSG Performance Near 1.0 Flow Stability Margin

- For flow velocity well below critical velocity
 - ◆ Coupling between the tube bundle and fluid flow is negligible
- For flow velocity near the critical velocity
 - ◆ Coupling force plays larger role in response resulting in a significant increase in vibration amplitude
- Standard approach recommended by ASME code is based on “joint acceptance” method
 - ◆ Does not include coupling between tube bundle and fluid flow
 - ◆ Underestimates vibration amplitudes when flow velocity is near critical

1/31/2002

25



Response to NRC Questions

■ 7.a.2) Basis for screening criteria for determining OTSG tubes susceptible to FIV if severed tubes have FSM >1.0

- Fatigue analysis not based on fluid-elastic instability (Connors' equation)
 - ◆ This determines only if tube is stable
- Fatigue analysis for tubes in flows close to critical velocity requires a more exact method
 - ◆ Non-linear structural dynamics
 - ◆ Direct time domain solution
 - Strictly model fluid-structure interaction force
- An acceptance criteria based only on FSM is not appropriate.
- Susceptible populations in OTSGs have been preliminarily identified. Any changes to the threshold for tube sever concerns would be addressed as part of the long term plan.

1/31/2002

26



Response to NRC Questions

- 7.a.3) OTSG flow stability margin prediction model conservatism re: FSM prediction using lower bound damping
 - Predicted FSM is consistent with field observations
 - ◆ No mid-span impacting of B66-130 on adjacent tubes - tube was stable prior to severance
 - Only 2 of 26 swollen tubes in the periphery were severed
 - Use of nominal damping would increase FSM to ~1.3

1/31/2002

27



Response to NRC Questions

- 8) OTSG risk assessment of generic implications of tube sever / wear
 - SGTR is an analyzed event and is modeled in PRAs
 - Typical initiating event frequency for SGTR is between $5e-3$ and $1e-2$ /year
 - Bounding increase in SGTR probability is $\leq 1e-2$
 - ◆ TMI precursor frequency: <1 SGTR per 492 susceptible tubes (assume one fuel cycle) = 0.0014 /tube-year
 - ◆ Bounding B&WOG plant has 11 susceptible tubes and 8 months until next outage
 - ◆ 0.0014 /tube-year x 11 Tubes x 8 Months = $1e-2$

1/31/2002

28



Response to NRC Questions

- 8) OTSG risk assessment of generic implications of tube sever / wear
 - SGTR is typically a small percentage of plant CDF and LERF
 - Based on B&WOG PRA
 - ◆ Conditional core damage probability given SGTR is about $1e-4$
 - ◆ Conditional large early release probability given SGTR is about $1e-5$
 - Therefore, one-time increase in core damage probability is $\leq 1e-6$ and large early release probability $\leq 1e-7$

1/31/2002

29



Summary and Conclusions

- SGMP is taking the lead
- An action plan is being developed and initial tasks are underway
- Meet with staff after initial tasks are completed
- Plants are operating safely and time is available to complete actions

1/31/2002

30

