

April 18, 2002

Mr. Douglas E. Cooper
Site Vice President
Palisades Nuclear Plant
Nuclear Management Company, LLC
27780 Blue Star Memorial Highway
Covert, MI 49043-9530

SUBJECT: PALISADES NUCLEAR GENERATING PLANT
NRC INSPECTION REPORT 50-255/02-02(DRP)

Dear Mr. Cooper:

On March 31, 2002, the NRC completed an inspection at your Palisades Nuclear Generating Plant. The enclosed report documents the inspection findings which were discussed on April 11, 2002, with members of your staff.

The inspection examined activities conducted under your license as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your license. The inspector reviewed selected procedures and records, observed activities, and interviewed personnel.

Based on the results of this inspection, we identified three issues of very low safety significance (Green) that were determined to involve violations of NRC requirements. However, because of the very low safety significance and because the issues were entered into your corrective action program, the NRC is treating these issues as Non-Cited Violations in accordance with Section VI.A.1 of the NRC's Enforcement Policy. If you deny these Non-Cited Violations, you should provide a response with a basis for your denial, within 30 days of the date of this inspection report, to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555-0001, with copies to the Regional Administrator, Region III; the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Resident Inspector Office at the Palisades facility.

D. Cooper

-2-

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/NRC/ADAMS/index.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Anton Vogel, Chief
Branch 6
Division of Reactor Projects

Docket No. 50-255
License No. DPR-20

Enclosure: Inspection Report 50-255/02-02(DRP)

cc w/encl: R. Fenech, Senior Vice President, Nuclear
Fossil and Hydro Operations
L. Lahti, Manager, Licensing
R. Anderson, Chief Nuclear Officer, NMC
A. Udrys, Esquire, Consumers Energy Company
S. Wawro, Nuclear Asset Director, Consumers Energy Company
W. Rendell, Supervisor, Covert Township
Office of the Governor
Michigan Department of Environmental Quality
Department of Attorney General (MI)

DOCUMENT NAME: G:\pali\ML021080831.wpd

To receive a copy of this document, indicate in the box: "C" = Copy without enclosure "E" = Copy with enclosure "N" = No copy

OFFICE	RIII	E	RIII		RIII	E		
NAME	Passehl/trn		Creed		Vegel			
DATE	04/18/02		04/18/02		04/18/02			

OFFICIAL RECORD COPY

ADAMS Distribution:

WDR

DFT

DSH

RidsNrrDipmlipb

GEG

HBC

JAL3

C. Ariano (hard copy)

DRPIII

DRSIII

PLB1

JRK1

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Docket No: 50-255
License No: DPR-20

Report No: 50-255/02-02(DRP)

Licensee: Nuclear Management Company, LLC

Facility: Palisades Nuclear Generating Plant

Location: 27780 Blue Star Memorial Highway
Covert, MI 49043-9530

Dates: February 10 through March 31, 2002

Inspectors: J. Lennartz, Senior Resident Inspector
R. Krsek, Resident Inspector
H. Peterson, Senior Operations Engineer (Lead Inspector)
M. Morris, License Examiner
H. Walker, Reactor Engineer

Approved by: Anton Vogel, Chief
Branch 6
Division of Reactor Projects

SUMMARY OF FINDINGS

IR 05000255/02-02 on 02/10/2002 - 03/31/2002, Nuclear Management Company, LLC, Palisades Nuclear Generating Plant. Maintenance Rule, Identification and Resolution of Problems, and Event Follow-up.

This report covers a 6-week routine inspection, and a baseline licensed operator requalification inspection. The inspections were conducted by resident and specialist inspectors.

A. Inspector Identified Findings

Cornerstone: Mitigating Systems

- Green. The inspectors identified one Green finding that is being treated as a Non-Cited Violation of 10 CFR 50, Appendix B, Criterion XVI, "Corrective Actions." Licensee personnel failed to promptly identify and correct repetitive failures of high pressure air system Check Valve CK-CA476, which had been occurring since the 1996 time frame. In addition, the most recent failure which occurred in April 2001, was a condition adverse to quality for which no apparent or root cause had been performed in accordance with the licensee's corrective action program.

This inspector identified finding was determined to be of very low safety significance (Green) by the significance determination process, because: (1) the finding was not a design or qualification deficiency; (2) the finding did not represent an actual loss of safety function based on as-found check valve leakage; (3) the finding did not represent an actual loss of a safety function of a single train for greater than Technical Specification outage time; (4) the finding did not represent an actual loss of a safety function of one or more Non-Technical Specification trains of equipment; (5) the finding did not screen as potentially risk significant due to a seismic, flooding, or severe weather initiating event; and (6) while the finding could potentially be a design or qualification deficiency, the licensee's operability determinations confirmed that the check valve leakage did not result in a loss of function per Generic Letter 91-18, Revision 1. (Section 1R12.1)

- Green. The inspectors identified one Green finding that is being treated as a Non-Cited Violation of 10 CFR 50, Appendix B, Criterion XVI, "Corrective Actions." Licensee personnel failed to identify during an apparent cause evaluation completed on February 4, 2002, for Condition Report CPAL0200059, "Fire Pump P-9A Tripped After Running For Approximately Three Minutes," that inadequate post maintenance testing activities were specified in a work order following electrical breaker maintenance for Fire Pump P-9A. Because the licensee's apparent cause failed to identify the inadequate post maintenance testing, there were no corrective actions developed to ensure that appropriate post maintenance testing would be specified on subsequent work orders for electrical breaker maintenance similar to that conducted on Fire Pump P-9A.

This inspector identified finding was determined to be of very low safety significance (Green) by the significance determination process, because: (1) the finding was not a design or qualification deficiency; (2) the finding did not represent an actual loss of safety function in that two other fire pumps were always available; (3) fire protection pumps are not in the Technical Specifications, and therefore the finding did not represent an actual loss of a safety function of a single train for greater than Technical Specification outage time; (4) the finding did not represent an actual loss of a safety function of one or more Non-Technical Specification trains of equipment in that two other fire pumps were always available; (5) the finding did not screen as potentially risk significant due to a seismic, flooding, or severe weather initiating event in that the finding did not involve the loss of degradation of equipment or function specifically designed to mitigate a seismic, flooding or severe weather initiating event; and (6) the finding did not involve the loss of a safety function that contributed to external event initiated core damage accident sequences from fires in that two fire pumps were always available. (Section 4OA2)

- Green. The inspectors identified a Green finding that is being treated as a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control," for the failure to ensure that the measures for verifying and checking the adequacy of the design for Specification Change SC-94-130 assured that the applicable regulatory requirements and the design basis of the containment sump check valves were met.

This inspector identified finding was determined to be of very low safety significance (Green) by the significance determination process, because the finding was a design deficiency confirmed not to result in a loss of function per NRC Generic Letter 91-18, Revision 1. The licensee's past operability analysis credited the use of containment overpressure and calculated plant parameters following a design basis accident and concluded that the available net positive suction head was above that required for all engineered safeguards system pumps considering the most limiting design basis accident conditions. Therefore, the engineered safeguards system pumps would have been able to perform the intended safety function and were operable, but nonconforming in accordance with Generic Letter 91-18, Revision 1. (Section 4OA3.1)

B. Licensee Identified Findings

None.

Report Details

A list of documents reviewed within each inspection area is included at the end of the report.

Summary of Plant Status

The plant was essentially at full power for the duration of the inspection period. Power was reduced and maintained at 99.5 percent to address issues with a relief valve on the balance of plant system (non-nuclear safety related system).

1. REACTOR SAFETY

Cornerstones: Initiating Events, Mitigating Systems, Barrier Integrity

1R04 Equipment Alignment (71111.04)

.1 Quarterly Equipment Alignment Walkdowns

a. Inspection Scope

The inspectors performed partial walkdowns of the East Safeguards High Pressure Air System, and the High Pressure Safety Injection Pump P-66B. The inspectors performed the walkdowns to verify proper system lineup while redundant plant equipment was out of service. The inspectors verified that power was available, that accessible equipment and components were appropriately aligned, and that no discrepancies existed which would impact the systems' function. Portions of the system alignment inspection included discussions and system walkdowns with operations and engineering personnel.

The inspectors also reviewed selected condition reports that had been entered into the licensee's corrective action program to verify that the corrective actions were reasonable and had been implemented as scheduled.

b. Findings

No findings of significance were identified.

1R05 Fire Protection (71111.05Q)

.1 Area Walkdowns

a. Inspection Scope

The inspectors toured the following areas in which a fire could affect safety related equipment:

- Control Room Complex (Fire Area 1); and
- Auxiliary Building 590-Foot Level Corridor (Fire Area 13).

The inspectors assessed the material condition of the passive fire protection features and verified that transient combustibles and ignition sources were appropriately controlled. Also, the inspectors reviewed documentation for randomly selected completed surveillances to verify the availability of the sprinkler fire suppression system, smoke detection system, and manual fire fighting equipment for these areas. The inspectors also verified that the fire protection equipment that was installed and available in the fire areas corresponded with the equipment which was referenced in the applicable portions of the Final Safety Analysis Report, Section 9.6, "Fire Protection."

b. Findings

No findings of significance were identified.

.2 (Closed) Temporary Instruction (TI) 2515/146: Hydrogen Storage Locations

a. Inspection Scope

The inspectors completed the inspection requirements of the TI to confirm that distances between any hydrogen storage capacity and ventilation intakes or risk significant tanks, systems, structures, or components were greater than 50 feet. The inspectors reviewed documents to verify that minor issues identified during the inspection were entered into the licensee's corrective action system.

b. Findings

No findings of significance were identified.

1R11 Licensed Operator Requalification (71111.11)

.1 Facility Operating History

a. Inspection Scope

The inspectors reviewed the plant's operating history from January 2001 through January 2002, to assess whether the Licensed Operator Requalification Training (LORT) program had addressed operator performance deficiencies noted at the plant.

b. Findings

No findings of significance were identified.

.2 Licensee Requalification Examinations

a. Inspection Scope

The inspectors performed a biennial inspection of the licensee's LORT program. The inspectors reviewed the annual requalification operating and written examination material to evaluate general quality, construction, and difficulty level. The operating portion of the examination was inspected during February 25 - March 1, 2002. The operating

examination material consisted of two dynamic simulator scenarios and five job performance measures (JPMs). No written examination was administered during this annual requalification examination. However, the 2001 biennial written examination material and overall results were reviewed. The biennial written examination consisted of 30 open reference multiple choice questions. The inspectors reviewed the methodology for developing the examinations, including the LORT program two year sample plan, probabilistic risk assessment insights, previously identified operator performance deficiencies, and plant modifications. The inspectors assessed the level of examination material duplication during the current year annual examinations and with last year's annual examinations. The inspectors also interviewed members of the licensee's management, operations, and training staff and discussed various aspects of the examination development.

b. Findings

No findings of significance were identified.

.3 Licensee Administration of Requalification Examinations

a. Inspection Scope

The inspectors observed the administration of the requalification operating test to assess the licensee's effectiveness in conducting the test and to assess the facility evaluators' ability to determine adequate performance using objective, measurable performance standards. The inspectors evaluated the performance of one staff crew and one operating shift crew during two dynamic simulator scenarios in parallel with the facility evaluators. In addition, the inspectors observed licensee evaluators administering five JPMs on a select number of operators. The inspectors observed the training staff personnel administering the operating test, including pre-examination briefings, observations of operator performance, individual and crew evaluations after dynamic scenarios, and techniques for JPM cuing. The final evaluation briefing for licensed operators was scheduled for the following week and was not observed. The inspectors noted the performance of the simulator to support the examinations. The inspectors also reviewed the licensee's overall examination security program.

b. Findings

No findings of significance were identified.

.4 Licensee Training Feedback System

a. Inspection Scope

The inspectors assessed the methods and effectiveness of the licensee's processes for revising and maintaining its LORT program up to date, including the use of feedback from plant events and industry experience information. The inspectors interviewed licensee personnel (operators, instructors, training management, and operations management) and reviewed the applicable licensee's procedures. In addition, the inspectors reviewed the licensee's quality assurance/quality control oversight activities,

including licensee's training and operations department self-assessment reports, to evaluate the licensee's ability to assess the effectiveness of its LORT program and to implement appropriate corrective actions.

b. Findings

No findings of significance were identified.

.5 Licensee Remedial Training Program

a. Inspection Scope

The inspectors assessed the adequacy and effectiveness of the remedial training conducted since the previous annual requalification examinations and the training planned for the current examination cycle to ensure that they addressed weaknesses in licensed operator or crew performance identified during training and plant operations. The inspectors reviewed remedial training procedures and individual remedial training plans, and interviewed licensee personnel (operators, instructors, and training management). In addition, the inspectors reviewed the licensee's current examination cycle remediation packages for unsatisfactory operator performance on the written examination and operating test to ensure that remediation and subsequent re-evaluations were completed prior to returning individuals to licensed duties.

b. Findings

No findings of significance were identified.

.6 Conformance with Operator License Conditions

a. Inspection Scope

The inspectors evaluated the facility and individual operator licensees' conformance with the requirements of 10 CFR Part 55. The inspectors reviewed the facility licensee's program for maintaining active operator licenses and to assess compliance with 10 CFR 55.53(e) and (f). The inspectors reviewed the procedural guidance and the process for tracking on-shift hours for licensed operators and which control room positions were granted credit for maintaining active operator licenses. The inspectors also reviewed six licensed operators' medical records maintained by the facility for ensuring the medical fitness of its licensed operators and to assess compliance with medical standards delineated in ANSI/ANS-3.4 and with 10 CFR 55.21 and 10 CFR 55.25. In addition, the inspectors reviewed the licensee's LORT program to assess compliance with the requalification program requirements as described by 10 CFR 55.59(c).

b. Findings

No findings of significance were identified.

.7 Quarterly Resident Inspector Licensed Operator Performance Observations

a. Inspection Scope (71111.11Q)

The inspectors observed licensed operator performance during annual requalification examinations on in-plant job performance measures to assess the operators ability to complete required actions in off-normal and emergency operating procedures. The inspectors also reviewed the completed operator evaluations to assess the licensee evaluator's ability to identify and assess operator performance deficiencies.

In addition the inspectors reviewed condition reports to verify that identified problems associated with licensed operator requalification training activities were appropriately characterized.

b. Findings

No findings of significance were identified.

1R12 Maintenance Rule Implementation (71111.12Q)

.1 Inadequate Corrective Actions for Repetitive Failures of a High Pressure Air System Check Valve

a. Inspection Scope

The inspectors reviewed the licensee's Maintenance Rule Scoping Document for the High Pressure Air System, which was designated as having high safety significance.

The inspectors reviewed the licensee's maintenance rule performance indicators associated with the system's maintenance rule category status. In addition, the inspectors discussed various technical issues with the applicable system engineer.

Further, the inspectors reviewed selected condition reports to verify that the identified issues were appropriately characterized and were dispositioned in accordance with the licensee's Maintenance Rule program. The inspectors reviewed selected condition reports to verify that designated corrective actions were reasonable and had been implemented as scheduled.

b. Findings

The inspectors identified a Green finding that is being treated as a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Actions," for the failure to promptly identify and correct conditions adverse to quality regarding repetitive failures of High Pressure Air System Check Valve CK-CA476.

Check Valve CK-CA476, a "Q" safety system component, was located in a high pressure air line used to cross-connect the nonsafety-related turbine building high pressure air system with the safety-related high pressure air system in the East and West Engineered Safeguards Rooms. The safety function of Valve CK-CA476 was to close in the event

that the Turbine Building high pressure air system failed while cross-connected to the safety-related air system. The closed check valve would prevent air leakage to the failed Turbine Building system.

The Turbine Building high pressure air system was normally isolated from the safety-related high pressure air system in the East and West Engineered Safeguards Rooms with locked closed manual valves. The safety- and nonsafety-related portions of the high pressure air system were only cross-connected for short periods of time when the associated East or West Safeguards air compressors were taken out of service for maintenance.

The inspectors reviewed the corrective actions associated with Condition Report CPAL0101229, "Check Valve CK-CA476 Soft Seat (O-Ring) Disengaged from Plug, and Piston Bore Found Unsatisfactorily." The inspectors noted that the significance level assigned to this condition report was a Level 4, which only required trending and if necessary, remedial action, with no apparent or root cause required.

The inspectors reviewed work order and condition report histories for this valve which revealed the following failure history associated with Check Valve CK-CA476:

- In December 1996, Condition Report CPAL9601793 was initiated and documented that Check Valve CK-CA476 failed the test acceptance criteria;
- In May 1998, Condition Report CPAL9800785 was initiated and documented that Check Valve CK-CA476 failed the test acceptance criteria;
- In October 1999, Condition Report CPAL9902216 was initiated and documented that Check Valve CK-CA476 failed the test acceptance criteria;
- In November 1999, Condition Report CPAL9902778 was initiated and documented that when the Turbine Building and East Engineered Safeguards High Pressure Air Systems were cross-connected Check Valve CK-CA476 exhibited leakby; and
- In April 2001, Condition Report CPAL0101229 was initiated and documented that the soft seat O-Ring of Check Valve CK-CA476 was found on the valve stem vice the soft seat thread.

The inspectors noted that while the valve failed the test acceptance criteria, the licensee's operability determinations documented that the exhibited as-found leakage had not yet affected the overall operability of the high pressure air system. However, the inspectors noted that in the last condition report (CPAL0101229), neither an apparent nor root cause was performed to determine the nature of the repetitive failures. Without an apparent or root cause, the inspectors also could not determine if the active Engineering Assistance Requests would correct the repetitive nature of the check valve failures. The inspectors noted that all condition reports associated with Check Valve CK-CA476 were closed out in the corrective action system as 100-percent complete.

The inspectors determined that the failure to promptly identify and correct conditions adverse to quality regarding the repetitive failures of High Pressure Air System Check Valve CK-CA476 and had a credible impact on safety and was more than a minor concern. The inspectors determined that the failures could credibly affect the availability, reliability or function of a mitigating system, during periods of time when the engineered safeguards high pressure air system was cross-connected to the turbine building high pressure air system. The East and West Safeguards High Pressure Air Systems provide the safety-related motive force for the opening and closing of safety-related valves in the respective trains of the Emergency Core Cooling System.

The inspectors used Manual Chapter 0609, "Significance Determination Process," Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations." The inspectors determined that:

- The finding did not represent an actual loss of safety function based on as-found check valve leakage;
- The finding did not represent an actual loss of a safety function of a single train for greater than Technical Specification outage time;
- The finding did not represent an actual loss of a safety function of one or more Non-Technical Specification trains of equipment;
- The finding did not screen as potentially risk significant due to a seismic, flooding, or severe weather initiating event; and
- While the finding could potentially be a design or qualification deficiency, the licensee's operability determinations confirmed that the check valve leakage did not result in a loss of function per Generic Letter 91-18, Revision 1.

Therefore, the finding screened as Green and was of very low safety significance.

10 CFR 50, Appendix B, Criterion XVI, "Corrective Actions," requires, in part, that conditions adverse to quality be promptly identified and corrected. Contrary to this, licensee personnel failed to promptly identify and correct the repetitive failures of the high pressure air system Check Valve CK-CA476. This violation is associated with an NRC identified finding that is characterized by the significance determination process as having very low risk significance (Green) and is being treated as a Non-Cited Violation of 10 CFR 50, Appendix B, Criterion XVI, consistent with Section VI.A.1 of the NRC Enforcement Policy. (NCV 50-255/02-02-01)

This finding is in the licensee's corrective action program as Condition Report CPAL0201343.

.2 Maintenance Rule Evaluations

a. Inspection Scope

The inspectors reviewed the licensee's Maintenance Rule Scoping Document for the following plant equipment designated as having high safety significance:

- Control Rod Drive System; and
- 2400-Volt AC Power System.

The inspectors reviewed the licensee's maintenance rule performance indicators associated with the system's maintenance rule category status. In addition, the inspectors discussed various technical issues with the applicable system engineer.

Further, the inspectors reviewed selected condition reports to verify that the identified issues were appropriately characterized and were dispositioned in accordance with the licensee's Maintenance Rule program. The inspectors reviewed selected condition reports to verify that designated corrective actions were reasonable and had been implemented as scheduled.

b. Findings

No findings of significance were identified.

1R13 Maintenance Risk Assessments and Emergent Work Evaluation (71111.13Q)

a. Inspection Scope

The inspectors reviewed, Operator's Risk Reports, Shift Supervisor logs and maintenance activity schedules to verify that the plant equipment necessary to minimize plant risk was operable and/or available as required. The inspectors randomly conducted plant tours to verify that the appropriate equipment was available for use during the following planned and emergent maintenance activities:

- Emergent failure of Component Cooling Water Pump P-52C Motor; and
- Planned maintenance on High Pressure Safety Injection Pump P-66A.

The inspectors discussed the shutdown operation equipment checklists and plant configuration control for the maintenance activities with operations, maintenance and work control center staff to verify that necessary steps were taken to control the work activities.

In addition, the inspectors reviewed select condition reports to verify that identified problems regarding maintenance risk assessments and control of emergent work activities were appropriately characterized and entered into the licensee's corrective action program.

b. Findings

No findings of significance were identified.

1R15 Operability Evaluations (71111.15Q)

a. Inspection Scope

The inspectors reviewed the operability assessments as documented in the associated condition reports for the following risk significant components:

- Component Cooling Water System Debris; and
- Past Operability for the Containment Sump Recirculation Check Valves CK-ES3181 and CK-ES3166.

The inspectors interviewed the cognizant engineers, and reviewed the supporting documents to assess the adequacy of the operability assessments for the current plant mode. The inspectors also reviewed the applicable sections of the Technical Specifications, Final Safety Analysis Report, and Design Basis Documents to verify that the operability assessments were technically adequate and that the components remained available, such that no unrecognized increase in plant risk had occurred.

Further, the inspectors reviewed select condition reports to verify that identified problems associated with the operability evaluations were appropriately characterized and entered into the licensee's corrective action program.

b. Findings

No findings of significance were identified.

1R17 Permanent Plant Modifications (71111.17)

a. Inspection Scope

The inspectors reviewed the engineering analyses, modification documents and design change information associated with the following permanent modification to the Component Cooling Water System Technical Specification Bases:

- Technical Specification Bases Change for Technical Specification 3.7.7 which removed Component Cooling Water Pump P-52C from the Bases.

The inspectors discussed the modifications with the responsible engineers, licensing and operations staff. In addition, the inspectors reviewed the applicable sections of the Technical Specifications and Updated Final Safety Analysis Report to verify that the modifications would not adversely impact the system's safety functions.

Further, the inspectors reviewed condition reports to verify that identified problems associated with the modifications were appropriately characterized and entered into the licensee's corrective action program

b. Findings

No findings of significance were identified.

1R19 Post Maintenance Testing (71111.19Q)

a. Inspection Scope

The inspectors observed portions of post maintenance testing and reviewed documented testing activities following scheduled maintenance to determine whether the tests were performed as written. The inspectors also verified that applicable testing prerequisites were met prior to the start of the tests and that the effect of testing on plant conditions was adequately addressed by control room staff. Post maintenance test activities were reviewed for the following:

- High Pressure Safety Injection Pump P-66A; and
- Control Room Heating and Ventilation System, Train A.

The inspectors reviewed post maintenance testing criteria specified in the applicable preventive and corrective work orders to verify that the test criteria was appropriate with respect to the scope of work performed and that the acceptance criteria were clear.

In addition, the inspectors reviewed the completed tests and procedures to verify that the tests adequately verified system operability. Documented test data was reviewed to verify that the data was complete, and that the equipment met the procedure acceptance criteria which demonstrated that the equipment was able to perform the intended safety functions.

Further, the inspectors reviewed condition reports regarding post maintenance testing activities to verify that identified problems were appropriately characterized.

b. Findings

No findings of significance were identified.

1R22 Surveillance Testing (71111.22)

a. Inspection Scope

The inspectors observed portions of the following surveillance testing activities conducted on risk-significant plant equipment to verify that testing was conducted in accordance with prescribed procedures:

- Battery Charger No. 1;
- Emergency Diesel Generator 1-2;
- Safety Injection System Logic;
- Reactor Protection System Trip Units; and
- Component Cooling Water Flow Verification Test to the Emergency Core Cooling System.

The inspectors also reviewed the documented test data for the Technical Specification Surveillance Test procedures and the associated basis documents to verify that testing acceptance criteria were satisfied.

In addition, the inspectors reviewed applicable portions of Technical Specifications, the Final Safety Analysis Report and Design Basis Documents to verify that the surveillance tests adequately demonstrated that system components could perform designated safety functions.

Further, the inspectors reviewed condition reports regarding surveillance testing activities to verify that identified problems were appropriately characterized.

b. Findings

No findings of significance were identified.

1R23 Temporary Plant Modifications

a. Inspection Scope

The inspectors reviewed the temporary modification package and associated 10 CFR 50.59 evaluation for the following temporary modification:

- TM 2001-014, "Due to damaged detectors, change locations of cabling at the reactor head for the incore detectors to provide the required 16 totally qualified detector installations. Also make corresponding changes to the addresses to provide proper signals to the PPC."

The licensee installed this temporary modification to relocate environmentally qualified cables to undamaged connections on the reactor vessel head.

In addition, the inspectors reviewed condition reports concerning this temporary modification to verify that identified problems were appropriately characterized and evaluated.

b. Findings

No findings of significance were identified.

4. OTHER ACTIVITIES (OA)

4OA1 Performance Indicator Verification (71151)

a. Inspection Scope

The inspectors verified that the data submitted by the licensee was accurate and complete for the safety system functional failure performance indicator. The inspectors reviewed control room logs, licensee monthly operating reports, licensee's Incident

Analysis System logs, completed Technical Specification Surveillance Tests, and the licensee's maintenance work order database for January through December 2001, to verify that the licensee had accurately reported the performance indicator for these quarters.

In addition, the inspectors discussed the data with the licensee staff responsible for gathering and reporting the information related to this performance indicator. Further, the inspectors reviewed condition reports regarding performance indicator data to verify that identified problems were appropriately characterized.

b. Findings

No findings of significance were identified.

4OA2 Identification and Resolution of Problems

.1 Inadequate Corrective Actions for Post Maintenance Testing Activities

a. Inspection Scope

The inspectors reviewed the apparent cause evaluation for Condition Report CPAL0200059, "Fire Pump P-9A Tripped After Running For Approximately Three Minutes," that was completed by licensee personnel on February 4, 2002. The apparent cause evaluation was selected for review because the Fire Protection System was designated as a high safety-significant system within the Palisades Systems Maintenance Rule Safety-Rankings. The inspectors reviewed the evaluation to determine if the identified causes for Fire Pump P-9A to trip after running for only three minutes were appropriate and to determine if the resultant corrective actions were reasonable.

b. Findings

The inspectors identified a Green finding that is being treated as a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Actions," for the failure to promptly identify and correct conditions adverse to quality regarding post maintenance testing activities on Fire Pump P-9A.

Licensee personnel generated Condition Report CPAL0200059, "Fire Pump P-9A Tripped After Running For Approximately Three Minutes," and entered the problem into the corrective action program. The events and circumstances pertaining to Fire Pump P-9A tripping after running for only 3 minutes were previously documented in Inspection Report 50-255/01-17(DRP), Section 1R19.

The apparent cause evaluation that licensee personnel completed for CPAL0200059 concluded that Fire Pump P-9A tripped after running for only 3 minutes because the long time trip relays on the associated electrical supply breaker were set improperly due to a lack of clarity on the retest record. Licensee personnel also concluded that maintenance technicians did not validate assumptions made during the maintenance activity and that the pre-job brief was ineffective.

The inspectors noted that the corrective actions appeared reasonable for the apparent causes that were identified by licensee personnel in their evaluation. However, the inspectors determined that the licensee failed to identify an apparent cause of inadequate post maintenance testing designated on the work order (WO2411415) that was utilized to set the long time overcurrent trips on the breaker.

The work order specified that post maintenance testing to be completed per Permanent Maintenance Procedure SPS-E-17, "Temporary Installation and Removal of Spare Circuit Breakers." However, Procedure SPS-E-17 contained no post maintenance testing instructions. Instead, the work order should have specified post maintenance testing to be done in accordance with Administrative Procedure 5.19, Attachment 2, "Guidelines for Post Maintenance Testing Electrical Maintenance."

The inspectors determined that the failure of licensee personnel to identify in their apparent cause evaluation that inadequate post maintenance testing activities were designated on WO2411415 was more than minor and had a credible impact on safety. Because the licensee's apparent cause failed to identify the inadequate post maintenance testing, there were no corrective actions developed to ensure that appropriate post maintenance testing activities would be specified on subsequent work orders for electrical breaker maintenance similar to that conducted on Fire Pump P-9A.

The inspectors used Manual Chapter 0609, "Significance Determination Process," Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," and concluded that this finding was of very low safety significance. The inspectors determined that the issue affected the mitigating system cornerstone in that the Fire Protection System was a backup for the Auxiliary Feedwater System. The inspectors determined that:

- The finding was not a design or qualification deficiency;
- The finding did not represent an actual loss of safety function in that two other fire pumps were always available;
- Fire protection pumps are not in the Technical Specifications, and therefore the finding did not represent an actual loss of a safety function of a single train for greater than Technical Specification outage time;
- The finding did not represent an actual loss of a safety function of one or more Non-Technical Specification trains of equipment in that two other fire pumps were always available;
- The finding did not screen as potentially risk significant due to a seismic, flooding, or severe weather initiating event in that the finding did not involve the loss of degradation of equipment or function specifically designed to mitigate a seismic, flooding or severe weather initiating event; and
- The finding did not involve the loss of a safety function that contributed to external event initiated core damage accident sequences from fires in that two fire pumps were always available.

Therefore, the finding screened as Green and was of very low safety significance.

10 CFR 50, Appendix B, Criterion XVI, "Corrective Actions," requires, in part, that conditions adverse to quality be promptly identified and corrected. Contrary to this, licensee personnel failed to identify during an apparent cause evaluation completed on February 4, 2002, for Condition Report CPAL0200059, "Fire Pump P-9A Tripped After Running For Approximately Three Minutes," that inadequate post maintenance testing activities were specified in WO2411415 following electrical breaker maintenance for Fire Pump P-9A. Because the licensee's apparent cause failed to identify the inadequate post maintenance testing, there were no corrective actions developed to ensure that appropriate post maintenance testing activities would be specified on subsequent work orders for electrical breaker maintenance similar to that conducted on Fire Pump P-9A. This violation is associated with an NRC identified finding that is characterized by the significance determination process as having very low risk significance (Green) and is being treated as a Non-Cited Violation of 10 CFR 50, Appendix B, Criterion XVI, consistent with Section VI.A.1 of the NRC Enforcement Policy. (NCV 50-255/02-02-02)

This finding is in the licensee's corrective action program as Condition Report CPAL0200622.

4OA3 Event Follow-up (71153)

- .1 (Closed) Unresolved Item 50-255/01-14-01, Licensee Event Report 01-005-00 and Associated Licensee Event Report Retraction: Containment Sump Check Valves/ Reduced Available Net Positive Suction Head.

The inspectors identified a Green finding that is being treated as a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control," for the failure to ensure that the measures for verifying and checking the adequacy of the design for Specification Change SC-94-130 assured that the applicable regulatory requirements and the design basis of the containment sump check valves were met.

The licensee made Event Notification 38477 and Licensee Event Report 01-005-00 based on the preliminary analyses of test data for the Containment Sump Check Valves CK-ES3166 and CK-ES3181. The mock-up testing of a full scale containment sump check valve was conducted to address the licensee's questioning of the ability of the containment sump check valves to go full open for the design basis accident, following a Recirculation Actuation Signal.

The testing performed discovered that the head loss through the containment sump check valves was greater than previously assumed; therefore, the increased head loss would have resulted in less than required available net positive suction head (NPSH) for the engineered safeguards system pumps during recirculation mode following a postulated loss of coolant accident. The licensee's design basis accident analyses had previously assumed the containment sump recirculation check valves would have fully open (resulting in minimal head loss through the containment sump check valves) during recirculation mode following a design basis accident, based on original vendor documentation supplied for the check valves.

The testing performed was a result of a corrective action to address an issue identified in Condition Report CPAL0100764, "Performance of Containment Sump Check Valves During Post-Design Basis Accident Recirculation Mode May Not Be Acceptable." However, the licensee's evaluation of the circumstances surrounding this issue revealed that concerns were raised regarding the potential for higher than assumed head loss values through the containment sump check valves as early as 1996.

Licensee personnel's subsequent evaluation of past operability of the engineered safeguards system pumps concluded that the pumps were operable, but nonconforming in accordance with NRC Generic Letter 91-18, Revision 1. Licensee personnel reached this conclusion through engineering analysis and evaluations which credited containment pressure and calculated plant parameters following postulated design basis accident scenarios. The credit of containment overpressure increased the available NPSH to greater than the required NPSH for the engineered safeguards system pumps considering the most limiting postulated post-accident conditions and scenarios.

As follow-up to the circumstances surrounding this issue, the inspectors reviewed the past history of the containment sump check valves as well as the results of the testing of the containment sump check valve mock-up performed in October 2001. The inspectors also reviewed design modifications made to the containment sump check valves since original plant installation. The inspectors noted that Specification Change SC-94-130 was implemented in 1995 and added an external lever arm and stuffing box assembly to Check Valves CK-ES3166 and CK-ES3181 to allow the valves to be stroke tested per Section XI of the American Society of Mechanical Engineers (ASME) Code. The inspectors noted this design change did not consider the potential effects on the operation of the check valve with the addition of the external lever arm and stuffing box assembly.

The licensee's mock-up test performed in October 2001 demonstrated that the operation of the check valve was significantly affected due to the addition of the stuffing box assembly and associated valve packing in 1995. The increased head loss through the containment sump check valves as a result of the 1995 design modification would have resulted in less than required available NPSH for the high pressure safety injection and the containment spray pumps during recirculation mode following a postulated design basis accident.

Therefore, the inspectors concluded that the licensee's failure to ensure that measures for verifying and checking the adequacy of the design for Specification Change SC-94-130 to assure that the applicable regulatory requirements and the design basis of the containment sump check valves were met was a violation of 10 CFR 50, Appendix B, Criterion III, "Design Control," and was more than minor. Specifically, the failure to meet the applicable regulatory requirements and the design basis of the containment sump check valves could have credibly affected the operability, reliability or function of the high pressure safety injection and containment spray mitigating systems.

The inspectors used Manual Chapter 0609, "Significance Determination Process," Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," and concluded that this finding was of very low safety significance. The inspectors determined that the finding was a design deficiency confirmed not to result in a

loss of function per NRC Generic Letter 91-18, Revision 1. The licensee's past operability analysis credited the use of containment overpressure and calculated plant parameters following a design basis accident and concluded that the available NPSH was above that required for all pumps considering the most limiting postulated conditions. Therefore, the engineered safeguards system pumps would have been able to perform the intended safety function and were operable, but nonconforming in accordance with Generic Letter 91-18, Revision 1.

The inspectors reviewed the licensee's engineering analysis and evaluations for past operability to verify the adequacy of crediting containment overpressure and calculated plant parameters for this issue. In addition, the inspectors reviewed the licensee's engineering analysis with NRC Regional personnel and the Office of Nuclear Reactor Regulation technical staff to verify the licensee's utilization of containment overpressure and calculated plant parameters was appropriate. The inspectors concluded the licensee's use of containment overpressure and calculated plant parameters was appropriate.

Therefore, the finding screened as Green and was of very low safety significance.

10 CFR 50, Appendix B, Criterion III, "Design Control," requires, in part, measures shall provide for verifying and checking the adequacy of the design. Contrary to this, the licensee personnel failed to ensure that the measures for verifying and checking the adequacy of the design for Specification Change SC-94-130 assured that the applicable regulatory requirements and the design basis of the containment sump check valves were met. This violation is associated with an NRC identified finding that is characterized by the significance determination process as having very low risk significance (Green) and is being treated as a Non-Cited Violation of 10 CFR 50, Appendix B, Criterion III, consistent with Section VI.A.1 of the NRC Enforcement Policy. (NCV 50-255/02-02-03)

This finding is in the licensee's corrective action program as Condition Reports CPAL0100764, and CPAL0103563.

The licensee completed corrective actions to address this condition prior to the startup of the plant from an extended outage in January 2002. The licensee modified plant equipment and procedures without further reliance on crediting containment overpressure, to ensure the Design Basis and Design Function of the Engineered Safeguards System were met in accordance with the facility's license.

- .2 (Closed) Escalated Enforcement Item 50-255/01-06-01: On June 27, 2001, the NRC issued a Notice of Violation and Imposed a Civil Penalty for the violation of 10 CFR 50.9, completeness and accuracy of information. The NRC issued the violation for the failure to provide complete and accurate information regarding the licensee's submittals for a Notice of Enforcement Discretion and exigent Technical Specification Change Request which the NRC granted in February 2000 to remove an underground (backup) steam supply to Auxiliary Feedwater Pump P-8B.

The inspectors reviewed the licensee's root cause and corrective actions for this violation to verify the following: 1) the root cause for this finding was identified; 2) the proposed corrective actions addressed the root cause and scope of problems identified by the

licensee during the review of this issue; and 3) corrective actions were implemented as scheduled. The inspectors identified that the actions taken and planned by the licensee addressed the root cause and causal factors of this issue.

In addition, the inspectors reviewed a random sample of seven licensee submittals made to the NRC from May 2001 through March 2002, and the inspectors verified that the licensee's corrective actions addressed the issue of completeness and accuracy of licensee submittals to the NRC. The inspectors have no further concerns on this issue and considered this inspection follow-up item closed.

- .3 (Closed) Inspection Follow-up Item 50-255/97201-22: Potential non-conservative compliance with Technical Specification Section 4.7.2c. During NRC Inspection 50-255/97201, the licensee performed an operability determination which concluded that the 4-hour station blackout battery load profile enveloped the 2-hour Design Basis Accident load profile. Licensee personnel completed a formal analysis of battery loading which considered the battery chargers in an alternate alignment, a combined event of LOCA/LOOP, and a single failure of AC power.

The inspectors reviewed the completed corrective actions for Condition Reports CPAL9701537, CPAL9701538, and CPAL9701582, as well as Action Item Record A-PAL-98-037, which documented the issue and the inspection follow-up item. Engineering Analyses EA-ELEC-LDTAR-009 and EA-ELEC-VOLT-026, which also addressed and evaluated the issue, were also reviewed. Completed documentation for two station battery surveillance tests, Surveillance Procedure FE-5A, Revision 9 and Surveillance Procedure RE-83A, Revision 12, were reviewed to verify that the actions taken by the licensee were effective. The inspectors have no further concerns on this issue and considered this inspection follow-up item closed.

- .4 (Closed) Licensee Event Report Supplement 01-004-01: The inspectors reviewed the licensee's supplement to Licensee Event Report 01-004-01, "Control Rod Drive Mechanism Upper Housing Assembly Crack Indications," dated March 14, 2002. The inspectors noted the supplemental report identified two additional licensee commitments and the inspectors did not identify any concerns with the accuracy or commitments contained in the submittal. The closure of the initial Licensee Event Report was documented in NRC Inspection Report 50-255/01-15 and supplemental response 01-004-01 is considered closed.

4OA4 Cross-Cutting Issues

Corrective Actions

While no new cross-cutting findings were identified during this inspection period, the inspectors identified examples of the continuing nature of the corrective action cross-cutting issue Finding FIN 50-255/01-17-05 documented in NRC Inspection Report 50-255/01-17, regarding the implementation of the licensee's corrective action program.

In Sections 1R12.1 and 4OA2.1 of this report two Green findings (50-255/02-02-01 and 50-255/02-02-01) are documented for the failure to promptly identify and correct conditions adverse to quality which affected the Mitigating Systems Cornerstone.

In addition, NRC Inspection Report 50-255/01-15, issued March 4, 2002, documented a Green finding (50-255-01-15-02) for the failure to take corrective actions to prevent recurrence for a significant condition adverse to quality which affected the Barrier Integrity Cornerstone.

4OA6 Meeting

Exit Meetings

The inspectors presented the inspection results to Mr. Cooper and other members of licensee management on April 11, 2002, after the inspection period ended. Licensee staff acknowledged the findings presented. No proprietary information was identified at the exit meeting.

Exit Meeting

Senior Official at Exit:	Douglas E. Cooper, Site Vice President
Date:	March 01, 2002
Proprietary (explain "yes")	No
Subject:	Results of an Inspection of the Licensee's Licensed Operator Requalification Program
Change to Inspection Findings:	No

KEY POINTS OF CONTACT

Licensee

B. Benson, Unit Supervisor
T. Brown, Manager, Chemical and Radiological Services
D. Cooper, Site Vice President
D. Crabtree, Systems Engineering Manager
B. Dotson, Licensing Analyst
J. J. Fletcher, Security Manager
P. Harden, Director, Engineering
G.W. Hettel, Manager, Maintenance and Construction
L. Lahti, Licensing Manager
D. G. Malone, Supervisor, Regulatory Assurance
D. J. Malone, General Plant Manager
G. Packard, Operations Superintendent
K. Smith, Operations Manager

Licensee

G. Baustian, Operations Training Supervisor
R. Bender, Operations Requal Training Supervisor
L. Bogue, Director, Training
D. Cooper, Site Vice President
B. Dotson, Licensing Analyst
D. G. Malone, Regulatory Compliance Supervisor
P. Harden, Director, Engineering
N. Haskell, Nuclear Oversight Manager
L. Lahti, Licensing Manager
M. Lake, Nuclear Control Operator
C. Main, Shift Engineer/ STA
D. Malone, Plant General Manager
K. Marbaugh, Nuclear Oversight
M. Menarick, Operations Training Coordinator
G. Packard, Operations Superintendent
P. Russell, Performance Improvement Manager
W. Townes, Nuclear Control Operator
J. Wicks, Shift Supervisor

NRC

J. Lennartz, Senior Resident Inspector, Palisades

NRC

D. Hood, Project Manager, NRR

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

Opened

50-255/02-02-01	NCV	Green. 10 CFR 50, Appendix B, Criterion XVI. Licensee personnel failed to promptly identify and correct the repetitive failures of the high pressure air system Check Valve CK-CA476, which had been occurring since the 1996 time frame.
50-255/02-02-02	NCV	Green. 10 CFR 50, Appendix B, Criterion XVI. Licensee personnel failed to identify during an apparent cause evaluation that inadequate post maintenance testing activities were designated for Fire Pump P-9A following electrical breaker maintenance. Consequently, no corrective actions were developed to correct the condition adverse to quality.
50-255/02-02-03	NCV	Green. 10 CFR 50, Appendix B, Criterion III, "Design Control." Licensee failed to assure that measures for checking the adequacy of a design modification made to the containment sump recirculation check valves in 1995 ensured the overall design function of the valves was not affected.
50-255/01-004-01	LER	Supplemental Response to Licensee Event Report (LER) 01-004-01, "Control Rod Drive Mechanism Upper Housing Assembly Crack Indications"
50-255/01-005-00	LER	Containment Sump Check Valves/Reduced Available Net Positive Suction Head and Associated Licensee Event Report Cancellation

Closed

50-255/02-02-01	NCV	Green. 10 CFR 50, Appendix B, Criterion XVI. Licensee personnel failed to promptly identify and correct the repetitive failures of the high pressure air system Check Valve CK-CA476, which had been occurring since the 1996 time frame.
50-255/02-02-02	NCV	Green. 10 CFR 50, Appendix B, Criterion XVI. Licensee personnel failed to identify during an apparent cause evaluation that inadequate post maintenance testing activities were designated for Fire Pump P-9A following electrical breaker maintenance. Consequently, no corrective actions were developed to correct the condition adverse to quality.
50-255/02-02-03	NCV	Green. 10 CFR 50, Appendix B, Criterion III, "Design Control." Licensee failed to assure that measures for checking the adequacy of a design modification made to the containment sump recirculation check valves in 1995 ensured the overall design function of the valves was not affected.

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED (Cont.)

Closed (cont.)

50-255/01-14-01	URI	Unresolved item to track and assess the completed test results from full scale testing of a containment sump check valve
50-255/97201-22	IFI	Potential non-conservative compliance with Technical Specification Section 4.7.2c.
50-255/01-06-01	EEI	Severity Level III Violation of 10 CFR 50.9 and associated Civil Penalty for the failure to provide complete and accurate information
50-255/01-004-01	LER	Supplemental Response to Licensee Event Report (LER) 01-004-01, "Control Rod Drive Mechanism Upper Housing Assembly Crack Indications
50-255/01-005-01	LER	Containment Sump Check Valves/Reduced Available Net Positive Suction Head and Associated Licensee Event Report Cancellation

LIST OF ACRONYMS USED

ANS	American National Standard
ASME	American Society of Mechanical Engineers
CFR	Code of Federal Regulations
CR	Condition Report
DRS	Division of Reactor Safety
FSAR	Final Safety Analysis Report
JPM	Job Performance Measure
LORT	Licensed Operator Requalification Training
NCV	Non-Cited Violation
NPSH	Net Positive Suction Head
NRC	Nuclear Regulatory Commission

LIST OF DOCUMENTS REVIEWED

1R04 Equipment Alignment

Plant Procedures

SOP-3	System Operating Procedure - Safety Injection and Shutdown Cooling System	Revision 46
-------	---	-------------

SOP-3	Attachment 17, Checklist 3.8 - Engineered Safeguards System Checklist (Heatup)	Revision 46
SOP-3	Attachment 18, Checklist 3.9 - Engineered Safeguards Administrative Control Verification	Revision 46
SOP-20	System Operating Procedure - High Pressure Control Air System	Revision 19
EOP Supplement - 4	Emergency Operating Procedure - High Pressure Safety Injection and Low Pressure Safety Injection Flow Curves	Revision 5
Admin. 4.02	Administrative Procedure - Control of Equipment	Revision 18

Miscellaneous Documents

DBD-2.02	Design Basis Document - High Pressure Safety Injection System	Revision 6
	Final Safety Analysis Report, Section 6.1-Safety Injection System	Revision 22
PPAC X-OPS-590	Predetermined and Periodic Activity Control - Blowdown Low Points in High Pressure Air System, completed activities from July 2001 through February 2002	

Condition Reports Reviewed To Assess Problem Identification Characterization

CPAL0201121	High Pressure Air Dryer M-9A Humidity Sensor Found Isolated by NRC
CPAL0201086	Valves Not Locked in Accordance with Administrative Procedure 4.02, More Than One Turn Possible

1R05 Fire Protection

Plant Procedures

ONP-12	Off-Normal Procedure - Acts Of Nature	Revision 16
AP-6.02	Administrative Procedure - Control Of Equipment	Revision 17
ONP-25.1	Off-Normal Procedure - Fire Which Threatens Safety-Related Equipment	Revision 11
ONP25.2	Off-Normal Procedure - Alternate Safe Shutdown Procedure	Revision 17

Miscellaneous Documents

EA-PSSA-00-001	Palisades Plant Post Fire Safe Shutdown Summary Report, for Fire Areas 1, 13, and 23	Revision 1
Palisades Plant Fire Hazards Analysis	Analysis for Fire Areas 1, 13, and 23	Revision 4
NFPA 50A	National Fire Protection Association Standard 50A - Gaseous Hydrogen Systems of Consumer Sites	1969 and 1978 Standards
EA-APR-98004	Engineering Analysis - Analysis of Problems Concerning Fire Doors	June 30, 1998
RP0686-0269A-PPO3	Engineering Analysis - Generic Letter 86-10 Analysis of Fire Door Between Switchgear Room 1-C and 590' Elevation Auxiliary Building Corridor	
TI 2515/146	U.S. NRC Temporary Instruction - Hydrogen Storage Locations	December 14, 2001
BTP ASB 9.5-1	U.S. NRC Branch Technical Position 9.5-1 - Guidelines for Fire Protection for Nuclear Power Plants	Revision 1
	Consumer Power Company - List of Changes and Response to Appendix A to Branch Technical Position APCSB 9.5-1 and Regulatory Guides 1.78 and 1.101	Revision 2 August 24, 1996
FSAR 9.6	Final Safety Analysis Report, Section 9.6 - Fire Protection	Revision 23
	U.S. NRC Fire Protection Safety Evaluation Report by the Office of Nuclear Reactor Regulation, U.S. Nuclear Regulatory Commission in the Matter of Consumers Power Company Palisades Plant	September 1, 1978

Condition Reports Reviewed To Assess Problem Identification Characterization

CPAL0200926	Incorrect Label on Turbine Building Exhaust Fan V-21R
-------------	---

CPAL0200606	Pressure Switch PS-1602A Sprinkler Header Air Pressure Switch to Volume Reduction System is Not Accurately Described in the AMMS Equipment Database
CPAL0201015	Diesel Driven Fire Pump P-9B Packing Overheated During Performance of Technical Specification Surveillance Test MO-7B
CPAL0201160	NRC Identified Diesel Generator Corridor Fire Door Frames Are Not in Compliance With Our 1978 Safety Evaluation Report Licensing Basis
CPAL0200988	MO-7B - Fire Water Pump P-9B Test Failed Due to Overheated Pump Packing
CPAL0201223	Attempt to Start Electric Fire Pump P-9A per SOP-21 Using T-handle was Unsuccessful
CIED0201224	Temporary Instruction 2515/146: Hydrogen Storage Locations
CPAL02001341	Condition Report 02-01160 Classified at a Lower Significance Level Than Appropriate

1R11 Licensed Operator Requalification
Sections 1R11.1 through R11.6

LORT Plan	Palisades Licensed Operator Requalification (PLOR) 2 Year Training Plan	2000-2002
Written Exam	2001 Licensed Operator Requalification Biennial Written Exam	June 24, 1905
Operating Exam Simulator Scenarios	2002 Two Simulator Scenarios; SPE-13, SPE-31	February 18, 2002
Operating Exam JPMs (Initial Set)	2002 Five JPMs; TBAM-16, TBAR-JP-04, TBAG-01, ASFA-01B, ASFE-04	February 18, 2002
Operating Exam JPMs (Replacement)	2002 Five JPMs to Replace Initial Set; TBAM-04, TBAB-04, ASHH-01, ASDC-01, ASAC-01A	February 21, 2002
Palisades Nuclear Training (PNT) Procedure No. 13.2	Licensed Operator Requalification Examination Development and Administration	Revision 2
PNT-11.0	Plant Operations Training Program Guides	Revision 1

PNT-12.0	Licensed Operator Examination Security	Revision 1
PLOR 2000 Cycle	Historical List of Training - 06/04/00 thru 12/13/01	Various
Program Description	Palisades Licensed Operator Requalification Training Program Description	Revision 0
Admin Procedure No. 4.00	Operations Organization, Responsibilities and Conduct	Revision 23
Admin Procedure No. 4.05	Operator Training	Revision 18
Admin Procedure No. 10.46	Plant Records	Revision 14
Admin Procedure No. 11.00	Plant Training Organization and Responsibilities	Revision 17
Admin Procedure No. 11.40	Systematic Approach To Training: Implementation	Revision 3
Admin Procedure No. 13.0	Evaluation and Test Item Development	Revision 0
TRRCMS RPT -205	Attendance Records For 12 Classes (Randomly Selected)	May 15, 2000 to February 26, 2002
Emergency Plan Implementing Procedure No. EI-1	Emergency Classification and Action	Revision 38
Emergency Plan Implementing Procedure No. EI-3	Communications and Notifications	Revision 18
Emergency Plan Implementing Procedure No. EI-6.10	Offsite Dose Calculation – Straight Line Gaussian (Manual Method)	Revision 5
Emergency Plan Implementing Procedure No. EI-6.13	Protective Action Recommendations For Offsite Population	Revision 10

Cycle 2000F	2001 Annual Performance Exams	June 24, 1905
Medical Records	Selection of Six Licensed Operator Medical Records	Various
Medical Records	Computer Print Out - Periodic Report on License Medical Data (Medical Exam Due Dates)	Various
CPAL0001362	Condition Report Concerning One Operator Failed Annual JPM Examination	April 28, 2000
CPAL0103093	Condition Report Concerning Learning Objectives	September 26, 2001
CPAL0200850	Condition Report Concerning Emergency Action Level Classification	March 1, 2002
CPAL0200790	Condition Report Concerning Exam Security	February 26, 2002
CPAL0200828	Condition Report Concerning Canceled Afternoon JPMs	February 28, 2002
CPAL0200852	Condition Report Concerning Enhancement to Exam Security Procedure	March 1, 2002
CPAL0200853	Condition Report Concerning Enhancement to Training Remediation Procedure	March 1, 2002
A-01-016	Nuclear Oversight Department Audit Report on Palisades Training and Staff Qualifications	November 1, 2001
Various	Matrix on Palisades Operations Training to Satisfy Risk Important Operator Actions	Various
2002-001-8-002	Nuclear Oversight Observation Report - Reactor Startup and Generator Synchronization	January 30, 2002
2001-004-8-032	Nuclear Oversight Observation Report - Licensed Operator Simulator Training for Plant Restart Preparations	December 14, 2001
PNT 7.0, Attn 5A	Current Year Simulator Scenario Crew and Individual Evaluation Reports - One Staff and One Shift Crews	February 27, 2002
S-00-04	Audit/Surveillance Report on Operations Training Records	March 20, 2000 to March 24, 2000
Training 2001-02	Palisades Operations Training Self-Assessment	July 23, 2001 to July 27, 2001

Self-Assessment	Palisades Nuclear Plant - Comprehensive Self-Evaluation for Select Training Programs	December 7, 2000 to December 15, 2000
PNT 7.0, Attn 5	Simulator Scenario Crew and Individual Evaluation Report - Three Shift Crew Failure and Subsequent Remediation Evaluation	December 18, 2000 February 15, 2001 March 8, 2001
SDR20-01-034	Palisades Simulator Deficiency Report	March 2, 2001
TRRCMS SRN-1300	Various Computer Print Out for Group Attendance Course Completion and Review	September 7, 2001 thru October 4, 2001
TRRCMS RPT-210	Computer Print Out - Requirements Completed Report for Emergency Plan - Dose Assessment Training	January 1, 2000 thru February 26, 2002
Various	Computer Print Outs on Task to Terminal and Enabling Objectives	February 26, 2002
TBAH-SEG 1.01C	Simulator Exercise Guide - Course Title: Continued Licensed Operator Training	September 4, 2001
Various	Staff Licensed Operations Proficiency Watch Record	Four Qtrs 2000, Four Qtrs 2001, First Qtr 2002

1R11.7 Resident Inspector Quarterly Licensed Operator Requalification

Plant Procedures

ONP-25.2	Alternate Safe Shutdown Procedure	Revision 17
SOP-2A	Chemical and Volume Control System	Revision 46
EOP Supplement 7	Battery #1 Load Stripping	Revision 5

Job Performance Measures

TBAR-JP-04	Reduce Station Battery #1 Loading To Less Than or Equal To 150 AMPS	Revision 1
------------	---	------------

TBAM-16.JPM	Re-energize Bus 13 Per The Alternate Safe Shutdown Procedure	Revision 1
-------------	--	------------

Miscellaneous Documents

Operator Performance Evaluation Examination Results

Condition Reports Reviewed To Assess Problem Identification Characterization

CPAL0200976	Annual Examination In-plant JPM Invalidated Due To Cuing
CPAL0201158	Re-Evaluation of Previously Taken JPM Results in Failure of that JAM
CPAL0201414	Inappropriate Significance Level Assigned to Corrective Action Documents

1R12 Maintenance Rule Implementation

	Control Rod Drive System Maintenance Rule Scoping Document and associated Maintenance Rule Performance Indicators	Revision 2
	Control Rod Drive System Health Assessments - 1st/2nd Quarter 2001	
	High Pressure Air System Maintenance Rule Scoping Document and associated Maintenance Rule Performance Indicators	Revision 2
	2400 Volt AC Maintenance Rule Scoping Document and associated Maintenance Rule Performance Indicators	Revision 2
	2400 Volt AC Power System Health Assessments - 1st/2nd Quarter 2001	
EM - 25	Maintenance Rule Program	Revision 3

Condition Reports Reviewed To Assess Maintenance Rule Evaluations

CPAL0101588	Water Inside Drive Motor of Control Rod Drive No. 35
-------------	--

CPAL0102186	Primary Coolant System Pressure Boundary Leakage, Control Rod Drive No. 21 Support Tube
CPAL0104064	Control Rod Drive Mechanism Seal Housing Component Cooling Water Hose Condition May Not Support Operation Until 2003 ReFout
CPAL0104204	Special Test T-370 Specifies Non-Conservative Shut-Down Margin
CPAL0100934	System Operating Procedure - 20, Attachment 4 Not Updated to Reflect Change Made to Meet Appendix R Concerns
CPAL0101229	Check Valve CK-CA476 Soft Seat (O-Ring) Disengaged from Plug, Piston Bore Found Unsatisfactory
CPAL0103600	Compressor C-6C High Pressure Air Compressor Oil Level Cutout Switch Unreliable
CAPL0104195	Unable To Realign 2400 V Busses 1C and 1E to the Safeguards Transformer

Condition Reports Reviewed To Assess Corrective Actions

CPAL0103069	Bus 1D Voltage Below 2300 Volts For Four Minutes
CPAL0102505	Inadequate Maintenance Rule Impact Determination For Degraded Grid Voltage
CPAL0101065	Inadequate Labeling Inside Junction Box J9400
CPAL0101229	Check Valve CK-CA476 Soft Seat (O-Ring) Disengaged from Plug, Piston Bore Found Unsatisfactory
CPAL9902216	Check Valve CK-CA476 Failed to Meet Test T-278-9C Acceptance Criteria
CPAL9902778	Re-work on Check Valve CK-CA476
CPAL9800785	Check Valve CK-CA476 Fails Leak Rate per Test T-278-9C
CPAL9601793	Predetermined and Periodic Activity Control PPAC X-OPS432 "Verification of Operability of Check Valve CK-CA476

Miscellaneous Documents

WO24112495	Work Order - Test Jacks on Switch "CC" Should Be Numbered	July 5, 2001
SOP-30, Section 4.2	Standard Operating Procedure -30, "Station Power," "Voltage Requirements"	Revision 31
EAR 2001-0524	Engineering Assistance Request, "Install Voltage Regulator ON Secondary Side of Startup Power Transformer 1-2 (EX-04)"	October 18, 2001
EAR-2001-0371	Engineering Assistance Request - Install New Type of Check Valve at CK-CA476	
EAR-99-0332	Engineering Assistance Request - CK-CA476 Failed During Test T-278-C, Install Filtration Upstream of Check Valve CK-CA476	
EA-SC-87-273	Completed Engineering Analysis - Replace Check Valve CK-CA476 in Response to D-PAL-87-087	October 1987
WO 24614622	Completed Work Order - CK-CA476 Failed Leak Test, Repair as Necessary	December 15, 1996
WO 24811410	Completed Work Order - CK-CA476 Failed Leak Rate per Test T-278-9C, CPAL9800785	May 5, 1998
WO 24913049	Completed Work Order - CK-CA476, Contingent Work Request. Replace soft seat in CK-CA476 Tested Unsatisfactory	November 2, 1999
WO 24913581	Completed Work Order - CK-CA476, Check Valve Leaks By, Rebuild as Needed C-PAL-99-02778	April 8, 2001
Vendor File M0114 0062	Vendor File - Henry Vogt Machine Co. Care and Maintenance Bulletin for Forged Steel Gate, Globe, Angle and Check Valves	
Vendor File M0114 0038	Vendor File - Henry Vogt Machine Co. Maintenance Instructions and Specifications for Zero Leakage Forged Steel Check Valves	

Condition Reports Reviewed To Assess Problem Identification Characterization

CPAL0201343	Untimely Implementation of Actions to Repair High Pressure Air Check Valve (CK-CA476)
-------------	---

1R13 Maintenance Risk Assessments and Emergent Work Evaluation

Plant Procedures

Admin. 4.02	Administrative Procedure 4.02 - Control of Equipment	Revision 18
-------------	--	-------------

Other Documents

Operator's Risk Reports and Shift Supervisor Log Entries for February 7 through February 12, 2002, during emergent maintenance activities on Component Cooling Water Pump P-52C

Operator's Risk Reports and Shift Supervisor Log Entries for March 18 through March 22, 2002, during scheduled maintenance activities on High Pressure Safety Injection Pump P-66A

Condition Reports Reviewed To Assess Problem Identification Characterization

CPAL0201127	QO-19 Inservice Test for High Pressure Safety Injection Pump P-66A Aborted Due to Packing Leak on MV-ES102 Pump P-66A Miniflow Bypass Valve
CPAL0201123	LIC-1001 Primary System Drain Tank T-74 Level Controller Would Not Allow Draining of the Primary System Drain Tank T-74 Which Caused Deletion of Section 5.3 of QO-19, "Inservice Test Procedure - High Pressure Safety Injection Pumps and Engineered Safeguards System Check Valve Operability Test"
CPAL0201455	Lack of Post Maintenance Test Following Hand Switch Cleaning Activities
CPAL0201431	Inadequate Post Maintenance Test Requirements/Documentation on CRHVAC Work Orders

1R15 Operability Evaluations

CPAL0200546	Operability Recommendation for Condition Report, "Valve Seat Material Found Loose In Component Cooling Water System"
-------------	--

CPAL0200702	Operability Recommendation for Condition Report, "Attempts To Disassemble MV-CC923 Aborted; Restoration Identifies New Condition"
CPAL013563	Past Operability Recommendation for Condition Report, "Containment Sump Check Valve Laboratory Testing Results are Inconsistent with Emergency Core Cooling System Model"

Miscellaneous Documents

	Correspondence to U.S. NRC from Nuclear Management Company, LLC, entitled, "Cancellation of Licensee Event Report 01-005, containment Sump Check Valves / Reduced Available Net Positive Suction Head"	March 4, 2002
Reg. Guide 1.1	NRC Regulatory Guide 1.1, "Net Positive Suction Head for Emergency Core Cooling and Containment Heat Removal System Pumps"	November 1970
Reg. Guide 1.82	NRC Regulatory Guide 1.82, "Water Sources for Long-Term Recirculation Cooling Following a Loss-of-Coolant Accident"	May 1996
NUREG-0869, Rev. 1	NRC NUREG, "Regulatory Analysis for Unresolved Safety Issue (USI) A-43 - Containment Emergency Sump Performance"	October 1985
NUREG-0897, Rev. 1	NRC NUREG, "Containment Emergency Sump Performance - Technical Findings Related to Unresolved Safety Issue A-43"	October 1985
EA-C-PAL-01-00764-02	Determination of the Head Loss Characteristics of Containment Sump Check Valves CK-ES3166 and CK-ES3181 for the Period from June 1995 to December 2001	Revision 0
	Licensee Developed Timeline Entitled, "Emergency Core Cooling System Net Positive Suction Head Issue Identification, Evaluation and Resolution Timeline"	February 2002
	Correspondence to U.S. NRC from Consumers Energy, entitled, "Response to Generic Letter 97-04 - Assurance of Sufficient Net Positive Suction Head for Emergency Core Cooling and Containment Heat Removal Pumps"	

Condition Reports Reviewed To Assess Problem Identification Characterization

CPAL0200527	Pieces of Hard Black Rubber Found Inside Pump Casing During Disassembly
CPAL0200756	Potential Containment Spray Pump Component Cooling Water Flow Rate Anomalies Recorded During 2001 Performance of Special Test T-223
CPAL0200562	CCW Pump P-52C Inboard Pump Bearing Oil Getting Dark
CPAL0201139	Engineering Analyses EA-GEJ-2002-01, Revision 0 Not Identified as Potentially Affected by Condition Report CPAL0201099
CPAL0201413	Condition Reports Not Generated as Expected

1R17 Permanent Plant Modifications

B3.7.7	Technical Specification Bases - Component Cooling Water System	August 1, 2001
FSAR Section 9.3	Component Cooling System	Revision 23
DBD 1.01	Design Basis Document - Component Cooling Water System	March 17, 2001
SOP-16	System Operating Procedure - 16 - Component Cooling Water System	Revision 22
QO-15	Technical Specification Surveillance Procedure - Inservice Test Procedure - Component Cooling Water Pumps	Revision 16
QO-15	Technical Specification Surveillance Procedure Basis Document - Inservice Test Procedure - Component Cooling Water Pumps	Revision 10
SDR-02-0110	Safety Determination Review - 10 CFR 50.59 Screen - Technical Specification Bases Change for B3.7.7	February 9, 2002
SER	NRC Safety Evaluation Reports for Improved Technical Specification 3.7.7 - Component Cooling Water System	

1R19 Post Maintenance Testing

Completed Work Orders and Post Maintenance Tests

24113516	TD-1 and TD-4; Inspect and Lubricate	March 6, 2002
24113337	V-26A Flow Control	March 5, 2002
24210859	FSX-1711: Relay Contacts 1, 7 Are Not Closing	March 5, 2002
24113336	Air Handling Unit V-95 Discharge Air Flow	March 5, 2002
24112314	PO-1745, General Condition Check	March 5, 2002
24113338	VC-11 Discharge Pressure Control	March 5, 2002
24113339	HVAC Power Supply P/S-1655 Testing	March 5, 2002
24113160	Air Handling Unit V-95 Modulating Damper D-2	March 6, 2002
24113283	Contact Cleaning For HS-1745A	March 5, 2002
QO-19	Technical Specification Surveillance and Special Test Procedure - Inservice Test Procedure - High Pressure Safety Injection Pumps and Engineered Safeguards System Check Valve Operability Test, March 21, 2002	Revision 22

Condition Reports Reviewed To Assess Problem Identification Characterization

CPAL0201127	QO-19 Inservice Test for High Pressure Safety Injection Pump P-66A Aborted Due to Packing Leak on MV-ES102 Pump P-66A Miniflow Bypass Valve
CPAL0201123	LIC-1001 Primary System Drain Tank T-74 Level Controller Would Not Allow Draining of the Primary System Drain Tank T-74 Which Caused Deletion of Section 5.3 of QO-19, "Inservice Test Procedure - High Pressure Safety Injection Pumps and Engineered Safeguards System Check Valve Operability Test"

1R22 Surveillance Testing

Completed Technical Specification Surveillance Tests

QI-2	Technical Specification Surveillance Procedure - Reactor Protective Trip Units, March 4, 2002	Revision 1
------	---	------------

RE-133	Technical Specification Surveillance Procedure - Performance Test - Battery Chargers, February 12, 2002	Revision 2
RE-132	Technical Specification Surveillance Procedure - Diesel Generator 1-2 Load Reject, February 20, 2002	Revision 2
QO-1	Technical Specification Surveillance Procedure - Safety Injection System, March 2, 2002	Revision 3
QO-16	Technical Specification Surveillance Procedure - Inservice Test Procedure - Containment Spray Pumps, March 12, 2002	Revision 19

Miscellaneous Documents

QI-2/QI-2A	Technical Specification Surveillance Procedure Basis Document	Revision 1
RE-133	Technical Specification Surveillance Procedure Basis Document - Performance Test - Battery Chargers	Revision 0
RE-132	Technical Specification Surveillance Procedure Basis Document - Diesel Generator 1-2 Load Reject	Revision 0
QO-1	Technical Specification Surveillance Procedure Basis Document - Safety Injection System	Revision 47
QO-16	Technical Specification Surveillance Procedure Basis Document - Inservice Test Procedure - Containment Spray Pumps	Revision 13
T-223	Completed Test Results from Special Test T-223 - Component Cooling Water Flow Balance from the 1999 and 2001 Tests Component Cooling Water Flow Data to Engineered Safeguards Pumps Taken During Normal Auxiliary Operator Rounds in March 2000	

Condition Reports Reviewed To Assess Problem Identification Characterization

CPAL0200883	RPS Inoperability Extended By Burnt Out Light Bulbs
CPAL0200864	Unexpected Safety Injection Tank T-82D HI/LO Level Alarm During Safety Injection System Testing

CPAL0200865	DC Bus #2 Ground Discovered During QO-1 Safety Injection Test
CPAL0200915	FA-0102D, Low Flow RPS Bistable Trip, Number One Matrix Light Burned Out
CPAL0201038	Incorrect System Engineering Guidance Given for QO-16 Revision
CPAL0201025	Component Cooling Water Flow Rates to Containment Spray Pump P-54C Below Expected Value
CPAL0201026	Component Cooling Water Flow Rates to Containment Spray Pump P-54B Below Expected Value
CPAL0201457	No Verification Performed of Critical Voltage Check During Technical Specification Test QI-2, "Reactor Protective Trip Units"
CPAL0201458	Unexpected Delay Occurred During the Performance of Technical Specification Test QI-2, "Reactor Protective Trip Units"

1R23 Temporary Plant Modifications

Admin. 9.03	Administrative Procedure - Temporary Modification Control	Revision 18
	Engineering Package for Temporary Modification No. TM-2001-026, including associated 10 CFR 50.59 Screening	January 4, 2002
W.O. 24114288	Work Order - Installation of Temporary Modification No. TM-2001-026	

4OA2 Identification and Resolution of Problems

Condition Reports Reviewed To Assess Corrective Actions

CPAL0200059	Fire Pump P-9A tripped after running for approximately three minutes apparent cause evaluation	February 4, 2002
-------------	--	------------------

Condition Reports Reviewed To Assess Problem Identification Characterization

CPAL0200622	Inadequate Post Maintenance Testing (PMT) Specified In Work Order 24114415 (52-1305)
-------------	--

4OA3 Event Follow-up

Admin. 3.21	Administrative Procedure - Validation of Correspondence to Regulatory Agencies and INPO	Revision 1
	Validation and Verification Package for Correspondence to U.S. NRC from Consumers Energy Corporation entitled, "Supplementary Information Regarding Resolution of Unresolved Item 95004-05"	May 25, 2001
	Validation and Verification Package for Correspondence to U.S. NRC from Consumers Energy Corporation entitled, "Licensee Event Report 01-003, Small Fire of Suspicious Origin Within the Plant Protected Area"	June 19, 2001
	Validation and Verification Package for Correspondence to U.S. NRC from Nuclear Management Company, LLC, entitled, "Plan for Implementation of Palisades Plant Emergency Minimum Staffing Changes"	July 31, 2001
	Validation and Verification Package for Correspondence to U.S. NRC from Nuclear Management Company, LLC, entitled, "Palisades Plant Response to NRC Bulletin 2001-01"	August 31, 2001
	Validation and Verification Package for Correspondence to U.S. NRC from Nuclear Management Company, LLC, entitled, "Response to NRC Request for Additional Information Regarding Emergency Plan Staffing Changes"	October 1, 2001
	Validation and Verification Package for Correspondence to U.S. NRC from Nuclear Management Company, LLC, entitled, "SQUG Outlier Resolution - Revision of Commitment"	January 15, 2002
	Correspondence to U.S. NRC from Nuclear Management Company, LLC, entitled, "NRC Bulletin 2001-01: Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles - Updated Response"	March 29, 2002
	Correspondence to U.S. NRC from Nuclear Management Company, LLC, entitled, "Cancellation of Licensee Event Report 01-005, containment Sump Check Valves / Reduced Available Net Positive Suction Head"	March 4, 2002

SC-94-130	Specification Change - Addition of Lever Arm and Stuffing Box Assembly to Containment Sump Check Valves CK-ES3166 and CK-ES3181	
Reg. Guide 1.1	NRC Regulatory Guide 1.1, "Net Positive Suction Head for Emergency Core Cooling and Containment Heat Removal System Pumps"	November 1970
Reg. Guide 1.82	NRC Regulatory Guide 1.82, "Water Sources for Long-Term Recirculation Cooling Following a Loss-of-Coolant Accident"	May 1996
NUREG-0869, Rev. 1	NRC NUREG, "Regulatory Analysis for Unresolved Safety Issue (USI) A-43 - Containment Emergency Sump Performance"	October 1985
NUREG-0897, Rev. 1	NRC NUREG, "Containment Emergency Sump Performance - Technical Findings Related to Unresolved Safety Issue A-43"	October 1985
EA-C-PAL-01-00764-02	Determination of the Head Loss Characteristics of Containment Sump Check Valves CK-ES3166 and CK-ES3181 for the Period from June 1995 to December 2001	Revision 0
	Licensee Developed Timeline Entitled, "Emergency Core Cooling System Net Positive Suction Head Issue Identification, Evaluation and Resolution Timeline"	February 2002
	Correspondence to U.S. NRC from Consumers Energy, entitled, "Response to Generic Letter 97-04 - Assurance of Sufficient Net Positive Suction Head for Emergency Core Cooling and Containment Heat Removal Pumps"	

Condition Reports Reviewed To Assess Problem Identification Characterization

CPAL0200906	NRC Commitment Requiring a Modification has no Supporting Engineering Assistance Request
-------------	--

Condition Reports Reviewed To Assess Evaluations and Corrective Actions

CPAL0100764	Performance of Containment Sump Check Valves During Post-Design Basis Accident Recirculation Mode May Not Be Acceptable
CPAL0103563	Containment Sump Check Valve Lab Testing Results Are Inconsistent with Emergency Core Cooling System Model
CPAL0100531	Appendix R Analyses Basis Does Not Adequately Document A Turbine Building Fire Safe Shutdown Path
CPAL0100259	Removal of Auxiliary Feedwater Control Valve CV-0522A Supply to Pump P-8B Was Not Adequately Reviewed Against Appendix R Analyses
CPAL0100797	Appendix R Program Deficiencies