

WOLF CREEK

NUCLEAR OPERATING CORPORATION

Gary B. Fader
Vice President Technical Services

SEP 13 2002

ET 02-0034

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Reference: Letter ET 02-0032, dated August 2, 2002, from Gary B. Fader, WCNOC, to the NRC

Subject: Docket No. 50-482: Licensee Event Report 2002-004-01

Gentlemen:

The enclosed Licensee Event Report (LER) 2002-004-01 is being submitted pursuant to 10 CFR 50.73(a)(2)(ii)(B) regarding an unanalyzed condition from a cable separation issue that could potentially affect post-fire safe shutdown equipment availability at Wolf Creek Generating Station.

This event is the second cable separation issue discovered as a result of validating the post-fire safe shutdown analysis, and is submitted as a supplement to LER 2002-004-00. Any reportable conditions identified similar to this issue will be also be reported by supplementing LER 2002-004.

Commitments made by Wolf Creek Nuclear Operating Corporation in the enclosed LER are identified in the Attachment.

If you have any questions concerning this matter, please contact me at (620) 364-4034 or Mr. Tony Harris, Manager Regulatory Affairs, at (620) 364-4038.

Very truly yours,



Gary B. Fader

GBF/rlr

Enclosure
Attachment

cc: J. N. Donohew (NRC), w/e
D. N. Graves (NRC), w/e
E. W. Merschoff (NRC), w/e
Senior Resident Inspector (NRC), w/e

IE22

LICENSEE EVENT REPORT (LER)

(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

WOLF CREEK GENERATING STATION

2. DOCKET NUMBER

05000482

3. PAGE

1 OF 6

4. TITLE

Cable Separation Issue That Could Potentially Affect Post Fire Safe Shutdown Equipment Availability

5. EVENT DATE

MO DAY YEAR
07 19 2002

6. LER NUMBER

YEAR SEQUENTIAL
NUMBER REV NO
2002 - 004 - 01

7. REPORT DATE

MO DAY YEAR
09 13 2002

8. OTHER FACILITIES INVOLVED

FACILITY NAME DOCKET NUMBER

FACILITY NAME DOCKET NUMBER

9. OPERATING
MODE

1

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR (Check all that apply)

20.2201(b)

20.2203(a)(3)(ii)

X 50.73(a)(2)(ii)(B)

50.73(a)(2)(ix)(A)

20.2201(d)

20.2203(a)(4)

50.73(a)(2)(iii)

50.73(a)(2)(x)

20.2203(a)(1)

50.36(c)(1)(i)(A)

50.73(a)(2)(iv)(A)

73.71(a)(4)

20.2203(a)(2)(i)

50.36(c)(1)(ii)(A)

50.73(a)(2)(v)(A)

73.71(a)(5)

20.2203(a)(2)(ii)

50.36(c)(2)

50.73(a)(2)(v)(B)

OTHER

20.2203(a)(2)(iii)

50.46(a)(3)(ii)

50.73(a)(2)(v)(C)

Specify in Abstract below or in

20.2203(a)(2)(iv)

50.73(a)(2)(i)(A)

50.73(a)(2)(v)(D)

NRC Form 366A

20.2203(a)(2)(v)

50.73(a)(2)(i)(B)

50.73(a)(2)(vii)

20.2203(a)(2)(vi)

50.73(a)(2)(i)(C)

50.73(a)(2)(viii)(A)

20.2203(a)(3)(i)

50.73(a)(2)(ii)(A)

50.73(a)(2)(vii)(B)

12. LICENSEE CONTACT FOR THIS LER

NAME

Karl A. (Tony) Harris, Manager Regulatory Affairs

TELEPHONE NUMBER (Include Area Code)

(620) 364-4038

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED

X YES (If yes, complete EXPECTED SUBMISSION DATE)

NO

15. EXPECTED
SUBMISSION
DATE

MONTH

10

DAY

05

YEAR

2002

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

At 0815 on June 7, 2002, the Wolf Creek Generating Station (WCGS) Shift Manager was notified of a postulated fire event that could cause a cable-to-cable hot short. If cable-to-cable hot shorts are assumed to occur, this event has the potential to cause water in the refueling water storage tank (RWST) to drain to the containment recirculation sump. It was discovered that the control cables for two redundant motor operated valves are routed in the same electrical raceway. The two valves are in the same electrical separation group, but are redundant in their function of conserving water inventory in the RWST. Further investigation determined that the control cables for motor operated valves in the opposite electrical separation group have the same configuration. The cause of this condition is that cable-to-cable interactions were not considered in the initial design of the plant.

At 0945 on July 19, 2002, the Shift Manager was notified of conditions where a postulated fire event could lead to the loss of motor control centers that power post-fire safe shutdown equipment in both trains due to inadequate horizontal separation in conjunction with improper breaker coordination.

The safety significance of these events is low.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
WOLF CREEK GENERATING STATION	05000482	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 6
		2002	-- 004	-- 01	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

Background:

Wolf Creek Nuclear Operating Corporation (WCNOC) is in the process of performing an analysis of fire areas as part of a post fire safe shutdown (PFSSD) project to determine whether a fire in a single area could adversely affect the safe shutdown of the plant. During the fire area inspection phase of the project, WCNOC personnel discovered that potential problems exist with the separation of cables for redundant components required for post-fire safe shutdown. The first condition was identified on June 7, 2002, and was described in LER 2002-004-00, dated August 2, 2002. This supplement describes a second condition, which was discovered on July 19, 2002.

Condition 1:

Valves EJHV8811A [EIS Code: BP-ISV] and BNHV8812A [EIS Code: BP-ISV] are motor operated valves that supply Residual Heat Removal (RHR) System [EIS Code: BP] pump suction from the containment recirculation sump and from the refueling water storage tank (RWST), respectively. During a fire in the plant, it is the function of valves EJHV8811A and BNHV8812A to provide a barrier to draining water in the RWST to the containment recirculation sump. Control circuits for these two valves are routed together in the "A" safety injection pump room (Fire Area A-2), the corridor of the auxiliary building [EIS Code: NF] at elevation 1974 ft. (Fire Area A-1) and the corridor of the auxiliary building at elevation 2000 ft. (Fire Area A-8). The same condition exists with the control circuits for valves EJHV8811B and BNHV8812B in the opposite train. Control circuits for these two valves are routed together in the "B" safety injection pump room (Fire Area A-4) and also in the auxiliary building corridor at elevation 1974 ft. A single fire in either pump room or in the auxiliary building corridor at elevation 1974 ft. could cause a hot short that could result in inadvertently draining the water in the RWST to the containment recirculation sump. Water normally available from the RWST to be used for the core cooling injection phase would not be available if this were to occur.

Condition 2:

The RHR pump room coolers and the Centrifugal Charging Pump (CCP) room coolers utilize Essential Service Water (EJ) [EIS Code: BI] as the cooling medium. During a fire in the plant, it is the function of these room coolers to provide adequate room cooling for the continued operation of their respective pumps in order to maintain the plant in a safe shutdown condition.

A postulated fire in the auxiliary building corridor at elevation 1974 ft. (Fire Area A-1) could cause the loss of motor control centers (MCCs) NG01A ("A" train) and NG02A ("B" train). These MCCs supply redundant PFSSD equipment such as "A" and "B" train pump room coolers and miscellaneous valves.

Plant Conditions Prior to Each Event:

MODE – 1
Power – 100 Percent
Normal Operating Temperature and Pressure

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
WOLF CREEK GENERATING STATION	05000482	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 6
		2002	-- 004	-- 01	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

Condition Descriptions:

Condition 1:

At 0815 on June 7, 2002, the Shift Manager was notified of a condition where a postulated fire event could cause a cable-to-cable hot short. This event has the potential to cause the RWST to drain to the containment recirculation sump. During the fire area inspection phase of the Post-Fire Safe Shutdown project, it was discovered that the control cables for two redundant motor operated valves, EJHV8811A and BNHV8812A, are routed together in the "A" safety injection pump room and in the auxiliary building corridors at elevations 1974 ft. and 2000 ft. The two valves are in the same electrical separation group, but are redundant in their function of conserving water inventory in the RWST. Further investigation determined that the control cables for motor operated valves EJHV8811B and BNHV8812B in the other electrical separation group have the same configuration since they are routed together in the "B" safety injection pump room and in the auxiliary building corridor at elevation 1974 ft. A fire in any one of these areas has the potential to damage the control cables to the EJHV8811A/B valves causing the valves to spuriously open due to a hot short. Fire damage to the control cables to the BNHV8812A/B valves could result in the valves not responding to a close signal due to an open circuit. This condition would cause the water in the RWST to drain to the containment recirculation sump.

Condition 2:

At 0945 on July 19, 2002, the Shift Manager was notified of conditions where a postulated fire event could lead to the loss of MCCs that power post fire safe shutdown equipment in both trains due to inadequate horizontal separation in conjunction with improper breaker coordination. During the fire area inspection phase of the Post Fire Safe Shutdown project, WCNOG personnel discovered that the power cables supplied from MCCs NG01A and NG02A for various non-PFSSD and PFSSD room coolers do not have adequate horizontal separation or proper breaker coordination as specified in 10 CFR 50 Appendix R. The PFSSD components are both trains of RHR pump room coolers and both trains of CCP room coolers. The non-PFSSD components are both trains of Safety Injection Pump room coolers and both trains of Containment Spray Pump room coolers. These cables are located in the auxiliary building corridor at elevation 1974 ft. A fire in this area has the potential to damage the power cables to these room coolers, resulting in loss of MCCs NG01A, NG02A and room cooling for the RHR pumps and CCPs. This issue has the potential to cause the RHR and Chemical and Volume Control (BG) [EIS Code: CB] systems to become unavailable to perform their post-fire safe shutdown functions.

Initial evaluation has indicated that existing breaker coordination is acceptable based on IEEE 242-1986, IEEE 603 Appendix A and IEEE Transaction on Industry Applications, Vol. 1A-8, No. 3, May/June 1972. Performance Improvement Request (PIR) 2002-1670 tracks completion of this evaluation and any resultant plant modification required to ensure adequate breaker coordination for the subject fire area (A-1). These actions will be completed on or before December 15th, 2002.

Basis for Reportability:

Condition 1:

A fire in any one of the subject fire areas (A-1, A-2, A-4 and A-8) has the potential to damage the control

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
WOLF CREEK GENERATING STATION	05000482	2002	-- 004	-- 01	4	OF 6

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

cables for valves EJHV8811A/B in a manner that causes the valve to spuriously open and damage the corresponding control cables for valves BNHV8812A/B in a manner that causes the valves to not respond to a signal to close. This would result in a flow path from the RWST through the open valves and into the containment recirculation sump. The post-fire safe shutdown function would be affected because the RWST function is required for hot shutdown.

Based on information known at the time of discovery, WCNOG made an eight hour Emergency Notification System call in association with 10 CFR 50.72(b)(3)(ii)(B) and 10 CFR 50.72(b)(3)(v)(A), (B) and (D). Further evaluation and a review of NUREG-1022, "Event Reporting Guidelines 10CFR50.72 and 50.73," determined that this condition is reportable pursuant to 10 CFR 50.72(b)(3)(ii)(B) / 10 CFR 50.73(a)(2)(ii)(B) for any event or condition that resulted in the nuclear power plant being in an unanalyzed condition that significantly degraded plant safety.

This condition does not meet the reporting requirements of 10 CFR 50.72(b)(3)(v)(A), (B) or (D), or 10 CFR 50.73(a)(2)(v)(A), (B) or (D), since there is a reasonable expectation that the safety function of preventing water from draining from the RWST would have been fulfilled by valves EJHV8811A/B in the event of a fire.

Condition 2:

Due to inadequate cable separation in conjunction with potential improper breaker coordination, a fire in the subject fire area (A-1) could result in the loss of PFSSD components. The post-fire safe shutdown function would be affected because the Residual Heat Removal and Chemical and Volume Control functions are required to maintain the post-fire safe shutdown decay heat removal, reactivity control and inventory control functions. Based on the above information WCNOG made an eight hour Emergency Notification System call in accordance with 10 CFR 50.72(b)(3)(ii)(B).

A review of NUREG-1022, "Event Reporting Guidelines 10CFR50.72 and 50.73," determined that the cable separation condition is reportable pursuant to 10 CFR 50.72(b)(3)(ii)(B) / 10 CFR 50.73(a)(2)(ii)(B) for any event or condition that resulted in the nuclear power plant being in an unanalyzed condition that significantly degraded plant safety.

Root Cause:

Condition 1:

The control cable configuration for valves EJHV8811A/B and BNHV8812A/B are per original plant design. Cable-to-cable hot shorts associated with the event in question were not analyzed as part of the Bechtel Fire Hazards Analysis. Therefore, the cause of this condition is due to cable-to-cable interaction not being considered in the initial plant design and specifically in relation to the routing of cables in the safety injection pump rooms and in the auxiliary building corridors at elevations 1974 ft. and 2000 ft.

Condition 2:

The improper breaker coordination for the room coolers has existed since plant startup. The cable configuration for the room coolers is per original plant design. The improper coordination necessary for the occurrence of a ground fault of the impedance required to open an upstream breaker prior to opening the

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
WOLF CREEK GENERATING STATION	05000482	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5 OF 6
		2002	-- 004	-- 01	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

load breaker is of very low probability and was not considered as part of the Bechtel Fire Hazards Analysis. Therefore, the cause of this condition is due to improper breaker coordination and inadequate consideration of horizontal separation in the initial plant design.

Corrective Actions:

Condition 1:

A continuous fire watch was established in Fire Areas A-1, A-2, A-4 and A-8 until procedure OFN KC-016, "Fire Response," was changed to add steps 11 through 21 to prevent draining the water in the RWST to the containment recirculation sump. After the procedure was changed, an hourly fire watch was established to monitor the safety injection pump rooms and the auxiliary building corridors at elevations 1974 ft. and 2000 ft.

Condition 2:

An hourly fire watch was established in Fire Area A-1. A corrective action plan was developed within the WCNOG corrective action program to address this issue.

Evaluation and corrective actions for the improper breaker coordination condition are being addressed in PIR 2002-1670. The evaluation and disposition or plant modification will be completed to ensure adequate breaker coordination for Fire Area A-1 by December 15, 2002.

Corrective actions for cable separation issues identified during the post-fire safe shutdown review are being addressed by PIR 2000-2378. These corrective actions are scheduled for implementation prior to the completion of Refuel 13, currently scheduled for November 21, 2003.

Safety Significance:

The safety significance of each event is low based on the following:

Condition 1:

Once the control rods insert during a reactor shutdown, the plant is immediately in a safe shutdown condition (i.e., hot standby). In order to maintain a safe shutdown condition in the plant, the Chemical and Volume Control System [EIS Code: CB] is required for boration and inventory makeup with the centrifugal charging pump (CCP) taking suction from the RWST.

If the RWST inventory were lost to the containment recirculation sump, the CCP would not have a direct suction path to the water. Makeup from the RWST to the Reactor Coolant System [EIS Code: AB] (RCS) would only be required to maintain the plant in a hot standby condition if the pressurizer level was decreasing or if positive reactivity was added. The safe shutdown methodology at WCGS relies on isolating the reactor such that very little makeup water would be needed and assumes no RCS cooldown.

Time would be available to take compensatory measures if the RWST water level was decreasing. If EJHV8811A or EJHV8811B were to inadvertently open, it would take approximately 55 minutes for the

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
WOLF CREEK GENERATING STATION	05000482	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	6 OF 6
		2002	-- 004	-- 01	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

RWST to drain to the lo-lo alarm set point and approximately 94 minutes for the tank to completely drain.

These times assume a flow rate of 4190 gallons per minute from the RWST to the containment recirculation sump as shown in calculation M-BN-21 revision 0.

Use of the Chemical and Volume Control System for boration is not required until xenon levels decrease, which is approximately 10 hours after reactor shutdown.

Condition 2:

The affected fire area (A-1) contains no significant fire loading. Therefore, a significant fire is not expected to occur in this area. However, should a fire occur, operators would take actions necessary to extinguish the fire and restore equipment necessary for post fire safe shutdown.

If a plant shutdown occurs, once the control rods insert the plant is immediately in a safe shutdown condition (i.e., Hot Standby (Mode 3)). The CCP room cooler is required for hot standby. Adequate protection for the CCP room coolers is provided by:

- Thirty-five feet of horizontal separation between the "A" and "B" trains of CCP room cooler cables. (Since intervening combustibles are located within this separation, the requirement for greater than 20 feet of cable separation with no intervening combustibles is not met.)
- high personnel traffic, such that any fire in the area would be quickly identified and acted upon; and
- overall low combustible loading in the area.

These factors improve the likelihood that the CCP room coolers will be available for Hot Standby conditions in the event of a fire.

During a reactor shutdown, if the RHR pump room coolers were unavailable due to a fire in area A-1, time would be available to take compensatory measures. The RHR system is not required until the decision is made to cool down the RCS from Hot Shutdown (Mode 4) to Cold Shutdown (Mode 5). Temporary ventilation units are available for use that could provide cooling for the pump motors. These units could be placed in service within two hours of the postulated fire, which is prior to the need for RHR system availability (a minimum of four hours following shutdown).

Based on these considerations, the safety significance of each event is low.

Previous Events:

An occurrence of a similar event was reported via licensee event report (LER) 1999-009-00. In LER 1999-009-00, it was determined that there was inadequate separation of cables for valves and level transmitters for the volume control tank. In the event of a fire, a potential existed for gas intrusion into the suction of the centrifugal charging pump. While corrective actions have been taken to address these conditions, an additional corrective action for LER 1999-009-00 was to validate the post fire safe shutdown analysis and to provide necessary correction to the Updated Safety Analysis Report (USAR). The validation consists of two phases: phase one reverifies the design criteria and phase two completes the post-fire safe shutdown analysis review. The conditions identified in this LER were discovered during phase two, which is currently in progress.

LIST OF COMMITMENTS

The following table identifies those actions committed to by Wolf Creek Nuclear Operating Corporation (WCNOC) in this document. Any other statements in this submittal are provided for information purposes and are not considered to be commitments. Please direct questions regarding these commitments to Mr. Tony Harris, Manager Regulatory Affairs at Wolf Creek Generating Station, (620) 364-4038.

COMMITMENT	Due Date/Event
A long-term resolution of this issue (which may include either re-routing of cable or wrapping the subject cable in fire retardant material) will be completed on or before the completion of Refuel 13 outage. The interim action of maintaining an hourly roving fire watches in the affected fire area remains in place until long-term resolution of this condition is implemented.	End of Refuel 13, currently scheduled for November 21, 2003.
Evaluation and disposition or plant modification for improper breaker coordination condition will be completed to ensure adequate breaker coordination for Fire Area A-1.	December 15, 2002