



May 23, 2003


L-PI-03-048
10 CFR 50.73

U S Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
DOCKET 50-282
LICENSE No. DPR-42

LER 1-03-01, RESIDUAL HEAT REMOVAL VALVE CV-31236 POSITIONER LINKAGE
FOUND BROKEN

The Licensee Event Report for this occurrence is attached. This letter and the attached report contain no new NRC commitments and no revisions to existing commitments. Please contact us if you require additional information related to this event.



Joseph M. Solymossy
Site Vice-President, Prairie Island Nuclear Generating Plant

CC Regional Administrator, USNRC, Region III
Project Manager, Prairie Island Nuclear Generating Plant, USNRC, NRR
NRC Resident Inspector – Prairie Island Nuclear Generating Plant
Glenn Wilson, State of Minnesota

Attachment

IE22

NRC FORM 366 (1-2001)			U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB NO. 3150-0104 EXPIRES 6-30-2001 Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.					
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)											
FACILITY NAME (1) Prairie Island Nuclear Generating Plant Unit 1						DOCKET NUMBER (2) 05000 282			PAGE (3) 1 OF 10		
TITLE (4) Residual Heat Removal Valve CV-31236 Positioner Linkage Found Broken											
EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
03	24	03	03	01	00	05	23	03	FACILITY NAME	DOCKET NUMBER	
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply) (11)									
1		20.2201(b) 20.2203(a)(3)(ii) 50.73(a)(2)(ii)(B) 50.73(a)(2)(ix)(A)									
POWER LEVEL (10)		20.2201(d) 20.2203(a)(4) 50.73(a)(2)(iii) 50.73(a)(2)(x)									
100		20.2203(a)(1) 50.36(c)(1)(i)(A) 50.73(a)(2)(iv)(A) 73.71(a)(4)									
		20.2203(a)(2)(i) 50.36(c)(1)(ii)(A) 50.73(a)(2)(v)(A) 73.71(a)(5)									
		20.2203(a)(2)(ii) 50.36(c)(2) 50.73(a)(2)(v)(B) OTHER									
		20.2203(a)(2)(iii) 50.46(a)(3)(ii) 50.73(a)(2)(v)(C) Specify in Abstract below or in NRC Form 366A									
		20.2203(a)(2)(iv) 50.73(a)(2)(i)(A) 50.73(a)(2)(v)(D)									
		20.2203(a)(2)(v) x 50.73(a)(2)(i)(B) 50.73(a)(2)(vii)									
		20.2203(a)(2)(vi) 50.73(a)(2)(i)(C) 50.73(a)(2)(viii)(A)									
20.2203(a)(3)(i) 50.73(a)(2)(ii)(A) 50.73(a)(2)(viii)(B)											
LICENSEE CONTACT FOR THIS LER (12)											
NAME Dale M. Vincent						TELEPHONE NUMBER (Include Area Code) 651-388-1121					
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	
A	BP	FCV	F125	Y							
SUPPLEMENTAL REPORT EXPECTED (14)						EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR	
YES (If yes, complete EXPECTED SUBMISSION DATE).						X NO					
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16) A wrench, left in the vicinity of the Unit 1 Train B Residual Heat Removal (RHR) heat exchanger outlet control valve during the November/December 2002 Unit 1 refueling outage, eventually became lodged in the valve operator. Subsequent operations of the valve with wrench interference caused the feedback linkage of the valve operator to fail. The position of the wrench and nature of the valve operator failure allowed this condition to be undetected until a system inspection on March 3, 2003. Upon discovery of the failed valve linkage on March 3, 2003, Technical Specification (TS) 3.5.2, Condition A was entered and valve repair was performed within the TS required Completion Time. The RHR control valve was found, with the wrench lodged in the operator, in the open safeguards position and the Control Room Operators could control the valve from the full open to full close positions, but could not modulate (throttle) the valve. An investigation determined that if the wrench became dislodged from the valve operator, the valve would have closed. A system status light would have alerted the Control Room Operators that the valve changed position but they may not have been able to reposition the valve to its open position. Valve operator air supply failure or isolation would have opened the valve. On March 24, 2003, with both units operating at 100% power, a Nuclear Management Company (NMC) evaluation determined that the misplaced wrench caused the RHR control valve to be inoperable.											

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Prairie Island Nuclear Generating Plant Unit 1	05000 282	03	- 01	- 00	2 OF 10

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT DESCRIPTION

On March 3, 2003, during an inspection of the Unit 1 Residual Heat Removal (RHR) system¹, the positioner feedback linkage² to the Train B air-operated control valve, RHR Heat Exchanger Reactor Coolant Outlet Flow Control Valve³, was noted to be disconnected and an adjustable wrench was observed lodged in the positioner linkage. It was later determined that the feedback linkage had deformed and failed during operation due to binding caused by the misplaced wrench lodged in the valve operator.

The positioner and controls for the Train B RHR heat exchanger outlet control valve were properly maintained in accordance with plant maintenance procedures on September 9, 2002. The maintenance procedure directs and documents the Instrumentation and Control (I&C) Specialist to specifically check the feedback linkage and nothing abnormal was noted during performance of this maintenance procedure.

A surveillance test was performed on November 21, 2002. Successful performance of this activity demonstrated that the valve's ability to modulate flow was functional. This was the last time that the feedback linkage was verified intact prior to discovery of its failure.

During investigation of this event, controlled test simulations demonstrated that for the feedback linkage failure to occur, following introduction of the adjustable wrench into the area of the valve positioner, the control valve must have been stroked from the closed position to the open position. Operation of the Train B RHR heat exchanger outlet control valve that could have damaged the feedback linkage happened for the first time on November 26, 2002 at 1108 hrs, again on November 29, 2002 at 0930 hrs, and finally on December 4, 2002 at 0130 hrs.

Investigation and analysis of activities performed in the Train B RHR pit during and following the Unit 1 outage in November/December 2002 determined that the Train B RHR heat exchanger outlet control valve linkage deformation and failure event most likely occurred on December 4, 2002 at 0130 hours when the Control Room Operator repositioned the valve to the open position from the control board⁴ in accordance with the instructions of plant procedures for operating the RHR system. However, the investigation could not rule out the possibility that the event occurred on November 26, 2002 or November 29, 2002.

On March 3, 2003, following discovery of the failed feedback linkage on the Train B RHR heat exchanger outlet control valve, Technical Specification (TS) 3.5.2 Condition A was entered to

¹ EIIS System Identifier: BP² EIIS System Identifier: BP Component Identifier: TC³ EIIS System Identifier: BP Component Identifier: FCV⁴ EIIS Component Identifier: MCB

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Prairie Island Nuclear Generating Plant Unit 1	05000 282	03	- 01	- 00	3 OF 10

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

allow repair of this valve. The Train B RHR heat exchanger outlet control valve was repaired and returned to service at 2128 hours that same day.

On March 24, 2003, the Nuclear Management Company (NMC) determined that if the wrench had become dislodged from the valve positioner feedback linkage, the valve would reposition to the closed position without Control Room Operator action. A system status light in the Control Room would provide indication of valve repositioning, however the Control Room Operator may not be able to reposition the valve to its open, safeguards position. If an event occurred in this configuration, which required the RHR valve to be open, isolation of the air supply⁵ to the actuator would open the valve and the valve would also fail open on a loss of air event.

CAUSE OF THE EVENT

A 10" adjustable wrench was inadvertently left in the vicinity of Train B RHR heat exchanger outlet control valve which likely entered into the area between the positioner and the mounting bracket when the valve was in its closed position. Workers failed to account for tools upon completion of their tasks near this valve.

ANALYSIS OF THE EVENT

TS 3.5.2 requires two trains of ECCS to be OPERABLE during Modes 1, 2, and 3. Unit 1 entered Mode 3 operation on December 4, 2002 at 0435 hours. TS 1.1, Definitions, defines a device as OPERABLE "when it is capable of performing its specified safety function(s)."

During the November/December 2002 Unit 1 refueling outage, a 10" adjustable wrench was left in an inappropriate location in the vicinity of the Train B RHR Heat Exchanger Reactor Coolant Outlet Flow Control Valve. The adjustable wrench was apparently left from one of three work activities that were performed on a manually operated valve⁶, located directly above the diaphragm case for the Train B RHR heat exchanger outlet control valve. The most likely area in which the wrench was left was on top of the positioner attached to the Train B RHR heat exchanger outlet control valve. The adjustable wrench apparently entered the area between the positioner and the mounting bracket when the valve was in its closed position. Operating the valve to the open position likely resulted in linkage binding resulting in deformation of the positioner feedback linkage, deformation of the standoff bolt between the

⁵ EIS System Identifier: LD

⁶ EIS System Identifier: BP Component Identifier: LOV

NRC FORM 366A (1-2001)		U.S. NUCLEAR REGULATORY COMMISSION		
LICENSEE EVENT REPORT (LER)				
FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)		
Prairie Island Nuclear Generating Plant Unit 1	05000 282	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
		03	- 01	- 00
		PAGE (3)		
		4 OF 10		

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

stem connector assembly and linkage, and separation of the bolt from the stem connector assembly.

In the "as-found" configuration, the wrench was resting on the positioner drive arm and the valve was in its safeguards position for power operation, full open. If the wrench had become dislodged from the Train B RHR heat exchanger outlet control valve, the capability to re-open the Train B RHR heat exchanger outlet control valve with the control room hand controller⁷ is dependent on the under range capability (<6.5 milliamp) of the hand controller. The Control Room Operator would have to position the hand controller beyond the full open position. The Control Room hand controller for the Train B RHR heat exchanger outlet control valve under range capability may not be sufficient to allow re-opening the valve.

Since operability of the Train B RHR heat exchanger outlet control valve could not be assured without the wrench lodged in the operator mechanism, the valve would not support operability of RHR Train B as required by TS LCO 3.5.2, which requires two trains of the Emergency Core Cooling System (ECCS) (RHR and safety injection⁸ (SI) systems) to be operable. Thus, this event has been determined to be reportable per 10CFR 50.73 (a)(2)(i)(B).

Impact on Safety System Functional Failure Performance Indicator

This condition could not have (by itself) prevented a safety function, because the Train B RHR heat exchanger outlet control valve inoperability only affects one train of RHR and the valve with the wrench cradled in the operating mechanism was in the safeguards position, full open. Also, the redundant RHR Train A, except for a few minutes during the period of possible inoperability of RHR Train B, could have continued to perform the required safety function. Thus, this event is not reportable per 10CFR 50.73 (a)(2)(v), and, therefore, does not impact the Safety System Functional Failure Performance Indicator.

Evaluation of Safety Significance

System Functions

The RHR system is a dual use system that provides a safeguards function as part of the ECCS and removes residual heat during normal evolutions such as plant cooldown from Mode 4 to Mode 5 and residual heat removal from the core during plant shutdown in Modes 5 and 6.

The Train B RHR heat exchanger outlet control valve is an air-operated valve on RHR Train B designed to fail open upon loss of instrument air pressure. The Train B RHR heat exchanger

⁷ EIIS System Identifier: BP Component Identifier: HC

⁸ EIIS System Identifier: BQ

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Prairie Island Nuclear Generating Plant Unit 1	05000 282	03	- 01	- 00	5 OF 10

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

outlet control valve is used to control the cooldown rate of the reactor coolant system⁹ (RCS) by controlling the flow rate through Train B RHR heat exchanger¹⁰. During normal operation, the valve is in the open position to allow full flow through Train B RHR heat exchanger for low head injection. The line from Train B RHR heat exchanger to Train B SI pump¹¹ for high head recirculation taps off upstream of the Train B RHR heat exchanger outlet control valve so the valve is not required for high head recirculation. When this valve is not full open, a light¹² illuminates on the "SI Not Ready" panel¹³ in the control room, which indicates that the system is not in its safeguards configuration for plant operation in Modes 1, 2, and 3.

Initiating Events Requiring the Train B RHR Heat Exchanger Outlet Control Valve Function

Since the RHR supply to the SI pump suction is upstream of the Train B RHR heat exchanger outlet control valve, this valve is only required to perform its safeguards function during transients and accidents that require RHR low head injection. The Train B RHR heat exchanger outlet control valve does not provide any function for high head recirculation so these initiating events are not affected by this valve's failure.

Because of the functions provided by the Train B RHR heat exchanger outlet control valve, it is required for the RHR system to mitigate the consequences of: (1) loss of coolant accidents (LOCAs) (including large break and small break LOCAs); and (2) steam generator¹⁴ tube rupture (SGTR) accidents.

Following a small break LOCA initiating event with successful SI system¹⁵ injection, the Control Room Operator can cooldown and depressurize the RCS to temperatures and pressures where the RHR system can be used to remove decay heat, thereby precluding the need for high head recirculation. The Train B RHR heat exchanger outlet control valve provides a function in this case as it can be used to control the RCS cooldown rate through Train B RHR heat exchanger. If SI system injection should fail, the RCS can be depressurized such that low head injection together with low head recirculation can prevent core damage. In this case, the Train B RHR heat exchanger outlet control valve allows full low head RHR flow to the reactor vessel¹⁶.

⁹ EIIS System Identifier: AB

¹⁰ EIIS System Identifier: BP Component Identifier: HX

¹¹ EIIS System Identifier: BQ Component Identifier: P

¹² EIIS System Identifier: IB Component Identifier: IL

¹³ EIIS System Identifier: IB

¹⁴ EIIS System Identifier: SB Component Identifier: SD

¹⁵ EIIS System Identifier: BQ

¹⁶ EIIS System Identifier: AB Component Identifier: RPV

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Prairie Island Nuclear Generating Plant Unit 1	05000 282	03	- 01	- 00	6 OF 10

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

For large break LOCAs, the functions provided by the Train B RHR heat exchanger outlet control valve are the only means to prevent core damage as low head injection together with low head recirculation are required to mitigate the accident.

Following a SGTR, SI system injection is needed to prevent core uncover. SI pumps will be sequentially stopped and RHR shutdown cooling would be needed to provide decay heat removal while the RCS is depressurized to atmospheric pressure. In this case, the functions provided by the Train B RHR heat exchanger outlet control valve are required to mitigate core damage.

Deterministic Assessment

In the "as-found" condition, the Train B RHR heat exchanger outlet control valve had an adjustable wrench lodged in the valve air-operated control mechanism and the feedback linkage was broken. The valve was open and could have performed its design basis safety function. The light on the "SI Not Ready" panel associated with this valve was not illuminated. Tests on a valve mockup determined that the valve could be fully closed and fully opened in this configuration but could not be modulated.

On the basis of tests performed on a valve mockup, if the wrench became dislodged from the valve operator, the valve would go to the fully closed position without any Operator action. The operators may not be able to re-open the valve when the wrench becomes dislodged and the valve would not be able to perform its safety function.

The wrench appears to have been lodged in the Train B RHR heat exchanger outlet control valve operator for nearly three months. The magnitude of force required to dislodge the wrench from this Train B RHR heat exchanger outlet control valve is not known. Pictures of the wrench in the "as-found" position and mockup tests demonstrated that that the combination of interferences and geometry of the valve positioner mounting bracket served to cradle the wrench.

If the wrench became dislodged during normal plant operations, without provocation, the valve would go to the fully closed position due to dislodgement of the wrench and the Control Room Operators would be alerted to the valve closure by the "SI Not Ready" panel light illumination. TS 3.5.2, Condition A would have been entered and the valve would be repaired on a timely basis.

For the purposes of discussion, it is postulated that likely causes for dislodging the wrench could include valve operations or an event which would shake the plant such as an earthquake. This valve is in an obscure location; so unobserved bumping by plant personnel resulting in wrench dislodgement is unlikely.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Prairie Island Nuclear Generating Plant Unit 1	05000 282	03	- 01	- 00	7 OF 10

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

An activity that dislodged the wrench and caused the valve to close during plant operation would have also caused the "SI Not Ready" light to illuminate. An operation associated with plant operation that possibly could cause dislodging the wrench would be moving the valve to attempt throttling RHR flow for a plant cooldown. When the valve went to the fully closed position due to dislodgement of the wrench, the Control Room Operators would have indications that the valve was not correctly positioned, such as lack of RHR flow and the "SI Not Ready" light illuminated. During normal plant operational evolutions, the valve going to fully closed and not capable of re-opening from the Control room would not involve safety significance. The plant operating evolution, such as plant cooldown, could be delayed until the valve was repaired. Once the broken feedback linkage was identified for the Train B RHR heat exchanger outlet control valve, repair was effected in approximately two hours. If the valve needed to be opened urgently, the Operators could isolate the instrument air supply to the valve from a location outside the RHR pit causing it to fail fully open.

An activity that involves significant plant shaking and could require response of the safety related plant systems is an earthquake. If the Train B RHR heat exchanger outlet control valve went to the fully closed position due to dislodgement of the wrench during an earthquake, the Control Room Operators would have indications that the valve was not correctly positioned such as lack of RHR flow and the "SI Not Ready" light illuminated. Since the instrument air system is not designed to withstand a design basis earthquake, it could also be postulated that the instrument air system would fail and the Train B RHR heat exchanger outlet control valve would return to the fully open position. In the very unlikely event of an earthquake that would require ECCS but not disable the instrument air system, the Control Room Operators would have indications that the valve was not correctly positioned such as lack of RHR flow and the "SI Not Ready" light illuminated. To establish Train B ECCS flow to the reactor core, the Operators could isolate the instrument air supply to the valve from a location outside the RHR pit causing it to fail fully open. An earthquake requiring ECCS is a very unlikely event.

The RHR system comprises two redundant trains of which only one is required to mitigate the consequences of an accident which requires ECCS. During the period from December 4, 2002 through March 3, 2003, Train A RHR was operable and would have provided the required ECCS flow during an accident except for nine minutes on January 29, 2003 during which Train A RHR was out of service for performance of a surveillance test. Thus, Train A was operable in excess of 99.99 percent of the time that Train B could be considered inoperable.

NRC FORM 366A (1-2001)		U.S. NUCLEAR REGULATORY COMMISSION		
LICENSEE EVENT REPORT (LER)				
FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)		PAGE (3)
Prairie Island Nuclear Generating Plant Unit 1	05000 282	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
		03	- 01	- 00
				8 OF 10

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Deterministic Assessment Conclusions

The RHR Train B control valve with broken feedback linkage and an adjustable wrench lodged in the valve air operator mechanism is considered an event of low safety significance. This conclusion is based on considerations presented above which include:

1. The redundant RHR train, Train A, was operable over 99.99 percent of the time that RHR Train B could be considered inoperable.
2. If the valve closed due to dislodgement of the wrench, the Control Room Operators would have indication from the "SI Not Ready" panel.
3. If wrench dislodgement was associated with an event during which the operators anticipate RHR flow to the reactor vessel, the Control Room Operators could also observe that there is no RHR Train B flow.
4. Postulated events such as an earthquake that could cause significant plant shaking to dislodge the wrench and require RHR flow are very unlikely. An earthquake that could dislodge the wrench could also disable the instrument air system (not designed to withstand seismic events) which would re-open the valve.

Risk Significance Assessment Assumptions

1. It was conservatively assumed for this risk analysis, that the Train B RHR heat exchanger outlet control valve was failed in the closed position.
2. It was assumed that the valve could not be opened from the Control Room.
3. Credit for local Operator action to fail air to the valve to open it was not credited.
4. It was assumed that the Train B RHR heat exchanger outlet control valve was failed in the closed position for 90 days from December 4, 2002 until discovery on March 3, 2003.
5. Large early release frequency (LERF) was not considered due to the insignificant impact of the RHR system on LERF results.

Risk Significance Initiating Events Impact

Because of the functions provided by the Train B RHR heat exchanger outlet control valve, it is required for the RHR system to mitigate the consequences of: (1) loss of coolant accidents (LOCAs) (including large break, medium break, small break and reactor coolant pump (RCP) seal LOCAs); and (2) steam generator tube rupture (SGTR) accidents.

NRC FORM 366A <small>(1-2001)</small>		U.S. NUCLEAR REGULATORY COMMISSION							
LICENSEE EVENT REPORT (LER)									
FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6) <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%; padding: 2px;">YEAR</td> <td style="width: 25%; padding: 2px;">SEQUENTIAL NUMBER</td> <td style="width: 25%; padding: 2px;">REVISION NUMBER</td> </tr> <tr> <td style="text-align: center; padding: 2px;">03</td> <td style="text-align: center; padding: 2px;">- 01</td> <td style="text-align: center; padding: 2px;">- 00</td> </tr> </table>	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	03	- 01	- 00	PAGE (3)
YEAR	SEQUENTIAL NUMBER	REVISION NUMBER							
03	- 01	- 00							
Prairie Island Nuclear Generating Plant Unit 1	05000 282		9 OF 10						

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Risk Significance Determination

The results of the analysis assuming that the Train B RHR heat exchanger outlet control valve is failed in the closed position for 90 days are a conditional core damage frequency (CCDF) of $1.65\text{E-}06/\text{yr}$ for Unit 1 and a conditional core damage probability (CCDP) of $4.07\text{E-}07$. Dominant sequences involve a small break LOCA or SGTR followed by failure of the component cooling system¹⁷ supply to Train A RHR heat exchanger or failure of the Train A RHR heat exchanger outlet control valve. Other sequences involving large break LOCA initiating events are of much less significance than those sequences involving a small break LOCA or SGTR initiating event.

Risk Significance Conclusions

The risk analysis performed using the current Prairie Island risk assessment model and assuming that the Train B RHR heat exchanger outlet control valve has failed in the closed position shows that the resulting CCDF is $1.65\text{E-}06/\text{yr}$. Using the value of 90 days during which the Train B RHR heat exchanger outlet control valve is assumed to be failed in the closed position, the CCDP is $4.07\text{E-}07$. By virtue of the CCDP being less than $1\text{E-}06$, the event can be classified as non-risk significant.

CORRECTIVE ACTIONS

Immediate:

The Train B RHR heat exchanger outlet control valve feedback linkage was reconnected and acceptance testing was performed.

Actions to Prevent Recurrence:

1. Develop a tool accountability program.
2. Perform training on tool management at the work site and tool accountability at the completion of the task or workday.

¹⁷ EIIS System Identifier: CC

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Prairie Island Nuclear Generating Plant Unit 1	05000 282	03	- 01	- 00	10 OF 10

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

FAILED COMPONENT IDENTIFICATION

Train B RHR heat exchanger outlet control valve CV-31236.

PREVIOUS SIMILAR EVENTS

No previous LERs with similar events.