

July 23, 2003

Mr. Mark E. Warner, Site Vice President
c/o James M. Peschel
Seabrook Station
FPL Energy Seabrook, LLC
P.O. Box 300
Seabrook, NH 03874

SUBJECT: SUMMARY OF PRE-OUTAGE CONFERENCE CALL WITH FPL ENERGY
SEABROOK, LLC REGARDING THE INSPECTION SCOPE FOR THE
UPCOMING STEAM GENERATOR INSPECTIONS AT THE SEABROOK
STATION, UNIT NO. 1 (TAC NO. MB8928)

Dear Mr. Warner:

On June 16, 2003, the U. S. Nuclear Regulatory Commission held a conference call with FPL Energy Seabrook, LLC, the licensee for the Seabrook Station, Unit No.1 (Seabrook), to discuss the inspection scope for the scheduled upcoming steam generator inspections at Seabrook during the next refueling outage. Currently, the planned scope includes inspection of 100% of the tubes in all four steam generators using a bobbin coil, with supplementary inspections using a rotating coil in tube locations with increased susceptibility to degradation.

Enclosed is a summary of the conference call.

Sincerely,

/RA/

Victor Nerses, Senior Project Manager, Section 2
Project Directorate I
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-443

Enclosure: Summary of Pre-Outage Conference Call

cc w/encl: See next page

July 23, 2003

Mr. Mark E. Warner, Site Vice President
c/o James M. Peschel
Seabrook Station
FPL Energy Seabrook, LLC
P.O. Box 300
Seabrook, NH 03874

SUBJECT: SUMMARY OF PRE-OUTAGE CONFERENCE CALL WITH FPL ENERGY SEABROOK, LLC REGARDING THE INSPECTION SCOPE FOR THE UPCOMING STEAM GENERATOR INSPECTIONS AT THE SEABROOK STATION, UNIT NO. 1 (TAC NO. MB8928)

Dear Mr. Warner:

On June 16, 2003, the U. S. Nuclear Regulatory Commission held a conference call with FPL Energy Seabrook, LLC, the licensee for the Seabrook Station, Unit No.1 (Seabrook), to discuss the inspection scope for the scheduled upcoming steam generator inspections at Seabrook during the next refueling outage. Currently, the planned scope includes inspection of 100% of the tubes in all four steam generators using a bobbin coil, with supplementary inspections using a rotating coil in tube locations with increased susceptibility to degradation.

Enclosed is a summary of the conference call.

Sincerely,

/RA/

Victor Nerses, Senior Project Manager, Section 2
Project Directorate I
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-443

Enclosure: Summary of Pre-Outage Conference Call

cc w/encl: See next page

DISTRIBUTION:

PUBLIC PDI-2 Rdg. CHolden JClifford VNerses CRaynor
OGC ACRS GHill(2) BMcDermott, RGN-I
ADAMS Accession Number: ML031970605

OFFICE	PDI-2/PM	PDI-2/LA	EMCB/SC	PDI-2/SC
NAME	VNerses	CRaynor	LLund	JClifford
DATE	7/21/03	7/21/03	7/21/03	7/23/03

OFFICIAL RECORD COPY

SUMMARY OF PRE-OUTAGE CONFERENCE CALL REGARDING THE INSPECTION

SCOPE FOR THE UPCOMING STEAM GENERATOR INSPECTION AT THE

SEABROOK STATION, UNIT NO. 1

As part of a U.S. Nuclear Regulatory Commission (NRC) normal oversight activity with plants that have steam generator issues (SG), the NRC, on June 16, 2003, held a conference call with FPL Energy Seabrook, the licensee for the Seabrook Station, Unit No. 1 (Seabrook). The purpose of the call was to discuss the planned SG inspection scope at Seabrook during the upcoming refueling outage. The scope is preliminary as the plant's SG tube degradation assessment is not yet complete.

Seabrook uses four Westinghouse Model F steam generators with thermally-treated Alloy 600 tubing, and is the first domestic plant to identify axial outside-diameter stress corrosion cracking (ODSCC) of SG tubes fabricated from this material. This degradation was identified during the Spring 2002 refueling outage and was attributed to non-optimal tube processing during the fabrication of the SG. Additional details are contained in NRC Information Notice (IN) 2002-21, "Axial Outside-Diameter Cracking Affecting Thermally Treated Alloy 600 Steam Generator Tubing" (Agencywide Document Access and Management System (ADAMS) Accession No. ML021770094); IN 2002-21, Supplement 1, "Axial Outside-Diameter Cracking Affecting Thermally Treated Alloy 600 Steam Generator Tubing" (ADAMS Accession No. ML030900517); and in the licensee's root cause analysis report (ADAMS Accession Nos. ML023300457 and ML023240524). The planned inspection scope consists of:

- inspection of 100% of the active tubes in all four SGs with a bobbin probe
- inspection of 50% of the tubes in all four SGs with a rotating probe in the hot leg top-of-tubesheet region (i.e., inspection from 3 inches above to 3 inches below the top-of-tubesheet region)
- inspection of 50% of the row 1 and 2 tubes in the U-bend region in all four SGs with a rotating probe
- inspection of 50% of dents and dings greater than 5 volts in the hot leg tubes in all four SGs with a rotating probe
- inspection of indications with a rotating probe that are identified as "I Codes," based on examination with a bobbin probe

Six tubes displaying an eddy current signal offset, characteristic of the tubes with axial ODSCC, will be plugged during the next refueling outage. These six tubes were determined to display the offset after completion of the 2002 refueling outage and exhibited no ODSCC crack-like indications during the 2002 SG inspection. Eddy current testing will be performed on these tubes prior to plugging, in order to assess their condition. Refer to ADAMS Accession No. ML023170187, "Summary of Conference Call With North Atlantic Energy Service Corporation Regarding The Seabrook Steam Generator Laboratory Examination Results," for additional information regarding the eddy current signal offset.

Eddy current analysis of site-specific orientation and testing will incorporate samples from the thermally-treated Alloy 600 tubing with ODSCC. The licensee indicated this was an enhancement to their training program, since the previous level of training had been sufficient to detect the ODSCC flaws in the previous outage.

Enclosure

Seabrook Station, Unit No. 1
cc:

Mr. J. A. Stall
Senior Vice President, Nuclear and
Chief Nuclear Officer
Florida Power & Light Company
P.O. Box 14000
Juno Beach, FL 33408-0420

Mr. Peter Brann
Assistant Attorney General
State House, Station #6
Augusta, ME 04333

Resident Inspector
U.S. Nuclear Regulatory Commission
Seabrook Nuclear Power Station
P.O. Box 1149
Seabrook, NH 03874

Town of Exeter
10 Front Street
Exeter, NH 03823

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Office of the Attorney General
One Ashburton Place, 20th Floor
Boston, MA 02108

Board of Selectmen
Town of Amesbury
Town Hall
Amesbury, MA 01913

Mr. Dan McElhinney
Federal Emergency Management Agency
Region I
J.W. McCormack P.O. &
Courthouse Building, Room 401
Boston, MA 02109

Mr. Jack Devine
Polestar Applied Technology
One First Street, Suite 4
Los Altos, CA 94019

Mr. Stephen McGrail, Director
ATTN: James Muckerheide
Massachusetts Emergency Management Agency
400 Worcester Road
Framingham, MA 01702-5399

Philip T. McLaughlin, Attorney General
Steven M. Houran, Deputy Attorney
General
33 Capitol Street
Concord, NH 03301

Mr. Donald Bliss, Director
New Hampshire Office of Emergency
Management
State Office Park South
107 Pleasant Street
Concord, NH 03301

Mr. Daniel G. Roy
Nuclear Training Manager
Seabrook Station
FPL Energy Seabrook, LLC
P.O. Box 300
Seabrook, NH 03874

Mr. Gene F. St. Pierre
Station Director
Seabrook Station
FPL Energy Seabrook, LLC
P.O. Box 300
Seabrook, NH 03874

Mr. M. S. Ross, Attorney
Florida Power & Light Company
P.O. Box 14000
Juno Beach, FL 33408-0420

Mr. Rajiv S. Kundalkar
Vice President - Nuclear Engineering
Florida Power & Light Company
P.O. Box 14000
Juno Beach, FL 33408-0420