

Stephen A. Byrne  
Senior Vice President, Nuclear Operations  
803.345.4622



December 15, 2003

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

Dear Sir / Madam:

Subject: VIRGIL C. SUMMER NUCLEAR STATION  
DOCKET NO. 50-395  
OPERATING LICENSE NO. NPF-12  
LICENSEE EVENT REPORT (LER 2003-005-00)  
FAILURE OF MASTER RELAY K507 DURING SOLID STATE  
PROTECTION SYSTEM TESTING

Attached is Licensee Event Report (LER) No. 2003-005-00, for the Virgil C. Summer Nuclear Station (VCSNS). The report describes a failure of Master Relay K507 During Solid State Protection System Testing and is being submitted in accordance with 10 CFR 50.73(a)(2)(vii) and 10 CFR 21.21.

Should you have any questions, please call Mr. Ron Clary at (803) 345-4757.

Very truly yours,

Stephen A. Byrne

JWP/SAB/dr  
Attachment

c: N. O. Lorick  
N. S. Carns  
T. G. Eppink (w/o attachment)  
R. J. White  
L. A. Reyes  
K. R. Cotton  
NRC Resident Inspector  
M. N. Browne  
Paulette Ledbetter  
D. L. Abstance

EPIX Coordinator  
K. M. Sutton  
INPO Records Center  
J&H Marsh & McLennan  
Maintenance Rule Engineer  
NSRC  
QC  
RTS (0-C-03-4288)  
File (818.07)  
DMS (RC-03-0248)

IE22

**LICENSEE EVENT REPORT (LER)**(See reverse for required number of  
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503.

**1. FACILITY NAME**

Virgil C. Summer Nuclear Station

**2. DOCKET NUMBER**

05000395

**3. PAGE**

1 OF 3

**4. TITLE**

Failure of Master Relay K507 During Solid State Protection System Testing

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
10	03	2003	2003	-005	- 00	12	15	2003	FACILITY NAME	DOCKET NUMBER
<b>9. OPERATING MODE</b>		1	<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)</b>							
<b>10. POWER LEVEL</b>		100	20.2201(b)			20.2203(a)(3)(ii)			50.73(a)(2)(ii)(B)	50.73(a)(2)(ix)(A)
			20.2201(d)			20.2203(a)(4)			50.73(a)(2)(iii)	50.73(a)(2)(x)
			20.2203(a)(1)			50.36(c)(1)(i)(A)			50.73(a)(2)(iv)(A)	73.71(a)(4)
			20.2203(a)(2)(i)			50.36(c)(1)(ii)(A)			50.73(a)(2)(v)(A)	73.71(a)(5)
			20.2203(a)(2)(ii)			50.36(c)(2)			50.73(a)(2)(v)(B)	X OTHER
			20.2203(a)(2)(iii)			50.46(a)(3)(ii)			50.73(a)(2)(v)(C)	Specify in Abstract below or in
			20.2203(a)(2)(iv)			50.73(a)(2)(i)(A)			50.73(a)(2)(v)(D)	NRC Form 366A
			20.2203(a)(2)(v)			50.73(a)(2)(i)(B)		X	50.73(a)(2)(vii)	
			20.2203(a)(2)(vi)			50.73(a)(2)(i)(C)			50.73(a)(2)(viii)(A)	
			20.2203(a)(3)(i)			50.73(a)(2)(ii)(A)			50.73(a)(2)(viii)(B)	

**12. LICENSEE CONTACT FOR THIS LER****NAME**

R. B. Clary, Mgr., Nuclear Licensing

**TELEPHONE NUMBER (Include Area Code)**

(803) 345-4757

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
B	JC	RelayxD	MidTex	Yes					

**14. SUPPLEMENTAL REPORT EXPECTED**

YES (If yes, complete EXPECTED SUBMISSION DATE). X NO

**15. EXPECTED SUBMISSION DATE**

MONTH DAY YEAR

**16. ABSTRACT (Limit to 1400 spaces. i.e., approximately 15 single-spaced typewritten lines)**

On December 1, 2003, it was determined by the Senior Vice President, Nuclear Operations that the following event was reportable as a significant safety hazard.

On October 3, 2003, the V. C. Summer Nuclear Station (VCSNS) was performing solid state testing. The testing is in accordance with Surveillance Test Procedure (STP) 345.037, Solid State Protection System Actuation Logic and Master Relay Testing. At 1300, Master Relay K507, which actuates the Feed Water Isolation circuits upon Hi/Hi Steam Generator Water Level, failed to actuate. This component was a master relay with a paper wrapped coil, manufactured by MidTex (part number [P/N] 156-14D200).

A Non-Conformance Notice (NCN 03-3099) was written, and the master relay was replaced on October 3, 2003.

The cause of the master relay failure was determined to be an open circuit in the coil resulting from corrosion caused by off-gassing of chlorine contamination from the paper used to wrap the coil, or the adhesive used to attach the paper to the coil. An investigation into other master relays at VCSNS revealed that three additional MidTex P/N 156-14D200 relays with paper wrapped coils were installed in the Solid State Protection System. Although none of these had actually failed, they were replaced during Refueling Outage 14. The majority of the MidTex P/N 156-14D200 relays installed at VCS have cloth wrapped coils, and showed no evidence of corrosion.

This event is being reported under 10 CFR 50.73(a)(2)(vii) and 10 CFR 21.21.

## LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
V. C. Summer Nuclear Station	05000395	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF3
		2003	-- 005 --	00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

**PLANT IDENTIFICATION**

Westinghouse - Pressurized Water Reactor

**EQUIPMENT IDENTIFICATION**

Solid State Protection System Master Relay K507

**IDENTIFICATION OF EVENT**

This event was identified during performance of Surveillance Test Procedure (STP) 345.037, Solid State Protection System Actuation Logic and Master Relay Testing. Master Relay K507 failed to actuate during the test. This condition was identified in Condition Evaluation Report (CER) 03-3099 as a Non-Conforming condition.

**EVENT DATE**

October 3, 2003

(Date of determination of significant safety hazard - December 1, 2003)

**REPORT DATE**

December 15, 2003

**CONDITIONS PRIOR TO EVENT**

The plant was in Mode 1, at 100% Power.

**DESCRIPTION OF EVENT**

On October 3, 2003, the V. C. Summer Nuclear Station (VCSNS) was performing solid state testing on the 'A' train. The testing is in accordance with Surveillance Test Procedure (STP) 345.037, Solid State Protection System Actuation Logic and Master Relay Testing. At 1300, Master Relay K507, which actuates the Feed Water Isolation circuits upon Hi/Hi Steam Generator Water Level, failed to actuate. This component was a master relay with a paper wrapped coil, manufactured by MidTex (part number [P/N] 156-14D200). MidTex has no address, as they are no longer in business.

A Non-Conformance Notice (NCN 03-3099) was written, and the master relay was replaced on October 3, 2003.

The affected master relay was sent to Pentas, Inc. for a Root Cause of Failure Analysis.

## LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
V. C. Summer Nuclear Station	05000395	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 3
		2003	- 005 -	00	

## 17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

The failure analysis results attributed the failure to be an open circuit in the coil resulting from corrosion caused by off-gassing of chlorine contamination from the paper used to wrap the coil, or the adhesive used to attach the paper to the coil. Another MidTex P/N 156-14D200 relay with a paper wrapped coil, sent to Pentas, Inc. for follow-up analysis, showed evidence of the same type of corrosion. Therefore, this failure is considered to be a manufacturing defect in a basic component, which could cause a loss of safety function.

An investigation into other master relays at VCSNS revealed that three additional MidTex P/N 156-14D200 master relays with paper wrapped coils were installed in 'A' Train Solid State Protection System cabinet XPN7010. Although none of these had actually failed, they were replaced with Potter & Brumfield relays during Refueling Outage 14 (November 2003). The majority of the MidTex P/N 156-14D200 relays installed at VCS have cloth wrapped coils, and showed no evidence of corrosion.

This event is being reported under 10 CFR 50.73(a)(2)(vii) and 10 CFR 21.21.

**ANALYSIS OF EVENT**

Although the redundant train for K507, which had a different type of master relay, was operable and could have actuated the Feed Water Isolation Valves on a Hi/Hi Steam Generator Water level, VCSNS has determined that this condition should be reported under 10 CFR 50.73(a)(2)(vii), since multiple components were potentially affected in various trains and systems by the corrosion due to off-gassing.

**CORRECTIVE ACTIONS**

The potentially affected master relays have been identified and replaced with Potter & Brumfield relays.

**PRIOR OCCURRENCES**

None