

November 10, 2004

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Stop P1-137  
Washington, DC 20555-0001

ULNRC-05089



Ladies and Gentlemen:

**DOCKET NUMBER 50-483  
CALLAWAY PLANT UNIT 1  
UNION ELECTRIC CO.  
FACILITY OPERATING LICENSE NPF-30  
Special Report on the Inoperability of Unit Vent High Range Radiation Monitor**

The enclosed Special Report is submitted in accordance with Final Safety Analysis Report (FSAR) section 16.3.3.4, Accident Monitoring Instrumentation Limiting Condition for Operation. On October 22, 2004, the Unit Vent Mid and High Range monitors were declared Inoperable and this report documents the cause of the inoperability, the actions taken to restore the monitors to an Operable status, and the preplanned alternate monitoring methods established during the time of Inoperability.

This letter does not contain new commitments.

Sincerely,

A handwritten signature in black ink that reads "Keith D. Young".

Keith D. Young  
Manager, Regulatory Affairs

Enclosure

IE22

ULNRC-05089  
November 10, 2004  
Page 2

cc: U.S. Nuclear Regulatory Commission (Original and 1 copy)  
Attn: Document Control Desk  
Mail Stop P1-137  
Washington, DC 20555-0001

Mr. Bruce S. Mallett  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011-4005

Senior Resident Inspector  
Callaway Resident Office  
U.S. Nuclear Regulatory Commission  
8201 NRC Road  
Steedman, MO 65077

Mr. Jack N. Donohew (2 copies)  
Licensing Project Manager, Callaway Plant  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Mail Stop 7E1  
Washington, DC 20555-2738

Missouri Public Service Commission  
Governor Office Building  
200 Madison Street  
PO Box 360  
Jefferson City, MO 65102-0360

ULNRC-05089  
November 10, 2004  
Page 3

bcc: G. L. Randolph (w/o)  
C. D. Naslund (w/o)  
K. D. Young (w/o)  
G. A. Hughes (w/a)  
D. E. Shafer (w/a) (470) (2 copies)  
S. L. Gallagher (w/o) (100)  
S. L. Klang (w/a) (NSRB)  
M. A. Reidmeyer (w/a)  
J. E. Ready (w/o)  
E210.0001  
A160.0761  
Chrono file

The following are sent without attachments:

Ms. Diane M. Hooper  
Supervisor, Licensing  
WCNOC  
P.O. Box 411  
Burlington, KS 66839

Mr. Scott Bauer  
Regulatory Affairs  
Palo Verde NGS  
P.O. Box 52034,  
Mail Station 7636  
Phoenix, AZ 85072-2034

Mr. Scott Head  
Supervisor, Licensing  
South Texas Project NOC  
Mail Code N5014  
P.O. Box 289  
Wadsworth, TX 77483

Mr. John O'Neill  
Shaw, Pittman  
2300 N. Street N.W.  
Washington, DC 20037

Mr. Dennis Buschbaum  
TXU Power  
Comanche Peak SES  
P.O. Box 1002  
Glen Rose, TX 76043

Mr. Stan Ketelsen  
Manager, Regulatory Services  
Pacific Gas & Electric  
Mail Stop 104/5/536  
P.O. Box 56  
Avila Beach, CA 93424

Certrec Corporation  
4200 South Hulen, Suite 630  
Fort Worth, TX 76109

Special Report: Inoperability of GTRE0021B

During quarterly Surveillance testing of the Unit Vent Radiation Monitor on October 22, 2004, the Mid/High Range Channel flow control circuit failed to achieve the required sample flow necessary for isokinetic sampling. Troubleshooting ultimately determined that the failure was due to improper reassembly of a filter canister located between the Mid/High Vacuum Pump discharge and the Mid/High Range Detector Chambers. The design of this filter relies on a tapered flange between both the canister body and canister lid which compresses a sealing o-ring when coupled together using a constricting steel band. Following discovery of the failure mechanism investigation revealed that the faulty reassembly occurred on October 5, 2004 when the filter was last replaced. Performance of the quarterly Surveillance was not coordinated with the filter replacement activity delaying the identification of faulty reassembly. The canister was properly reassembled and a tight seal was verified by achieving correct flow characteristics for the Mid/High Range flow control circuit. On October 28, 2004, the Mid/High Range Unit Vent Radiation Monitor was declared Operable and returned to service.

During the performance of the quarterly Surveillance on October 22, 2004, the preplanned alternate method of monitoring was instituted in accordance with plant procedures. This constituted monitoring Unit Vent releases in accordance with Emergency Plan Implementing Procedures in the event an emergency were to occur and would rely upon data supplied by field monitoring teams. This alternate method remained in effect until the problem was corrected on October 28, 2004.