

July 20, 2006

Mr. David A. Christian
Sr. Vice President and Chief Nuclear Officer
Dominion Nuclear Connecticut, Inc.
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

SUBJECT: BULLETIN 2004-01, "INSPECTIONS OF ALLOY 82/182/600 MATERIALS USED IN THE FABRICATION OF PRESSURIZER PENETRATIONS AND STEAM SPACE PIPING CONNECTIONS AT PRESSURIZED-WATER REACTORS," RESPONSE FOR MILLSTONE POWER STATION, UNIT NO. 3 (TAC NO. MC3490)

Dear Mr. Christian:

On May 28, 2004, the U.S. Nuclear Regulatory Commission (NRC) issued Bulletin 2004-01, "Inspections of Alloy 82/182/600 Materials Used in the Fabrication of Pressurizer Penetrations and Steam Space Piping Connections at Pressurized-Water Reactors," to the industry. This bulletin informed addressees that current methods of inspecting the pressurizer penetrations and steam space piping connections fabricated from Alloy 82/182/600 materials may need to be supplemented with additional measures (e.g., bare-metal visual inspections) to detect pressurizer penetration and steam space piping connection flaws or leakage. The bulletin requested that addressees provide the NRC with information related to the materials of construction, the inspections that have been performed, and the inspections which will be performed to verify the integrity of the pressurizer penetrations and steam space piping connections.

By letter dated July 27, 2004 (and by a supplemental letter dated December 15, 2005), Dominion Nuclear Connecticut (DNC) provided its responses to items 1a, 1b, 1c, and 1d of Bulletin 2004-01 for Millstone Power Station, Unit No. 3 (MPS3). DNC's responses described its materials of fabrication and past, current, and future pressurizer penetrations and steam space piping inspection programs at MPS3.

DNC's response to item 1a reported that some of the materials used in the fabrication of the pressurizer penetrations and steam space piping connections were Alloy 82/182/600 materials. This reply required you to provide further responses to the remaining items in the bulletin.

In response to item 1b, DNC described prior inspections and inspection results of pressurizer penetrations and steam space piping connections which had been performed at MPS3. DNC's response included the basis for concluding that MPS3 satisfies the applicable regulatory requirements related to the integrity of pressurizer penetrations and steam space piping connections.

In response to item 1c in the bulletin, DNC provided a description of the Alloy 82/182/600 pressurizer penetration and steam space piping connection inspection program that will be

implemented at MPS3 during the next, and subsequent, refueling outages. The description included the items to be inspected; the percent coverage that would be performed at each location; the inspection methods to be used; the qualification standards for the inspection methods and personnel; the process used to resolve any inspection indications; the inspection documentation to be generated; and the basis for concluding that MPS3 will satisfy the applicable regulatory requirements related to the structural and leakage integrity of pressurizer penetrations and steam space piping connections. If leaking pressurizer penetrations or steam space piping connections are found, DNC indicated that a follow-up nondestructive examination (NDE) will be performed to characterize flaws in the leaking penetrations. DNC provided its plans for expansion of the scope of the NDE to be performed if circumferential flaws are found in any portion of the leaking pressurizer penetrations or steam space piping connections.

In response to item 1d in the bulletin, DNC explained why the inspection program identified in the response to item 1c in the bulletin is adequate for the purpose of maintaining the integrity of the MPS3 reactor coolant pressure boundary and for meeting all applicable regulatory requirements which pertain to MPS3.

By letter dated July 27, 2004, you provided a response to item 2a in Bulletin 2004-01. This letter provided a statement to the NRC indicating that the inspections described in your response to item 1c of the bulletin were completed during a recent MPS3 outage and a description of the as-found condition of the locations inspected was provided. DNC also described any findings of relevant indications of through-wall leakage and follow-up NDE performed to characterize flaws in leaking penetrations or steam space piping connections. A summary of all relevant indications found by NDE, a summary of the disposition of any findings of boric acid, and a description of any corrective actions taken and/or repairs made as a result of the indications found was also provided in this letter.

The NRC staff has completed its activities associated with the review of DNC's responses to Bulletin 2004-01 and finds DNC's response to be acceptable. It should be noted that industry commitments or staff regulatory actions may result in the need for you to modify your plans for the inspection and repair of items discussed in Bulletin 2004-01. It is the staff's expectation that you will revise your plan for the inspection and repair of items discussed in Bulletin 2004-01 consistent with other industry commitments or staff regulatory actions. This closes the staff's efforts with regard to the review of the Bulletin 2004-01 response for MPS3. Please contact me at (301) 415-1484 if you have any questions on this issue.

Sincerely,

/RA/

Victor Nerses, Sr. Project Manager
Plant Licensing Branch I-2
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-423

cc: See next page

implemented at MPS3 during the next, and subsequent, refueling outages. The description included the items to be inspected; the percent coverage that would be performed at each location; the inspection methods to be used; the qualification standards for the inspection methods and personnel; the process used to resolve any inspection indications; the inspection documentation to be generated; and the basis for concluding that MPS3 will satisfy the applicable regulatory requirements related to the structural and leakage integrity of pressurizer penetrations and steam space piping connections. If leaking pressurizer penetrations or steam space piping connections are found, DNC indicated that a follow-up nondestructive examination (NDE) will be performed to characterize flaws in the leaking penetrations. DNC provided its plans for expansion of the scope of the NDE to be performed if circumferential flaws are found in any portion of the leaking pressurizer penetrations or steam space piping connections.

In response to item 1d in the bulletin, DNC explained why the inspection program identified in the response to item 1c in the bulletin is adequate for the purpose of maintaining the integrity of the MPS3 reactor coolant pressure boundary and for meeting all applicable regulatory requirements which pertain to MPS3.

By letter dated July 27, 2004, you provided a response to item 2a in Bulletin 2004-01. This letter provided a statement to the NRC indicating that the inspections described in your response to item 1c of the bulletin were completed during a recent MPS3 outage and a description of the as-found condition of the locations inspected was provided. DNC also described any findings of relevant indications of through-wall leakage and follow-up NDE performed to characterize flaws in leaking penetrations or steam space piping connections. A summary of all relevant indications found by NDE, a summary of the disposition of any findings of boric acid, and a description of any corrective actions taken and/or repairs made as a result of the indications found was also provided in this letter.

The NRC staff has completed its activities associated with the review of DNC's responses to Bulletin 2004-01 and finds DNC's response to be acceptable. It should be noted that industry commitments or staff regulatory actions may result in the need for you to modify your plans for the inspection and repair of items discussed in Bulletin 2004-01. It is the staff's expectation that you will revise your plan for the inspection and repair of items discussed in Bulletin 2004-01 consistent with other industry commitments or staff regulatory actions. This closes the staff's efforts with regard to the review of the Bulletin 2004-01 response for MPS3. Please contact me at (301) 415-1484 if you have any questions on this issue.

Sincerely,

/RA/

Victor Nerses, Sr. Project Manager
Plant Licensing Branch I-2
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-423

cc: See next page

DISTRIBUTION:

Non-Public
RidsNrrPMVNerses
LPL1-2 R/F
RidsNrrDssSnpb

MMitchell
RidsNrrLACRaynor
RidsNrrDorlLPL1-2
RidsAcraAcnwMailCenter

RidsNrrPMTColburn
RidsNrrDorlDpr
RidsOgcRp

ADAMS Accession Number: **ML061430011**

OFFICE	LPLI-2/PM	LPLI-2/LA	LPLI-2/BC (A)
NAME	VNerses	CRaynor	BPoole
DATE	7/19/06	7/18/06	7/20/06

OFFICIAL RECORD COPY

Millstone Power Station, Unit No. 3

cc:

Lillilan M. Cuoco, Esquire
Senior Counsel
Dominion Resources Services, Inc.
Building 475, 5th Floor
Rope Ferry Road
Waterford, CT 06385

Edward L. Wilds, Jr., Ph.D.
Director, Division of Radiation
Department of Environmental Protection
79 Elm Street
Hartford, CT 06106-5127

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

First Selectmen
Town of Waterford
15 Rope Ferry Road
Waterford, CT 06385

Mr. J. W. "Bill" Sheehan
Co-Chair NEAC
19 Laurel Crest Drive
Waterford, CT 06385

Mr. Evan W. Woollacott
Co-Chair
Nuclear Energy Advisory Council
128 Terry's Plain Road
Simsbury, CT 06070

Senior Resident Inspector
Millstone Power Station
c/o U.S. Nuclear Regulatory Commission
P. O. Box 513
Niantic, CT 06357

Ms. Nancy Burton
147 Cross Highway
Redding Ridge, CT 00870

Mr. Joseph Roy,
Director of Operations
Massachusetts Municipal Wholesale
Electric Company
Moody Street
P.O. Box 426
Ludlow, MA 01056

Mr. J. Alan Price
Site Vice President
Dominion Nuclear Connecticut, Inc.
Building 475, 5th Floor
Rope Ferry Road
Waterford, CT 06385

Mr. Chris Funderburk
Director, Nuclear Licensing and
Operations Support
Dominion Resources Services, Inc.
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

Mr. David W. Dodson
Licensing Supervisor
Dominion Nuclear Connecticut, Inc.
Building 475, 5th Floor
Rope Ferry Road
Waterford, CT 06385