



BRUCE H HAMILTON
Vice President
Oconee Nuclear Station

Duke Energy Corporation
ON01VP / 7800 Rochester Highway
Seneca, SC 29672

864 885 3487
864 885 4208 fax
bhhamilton@duke-energy.com

June 30, 2006

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555-0001

Subject: Duke Power Company,
Oconee Nuclear Station, Unit 3
Docket No. 50-287
Steam Generator Inservice Inspection
Steam Generator Tube Plugging and Repair 30-day Report

As required by Technical Specification 5.6.8, a, this letter provides the number of tubes plugged or repaired during the Steam Generator (SG) Tube Inservice Inspection for the Unit 3 Cycle 22 refueling outage:

<u>Steam Generator</u>	<u>No. of Tubes Repaired</u>	<u>Reason/Repair Method</u>
A	0	No SG tubes exceeded plugging limit.
B	0	No SG tubes exceeded plugging limit.

For your information, 100% eddy current inspections were performed on Steam Generators 3A and 3B during this refueling outage.

Please address any questions to Randy Todd at (864) 885-3418.

Very Truly Yours,

Bruce H. Hamilton,
Site Vice President,
Oconee Nuclear Station

A047

US Nuclear Regulatory Commission
June 30, 2006
Page 2

cc:

Mr. William D. Travers
Administrator, Region II
U.S. Nuclear Regulatory Commission
Atlanta Federal Center
61 Forsyth St., SWW, Suite 23T85
Atlanta, GA 30303

L. N. Olshan, Project Manager, Section 1
Project Directorate II
Division of Licensing Project Management
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555-0001

D. W. Rich
Senior NRC Resident Inspector
Oconee Nuclear Station

US Nuclear Regulatory Commission
June 30, 2006
Page 3

bcc: B. Graham Davenport
Parker Downing, Jr.
Jeff D. Gilreath
Randall P. Todd

Reene V. Gambrell

Lisa F. Vaughn
C. Jeff Thomas - MNS
Randall D. Hart - CNS
Robert L. Gill -NAID
ELL
NSRB
Document Management - (OS-18.0)