



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30323

R2-B15

MAR 25 1992

Ms. Michele Landis
Oak Ridge Associated Universities
Post Office Box 117
Oak Ridge, TN 37831-117


Dear Ms. Landis:

SUBJECT: COLUMBIA AREA SAMPLING PLAN

Enclosed please find a sampling plan for soil and water samples taken from an area near the Westinghouse-Columbia plant. Also enclosed is a copy of the presentation made to the NRC by Westinghouse which provided information regarding uranium contamination discovered beneath the floor of the processing area.

Please evaluate the sampling plan and advise us as to the number of these samples which should be analyzed in order to determine whether the contamination has spread from beneath the building. Also please provide a cost estimate for performing the analysis.


If you have any questions regarding this request, please call me at (FTS) 841-5592.


Daniel W. Jones

Enclosures:
As Stated

C-11

SAMPLING LOCATIONS
WESTINGHOUSE-COLUMBIA



HC-"Hydrocone" sampling locations

Soil samples taken from these locations at depths of 3 ft, 6 ft, and 9 ft.

Water samples taken from these locations at depths of 10ft and 20 ft.

HA-Hand Auger sampling locations

Soil samples taken from these locations at depths of 3 ft, 6 ft, and 9 ft.

NRC MEETING AGENDA

- **INTRODUCTION/BACKGROUND**
- **GENERAL AREA DESCRIPTION**
- **SITE DESCRIPTION**
- **SITE GEOHYDROLOGY**
- **BUILDING LAYOUT**
- **URANIUM RECOVERY AREA**
- **SOIL SAMPLING RESULTS**
- **MONITORING WELL RESULTS**
- **SOURCE TERM ELIMINATION**
- **CONFIRMATORY ACTION PLAN**







FIGURE 1-1 10 MILE SITE CIRCUMFERENCE
ON COUNTY ROAD MAPS






WESTINGHOUSE
COLUMBIA PLANT




Westinghouse Environmental
and Geotechnical Services, Inc.

GENERALIZED
STRATIGRAPHIC COLUMN

FIGURE 3-1. GENERALIZED GEOLOGIC CROSS-SECTION A-A', of SOUTHERN RICHLAND COUNTY.





AREA OF ENLARGEMENT FROM FIGURE 1-3.

200





0

200

400

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18

CC
BU
AA
B
C
D
E
F
G
H



COLUMBIA ROOF PLAN
of YEAR INSTALLED & SQ. FT

TOTAL PLANT 9 1/4 ACRES

COMMERCIAL NUCLEAR FUEL DIVISION COLUMBIA, S. C. PLANT

URANIUM RECOVERY AREA

FEED
CONC.


SOLVENT EXTRACTION
AREA

DISSOLVERS

PROD.
CONC.

S. E.
CONTROL
ROOM

SOLVENT EXTRACTION FLOW SHEET




COMMERCIAL NUCLEAR FUEL DIVISION COLUMBIA, S. C. PLANT

SOIL SAMPLING RESULTS

SAMPLE NUMBER	SAMPLE ACTIVITY(PCI/GM) @ VARIOUS DEPTHS(IN)						
	6"	12"	18"	24"	30"	36"	42"
1	203	195	311	328	193	213	326
2	434	631	831	776	737	956	828
3	2	1	—	—	—	—	—
4	314	141	—	—	—	—	—
5	9	2	3	—	—	—	—
6	2	2	—	—	—	—	—
7	12	3	—	—	—	—	—
8	30	41	—	—	—	—	—
9	4	3	5	3	—	—	—

SAMPLE LOCATIONS WITHIN FACILITY





COMMERCIAL NUCLEAR FUEL DIVISION COLUMBIA, S. C. PLANT

SOIL SAMPLING RESULTS

SAMPLE NUMBER	SAMPLE ACTIVITY(PCI/GM) " VARIOUS DEPTHS(FT)					
	2'	4'	6'	8'	10'	12'
1	645	2068	2711	2584	2412	—
2	752	549	184	—	—	—
3	385	69	811	328	3	—
4	1962	1601	2045	—	—	—
5	44	11	—	—	—	—
6	3	5	—	—	—	—
7	208	8	—	—	—	—
8	9	10	5	4	6	2
9	3	5	—	—	—	—
10	24	5	—	—	—	—
11	24	27	11	34	3	—
12	16	5	3	3	2	—
13	252	183	—	—	—	—

SAMPLE LOCATIONS WITHIN FACILITY





AREA OF ENLARGEMENT FROM FIGURE 1-3.



MONITORING WELL RESULTS
AVERAGE GROSS ALPHA ACTIVITY

$\mu\text{Ci/ml} \times E^{-06}$

<u>WELL</u> <u>NO</u>	<u>1981-1983</u>	<u>1990-1991</u>
3A	0.003 ^{ab}	0.003
7	0.023	0.011
10	0.008	0.022
13	0.018	0.022
14	0.001	0.003
15	0.010	0.007
16	0.006	0.004
18	0.041	0.045
19	0.028	0.049
20	0.001	0.002
22	0.031	0.004
23	0.009	0.010
24	0.005	0.004
26	0.008	0.011
27	0.004	0.003
29	0.016	0.017
30	0.214	0.028
32	0.010	0.012

***EARLIEST DATA FROM 1985**

SOLVENT EXTRACTION SOIL SAMPLING

CHEMICAL RESULTS

NOVEMBER 22, 1991

<u>SAMPLE</u>	<u>DEPTH</u>	<u>RESULT. PPM NO3</u>
1	12'	1440
2	6'	163
3	10'	274
4	6'	1620
5	4'	109
6	4'	67
7	4'	91
8	10'	71
9	4'	13
10	4'	13
11	10'	8
12	10'	15
13	3'	391

MANUFACTURING IMPROVEMENTS IN THE SOLVENT EXTRACTION AREA

IMPROVEMENTS TO PROCESS EQUIPMENT

IMPROVEMENTS TO LEAK CONTAINMENT AND EQUIPMENT REPAIR

IMPROVED HOUSEKEEPING PRACTICES

ATTENTION TO FLOOR INTEGRITY

Manufacturing Improvements in the Solvent Extraction Area

Improved Process Equipment

- 1987 Introduced fluoride stripping of feed materials
- 1988 Discontinued using acid recovery system
- 1989/90 Improved piping in Dissolver area
 - Installed 2" dia SS Schedule 80 piping
 - Replaced elbows with Tees
 - Replaced unions with flanges
 - Used inconel welding rods
 - Removed idle piping
 - Replaced Teflon coated gaskets with solid
- 1989/90 Improved pumps in the dissolver area
 - Reduced motor speed
 - Replaced single mechanical seal with double mechanical seal/ water flush system
 - Instituted pump rebuild shop with dedicated mechanics

Manufacturing Improvements in the Solvent Extraction Area

Improved Leak Containment and Repair

- 1987/88 Installed drip pans under cartridge filter housings
- 1989/90 Installed improved pump bases with integral drip pans
- 1991/92 Focused management attention on leak prevention:
 - Formal supervisor performance objective
 - "Leak Log"
 - Formal procedure

Manufacturing Improvements in the Solvent Extraction Area

Improved Housekeeping

- Removed idle equipment
 - Centrifuge near dissolver #1
 - Leaching bag filter system
 - Precoat and water wash system
 - Acid storage tank
 - Acid recovery system pumps
- Designed drainage system for Wilfley pump system to preclude leaks during week-end shutdown
- Implemented formal housekeeping schedule

Manufacturing Improvements in the Solvent Extraction Area

Floor Repair and Upgrade

- 1987 Resurfaced 3600 sq. ft. of floor
 - Removed loose concrete
 - Patched subsurface with Swindless bond,
capped with epoxy/quartz sand mixture
 - Topcoated with clear epoxy, approx 1/4"
- 1988 Applied second coat of epoxy
- 1989 Replaced floor under disseolver (64 sq. ft.)
- 1989/91 Performed minor patching and floor repair
- 1991/92 Coated aiseways with vinyl ester; patched with
epoxy due to adherence problems

CONFIRMATORY ACTION PLAN

ACTION	DATE
● COLLECT "HYDROCONE" GROUNDWATER SAMPLES OUTSIDE WEST AND SOUTH WALLS OF PLANT BUILDING	2/15/92
● COLLECT SOIL SAMPLES OUTSIDE WEST WALL OF URANIUM RECOVERY AREA	2/15/92
● INSTALL PERMANENT WELL OUTSIDE WEST WALL OF URANIUM RECOVERY AREA	2/21/92
● ANALYZE SOIL AND GROUNDWATER SAMPLES, EVALUATE RESULTS AND IDENTIFY FUTURE ACTIONS	4/30/92

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-11-92-01

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region II staff on this date.

FACILITY: Westinghouse Electric Corporation
Columbia, SC
Docket No. 70-1151

Licensee Emergency Classification:
☐ Notification of Unusual Event
☐ Alert
☐ Site Area Emergency
☐ General Emergency
☒ Not Applicable

SUBJECT: URANIUM CONTAMINATION IN SOIL BELOW RECOVERY AREA FLOOR

At 3:25 p.m. on January 3, 1992, Westinghouse notified Region II that they had discovered uranium contamination beneath the floor of their Columbia, SC fuel fabrication facility. According to the licensee, the contamination appears to be restricted to the scrap recovery area within an area of 30 feet by 13 feet and to a depth of 12 feet with the most significant concentration being in the area beneath their dissolver. The maximum contamination detected was 2700 pCi/gram. Westinghouse obtained 13 core samples to a maximum depth of 12 feet and from those analyzed 45 samples in their initial scoping of the extent of the contamination. According to the licensee, there is sandy soil in the area to a depth of about 30 feet. The licensee is in the process of assuring that no additional contamination is entering the ground, and determining whether the existing contamination is migrating. The licensee is not seeing any elevated radioactivity at their normal monitoring wells. The licensee will meet with NRC in the near future to discuss the situation and possible remedial actions.

Region II will continue to monitor the situation.

The State of South Carolina has been notified.

This information is current as of 9:30 a.m. on January 6, 1992.

CONTACT: E. McAlpine - 841-5547

DISTRIBUTION:

One White
Flint North
Chairman Selin
Comm. Rogers
Comm. Curtiss
Comm. Remick
Comm. de Planque
OGC
OCA
GPA/SLITP/PA
EDO
NRR
NMSS
OE

M'land Nat'l
Bank Bldg
IRM
OIG
AEOD
NRC Ops Ctr

Nicholson Lane
RES

L Street
PDR

Regions
Region I
Region II
Region III
Region IV
Region V

Phillips Bldg
ACRS

EW
ASLAP

MAIL TO: DCS (Original IE 34)
DOT (Transportation Only) 100
FAX TO: Chairman Selin 1:00
OIG 1:02
INPO 1:05
LICENSEE (Corporate) 1:06
and site
RII Resident
PM, NRR

5520: 1/06/92 0 TO REGIONS AND HQ
