

(10-2003)
10 CFR 2.201

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Snyder & Staley Engineering, P. L. C.
3160 Christy Way, Suite 6
Saginaw, MI 48603

2. NRC/REGIONAL OFFICE

REGION III
US NUCLEAR REGULATORY COMMISSION
2443 WARRENVILLE ROAD, SUITE 210
LISLE, ILLINOIS 60532

REPORT 2006-001

3. DOCKET NUMBER(S)

030-37084

4. LICENSEE NUMBER(S)

21-32606-01

5. DATE(S) OF INSPECTION

July 8, 2006

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Ed Kulzer	E. L. Kulzer	7/18/06

Docket File Information
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE

Synder & Staley Engineering, P.L.C.

REPORT

2. NRC/REGIONAL OFFICE

Region III

3. DOCKET NUMBER(S)

030-37084

4. LICENSE NUMBER(S)

21-32606-01

5. DATE(S) OF INSPECTION

July 18, 2006

6. INSPECTION PROCEDURES USED

87124

7. INSPECTION FOCUS AREAS

03.01 - 03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM

03121

2. PRIORITY

5

3. LICENSEE CONTACT

Michael Staley

4. TELEPHONE NUMBER

989.797.1710

☐

Main Office Inspection

Next Inspection Date: July 2011

☐

Field

☐

Temporary Job Site

Caro middle school, Caro, MI

PROGRAM SCOPE

Program Scope

The license is a small engineering firm that employs 12 individuals. The licensee possesses two Troxler moisture density gauges for use daily/weekly during the construction season (May-November) for soils engineering projects. The licensee does not perform any service or maintenance activities on its gauges; these services are performed by the manufacturer. Currently, the licensee employs seven authorized gauge users who have completed manufacturers training. Device is stored in a vault in the licensee's office in Saginaw, Michigan.

Performance Observations

The inspector observed operations at a temporary jobsite in Caro, Michigan. The operator possessed required shipping papers which contained all appropriate information and were accessible in the transport vehicle. The gauge/case were locked and chained to the rear of a minivan during transport. The operator demonstrated an adequate level of understanding of emergency and handling procedures during job-site interviews. Security during transport and at the job-site was described and observed respectively with no problems noted. The inspector performed independent and confirmatory radiation measurements which indicated similar results as noted in the licensee's survey records.