



**UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-4005**

August 18, 2006

John S. Keenan, Senior Vice
President of Generation and
Chief Nuclear Officer
Mail Code B32
Pacific Gas and Electric Company
P.O. Box 770000
San Francisco, CA 94177-0001

Dear Mr. Keenan:

**SUBJECT: ERRATA FOR DIABLO CANYON POWER PLANT - NRC INSPECTION
REPORT 05000275/2005005 and 05000323/2005005**

Please insert the enclosure to this letter as replacement for page 42 of NRC Inspection Report 05000275/2005005 and 05000323/2005005. A problem identification and resolution crosscutting aspect was incorrectly referenced in Section 4OA2.7 for Noncited Violation 05000275/2005-05-01, Failure to Adequately Assess and Manage Risk Associated with Startup Transformer 1-1 Maintenance. Section 1R14 of the report appropriately characterizes the cause of the finding as related to the crosscutting aspect of human performance in that maintenance personnel failed to follow procedures.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

William B. Jones, Chief
Project Branch B
Division of Reactor Projects

Dockets: 50-275
50-323
Licenses: DPR-80
DPR-82

Enclosure:

Page 42 of NRC Inspection Report
05000275/2005005 and 05000323/2005005

cc w/enclosure:

Donna Jacobs
Vice President, Nuclear Services
Diablo Canyon Power Plant
P.O. Box 56
Avila Beach, CA 93424

James R. Becker, Vice President
Diablo Canyon Operations and
Station Director, Pacific Gas and
Electric Company
Diablo Canyon Power Plant
P.O. Box 56
Avila Beach, CA 93424

Sierra Club San Lucia Chapter
ATTN: Andrew Christie
P.O. Box 15755
San Luis Obispo, CA 93406

Nancy Culver
San Luis Obispo Mothers for Peace
P.O. Box 164
Pismo Beach, CA 93448

Chairman
San Luis Obispo County Board of
Supervisors
County Government Building
1055 Monterey Street, Suite D430
San Luis Obispo, CA 93408

Truman Burns\Robert Kinosian
California Public Utilities Commission
505 Van Ness Ave., Rm. 4102
San Francisco, CA 94102-3298

Diablo Canyon Independent Safety Committee
Robert R. Wellington, Esq.
Legal Counsel
857 Cass Street, Suite D
Monterey, CA 93940

Pacific Gas and Electric Company

- 3 -

Director, Radiological Health Branch
State Department of Health Services
P.O. Box 997414 (MS 7610)
Sacramento, CA 95899-7414

Richard F. Locke, Esq.
Pacific Gas and Electric Company
P.O. Box 7442
San Francisco, CA 94120

City Editor
The Tribune
3825 South Higuera Street
P.O. Box 112
San Luis Obispo, CA 93406-0112

James D. Boyd, Commissioner
California Energy Commission
1516 Ninth Street (MS 34)
Sacramento, CA 95814

Jennifer Tang
Field Representative
United States Senator Barbara Boxer
1700 Montgomery Street, Suite 240
San Francisco, CA 94111

Electronic distribution by RIV:

Regional Administrator (**BSM1**)

DRP Director (**ATH**)

DRS Director (**DDC**)

DRS Deputy Director (**RJC1**)

Senior Resident Inspector (**TWJ**)

Branch Chief, DRP/B (**WBJ**)

Senior Project Engineer, DRP/E (**FLB2**)

Team Leader, DRP/TSS (**RLN1**)

RITS Coordinator (**KEG**)

DRS STA (**DAP**)

V. Dricks, PAO (**VLD**)

J. Lamb, OEDO RIV Coordinator (**JGL1**)

ROPreports

DC Site Secretary (**AWC1**)

SUNSI Review Completed: wbj ADAMS: : Yes ☐ No Initials: wbj
 : Publicly Available ☐ Non-Publicly Available ☐ Sensitive : Non-Sensitive

R:\ REACTORS\ DC\2005\DC2005-05RP-TWJ Errata.wpd

RIV:SRI:DRP/B	C:DRP/B			
TWJackson;df	WBJones			
T - WBJones	/RA/			
8/18/06	8/18/06			

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

.7 PI&R Crosscutting Aspects

Section 2OS1 identified a problem identification and resolution crosscutting aspect for the failure of radiation protection personnel to post a radiation area and the violation was similar to a violation previously identified in NRC Inspection Report 050000275; 323/2002004.

Section 4OA2.2 identified a problem identification and resolution crosscutting aspect for the failure of PG&E to adequately evaluate and implement timely corrective actions to ECCS check valve back-leakage.

4OA3 Event Follow-up (71153)

.1 (Closed) Licensee Event Report 05000323/2005001-00, TS 3.4.10 Not Met During Pressurizer Safety Valve Surveillance Testing Due to Random Lift Spread

On January 27, 2005, during scheduled testing of Unit 2 pressurizer safety valves, PG&E identified two of three pressurizer safety valves outside the TS 3.4.10 lift setting of ≥ 2460 and ≤ 2510 psig.

In NRC Inspection Report 05000275; 323/2005003, an NRC-identified, Green NCV of 10 CFR Part 50, Criterion XVI, was identified for this issue. PG&E documented the problem in Nonconformance Report N0002197. No new information that would change the disposition of this issue was provided in this LER. This LER is closed.

4OA5 Other

.1 TI 2515/160 - Pressurizer Penetration Nozzles and Steam Space Piping Connections in U.S. Pressurized Water Reactors

a. Inspection Scope

The inspectors reviewed PG&E's actions regarding the inspection and repair associated with Alloy 82/182/600 material that may have been used in pressurizer penetration nozzles, steam space piping connections, heads, and shells. Specifically, the inspectors reviewed PG&E's response to NRC Bulletin 2004-01, "Inspection of Alloy 82/182/600 Materials Used in the Fabrication of Pressurizer Penetrations and Steam Space Piping Connections at Pressurized Water Reactors." PG&E documented in their response to the bulletin that no Alloy 82/182/600 material was used in the construction or welds of the Unit 1 pressurizer. PG&E did not commit to, or perform, any nondestruction examination methods for the Unit 1 pressurizer. PG&E did perform a boric acid walkdown of the pressurizer, and the inspectors performed an independent boric acid inspection of pressurizer.

The activities required in TI 2515/160 for Diablo Canyon Power Plant Unit 1 have been completed. This temporary instruction is closed for Unit 1.