



Entergy Nuclear South  
Entergy Operations, Inc.  
17265 River Road  
Killona, LA 70057-3093  
Tel 504-739-6715  
Fax 504-739-6698  
rmurill@entergy.com

Robert J. Murillo  
Licensing Manager  
Waterford 3

W3F1-2006-0043

August 29, 2006

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

SUBJECT: Additional Information in Response to NRC Bulletin 2004-01, Inspection of Alloy 82/182/600 Materials Used In Pressurizer Penetrations and Steam Space Piping Connections  
Waterford Steam Electric Station, Unit 3  
Docket No. 50-382

REFERENCES: 1 NRC letter dated May 28, 2004, *NRC Bulletin 2004-01: Inspection of Alloy 82/182/600 Materials Used In the Fabrication of Pressurizer Penetrations and Steam Space Piping Connections at Pressurized-Water Reactors*

2 Entergy letter dated July 27, 2004, *Response to NRC Bulletin 2004-01 Regarding Inspection of Alloy 82/182/600 Materials Used In Pressurizer Penetrations and Steam Space Piping Connections (W3F1-2004-0058)*

Dear Sir or Madam:

On May 28, 2004, the Nuclear Regulatory Commission (NRC) issued NRC Bulletin 2004-01, *Inspection of Alloy 82/182/600 Materials Used In the Fabrication of Pressurizer Penetrations and Steam Space Piping Connections at Pressurized-Water Reactors* (Reference 1). The NRC requested that all pressurized water reactor addressees provide description of their pressurizer heater and steam space penetrations and inspection plans for the forthcoming and subsequent refueling outages. On July 27, 2004 (Reference 2), Entergy provided the required response for the Waterford Steam Electric Station, Unit 3 (Waterford-3).

In the response, Entergy had noted that weld repairs/replacements were being planned during the spring 2005 refueling outage (RF-13) for the pressurizer heater and small bore Alloy 600 pressurizer nozzles and welds. The purpose of this letter is to confirm that associated repairs or replacements were performed. The attachment to this letter provides details on the repairs that were performed during the RF-13 outage.

A110

There are no commitments associated with this letter. If you have any questions or require additional information, please contact Steve Bennett at 479-858-4626.

Sincerely,



RJM/SAB/ssf

Attachment: Repairs Performed on the Waterford-3 Pressurizer During the Spring 2005  
Refueling Outage

cc: Dr. Bruce S. Mallett  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

NRC Senior Resident Inspector  
Waterford 3  
P.O. Box 822  
Killona, LA 70066-0751

U.S. Nuclear Regulatory Commission  
Attn: Mr. Mel Fields MS O-07D1  
Washington, DC 20555-0001

Wise, Carter, Child & Caraway  
Attn: J. Smith  
P.O. Box 651  
Jackson, MS 39205

Winston & Strawn  
Attn: N.S. Reynolds  
1400 L Street, NW  
Washington, DC 20005-3502

Louisiana Department of Environmental Quality  
Office of Environmental Compliance  
Surveillance Division  
P. O. Box 4312  
Baton Rouge, LA 70821-4312

American Nuclear Insurers  
Attn: Library  
Town Center Suite 300S  
29<sup>th</sup> S. Main Street  
West Hartford, CT 06107-2445

**Attachment**

**W3F1-2006-0043**

**Repairs Performed on the Waterford-3 Pressurizer  
During the Spring 2005 Refueling Outage**

## **Repairs Performed on the Waterford-3 Pressurizer During the Spring 2005 Refueling Outage**

### **Heater Sleeves**

The Waterford-3 Pressurizer contains thirty (30) heater sleeves. Pressurizer Heater Sleeve F-4 was repaired during the fall 2000 refueling outage with an Alloy 690 plug. This plug was retained and no additional repairs or modifications were performed in the spring 2005 refueling outage (RF-13). The remaining twenty nine (29) nozzles were replaced using a half nozzle, mid-wall repair during RF-13. The half nozzle repair design relocates the reactor coolant pressure boundary from a partial penetration (J-groove) weld on the inside surface of the pressurizer to a partial penetration weld at the mid-wall of the pressurizer shell. The new pressure boundary for these sleeves is constructed with Alloy 690 materials.

### **Small Bore Pressurizer Penetrations**

The Waterford-3 Pressurizer contains six (6) small bore instrument nozzles and 1 (one) temperature nozzle located both in the steam and water space of the pressurizer. Two upper steam space nozzles were repaired in the spring of 1999 using Alloy 600 weld filler and two were repaired using Alloy 690 materials in the fall 2000 refueling outages. The 2 previously repaired nozzles using Alloy 600 weld filler, the temperature nozzle and the remaining two instrument nozzles, were replaced during RF-13 utilizing a new half-nozzle welded to a pad on the outside of the pressurizer shell using Alloy 690 half-nozzles and weld filler.

Note: There are 5 remaining large bore pressurizer welds and nozzles consisting of two 6-inch pressurizer relief valve nozzles, a spare 6-inch nozzle, the 4-inch pressurizer spray line, and 12-inch surge line. No repairs have been performed on these welds or nozzles to date.