

RAS 12266

Exelon.

Nuclear

Exelon Generation Company, LLC
Dresden Nuclear Power Station
6500 North Dresden Road
Morris, IL 60450-9765

www.exeloncorp.com

July 6, 2004

SVPLTR: #04-0045

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

DOCKET NUMBER
PROD. & UTIL. FAC. 50-271-0LA

10 CFR 50.73

SEP 19 PM 3:36

DOCKETED
USNRC

ADJUDICATIONS STAFF
THE SECRETARY

Dresden Nuclear Power Station, Units 2 and 3
Facility Operating License Nos. DRP-19 and DPR-25
NRC Docket Nos. 50-237 and 50-249

Subject: Licensee Event Report 2004-003-00, "Unit 3 Scram Due to Loss of Offsite Power and Subsequent Inoperability of the Standby Gas Treatment System for Units 2 and 3"

Enclosed is Licensee Event Report 2004-003-00, "Unit 3 Scram Due to Loss of Offsite Power and Subsequent Inoperability of the Standby Gas Treatment System for Units 2 and 3," for Dresden Nuclear Power Station. This event is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A), "Any event or condition that resulted in manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) of this section," and 10 CFR 50.73(a)(2)(i)(B), "Any operation or condition which was prohibited by the plant's Technical Specifications."

Should you have any questions concerning this report, please contact Jeff Hansen, Regulatory Assurance Manager, at (815) 416-2800.

Respectfully,

David B. Wozniak

Danny G. Bost
Site Vice President
Dresden Nuclear Power Station

Enclosure

cc: Regional Administrator - NRC Region III
NRC Senior Resident Inspector - Dresden Nuclear Power Station

U.S. NUCLEAR REGULATORY COMMISSION

In the Matter of Entergy Nuclear Vermont Yankee, L.L.C.

Docket No. 50-271 Official Exhibit No. Entergy 16

OFFERED by: Applicant/Licensee Intervenor _____

NRC Staff _____ Other _____

IDENTIFIED on 9/13/06 Witness/Panel Nichols/Casillas

Action Taken: ADMITTED REJECTED WITHDRAWN

Reporter/Clerk HAC

JE22

Template=SECY-028

SECY-02

| | | | | | | | |
|---|--------|---|---------------|--|------------------------------|------------------------------|-----------|
| NRC FORM 366 (7-2001) | | U.S. NUCLEAR REGULATORY COMMISSION | | APPROVED BY OBM NO. 3150-0104 EXP 7-31-2004 Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by Internet e-mail to: bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection. | | | |
| LICENSEE EVENT REPORT (LER) | | | | | | | |
| 1. FACILITY NAME | | | | 2. DOCKET NUMBER | | 3. PAGE | |
| Dresden Nuclear Power Station Unit 3 | | | | 05000249 | | 1 of 4 | |
| 4. TITLE Unit 3 Scram Due to Loss of Offsite Power and Subsequent Inoperability of the Standby Gas Treatment System for Units 2 and 3 | | | | | | | |
| 5. EVENT DATE | | | 6. LER NUMBER | | | 7. REPORT DATE | |
| MO | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REV NO | MO | DAY |
| 05 | 05 | 2004 | 2004 | 003 | 00 | 07 | 06 |
| | | | | | | 8. OTHER FACILITIES INVOLVED | |
| | | | | | | FACILITY NAME | |
| | | | | | | Dresden Unit 2 | |
| | | | | | | DOCKET NUMBER | |
| | | | | | | 05000237 | |
| | | | | | | FACILITY NAME | |
| | | | | | | N/A | |
| | | | | | | DOCKET NUMBER | |
| | | | | | | N/A | |
| 9. OPERATING MODE | | 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply) | | | | | |
| 1 | | 20.2201(b) | | 20.2203(a)(3)(II) | | 50.73(a)(2)(II)(B) | |
| | | 20.2201(d) | | 20.2203(a)(4) | | 50.73(a)(2)(III) | |
| 10. POWER LEVEL | | 20.2203(a)(1) | | 50.36(c)(1)(I)(A) | | 50.73(a)(2)(IV)(A) | |
| 100 | | 20.2203(a)(2)(I) | | 50.36(c)(1)(II)(A) | | 50.73(a)(2)(V)(A) | |
| | | 20.2203(a)(2)(II) | | 50.36(c)(2) | | 50.73(a)(2)(V)(B) | |
| | | 20.2203(a)(2)(III) | | 50.46(a)(3)(II) | | 50.73(a)(2)(V)(C) | |
| | | 20.2203(a)(2)(IV) | | 50.73(a)(2)(II)(A) | | 50.73(a)(2)(V)(D) | |
| | | 20.2203(a)(2)(V) | | X 50.73(a)(2)(I)(B) | | 50.73(a)(2)(VI) | |
| | | 20.2203(a)(2)(VI) | | 50.73(a)(2)(I)(C) | | 50.73(a)(2)(VII)(A) | |
| | | 20.2203(a)(3)(I) | | 50.73(a)(2)(II)(A) | | 50.73(a)(2)(VII)(B) | |
| 12. LICENSEE CONTACT FOR THIS LER | | | | | | | |
| NAME | | | | TELEPHONE NUMBER (Include Area Code) | | | |
| George Papanic Jr. | | | | (815) 416-2815 | | | |
| 13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT | | | | | | | |
| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO EPIX | CAUSE | SYSTEM | COMPONENT |
| X | FK | BRK | 1005 | N | | | |
| 14. SUPPLEMENTAL REPORT EXPECTED | | | | | 15. EXPECTED SUBMISSION DATE | | |
| X YES (If yes, complete EXPECTED SUBMISSION DATE) | | | | | MONTH DAY YEAR | | |
| | | | | | 10 30 2004 | | |
| 16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) | | | | | | | |

On May 5, 2004, at 1327 hours (CDT), with Unit 3 at 100 percent power in Mode 1, an automatic scram occurred due to a Main Generator Load Reject when a loss of offsite power occurred. The Emergency Diesel Generators automatically started and powered their respective electrical busses. All control rods fully inserted and Group I, II and III Isolations occurred as expected. Operations personnel manually initiated the Isolation Condenser System for reactor pressure control, the High Pressure Coolant Injection System for reactor water level control, and the Low Pressure Coolant Injection System for Torus cooling. All systems initially responded to the scram as expected except the Standby Gas Treatment System was unable to maintain the Secondary Containment at the Technical Specification Surveillance Requirement limit of greater than or equal to 0.25 inches of vacuum water gauge. An Unusual Event for the loss of offsite power was declared at 1342 hours (CDT) and terminated at 1601 hours (CDT) on May 5, 2004. Additionally, during restoration of offsite electrical power to Bus 33, the Emergency Diesel Generator 2/3 output electrical breaker tripped.

The root causes associated with the load reject and loss of offsite power and the low Secondary Containment vacuum were respectively, equipment failure in the "C" phase of the 345 kilovolt circuit breaker 8-15 and a degraded Secondary Containment boundary not detected due to an inadequate leak rate test procedure. The cause of the Emergency Diesel Generator output breaker trip remains under investigation.

LICENSEE EVENT REPORT (LER)

| 1. FACILITY NAME | 2. DOCKET NUMBER | 6. LER NUMBER | | | 3. PAGE |
|--------------------------------------|------------------|---------------|----------------------|--------------------|---------|
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | |
| Dresden Nuclear Power Station Unit 3 | 05000249 | 2004 | 003 | 00 | 2 of 4 |

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

Dresden Nuclear Power Station (DNPS) Units 2 and 3 are a General Electric Company Boiling Water Reactor with a licensed maximum power level of 2957 megawatts thermal. The Energy Industry Identification System codes used in the text are identified as [XX].

A. Plant Conditions Prior to Event:

| | | |
|--|----------------------------|--------------------------|
| Unit: 03 | Event Date: 5-5-2004 | Event Time: 1327 CDT |
| Reactor Mode: 1 | Mode Name: Power Operation | Power Level: 100 percent |
| Reactor Coolant System Pressure: 1000 psig | | |

B. Description of Event:

On May 5, 2004, electrical breaker switching was being performed in the DNPS switchyard to support the testing of a 345 kilovolt (kv) offsite electrical line. A loss of offsite power (LOOP) occurred to Unit 3 when 345 kv breaker 8-15 [BKR] located in the switchyard [FK] was opened.

On May 5, 2004, at 1327 hours (CDT), with Unit 3 at 100 percent power in Mode 1, an automatic scram occurred due a Main Generator Load Reject when the LOOP occurred. The Emergency Diesel Generators (EDGs) [DG] automatically started and powered their respective electrical busses. All control rods fully inserted and Group I, II and III isolations occurred as expected. Operations personnel manually initiated the Isolation Condenser System [BL] for reactor pressure control, High Pressure Coolant Injection System [BJ] for reactor water level control, and Low Pressure Coolant Injection System [BO] for Torus cooling. All systems initially responded as expected to the scram except for the Standby Gas Treatment System (SGT) [BH] that was unable to maintain the Secondary Containment at the Technical Specification Surveillance Requirement limit of greater than or equal to 0.25 inches of vacuum water gauge. Secondary containment was declared inoperable for Units 2 and 3.

An Unusual Event for the LOOP was declared at 1342 hours (CDT). An ENS call was made at 1429 hours (CDT) for the above-described event. The assigned ENS event number was 40727.

At 1558 hours (CDT), the EDG 2/3 output electrical breaker tripped on reverse power during restoration of offsite electrical power to Bus 33 that was being fed from EDG 2/3. Bus 33 remained powered from the offsite source.

The Unusual Event was terminated at 1601 hours (CDT) when offsite power was restored to Unit 3.

At 1630 hours (CDT), SGT was declared operable when the Secondary Containment pressure was restored to greater than 0.25 inches of vacuum water gauge.

This event is being reported in accordance with:

- 10 CFR 50.73(a)(2)(iv)(A), "Any event or condition that resulted in manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) of this section," and
- 10 CFR 50.73(a)(2)(i)(B), "Any operation or condition which was prohibited by the plant's Technical Specifications."

| | | | | | |
|--------------------------------------|-------------------------|------------------------------------|----------------------|--------------------|----------------|
| NRC FORM 366A (7-2001) | | U.S. NUCLEAR REGULATORY COMMISSION | | | |
| LICENSEE EVENT REPORT (LER) | | | | | |
| 1. FACILITY NAME | 2. DOCKET NUMBER | 6. LER NUMBER | | | 3. PAGE |
| Dresden Nuclear Power Station Unit 3 | 05000249 | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | 3 of 4 |
| | | 2004 | 003 | 00 | |

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

These events are addressed in the NRC Special Inspection Report Number 05000249/2004009 dated June 21, 2004.

C. Cause of Event:

The root causes associated with the load reject and LOOP and the low Secondary Containment vacuum were respectively, equipment failure in the "C" phase of the 345 kv circuit breaker 8-15 and a degraded secondary containment boundary not detected due to an inadequate leak rate test procedure. The cause of the EDG output breaker trip is still under investigation.

The equipment failure of the 345 kv circuit breaker 8-15 circuit breaker occurred due to age-related and application related degradation. The vendor, prior to the event, did not provide information to Exelon Corporation, a product advisory issued in July 2003, regarding the possibility of breaker slow operation or failure to operate. This is applicable to circuit breakers 8-15 and 6-7. The corrective action to prevent reoccurrence is to revise the preventative maintenance procedure governing both circuit breakers 8-15 and 6-7 to implement the product advisory recommendations.

The degraded secondary containment boundary resulted from air in-leakage into the Unit 2 Drywell and Torus Purge Exhaust (DTPE) filter housings. At the time of the event, Unit 2 was in a maintenance outage and the DTPE fans were in operation due to activities in the Unit 2 drywell. The DTPE fans are not normally in operation and the secondary containment leak rate test procedure does not test with the DTPE fans operating as a part of the secondary containment barrier. Two corrective actions to prevent reoccurrence are being taken:

The first is to modify the current design to trip the DTPE fans on both units following an automatic SGT system initiation from either unit, rather than operate the DTPE fans during the secondary containment leak rate test. The second action is to develop a source document that clearly identifies the secondary containment boundaries.

D. Safety Analysis:

The safety significance of the LOOP event was minimal. All systems initially responded as expected to the scram except for the SGT system that was unable to maintain the secondary containment at the Technical Specification Surveillance Requirement limit of greater than or equal to 0.25 inches of vacuum water gauge. However, secondary containment was maintained at a negative pressure at all times during the event. The EDGs were supplying power to their respective busses, as designed, and offsite power was available through Unit 2.

Therefore, the consequences of this event had minimal impact on the health and safety of the public and reactor safety.

E. Corrective Actions:

345 kv circuit breaker 8-15 was repaired and a vendor upgrade kit was installed. The circuit breaker upgrade kit will be installed on circuit breaker 6-7 at the next available opportunity.

The preventive maintenance procedure for circuit breakers 8-15 and 6-7 will be revised to incorporate appropriate vendor advisory recommendations.

DNPS procedures were revised to require the securing of the DTPE Fans upon initiation of SGT.

The DTPE filter housing in-leakage has been repaired to correct air inleakage.

The SGT Initiation logic will be changed to include the tripping of the DTPE Fans for both units.

| | | | | | |
|--------------------------------------|-------------------------|------------------------------------|----------------------|--------------------|----------------|
| NRC FORM 366A (7-2001) | | U.S. NUCLEAR REGULATORY COMMISSION | | | |
| LICENSEE EVENT REPORT (LER) | | | | | |
| 1. FACILITY NAME | 2. DOCKET NUMBER | 6. LER NUMBER | | | 3. PAGE |
| Dresden Nuclear Power Station Unit 3 | 05000249 | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | |
| | | 2004 | 003 | 00 | |

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

The final corrective actions to prevent reoccurrence for the Emergency Diesel Generator output breaker will be described in a supplemental report scheduled to be submitted no later than October 30, 2004.

F. Previous Occurrences:

A review of Dresden Nuclear Power Station Licensee Event Reports (LERs) and operating experience identified the following LER.

Unit 3 LER 89-001-01 described a March 25, 1989, event in which an electrical fault in the 345 kilovolt circuit breaker 8-15 phase A internal ground capacitor and slow transfer of the 4 kv Bus 32 from transformer 32 to 31 caused a LOOP for Unit 3. The corrective actions included the removal of the internal ground capacitors from 345 kilovolt circuit breaker 8-15.

G. Component Failure Data:

I.T.E. Power Circuit Breaker, Model C Type GA