

***Docket File Information***  
**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

<b>1. LICENSEE</b> Toledo Cardiology Consultants, Inc.		<b>2. NRC/REGIONAL OFFICE</b> U.S. Nuclear Regulatory Commission, Region III 2443 Warrenville Road, Suite 210 Lisle, Illinois 60532	
REPORT NUMBER(S) 11-02			
<b>3. DOCKET NUMBER(S)</b> 150-00034 (Reciprocity)	<b>4. LICENSEE NUMBER(S)</b> Ohio 02220490000	<b>5. DATE(S) OF INSPECTION</b> July 27, 2011	
<b>6. INSPECTION PROCEDURES</b> 87130	<b>7. INSPECTION FOCUS AREAS</b> 03.01 – 03.07		

**SUPPLEMENTAL INSPECTION INFORMATION**

<b>1. PROGRAM</b> 2220	<b>2. PRIORITY</b> 3	<b>3. LICENSEE CONTACT</b> Tim Depinet, Nuclear Administrator	<b>4. TELEPHONE NUMBER</b> 419-251-3700
---------------------------	-------------------------	--	--

- ☐ Main Office Inspection  
☐ Field Office Inspection  
☒ Temporary Job Site Inspection
- Next Inspection Date: TBD
- Downriver Medical Group, 15400 Northline Rd, Suite 101, Southgate, MI

**PROGRAM SCOPE**

The licensee provided mobile nuclear cardiology services in the southern Detroit suburbs under reciprocity. At the job site in Southgate, Michigan, one technologist performed between five and eight diagnostic cardiology procedures daily when on site, approximately twice monthly. Doses were received from a licensed nuclear pharmacy at the base location in Toledo, Ohio, assayed at that site, and transported to sites in Michigan. All waste and unused doses were returned to the base location in Toledo for decay in storage or to be returned to the pharmacy.

**PERFORMANCE OBSERVATIONS**

The inspector observed five resting doses of technicium-99m being administered during the inspection. These observations, as well as interviews with available staff, revealed an adequate understanding of emergency and material handling procedures and techniques. Radioactive package receipt, daily surveys and wipe tests, and waste handling and disposal procedures were successfully demonstrated. An outside consultant performed quarterly program audits that were adequate to oversee the program.

Licensed material was adequately secured and not readily accessible to members of the general public. The licensee possessed a radiation survey meter that was calibrated, operational, and performed well in side-by-side comparison with an NRC instrument. Independent measurements did not indicate readings in excess of Title 10 of the Code of Federal Regulations (10 CFR) Part 20 limits in restricted or unrestricted areas. Personal whole body and extremity dosimetry were observed worn by the staff during the inspection, and records did not indicate doses in excess of 10 CFR Part 20 limits.

No violations were identified during this inspection.