



LIC-12-0043
May 1, 2012

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

Reference: Docket No. 50-285

Subject: Licensee Event Report 2012-002, Revision 0, for the Fort Calhoun Station

Please find attached Licensee Event Report 2012-002, Revision 0, dated May 1, 2012. This report is being submitted pursuant to 10 CFR 50.73(a)(2)(ii)(B) and 10 CFR 50.73(a)(2)(i)(B).

If you should have any questions, please contact me.

Sincerely,

D. J. Bannister
Site Vice President and CNO

DJB /epm

Attachment

c: E. E. Collins, Jr., NRC Regional Administrator, Region IV
L. E. Wilkins, NRC Project Manager
J. C. Kirkland, NRC Senior Resident Inspector
INPO Records Center

LICENSEE EVENT REPORT (LER)(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Fort Calhoun Station

2. DOCKET NUMBER

05000285

3. PAGE

1 OF 3

4. TITLE

Inadequate Qualifications for Containment Penetrations Renders Containment Inoperable

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
3	2	2012	2012	- 002	- 0	5	1	2012	FACILITY NAME	DOCKET NUMBER 05000
									FACILITY NAME	DOCKET NUMBER 05000

9. OPERATING MODE

1

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)

<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input checked="" type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

10. POWER LEVEL

100

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME

Erick Matzke

TELEPHONE NUMBER (Include Area Code)

402-533-6855

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED☒ YES (If yes, complete 15. EXPECTED SUBMISSION DATE)☐ NO**15. EXPECTED SUBMISSION DATE**

MONTH	DAY	YEAR
7	18	2012

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

During a review of environmental qualification records for reactor containment building electrical penetrations, six penetrations were identified that may not provide an adequate seal during worst case (Design Basis Accident (DBA)) conditions as required. These penetrations are through wall from the containment into the auxiliary building.

A cause analysis is in progress and the results will be included in a supplement to this LER.

The station is currently in a refueling mode. Corrective actions to address the causes of this condition will be documented in the supplement to this LER.

The subject penetrations will be restored to full environmental qualifications prior to plant startup.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 3
		2012	- 002	- 0	

NARRATIVE

BACKGROUND

Fort Calhoun Station Technical Specification (TS) 2.6(1)a. states:

Containment integrity shall not be violated unless the reactor is in a cold or refueling shutdown condition. Without containment integrity, restore containment integrity within one hour or be in at least hot shutdown within the next 6 hours, in at least subcritical and greater than 300 degrees Fahrenheit within the next 6 hours and in cold shutdown within the following 30 hours. Normally locked or sealed-closed valves (except for PCV-742A/B/C/D) may be opened intermittently under administrative control without constituting a violation of containment integrity.

EVENT DESCRIPTION

During research into the qualification of electrical penetrations in reactor containment building, discrepancies in the qualification basis of six sealing mechanisms (penetration feedthrough assemblies) have been identified. RE-091A and RE-091B (Containment Hi Range Monitors) signal cables are affected. HCV-240 (Pressurizer RC-4 Auxiliary Spray Inlet Valve), TCV-202 (Reactor Coolant System Loop 2A Letdown Temperature Control Valve), HCV-248 (Reactor Coolant System Loop 2A Charging Line Stop Valve) and HCV-249 (Pressurizer RC-4 Aux Spray Inlet Valve HCV-240 bypass valve) cables are affected. The affected penetrations are original plant equipment. The condition of these penetrations violates TS 2.6(1)a. This report is being made per 10 CFR 50.73(a)(2)(ii)(B) and 10 CFR 50.73(a)(2)(i)(B).

CONCLUSION

A cause analysis is in progress and the results will be included in a supplement to this LER.

CORRECTIVE ACTIONS

The station is currently in a refueling mode. Corrective actions to address the causes of this condition will be documented in a supplement to this LER.

The subject electrical penetrations will be restored to full qualification prior to plant startup.

SAFETY SIGNIFICANCE

An evaluation of the safety significance of this issue will be completed following the completion of the cause analysis.

U.S. NUCLEAR REGULATORY COMMISSION

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 3
		2012	- 002 -	0	

NARRATIVE

SAFETY SYSTEM FUNCTIONAL FAILURE

This event does not result in a safety system functional failure in accordance with NEI-99-02.

PREVIOUS EVENTS

No previous qualifications issues with containment penetrations have been identified.