



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D.C. 20555-0001

March 18, 2013

Mr. Lawrence J. Weber  
Senior Vice President and  
Chief Nuclear Officer  
Indiana Michigan Power Company  
Nuclear Generation Group  
One Cook Place  
Bridgman, MI 49106

SUBJECT: DONALD C. COOK NUCLEAR PLANT, UNIT 1 - UPCOMING STEAM  
GENERATOR TUBE INSERVICE INSPECTION (TAC NO. MF0875)

Dear Mr. Weber:

Inservice inspections of steam generator (SG) tubes play a vital role in assuring SG tube integrity. A telephone conference call has been arranged with members of your staff to discuss the ongoing results of the SG tube inspections to be conducted during the upcoming Donald C. Cook Nuclear Plant, Unit 1, refueling outage. This call will occur after the majority of the tubes have been inspected, but before the SG inspection activities have been completed. Enclosed is a list of discussion points to facilitate this call.

The U.S. Nuclear Regulatory Commission (NRC) staff will document a summary of the conference call, including any material that you provide to the NRC staff in support of the call.

Should you have any questions you can contact me at 301-415-4037.

Sincerely,

A handwritten signature in black ink, reading "Thomas J. Wengert", is positioned above the typed name.

Thomas J. Wengert, Senior Project Manager  
Plant Licensing Branch III-1  
Division of Operating Reactor Licensing  
Office of Nuclear Reactor Regulation

Docket No. 50-315

Enclosure:  
Steam Generator Tube Inspection Discussion Points

cc: Distribution via Listserv

## STEAM GENERATOR TUBE INSPECTION DISCUSSION POINTS

The following discussion points have been prepared to facilitate the conference call arranged with the licensee to discuss the results of the steam generator (SG) tube inspections to be conducted during the upcoming spring 2013 refueling outage at Donald C. Cook, Unit 1. This conference call is scheduled to occur towards the end of the planned SG tube inspections, but before the unit completes the inspections and repairs.

The U.S. Nuclear Regulatory Commission staff plans to document a summary of the conference call, as well as any material that is provided in support of the call.

1. Discuss any trends in the amount of primary-to-secondary leakage observed during the recently completed cycle.
2. Discuss whether any secondary side pressure tests were performed during the outage and the associated results.
3. Discuss any exceptions taken to the industry guidelines.
4. For each SG, provide a description of the inspections performed including the areas examined and the probes used (e.g., dents/dings, sleeves, expansion-transition, U-bends with a rotating probe), the scope of the inspection (e.g., 100 percent of dents/dings greater than 5 volts and a 20 percent sample between 2 and 5 volts), and the expansion criteria.
5. For each area examined (e.g., tube supports, dent/dings, sleeves, etc), provide a summary of the number of indications identified to-date for each degradation mode (e.g., number of circumferential primary water stress corrosion cracking indications at the expansion transition). For the most significant indications in each area, provide an estimate of the severity of the indication (e.g., provide the voltage, depth, and length of the indication). In particular, address whether tube integrity (structural and accident induced leakage integrity) was maintained during the previous operating cycle. In addition, discuss whether any location exhibited a degradation mode that had not previously been observed at this location at this unit (e.g., observed circumferential primary water stress corrosion cracking at the expansion transition for the first time at this unit).
6. Describe repair/plugging plans.
7. Describe in-situ pressure test and tube pull plans and results (as applicable and if available).
8. Discuss the following regarding loose parts:
  - what inspections are performed to detect loose parts
  - a description of any loose parts detected and their location within the SG (including the source or nature of the loose part, if known)

Enclosure

- if the loose parts were removed from the SG
  - indications of tube damage associated with the loose parts
9. Discuss the scope and results of any secondary side inspection and maintenance activities (e.g., in-bundle visual inspections, feedring inspections, sludge lancing, assessing deposit loading, etc).
  10. Discuss any unexpected or unusual results.
  11. Provide the schedule for steam generator-related activities during the remainder of the current outage.

March 18, 2013

Mr. Lawrence J. Weber  
Senior Vice President and  
Chief Nuclear Officer  
Indiana Michigan Power Company  
Nuclear Generation Group  
One Cook Place  
Bridgman, MI 49106

SUBJECT: DONALD C. COOK NUCLEAR PLANT, UNIT 1 - UPCOMING STEAM  
GENERATOR TUBE INSERVICE INSPECTION (TAC NO. MF0875)

Dear Mr. Weber:

Inservice inspections of steam generator (SG) tubes play a vital role in assuring SG tube integrity. A telephone conference call has been arranged with members of your staff to discuss the ongoing results of the SG tube inspections to be conducted during the upcoming Donald C. Cook Nuclear Plant, Unit 1, refueling outage. This call will occur after the majority of the tubes have been inspected, but before the SG inspection activities have been completed. Enclosed is a list of discussion points to facilitate this call.

The U.S. Nuclear Regulatory Commission (NRC) staff will document a summary of the conference call, including any material that you provide to the NRC staff in support of the call.

Should you have any questions you can contact me at 301-415-4037.

Sincerely,

/RA/

Thomas J. Wengert, Senior Project Manager  
Plant Licensing Branch III-1  
Division of Operating Reactor Licensing  
Office of Nuclear Reactor Regulation

Docket No. 50-315

Enclosure:

Steam Generator Tube Inspection Discussion Points

cc: Distribution via Listserv

**DISTRIBUTION**

PUBLIC

RidsNrrPMDCCook Resource  
RidsAcraAcnw\_MailCTR Resource  
RidsRgn3MailCenter Resource  
CHunt, NRR

LPL3-1 r/f  
RidsNrrLASRohrer Resource  
RidsNrrDeEviB Resource  
RidsNrrDorIDpr Resource  
AJohnson, NRR

RidsNrrDorLpl3-1 Resource  
RidsOgcRp Resource  
DHills, RIII  
KKarwoski, NRR

**ADAMS Accession No.: ML13066A614**

OFFICE	NRR/LPL3-1/PM	NRR/LPL3-2/LA	NRR/EVIB/BC	NRR/LPL3-1/BC	NRR/LPL3-1/PM
NAME	TWengert	SRohrer	GKulesa (MYoder for)	RCarlson (TBeltz for)	TWengert
DATE	03/11/13	03/11/13	03/15/13	03/15/13	03/18/13

OFFICIAL RECORD COPY