

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8901170077 DOC.DATE: 89/01/03 NOTARIZED: NO DOCKET #
 FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
 AUTH.NAME AUTHOR AFFILIATION
 MORGAN,H.E. Southern California Edison Co.
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 88-032-00:on 881202,TGIS Tain A spurious actuation due
 to failed ammonia analyzer oscillator circuit board.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 6
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1	PD5 PD	1 1
	HICKMAN,D	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	ARM/DCTS/DAB	1 1	DEDRO	1 1
	NRR/DEST/ADE 8H	1 1	NRR/DEST/ADS 7E	1 0
	NRR/DEST/CEB 8H	1 1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
	NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
	NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
	NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/QAB 10	1 1
	NRR/DOEA/EAB 11	1 1	NRR/DREP/RAB 10	1 1
	NRR/DREP/RPB 10	2 2	NRR/DRIS/SIB 9A	1 1
	NUDOCS-ABSTRACT	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RES/DSR/PRAB	1 1
	RGN5 FILE 01	1 1		
EXTERNAL:	EG&G WILLIAMS,S	4 4	FORD BLDG HOY,A	1 1
	H ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC HARRIS,J	1 1
	NSIC MAYS,G	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 45 ENCL 44

R
I
D
S
/
A
D
S
/
A
D
D
S

1104
88

LICENSEE EVENT REPORT (LER)

Facility Name (1) SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 2										Docket Number (2) 0 5 0 0 0 3 6 1					Page (3) 1 of 0 5							
Title (4) TOXIC GAS ISOLATION SYSTEM TRAIN A SPURIOUS ACTUATION DUE TO FAILED AMMONIA ANALYZER OSCILLATOR CIRCUIT BOARD																						
EVENT DATE (5)			LER NUMBER (6)					REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
Month	Day	Year	Year	///	Sequential Number	///	Revision Number	Month	Day	Year	Facility Names				Docket Number(s)							
1 2	0 2	8 8	8 8	---	0 3 2	---	0 0	0 1	0 3	8 9	SONGS, UNIT 3				0 5 0 0 0 3 6 2							
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)																			
POWER LEVEL (10) 1 0 0 //////////////////////////////////// //////////////////////////////////// //////////////////////////////////// //////////////////////////////////// ////////////////////////////////////			<input type="checkbox"/> 20.402(b)					<input type="checkbox"/> 20.405(c)					<input checked="" type="checkbox"/> 50.73(a)(2)(iv)					<input type="checkbox"/> 73.71(b)				
			<input type="checkbox"/> 20.405(a)(1)(i)					<input type="checkbox"/> 50.36(c)(1)					<input type="checkbox"/> 50.73(a)(2)(v)					<input type="checkbox"/> 73.71(c)				
			<input type="checkbox"/> 20.405(a)(1)(ii)					<input type="checkbox"/> 50.36(c)(2)					<input type="checkbox"/> 50.73(a)(2)(vii)					<input type="checkbox"/> Other (Specify in				
			<input type="checkbox"/> 20.405(a)(1)(iii)					<input type="checkbox"/> 50.73(a)(2)(i)					<input type="checkbox"/> 50.73(a)(2)(viii)(A)					Abstract below and				
			<input type="checkbox"/> 20.405(a)(1)(iv)					<input type="checkbox"/> 50.73(a)(2)(ii)					<input type="checkbox"/> 50.73(a)(2)(viii)(B)					in text)				
<input type="checkbox"/> 20.405(a)(1)(v)					<input type="checkbox"/> 50.73(a)(2)(iii)					<input type="checkbox"/> 50.73(a)(2)(x)												
LICENSEE CONTACT FOR THIS LER (12)																						
Name H. E. Morgan, Station Manager										TELEPHONE NUMBER AREA CODE 7 1 4 3 6 8 - 6 2 4 1												
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																						
CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS	/////	CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS	/////											
X	V I	A I	B 1 3 5	N	/////						/////											
					/////						/////											
SUPPLEMENTAL REPORT EXPECTED (14)												Expected Submission Date (15)		Month	Day	Year						
<input type="checkbox"/> Yes (If yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO																						
ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)																						

At 1007 on 12/2/88, with Units 2 and 3 at 100% power, a Toxic Gas Isolation System (TGIS) Train A spurious actuation occurred. The actuation was verified to be spurious by observation of a failed low indication of the TGIS Train A ammonia channel. All TGIS Train A components were verified to have actuated as required.

A failed ammonia analyzer oscillator circuit board resulted in the downscale failure of the analyzer. This, in turn, caused a high alarm and actuation through capacitive coupling. The proximity of the alarm relays and contacts to the detector circuitry provided for the capacitive coupling.

The oscillator circuit board was replaced, and TGIS Train A was returned to service at 0930 on 12/4/88. The alarm relays will be moved away from the detector circuitry such that capacitive coupling will be minimized. A voltage suppressing circuit will be added, if necessary, to the alarm contacts to further minimize any additional capacitive coupling. Appropriate corrective actions will be implemented as necessary from the results of the analysis of the oscillator circuit board.

There is no safety significance to this event since ammonia levels remained normal and all components associated with TGIS Train A actuated as required.

8901170077 890103
PDR ADOCK 05000361
S PDC

IED 4/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

SAN ONOFRE NUCLEAR GENERATION STATION UNIT 2	DOCKET NUMBER 05000361	LER NUMBER 88-032-00	PAGE 2 OF 5
---	---------------------------	-------------------------	----------------

Plant: San Onofre Nuclear Generating Station
Unit: Two
Reactor Vendor: Combustion Engineering
Event Date: 12/02/88
Time: 1007

A. CONDITIONS AT TIME OF THE EVENT:

Mode: 1, Power Operation

B. BACKGROUND INFORMATION:

The Toxic Gas Isolation System (TGIS) and associated Control Room Emergency Air Cleanup System (CREACUS) (EIIS System Code VI) consists of two independent trains of: ammonia, butane, and chlorine analyzers (EIIS Component Code AI); emergency air conditioning (EAC) units (E-418 and E-419) (EIIS Component Code ACU); cabinet area emergency air cooling units (E-423, E-424, E-426, and E-427) (EIIS Component Code ACU); and associated emergency isolation dampers (EIIS Component Code BDMP). Upon receipt of a high signal from one of the analyzers, CREACUS is actuated in the isolation mode; i.e., the common Units 2 and 3 control room is isolated from outside air by closing the isolation dampers, and air is recirculated by the EAC units (which also contain filtration units (EIIS Component Code FLT)), thus providing filtered and cooled air to control room personnel.

Technical Specification 3.3.2 requires that within one hour of the time that both trains of TGIS instrumentation are determined to be inoperable, CREACUS must be initiated and maintained in the isolation mode.

C. DESCRIPTION OF THE EVENT:

1. Event:

At 1007 on 12/2/88, with Units 2 and 3 at 100% power, a TGIS Train A spurious actuation occurred. The actuation was verified to be spurious by observation of a failed low indication of the TGIS Train A ammonia channel. All TGIS Train A components were verified to have actuated as required.

2. Inoperable Structures, Systems or Components that Contributed to the Event:

Since TGIS Train B was out of service for a routine surveillance when the actuation occurred, CREACUS was operated in the isolation mode until after Train B was returned to service.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

SAN ONOFRE NUCLEAR GENERATION STATION UNIT 2	DOCKET NUMBER 05000361	LER NUMBER 88-032-00	PAGE 3 OF 5
---	---------------------------	-------------------------	----------------

3. Sequence of Events:

<u>TIME</u>	<u>DATE</u>	<u>ACTION</u>
1007	12/2	Spurious TGIS Train A actuation occurred. CREACUS actuated in isolation mode.
1411	12/2	TGIS Train B, which had been out of service for a routine surveillance, was returned to service.
1440	12/2	Control Room ventilation lineup returned to normal.
0930	12/4	TGIS Train A returned to service.

4. Method of Discovery:

Control Room alarms and indications alerted the operators of the TGIS actuation.

5. Personnel Actions and Analysis of Actions:

The operators responded properly by verifying: 1) the actuation was spurious by observing the downscale failure of the ammonia channel; and 2) each TGIS Train A component actuated as required. The Control Room ventilation lineup was returned to normal after TGIS B was returned to service.

6. Safety System Responses:

All TGIS Train A components actuated as required.

D. CAUSE OF THE EVENT:

1. Immediate Cause:

A spurious high ammonia gas signal caused the actuation.

2. Intermediate Cause:

A failed oscillator circuit board resulted in the downscale failure of the ammonia analyzer. This, in turn, caused a contact in the low alarm circuit to open (causing the low alarm). The opening of the contact resulted in a high voltage in the relay circuitry, which in turn generated a spurious voltage signal in the detector circuitry due to capacitive coupling. This caused the analyzer signal to spike above the high alarm and actuation setpoint. The opening of a contact in the high alarm circuit also caused the analyzer signal to spike high (combining with the earlier spike) due to capacitive coupling. Although a time delay had been installed in the actuation circuitry, the decay of the signal spike combination was sufficiently long to cause the actuation.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

SAN ONOFRE NUCLEAR GENERATION STATION
UNIT 2

DOCKET NUMBER
05000361

LER NUMBER
88-032-00

PAGE
4 OF 5

3. Root Cause:

The ammonia analyzers provided to SCE are modified by the vendor to include alarm relays and contacts. It was noted after replacement of the Train A ammonia analyzer in February 1988 that the location of the alarm relays and contacts on the analyzer had been moved by the vendor from the external rear panel of the analyzer to inside a drawer near the detector circuitry. An evaluation that was performed at that time accepted the new configuration. It is now known, however, that the proximity of the alarm relays to the detector circuitry provides for the capacitive coupling mentioned above.

The failed oscillator circuit board has been retained for further analysis. If any significant additional information is identified by this analysis, a supplement to this report will be submitted.

E. CORRECTIVE ACTIONS:

1. Corrective Actions Taken:

The oscillator circuit board was replaced, and TGIS Train A was returned to service at 0930 on 12/4/88.

2. Planned Corrective Actions:

The alarm relays will be moved away from the detector circuitry such that capacitive coupling will be minimized.

A voltage suppressing circuit will be added, if necessary, to the alarm contacts to further minimize any additional capacitive coupling.

Appropriate corrective actions will be implemented as necessary from the results of the analysis of the oscillator circuit board.

F. SAFETY SIGNIFICANCE OF THE EVENT:

There is no safety significance to this event since ammonia levels remained normal and all components associated with TGIS Train A actuated as required.

G. ADDITIONAL INFORMATION:

1. Component Failure Information:

The ammonia analyzer (model no. 865) and oscillator circuit board (P/N 633296) are manufactured by Beckman Instruments, Inc.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

SAN ONOFRE NUCLEAR GENERATION STATION UNIT 2	DOCKET NUMBER 05000361	LER NUMBER 88-032-00	PAGE 5 OF 5
---	---------------------------	-------------------------	----------------

2. Previous LERs on Similar Events (Docket No 50-361):

a. LER 88-023 (8/25/88)

A spurious TGIS Train B actuation was caused by a false high ammonia gas signal attributed to random electronic noise. The root cause was indeterminate. The corrective action was to extend the time delay in the actuation circuit from 5 sec to 15 sec. This action did not prevent this event (LER 88-032) since the decay of the signal spike combination was sufficiently long to cause the actuation. In addition, the evaluation of the current state of technology to determine if a superior design is available has been completed; the system presently in use will be retained.

b. LER 88-005 (2/20/88)

A spurious TGIS Train A actuation was caused by intermittent spiking of the ammonia analyzer, which was attributed to a defective heating element chip. A program is being implemented to perform annual replacements of the ammonia analyzers with new/refurbished analyzers. This program is expected to minimize (but cannot be expected to totally eliminate) actuations due to ammonia analyzer failures.

c. LER 86-016, 85-047, and 85-043

These spurious TGIS actuations were caused either by spurious electrical signals in the ammonia channel or by a failure in the ammonia analyzer. Corrective actions for these events are bounded by the above events (a. and b.).

3. Results of NPRDS Search:

The failures of the ammonia analyzer or its circuit board are not reportable to NPRDS; therefore, no entries were found.

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN
STATION MANAGER

TELEPHONE
(714) 368-6241

January 3, 1989

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-361
30-Day Report
Licensee Event Report No. 88-032
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to 10 CFR 50.73(a)(2)(iv), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving a spurious actuation of the Toxic Gas Isolation System. Since this event involved a system shared between Units 2 and 3, a single report is being submitted in accordance with NUREG-1022. This occurrence had no effect on the health and safety of either plant personnel or the public.

If you require any additional information, please so advise.

Sincerely,

H. E. Morgan

Enclosure: LER No. 88-032

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)
J. B. Martin (Regional Administrator, USNRC Region V)
Institute of Nuclear Power Operations (INPO)

LE 88-032
11