

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9001300161 DOC.DATE: 90/01/12 NOTARIZED: NO DOCKET #
 FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
 AUTH.NAME AUTHOR AFFILIATION
 MORGAN,H.E. Southern California Edison Co.
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 83-078/03L-1:on 830713,CST 2T-121 water level fell below
 TS limit twice when water usage by AFW sys exceeded makeup.
 W/8 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1	PD5 PD	1 1
	KOKAJKO, L.	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	NRR/DET/ECMB 9H	1 1
	NRR/DET/EMEB9H3	1 1	NRR/DET/ESGB 8D	1 1
	NRR/DLPQ/LHFB11	1 1	NRR/DLPQ/LPEB10	1 1
	NRR/DOEA/OEAB11	1 1	NRR/DREP/PRPB11	2 2
	NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
	NUDOCS-ABSTRACT	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RGNS FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS, S	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS, G	1 1	NSIC MURPHY, G.A	1 1
	NUDOCS FULL TXT	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 38 ENCL 38

AO-4

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN
STATION MANAGER

January 12, 1990

TELEPHONE
(714) 368-6241

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-361
Supplemental Report
Licensee Event Report No. 83-078, Revision 1
San Onofre Nuclear Generating Station, Unit 2

Reference: Letter, H. B. Ray (SCE) to USNRC, Office of Inspection and
Enforcement, Region V, dated August 12, 1983.

The referenced letter provided Licensee Event Report (LER) No. 83-078 for an occurrence in which a Limiting Condition for Operation associated with a Condensate Storage Tank was exceeded. This revision modifies the proposed corrective actions to prevent recurrence which were reported in the initial LER to those corrective actions which were implemented. Neither the health and safety of plant personnel or the public was affected by this occurrence.

If you require any additional information, please so advise.

Sincerely,

H E Morgan

Enclosure: LER No. 83-078, Revision 1

cc: C. W. Caldwell (USNRC Senior Resident Inspector, Units 1, 2 and 3)
J. B. Martin (Regional Administrator, USNRC Region V)
Institute of Nuclear Power Operations (INPO)

7001300161 900112
PDR ADDCK 05000361
S PDC

IE 22

111

ATTACHMENT TO LER 83-078, REVISION 1
SOUTHERN CALIFORNIA EDISON COMPANY
SAN ONOFRE NUCLEAR GENERATING STATION
UNIT 2, DOCKET NO. 50-361

SUPPLEMENTAL INFORMATION FOR EVENT DESCRIPTION AND PROBABLE CONSEQUENCES:

At 2240 the level was returned to within specified limits and the Action Statement was satisfied. The health and safety of plant personnel and the public were not affected by this incident.

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION AND CORRECTIVE ACTIONS:

In LER 83-002 we stated that an automatic tank level control system to prevent depletion of the water level of the condensate storage tanks below the Technical Specification required limit, was expected to be implemented in April 1983. This system was installed and has been made operation, and was noted as such, in NRC Inspection Report 50-361/83-24.

Even though the level control system operated as designed, it was not adequate for the water demands placed on 2T-121 in this event. In this case, the extent to which water demand exceeds automatic makeup was decreased due to make-up being aligned to both CST's 2T-121 and 2T-120, thereby reducing the effective make-up water rate to 2T-121.

The main cause of this and other similar events associated with the lowering of water level in CST 2T-121 is due to the difficulty of controlling the makeup to 2T-121 in such a fashion as to maintain the contained water volume within the tight tolerance represented by the overflow level and the Technical Specification limit for minimum level.

To prevent recurrence of this event the following actions were completed:

- (a) The event was reviewed with all operations personnel with the objective that, during periods of high water demand from 2T-121, the make-up should be aligned to 2T-121 only. Also, the operating instructions were revised accordingly in September, 1983.
- (b) A design review of the automatic level control system was completed which resulted in design changes, implemented in August 1986, which assure that make-up water is not diverted from 2T-121 during periods of high water demand. Additionally, a high flow make-up demineralizer system was added (in-service since September, 1986) which assures that sufficient make-up water is available for Units 1, 2 and 3.

NRC FORM 366 (12-E1) JANUARY 1980															U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT															APPROVED BY OMB 3150-0011																	
CONTROL BLOCK:															(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)																																
01 C A S O S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4																																															
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58																																															
CONT																																															
01 REPORT SOURCE L 0 5 0 0 0 3 6 1 0 7 1 3 8 3 0 1 1 2 9 0																																															
DOCKET NUMBER EVENT DATE REPORT DATE																																															
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES																																															
With Unit 2 in Mode 2, CST 2T-121 water level fell below the Technical Specification limit twice when water usage by the Auxiliary Feedwater System, which draws water from 2T-121, exceeded makeup to 2T-121. The Action Statement associated with LCO 3.7.1.3 was entered at 1839 and satisfied at 1844 by returning the water level to within acceptable limits. The Action Statement was again entered at 2200 when Unit 2 began raising power level and the auxiliary feed rate increased. See LER 83-016 and LER 83-002. (See Attachment).																																															
<table border="0" style="width:100%;"> <tr> <td>SYSTEM CODE</td><td>CAUSE CODE</td><td>CAUSE SUBCODE</td><td>COMPONENT CODE</td><td>COMP. SUBCODE</td><td>VALVE SUBCODE</td></tr> <tr> <td>W F 11</td><td>X 12</td><td>Z 13</td><td>A C C U M U 14</td><td>Z 15</td><td>Z 16</td></tr> </table>																														SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE	W F 11	X 12	Z 13	A C C U M U 14	Z 15	Z 16						
SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE																																										
W F 11	X 12	Z 13	A C C U M U 14	Z 15	Z 16																																										
<table border="0" style="width:100%;"> <tr> <td>LER/RO REPORT NUMBER</td><td>EVENT YEAR</td><td>SEQUENTIAL REPORT NO.</td><td>OCCURRENCE CODE</td><td>REPORT TYPE</td><td>REVISION NO.</td></tr> <tr> <td>17</td><td>8 3</td><td>0 7 8</td><td>0 3</td><td>L</td><td>1</td></tr> </table>																														LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.	17	8 3	0 7 8	0 3	L	1						
LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.																																										
17	8 3	0 7 8	0 3	L	1																																										
<table border="0" style="width:100%;"> <tr> <td>ACTION TAKEN</td><td>FUTURE ACTION</td><td>EFFECT ON PLANT</td><td>SHUTDOWN METHOD</td><td>HOURS</td><td>ATTACHMENT SUBMITTED</td><td>NPRD-4 FORM SUB.</td><td>PRIME COMP. SUPPLIER</td><td>COMPONENT MANUFACTURER</td></tr> <tr> <td>X 18</td><td>X 19</td><td>Z 20</td><td>Z 21</td><td>0 0 0 0</td><td>Y 23</td><td>N 24</td><td>A 25</td><td>Z 9 9 9 9</td></tr> </table>																														ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER	X 18	X 19	Z 20	Z 21	0 0 0 0	Y 23	N 24	A 25	Z 9 9 9 9
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER																																							
X 18	X 19	Z 20	Z 21	0 0 0 0	Y 23	N 24	A 25	Z 9 9 9 9																																							
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS																																															
This event was caused primarily by water demand higher than the make-up to Tank T-121. (See Attachment).																																															
<table border="0" style="width:100%;"> <tr> <td>FACILITY STATUS</td><td>% POWER</td><td>OTHER STATUS</td><td>METHOD OF DISCOVERY</td><td>DISCOVERY DESCRIPTION</td></tr> <tr> <td>B 28</td><td>0 0 5 29</td><td>NA</td><td>A 31</td><td>Operator Observation</td></tr> </table>																														FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION	B 28	0 0 5 29	NA	A 31	Operator Observation								
FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION																																											
B 28	0 0 5 29	NA	A 31	Operator Observation																																											
<table border="0" style="width:100%;"> <tr> <td>ACTIVITY CONTENT RELEASED OF RELEASE</td><td>AMOUNT OF ACTIVITY</td><td>LOCATION OF RELEASE</td></tr> <tr> <td>Z 33</td><td>Z 34 NA</td><td>NA</td></tr> </table>																														ACTIVITY CONTENT RELEASED OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE	Z 33	Z 34 NA	NA												
ACTIVITY CONTENT RELEASED OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE																																													
Z 33	Z 34 NA	NA																																													
<table border="0" style="width:100%;"> <tr> <td>PERSONNEL EXPOSURES NUMBER</td><td>TYPE</td><td>DESCRIPTION</td></tr> <tr> <td>0 0 0 37</td><td>Z 38</td><td>NA</td></tr> </table>																														PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION	0 0 0 37	Z 38	NA												
PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION																																													
0 0 0 37	Z 38	NA																																													
<table border="0" style="width:100%;"> <tr> <td>PERSONNEL INJURIES NUMBER</td><td>DESCRIPTION</td></tr> <tr> <td>0 0 0 40</td><td>NA</td></tr> </table>																														PERSONNEL INJURIES NUMBER	DESCRIPTION	0 0 0 40	NA														
PERSONNEL INJURIES NUMBER	DESCRIPTION																																														
0 0 0 40	NA																																														
<table border="0" style="width:100%;"> <tr> <td>LOSS OF OR DAMAGE TO FACILITY TYPE</td><td>DESCRIPTION</td></tr> <tr> <td>Z 42</td><td>NA</td></tr> </table>																														LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION	Z 42	NA														
LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION																																														
Z 42	NA																																														
<table border="0" style="width:100%;"> <tr> <td>PUBLICITY ISSUED</td><td>DESCRIPTION</td></tr> <tr> <td>N 44</td><td>NA</td></tr> </table>																														PUBLICITY ISSUED	DESCRIPTION	N 44	NA														
PUBLICITY ISSUED	DESCRIPTION																																														
N 44	NA																																														
NAME OF PREPARER H. E. MORGAN																				PHONE (714) 368-6241																											