

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8911130237 DOC.DATE: 89/11/06 NOTARIZED: NO DOCKET #
 FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
 AUTH.NAME AUTHOR AFFILIATION
 NANDY,F.R. Southern California Edison Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Advises that internal insp will be performed on MSIV
 2HV-8205 only,during Cycle 5 refueling outage.

DISTRIBUTION CODE: A001D COPIES RECEIVED:LTTR 1 ENCL 0 SIZE: 2
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1		PD5 PD	1 1
	KOKAJKO,L.	5 5			
INTERNAL:	ACRS	6 6		NRR/DEST/ADS 7E	1 1
	NRR/DEST/ESB 8D	1 1		NRR/DEST/ICSB	1 1
	NRR/DEST/MTB 9H	1 1		NRR/DEST/RSB 8E	1 1
	NRR/DOEA/TSB 11	1 1		NUDOCS-ABSTRACT	1 1
	OC/LEMB	1 0		OGC/HDS2	1 0
	<u>REG FILE</u> 01	1 1		RES/DSIR/EIB	1 1
EXTERNAL:	LPDR	1 1		NRC PDR	1 1
	NSIC	1 1			

ms-4

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 27 ENCL 25 0



Southern California Edison Company

23 PARKER STREET
IRVINE, CALIFORNIA 92718

November 6, 1989

F. R. NANDY
MANAGER OF NUCLEAR LICENSING

TELEPHONE
(714) 587-5400

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361
Deferral of MSIV 2HV-8204 Boroscopic Inspection
San Onofre Nuclear Generating Station
Unit 2

This letter documents discussions with the Office of Nuclear Reactor Regulation (NRR) SONGS Units 2 and 3 Project Manager that a boroscopic examination of the Unit 2 Main Steam Isolation Valve (MSIV) 2HV-8204 will not be performed during the Cycle 5 refueling outage. On August 17, 1989, the NRR Project Manager concurred with SCE's modified MSIV inspection plan for Unit 2.

SCE had originally committed to boroscopic inspections of the Units 2 and 3 MSIVs by letter dated September 27, 1988. These commitments were made as a result of internal damage observed in the Waterford and, to a lesser extent, the SONGS MSIVs. The root cause of the MSIV internal damage has been determined to be associated with excessively fast valve closure.

In February 1989, both of Unit 2's MSIVs were inspected with a boroscope. The MSIV 2HV-8205 was found in good condition. However, the boroscopic examination of MSIV 2HV-8204 suggested the presence of some debris and the valve was disassembled. The internals of MSIV 2HV-8204 were found in excellent condition. Based on this internal examination of MSIV 2HV-8204 and the boroscopic examination of 2HV-8205, SCE concluded that the boroscopic inspection of MSIV 2HV-8204 during the Cycle 5 refueling outage was not necessary.

Accordingly, during the Unit 2 Cycle 5 refueling outage, an internal inspection will only be performed on MSIV 2HV-8205 since it is being

8911130237 891106
PDR ADCCK 05000361
Q PDC

A001
110

November 6, 1989

disassembled to replace its stem. In addition, modifications will be made to both MSIVs to slow the valves' closure time and thus minimize the potential for internal damage.

If you have any questions, please feel free to call me.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. B. Martin". The signature is fluid and cursive, with the first letters of the first and last names being capitalized and prominent.

cc: J. B. Martin, Regional Administrator, NRC Region V
C. Caldwell, NRC Senior Resident Inspector, San Onofre Units 1, 2, and 3