

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8106030199 DOC. DATE: 81/05/28 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern California 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern California 05000362
 AUTH. NAME AUTHOR AFFILIATION
 PAPAY, L.T. Southern California Edison Co.
 RECIP. NAME RECIPIENT AFFILIATION
 ENGELKEN, R.H. Division of Engineering & Technical Inspection

SUBJECT: Final deficiency rept re use of Target Rock Y-pattern globe valves in safety injection tank fill lines, initially reported 810430. Review of all valves indicates unique situation. Seismic Category I check valves will be installed.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Send all FSAR & ER amends to L Chandler. 05000361
 1 cy: J Hanchett (Region V). D Scaletti, 1 cy of all envir info
 Send all FSAR & ER amends to L Chandler. 05000362
 1 cy: J Hanchett (Region V). D Scaletti, 1 cy of all envir info

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
ACTION:	A/D LICENSNG 04	1	1	LIC BR #3 BC 05	1	1
	LIC BR #3 LA 06	1	1	ROOD, H. 07	1	1
INTERNAL:	ASLBP/J. HARD	1	1	D/DIR HUM FAC15	1	1
	EDO & STAFF 19	1	1	EQUIP QUAL BR11	1	1
	HYD/GEO BR 22	1	1	I&E 09	1	1
	IE/EES	1	1	LIC QUAL BR 12	1	1
	MPA 20	1	1	NRC PDR 02	1	1
	OELD 21	1	1	PROC/TST REV 13	1	1
	QA BR 14	1	1	<u>REG FILE</u> 01	1	1
	STANDRDS DEV 21	1	1			
EXTERNAL:	ACRS 16	16	16	LPDR 03	1	1
	NSIC 08	1	1			

JUN 05 1991

MA 1

TOTAL NUMBER OF COPIES REQUIRED: LTTR

38

ENCL

38

Southern California Edison Company

SCE

P. O. BOX 800

2244 WALNUT GROVE AVENUE


ROSEMEAD, CALIFORNIA 91770

L. T. PAPAY
VICE PRESIDENT

TELEPHONE
213-572-1474

May 28, 1981

Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, California 94506



Dear Mr. Engelken:

Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station, Units 2 and 3

In a letter to your office dated April 30, 1981 we identified a condition which we considered potentially reportable in accordance with 10CFR50.55(e). The condition concerns the use of Y-pattern, unidirectional valves in the nitrogen pressurizer lines to the safety injection tanks.

Enclosed are twenty-five (25) copies of a final report entitled, "FINAL REPORT ON THE USE OF TARGET ROCK Y-PATTERN GLOBE VALVES IN THE SAFETY INJECTION TANK FILL LINES, San Onofre Nuclear Generating Station, Units 2 and 3."

If you have any questions regarding this report we would be pleased to discuss them with you at your convenience.

Very truly yours,

A handwritten signature in dark ink, appearing to read "V. Stello".

B019
S
1/1

Enclosures

cc: Victor Stello (NRC, Director I&E)
R. J. Pate (NRC, San Onofre Units 2 and 3)

S

8106030199

FINAL REPORT ON THE USE OF TARGET ROCK Y-PATTERN GLOBE VALVES IN THE SAFETY INJECTION TANK FILL LINES

San Onofre Nuclear Generating Station, Units 2 and 3

INTRODUCTION

This report is submitted pursuant to 10CFR50.55(e)(3). It describes a condition in which the nitrogen pressurization of the safety injection tanks (SIT) could be vented during a seismic or high energy line break event. This report includes a description of the deficiency, analysis of the safety implications and a summary of the corrective actions taken. By letter dated April 30, 1981, Edison confirmed notification to the NRC of this potentially reportable condition.

BACKGROUND

During the review of high energy piping for potential pipe breaks and system responses, it was determined that it would be beneficial to depressurize the Seismic Category II portion of the nitrogen supply header inside containment during operation in order to minimize the potential for high energy pipe breaks. A review of the SIT isolation valves showed that they are unidirectional and would not be effective with a reverse pressure differential (vented fill line). Further review indicated that the valves and their associated supports were class boundaries between seismic category I and II systems. Consequently, if the nitrogen supply header (seismic category II) failed during a seismic event, the safety injection tanks would have depressurized.

DISCUSSION

The following discussion is responsive to 10CFR50.55(e)(3).

Description of the Deficiency

The nitrogen fill valves (HV-9344, -9354, -9364, -9374) to the safety injection tanks are solenoid operated unidirectional Y-pattern globe valves manufactured by Target Rock. A pressure differential in the direction opposite to the normal direction of flow will unseat these valves, resulting in the simultaneous loss of nitrogen overpressure to all safety injection tanks.

FINAL REPORT ON THE USE OF TARGET ROCK Y-PATTERN
GLOBE VALVES IN THE SAFETY INJECTION TANK FILL LINES
San Onofre Nuclear Generating Station, Units 2 and 3

Page 2

Analysis of Safety Implications

If the seismic category I nitrogen supply header failed during a seismic event, the safety injection tanks would depressurize and not serve their safety function.

CORRECTIVE ACTION

A review of the use of all solenoid operated Target Rock Y-pattern globe valves was performed to determine whether this deficiency was present in any other system. The results of that investigation indicated that this was a unique situation.

Seismic Category I check valves will be installed upstream of the Target Rock valves to prevent depressurization through the valves. Schedule for completion is August 1, 1981.