

RV THERMAL SHOCK WITH REPRESSURIZATION

OVERVIEW OF SCOPING ANALYSIS METHODS

AND SOME PRELIMINARY RESULTS

D. J. AYRES

JULY 30 1981

Enclosure 6

CE Owners Group Presentation

PRESSURIZED THERMAL SHOCK

TRANSIENTS ANALYSES

MATERIAL PROPERTIES

FLUENCE DISTRIBUTIONS

VESSEL INTEGRITY EVALUATIONS

⊥

LOCAL TEMPERATURE, T_L

T_B


CORE
BARREL →

T_L

NOZZLE


CORE

RV



PRESSURE


P



time



BULK TEMPERATURE

T_{∞}





time

TOUGHNESS




LOCAL HEAT TRANSFER






* ASSUMED TO BE CLAD
 VESSEL WALL THICKNESS

SUPERIMPOSED FLUENCE AND WELD MAPS












Figure 1 Predicted Adjustment of Reference Temperature, "A", as a Function of Fluence and Copper Content.
For Copper and Phosphorus Contents Other Than Those Plotted, Use the Expression for "A" Given on the Figure.



REACTOR VESSEL WITH AXIAL CRACK




FRACTURE MECHANICS ANALYSIS




2.0 IN. CRACK AT I.D. OF REACTOR VESSEL
RADIAL
PERIPHERIAL



CRACK DEPTH



EVALUATION SUMMARY



E VALUATION




CONSERVATIVE ASSUMPTIONS IN

FRACTURE EVALUATION

1. LONG AXIAL CRACKS
2. WELD WITH HIGHEST NDT
3. AXIAL PEAK FLUENCE
4. NO FLUID HEATING FROM WALL
5. FULL PRESSURE IN CRACK
6. DIFFERENTIAL THERMAL EXPANSION
OF CLAD
7. REG. GUIDE 199 NDT SHIFT
8. LINEARIZED FLUENCE ATTENUATION

EVALUATION SUMMARY



CRITICAL CRACK DEPTH VS. TIME

CRACK DEPTH, IN

1.00

.90

.80

.70

.60

.50

.40

.30

.20

.10

0.0

800.

1600.

2400.

3200.

4000.

4800.

5600.

6400.

7200.

8000.

TIME (SEC.)

RV Surface Fluence = $.46 \times 10^{19}$ n/cm²

% Cu = .35

% P = .013


RTNDT₀ = 10 °F

LOFW → SB LOCA


(E7IME

REFERENCE
OVERCOOLING TRANSIENT

LOFW — SB LOCA



STEAM LINE BREAK TRANSIENT
(ZERO POWER AC AVAILABLE)



CRITICAL CRACK DEPTH VS. TIME

CRACK DEPTH, A/M

1.00/

.90/

.80/

.70/

.60/

.50/

.40/

.30/

.20/

.10/

0.0

800.

1600.

2400.

3200.

4000.

4800.

5600.

6400.

7200.

8000.

TIME (SEC.)

RV Surface Flux = $.91 \times 10^{19}$ N/cm² (E/M
 % Cu = .35
 % P = .013
 RTNDT₀ = 10 °F

LOFW → SB LOCA

CRITICAL CRACK DEPTH VS. TIME

CRACK DEPTH, A/W

1.00/

.90/

.80/

.70/

.60/

.50/

.40/

.30/

.20/

.10/

0.0

180.

360.

540.

720.

900.

1080.

1260.

1440.

1620.

1800.

TIME (SEC.)

RV Surface Flux = $.91 \times 10^{19} \text{ n/cm}^2 (\text{E})$

% Cu = .35

% P = .013


RTNDT₀ = 10 °F

Steam Line Break

WPS

ARREST

INITIATION



CRITICAL CRACK DEPTH VS. TIME

CRACK DEPTH, A/M

1.00/

.90/

.80/

.70/

.60/

.50/

.40/

.30/

.20/

.10/

0.0

100.

360.

540.

720.

900.

1080.

1260.

1440.

1620.

1800.

TIME (SEC.)

RP Surface Fluence = $.46 \times 10^{19} \text{ n/cm}^2 (\text{E71})$


% Cu = .35

% P = .013

RTNDT₀ = 10°F

Steam Line Break

ARREST



CRITICAL CRACK DEPTH VS. TIME

CRACK DEPTH, A/N

1.00/

.90/

.80/

.70/

.60/

.50/

.40/

.30/

.20/

.10/

0.0

100.

360.

540.

720.

900.

1080.

1200.

1440.

1620.


1800.


TIME (SEC.)

RU Surface Fluence = $3.9 \times 10^{19} \text{ n/cm}^2$ { (E)IM
% Cu = .35
% P = .018
RTNDT₀ = 10°F

Steam Line Break
Transient No. 2

ARREST





CRACK DEPTH, A/B

1.00/

RV Surface

Fluence = $.73 \times 10^{19} \text{ N/cm}^2$ ($E > 1 \text{ MEV}$)

% Cu = .35

% P = .018

RTNDT₀ = 10°F{ weld
materialSteam line Break
Transient No. 2

.60/

.50/

.40/

.30/

.20/

.10/

0.0

100.

300.

500.

700.

900.

1000.

1200.

1400.

1600.

1800.


TIME (SEC.)


WPS

ARREST

INITIATION

C







UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

August 21, 1981

Docket No. 50-289

Mr. Henry D. Hukill, Vice President
and Director - TMI-1
Metropolitan Edison Company
P. O. Box 480
Middletown, Pennsylvania 17057

Dear Mr. Hukill:

SUBJECT: PRESSURIZED THERMAL SHOCK TO REACTOR PRESSURE VESSELS

We have reviewed the PWR Owners' Groups responses of May 15, 1981 and the licensees' responses of May 22, 1981 to our letter dated April 20, 1981 concerning the subject issue. The EPRI work which bears on the issue was included in the licensees' responses. On the basis of our independent review, of the plants where neutron irradiation has significantly reduced the fracture toughness of the reactor pressure vessels (RPVs), all plants could survive a severe overcooling event for at least another year of full power operation. However, we believe that additional action should be taken now to resolve the long-term problems.

This belief is based upon our analyses which indicate that reductions in fracture toughness for some RPVs are approaching levels of concern. It is also based in part on the fact that any proposed corrective action must allow adequate lead time for planning, review, approval, procurement and installation. These conclusions were recently discussed with the PWR Owners Groups on July 28-30, 1981. At those meetings, the Owners Groups reviewed the programs underway at the three PWR vendors which are designed to scope the magnitude and applicability of the generic problem and to be completed by late 1981. The three programs appeared to contain the necessary elements for resolution of the problem on a generic basis and the NRC plans to make full use of the reports due by the end of the year. While the vendors and Owners Groups are to be commended and encouraged in addressing the generic issue, there is also a need for plant-specific information for your plant.

Based on current vessel reference temperature and/or system characteristics, we have identified Ft. Calhoun, Robinson 2, San Onofre 1, Maine Yankee, Oconee 1, Turkey Point 4, Calvert Cliffs 1 and Three Mile Island 1 as plants from which we require additional information at this time.

The staff has used the time-dependent pressure and temperature data from the March 20, 1978 Rancho Seco transient as a starting point for our evaluation of this issue because: (1) it is the most severe overcooling event experienced to date in an operating plant; (2) it is a real, as

Dupe 8109140225

- opposed to a postulated, event; and (3) it was severe enough that it could challenge the RPY when combined with physically reasonable values of irradiated fracture toughness and initial crack size. In future reviews the staff plans to use the steam line break accident or other appropriate transient/accident in order to estimate minimum operational times available before plant modifications are required.

Using calculated RPY steel mechanical properties, credible initial flaw sizes, reasonable thermal-hydraulic parameters, and a simplified pressure-temperature transient similar to that observed during the Rancho Seco event, the staff has concluded that all operating plants could safely survive such an event at the present time and for at least an additional year of full power operation. However, because of the required lead times for future actions, the margins in time for long term operation are not large, and there is considerable uncertainty in the probability that similar or more severe transients may occur. It is clear that positive action must be initiated soon for those plants with significantly high transition temperatures. As indicated above, several such plants have been selected by the staff, based on estimates of the current reference temperature for the nil ductility transition (RT_{NDT}) of the RPVs.

NDT

The need to initiate further action at this time is emphasized by the recognition that implementation of any proposed fixes or remedial actions must allow for adequate lead time. Because long-term solutions may require a year or more, you should explore short-term approaches as well. Although clear, concise instructions should be provided to operators to reduce the likelihood of repressurization during overcooling transients, the NRC staff believes that reliance on operator actions to prevent repressurization during an overcooling transient will be very difficult to justify as an acceptable long-term solution to the problem.

In accordance with 10 CFR 50.54(f) of the Commission's regulations, you are requested to submit written statements, signed under oath or affirmation, to enable the Commission to determine whether or not your license should be modified, suspended or revoked. Specifically, you are requested to submit the following information to the NRC within 60 days from the date of this letter:

- (1) provide the RT_{NDT} values of the critical welds and plates (or forgings) in your vessel for:
 - (a) initial (as-built) conditions and location (e.g., 1/4 T) and
 - (b) current conditions (include fluence level) at the RPY inside carbon steel surface.

- (2) At what rate is RT increasing for these welds and plate material?
- (3) What value of RT_{NDT} for the critical welds and plate material do you consider appropriate as a limit for continued operation?
- (4) What is the basis for your proposed limit?
- (5) Provide a listing of operator actions which are required for your plant to prevent pressurized thermal shock and to ensure vessel integrity. Include a description of the circumstances in which these operator actions are required to be taken. Included in this summary should be the specific pressure, temperature and level values for:
a) high pressure injection (HPI) termination criteria presently used at your facility, b) HPI throttling criteria and instruction presently used at your facility and c) criteria for throttling feedwater presently used at your facility. For each required operator action, give the information available to the operator and the time available for his decision and the required action. State how each required operator action is incorporated in plant operating procedures and in training and requalification training programs.

You are also requested to submit a plan for Three Mile Island, Unit No. 1 to the NRC within 150 days of the date of this letter that will define actions and schedules for resolution of this issue and analyses supporting continued operation. We request that you include consideration and evaluation of the following possible actions:

- (1) reduction of further neutron radiation damage at the beltline by replacement of outer fuel assemblies with dummy assemblies or other fuel management changes;
- (2) reduction of the thermal shock severity by increasing the ECC water temperature;
- (3) recovery of RPV toughness by in-place annealing (include the basis for demonstrating that your plant meets the requirements in 10 CFR 50 Appendix G IV C);
- (4) design of a control system to mitigate the initial thermal shock and control repressurization.

For these, as well as for any other alternative approaches, provide implementation schedules that would assure continuance of adequate safety margins.


In the interest of efficient evaluation of your submittal, we request that you include with the above plan, a response to the enclosed request for additional information.

Mr. Henry D. Hukill

-4-

Due to the nature of this review, and the past review effort that has been expended, we consider the above schedules to be reasonable; however, inform us within 30 days if you anticipate conflicts with previous commitments with either submittal and a basis for any delay. We also expect participation by the appropriate PWR Owners Group and NSSS vendors in developing solutions to the problem.

Sincerely,


for Darrell G. Cisenhut, Director
Division of Licensing
Office of Nuclear Reactor Regulation

Enclosure:
Request for Additional
Information

cc w/enclosure:
See next page

cc w/enclosure(s):

Mr. Marvin I. Lewis
6604 Bradford Terrace
Philadelphia, Pennsylvania 19149

Walter W. Cohen, Consumer Advocate
Department of Justice
Strawberry Square, 14th Floor
Harrisburg, Pennsylvania 17127

Dr. Walter H. Jordan
881 W. Outer Drive
Oak Ridge, Tennessee 37830

Dr. Linda W. Little
5000 Hermitage Drive
Raleigh, North Carolina 27612

Robert L. Knupp, Esq.
Assistant Solicitor
Knupp and Andrews
P. O. Box P
407 N. Front Street
Harrisburg, Pennsylvania 17108

Ms. Gail P. Bradford
Anti-Nuclear Group Representing
New York
245 W. Philadelphia Street
York, Pennsylvania 17404

John E. Minnich, Chairman
Dauphin Co. Board of Commissioners
Dauphin County Courthouse
Front and Market Streets
Harrisburg, Pennsylvania 17101

John Levin, Esq.
Pennsylvania Public Utilities Comm.
Box 3265
Harrisburg, Pennsylvania 17120

Atomic Safety and Licensing Appeal Board
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Jordan D. Cunningham, Esq.
Fox, Farr and Cunningham
2320 North 2nd Street
Harrisburg, Pennsylvania 17110

Atomic Safety and Licensing Board Panel
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Ms. Louise Bradford
PHA
1011 Green Street
Harrisburg, Pennsylvania 17102

Bookkeeping and Service Section
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Ms. Marjorie W. Amodeo
PHO 145
Coatesville, Pennsylvania 19320

Robert Q. Pollard
679 Connelley Street
Baltimore, Maryland 21213

Ms. Karen Sheldon
Sheldon, Harton & Weiss
1251 Street, N.W. - Suite 506
Washington, D. C. 20005

Stanley Keeford
Edith M. Jonesrud
Boy's Commercial Corporation on Nuclear Power
400 Orlando Avenue
State College, Pennsylvania 16801

Earl B. Hoffman
Dauphin County Commissioner
Dauphin County Courthouse
Front and Market Streets
Harrisburg, Pennsylvania 17101

Ms. Ellen R. Weiss, Esq.
Sheldon, Harton & Weiss
1251 Street, N.W.
Suite 506
Washington, D. C. 20005

Miss Anne C. Carr
402 Marlene Drive
Harrisburg, Pennsylvania 17109

Mr. Steven C. Sholly
Union of Concerned Scientists
1725 I Street, N.W. Suite 501
Washington, DC 20006

Metropolitan Edison Company

- 2 -

Mr. Thomas Gerusky
Bureau of Radiation Protection
Department of Environmental Resources
P. O. Box 2063
Harrisburg, Pennsylvania 17120

Ms. Jane Lee
R.D. 3, Box 3521
Etters, Pennsylvania 17319

Karin W. Carter, Esq.
505 Executive House
P. O. Box 2357
Harrisburg, Pennsylvania 17120

Honorable Mark Cohen
512 D-3 Main Capital Building
Harrisburg, Pennsylvania 17120

Dauphin County Office Emergency
Preparedness
Court House, Room 7
Front & Market Streets
Harrisburg, Pennsylvania 17101

Department of Environmental Resources
ATTN: Director, Office of Radiological
Health
P. O. Box 2063
Harrisburg, Pennsylvania 17105

Ms. Lennie Prough
U. S. N. R. C. - TMI Site
P. O. Box 311
Middletown, Pennsylvania 17057

Mr. Robert B. Borsum
Babcock & Wilcox

Nuclear Power Generation Division
Suite 420, 7735 Old Georgetown Road
Bethesda, Maryland 20011

Ivan W. Smith, Esq.
Atomic Safety & Licensing Board Panel
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Ms. Kathy McCaughin
Three Mile Island Alert, Inc.
23 South 21st Street
Harrisburg, Pennsylvania 17104

Mr. C. W. Smyth
Supervisor of Licensing TMI-1
Metropolitan Edison Company
P. O. Box 480
Middletown, Pennsylvania 17057

G. F. Trowbridge, Esq.
Shaw, Pittman, Potts & Trowbridge
1600 M Street, N.W.
Washington, D. C. 20036

Mr. E. G. Wallace
Licensing Manager
GPU Service Corporation
100 Interpace Parkway
Parsippany, New Jersey 07054

Ms. Virginia Southard, Chairman
Citizens for a Safe Environment
251 Walton Street
Lemoine, Pennsylvania 17043

Government Publications Section
State Library of Pennsylvania
Box 1601 (Education Building)
Harrisburg, Pennsylvania 17125

Mr. David O. Maxwell, Chairman
Board of Supervisors
Londonderry Township
Rural - Meyers Church Road
Middletown, Pennsylvania 17057

U. S. Environmental Protection Agency
Region III Office
ATTN: EIS COORDINATOR
Curtis Building (Sixth Floor)
5th and Walnut Streets
Philadelphia, Pennsylvania 19106

Metropolitan Edison Company

- 3 -

Mr. R. J. Toole
Manager, TMI-1
Metropolitan Edison Company
P. O. Box 480
Middletown, Pennsylvania 17057

Allen R. Carter, Chairman
Joint Legislative Committee on Energy
P. O. Box 142
Suite 513
Senate Gressette Building
Columbia, South Carolina 29202

Daniel M. Pell, Esq.
ANGRY
32 South Beaver Street
York, Pennsylvania 17401

William S. Jordan, III, Esq.
Harmon & Weiss
1725 I Street, NW, Suite 506
Washington, DC 20006

J. B. Lieberman, Esq.
Berlock, Israel & Liberman
26 Broadway
New York, NY 10004

General Counsel
Federal Emergency Management Agency
ATTN: Docket Clerk
1725 I Street, NW
Washington, DC 20472

York College of Pennsylvania
Country Club Road
York, Pennsylvania 17405

Mr. Donald R. Haverkamp
Senior Resident Inspector (TMI-1)
U. S. N. R. C.
P. O. Box 311
Middletown, Pennsylvania 17057

Mr. Richard Roberts
The Patriot
312 Market Street
Harrisburg, Pennsylvania 17105

Governor's Office of State Planning
and Development
ATTN: Coordinator, Pennsylvania
State Clearinghouse
P. O. Box 1323
Harrisburg, Pennsylvania 17120

Enclosure

REQUEST FOR ADDITIONAL INFORMATION

1. Geometry

Geometrical description including design and as-built (when available) dimensions of the core, assemblies, shroud/baffle, thermal shield, downcomer, vessel, cavity, and surrounding shield and/or support structure.

2. Material Description

Region-wise material composition and material isotopic number densities (atoms/barn-cm) for the core, near-core regions and RPV, suitable for neutron transport calculations.

3. Neutron Source

Present and expected EOL:

- a) Assembly-wise and core power history (EFPY).
- b) Rod-wise and core power history (EFPY) for peripheral assemblies.
- c) Core average axial power history distribution.

4. Vessel Fluence

- a) Description of available calculations of the vessel fluence including fluence values, locations, and corresponding power histories (EFPY), including 1/4T, 1/2T and 3/4T through the RPV.
- b) Description of available capsule-inferred vessel fluences including fluence values, locations, and corresponding power histories (EFPY).

5. Surveillance Capsules

- a) Capsule materials, radial and axial dimensions and locations.
- b) Capsule fluence measurements, together with the accumulated power history (EFPY) and a description of the lead factors used to extrapolate the measurements to the peak wall fluence location.

5. Vessel Welds

axial and azimuthal locations of vessel weld-seams with respect to the core. Overlay of current fluence map with weld locations. Identify the critical welds, vertical and circumferential, and give the weld wire heat numbers. Give weld chemistry for the critical welds. For each weld wire heat number, report the estimated mean copper content, the range and the standard deviation, based on all the reported measurements for that weld wire heat. The welds may be surveillance weldments for your vessel or others, nozzle dropouts that contain a weld, weld metal qualification data, or archive material. In the absence of any information, assume that copper content is at its upper limit (0.35 percent when using R.G. 1.99, Rev. 1) and that the nickel content is high.

7. Systems Analysis

a) Provide a list of transients or accidents by class (for example: excessive feedwater, operating transients which result from multiple failures including control system failures and/or operator error, steam line break and small break LOCA) which could lead to inside vessel fluid temperatures of 300 F or lower. Provide any Failure Modes and Effects Analyses (FMEAs) of control systems currently available or reference any such analyses already submitted. Provide the analysis of the most limiting transient or accident with regard to vessel thermal shock considerations. Estimate the frequency of occurrence of this event and provide the basis for this estimate. Discuss the assumptions made regarding reactor operator actions.

b) Identify the computer programs used to calculate the limiting transient or accident. Indicate the degree to which the computer programs used have been verified and any other additional verification required to demonstrate that the computer program models adequately treat the identified important physical models (i.e., ECC mixing, heat transfer, and repressurization).

PRESSURIZED THERMAL SHOCK OF PRESSURE VESSELS

COMMISSION BRIEFING

T.E. MURLEY
SEPTEMBER 15, 1981

DESIGNATED ORIGINAL

Certified By

10/6/81

T.E. Murley



Dupe 848922000000

PRESSURIZED THERMAL SHOCK OF PRESSURE VESSELS
COMMISSION BRIEFING

- I. SUMMARY OF THE PROBLEM
- II. DISCUSSIONS WITH INDUSTRY
- III. RECENT INFORMATION
- IV. POSSIBLE REGULATORY LIMITS
- V. STAFF CONCLUSIONS


I. SUMMARY OF THE PROBLEM

RANCHO SECO 3-20-78 TRANSIENT





B1

VESSEL WALL TEMPERATURE VS. TIME AND DEPTH




STRESS DISTRIBUTION




MATERIAL TOUGHNESS VS. TEMPERATURE

MATERIAL
TOUGHNESS




NEUTRON-RADIATION-INDUCED TOUGHNESS CHANGES

MATERIAL
TOUGHNESS



MATERIAL
TOUGHNESS



II. DISCUSSIONS WITH INDUSTRY

DISCUSSIONS WITH INDUSTRY GROUPS

- MARCH 31, 1981, MEETING WITH PWR REGULATORY RESPONSE GROUPS
- APRIL 29, 1981, PROGRESS BRIEFING FROM PWR OWNERS GROUPS
- MAY 15, 1981, REPORTS FROM OWNERS GROUPS
- MAY 30, 1981, REPORTS FROM PWR LICENSEES
- JULY 28-30, 1981, MEETINGS WITH OWNERS GROUPS
- AUGUST 21, 1981, LETTERS TO 8 LICENSEES
- SCHEDULE FOR MEETINGS ON TECHNICAL ISSUES
 - W OWNERS GROUP - SEPTEMBER 18, 1981
 - B&W OWNERS GROUP - SEPTEMBER 22, 1981
 - CE OWNERS GROUP - OCTOBER 7, 1981

PRELIMINARY STAFF CONCLUSIONS PRESENTED TO OWNERS GROUPS

1. EFFORTS SHOULD CONTINUE TO REDUCE THE PROBABILITY AND SEVERITY OF OVERCOOLING TRANSIENTS
2. RELIANCE ON THE OPERATOR ACTION TO PREVENT REPRESSURIZATION IS NOT AN ACCEPTABLE LONG-TERM SOLUTION
3. A LIMIT SHOULD BE ESTABLISHED ON RT_{NDT} FOR CONTINUED OPERATION

INDUSTRY VIEWS -- B&W PLANTS

- BOUNDING TRANSIENT IS SMALL BREAK LOCA
- PRELIMINARY ANALYSIS USING REALISTIC ASSUMPTIONS SHOWED OCONEE-1
VESSEL COULD SUSTAIN THE SBLOCA AFTER 32 EFPY
- ANALYSIS ASSUMES OPERATOR ACTION TO PREVENT REPRESSURIZATION
- PLANT SPECIFIC ANALYSES PLANNED

OCONEE 1 - DECEMBER 31, 1981

RANCHO SECO - MARCH 1, 1982

OTHER PLANTS - LATER IN 1982

INDUSTRY VIEWS -- WESTINGHOUSE PLANTS

- BOUNDING TRANSIENT IS PLANT SPECIFIC (LARGE LOCA, SMALL LOCA OR STEAM LINE BREAK)
- ALL W PLANTS CAN SAFELY SUSTAIN SEVERE THERMAL SHOCK TRANSIENT, INCLUDING REPRESSURIZATION, TO BEYOND JANUARY 1983
- GENERIC ANALYSIS SCHEDULED FOR COMPLETION DECEMBER 31, 1981

INDUSTRY VIEWS -- CE PLANTS

- BOUNDING TRANSIENT IS A STEAM LINE BREAK
- MOST LIMITING PLANT CAN SAFELY SUSTAIN THE MOST SEVERE OVERCOOLING TRANSIENT FOR AN ADDITIONAL 5 EFPY
- ANALYSIS ASSUMES NO OPERATOR ACTION BEYOND THOSE PRESCRIBED BY PROCEDURES
- GENERIC ANALYSIS SCHEDULED FOR COMPLETION DECEMBER 31, 1981

Reference Temperature for the Reactor Vessels
Owned by the Eight Recipients of the Aug. 21, 1981
Letter on Pressurized Thermal Shock

Plant	NSSS Vendor	Vessel Fabricator	Reference Temperature, RTNDT, deg. F.	
			Cir. Welds	Long. Welds
Oconee 1	B&W	B&W	150	170
Three Mile Is. 1	B&W	B&W	180	160
Fort Calhoun	CE	CE	280	280
Maine Yankee	CE	CE	240	240
Calvert Cliffs 1	CE	CE	230	230
Robinson 2	West.	CE	290	290
San Onofre 1	West.	CE	270	270
Turkey Point 4	West.	B&W	290	Forgings

SUMMARY OF INFORMATION REQUESTED FROM 8 LICENSEES

60 Days

- RT_{NDT} VALUES OF THE CRITICAL WELDS AND PLATES
- RATE OF INCREASE OF RT_{NDT}
- APPROPRIATE LIMIT ON RT_{NDT} FOR CONTINUED OPERATION
- OPERATOR ACTIONS TO PREVENT PRESSURIZED THERMAL SHOCK

150 Days

- PLAN FOR RESOLVING THE ISSUE
- EVALUATION OF POSSIBLE CORRECTIVE ACTIONS
- IMPLEMENTATION SCHEDULES
- DETAILED INFORMATION FOR STAFF EVALUATIONS

III. RECENT INFORMATION

RECENT INFORMATION

- OCONEE-1 IN-SERVICE INSPECTION SHOWING INDICATIONS OF SMALL CRACKS UNDER THE CLADDING
- OVERCOOLING TRANSIENTS AT BORSSELE AND SAN ONOFRE
- SENSITIVITY CALCULATIONS BY STAFF
 - RANCHO SECO TRANSIENT AS A BENCHMARK
 - NOMINAL MATERIAL PROPERTIES
 - VERY CONSERVATIVE PARAMETERS AND MATERIAL PROPERTIES

LOVIISA 1 EXPERIENCE

- MONITORING PROGRAM SHOWED WELD EMBRITTLEMENT FASTER THAN EXPECTED
- RT_{NDT} INCREASED FROM 45°F TO 182°F
- 36 OUTER FUEL ELEMENTS WERE REPLACED BY DUMMY ELEMENTS
- NEUTRON FLUX AT VESSEL WALL REDUCED TO 1/3 ORIGINAL VALUE
- TEMPERATURE OF ECC WATER FROM HPI RAISED FROM 68°F TO 113-131°F

BORSELLE EVENT - MARCH 2, 1981

- 400 MWE, 2 LOOP, 2 S-G, KWU DESIGN
- DURING MAINTENANCE, SOME ELECTRICAL CONNECTIONS AFFECTING SECONDARY SAFETY VALVES WERE INTERCHANGED
- DURING STARTUP (NOT CRITICAL) OPERATOR TESTED POWER TO A PILOT VALVE, CAUSING S-G SAFETY VALVE TO OPEN
- VALVE DID NOT RECLOSE (APPARENT INDEPENDENT FAILURE)
- ONE S-G BOILED DRY, OPERATORS ISOLATED SECOND S-G, TURNED ON CHARGING PUMPS TO REGAIN PRESSURIZER LEVEL
- PRIMARY TEMPERATURE DECREASED FROM 446⁰F TO 284⁰F IN 20 MIN.
- PRIMARY PRESSURE DROPPED TO 2130 PSIG, THEN INCREASED TO 2350 PSIG BY CHARGING PUMPS

SAN ONOFRE FEEDWATER TRANSIENT - SPET. 3, 1981

- POWER SUPPLY FAILURE CAUSED PARTIAL CONTROL SYSTEM FAILURE
- OSCILLATIONS OBSERVED IN FLOW AND LEVEL OF STEAM GENERATORS
- OPERATORS TRIPPED THE REACTOR MANUALLY
- NATURAL CIRCULATION WAS ESTABLISHED IN ACCORDANCE WITH PROCEDURES
- AFTER 8 MINUTES SAFETY INJECTION OCCURRED DUE TO LOW PRESSURE
- OPERATORS IMPLEMENTED THE LOCA PROCEDURE UNTIL IT WAS ESTABLISHED THAT A LOCA HAD NOT OCCURRED
- COLD LEG TEMPERATURE DROPPED FROM 532°F TO 462°F IN 10 MINUTES
- NO DATA ON PRESSURE WAS RECORDED

IV. POSSIBLE REGULATORY LIMITS

POSSIBLE CORRECTIVE ACTIONS

1. REDUCE THE PROBABILITY OF OVERCOOLING TRANSIENTS
(E.G., MORE RELIABLE CONTROL SYSTEM)
2. REDUCE THE SEVERITY OF OVERCOOLING TRANSIENTS
(E.G., RAISE TEMPERATURE OF ECC WATER)
3. REDUCE THE LIKELIHOOD OF REPRESSURIZATION
(E.G., OPERATOR PROCEDURES OR CONTROL SYSTEM MODIFICATIONS)
4. MAINTAIN HIGH FRACTURE TOUGHNESS OF VESSEL
(E.G., REMOVE OUTER FUEL TO REDUCE FLUX AT VESSEL)
5. REGAIN FRACTURE TOUGHNESS OF VESSEL
(E.G., IN-PLACE ANNEALING)

WHAT SHOULD BE THE REGULATORY LIMIT?

WHAT SHOULD BE THE DESIGN BASIS TRANSIENTS?

IS RT_{NDT} THE PROPER CRITERION?

IF SO:

WHAT SHOULD BE THE LIMIT ON RT_{NDT} ?

WHAT SHOULD THE EVALUATION MODEL FOR CALCULATING RT_{NDT} ?

HOW SHOULD UNCERTAINTIES BE TREATED?

SHOULD ONE DIFFERENTIATE BETWEEN CIRCUMFERENTIAL AND LOGITUDINAL
WELDS?

RATE OF INCREASE OF RT_{NDT}

<u>PLANT</u>	<u>CURRENT RT_{NDT}</u>	<u>ADDITIONAL EFPY TO REACH $RT_{NDT} = 300^{\circ}F$</u>
FT. CALHOUN	280 ⁰ F	2.0 EFPY
ROBINSON 2	290 ⁰ F	1.4 EFPY
SAN ONOFRE 1	270 ⁰ F	2.7 EFPY
TURKEY POINT 4	280 ⁰ F	2.2 EFPY
MAINE YANKEE	240 ⁰ F	7.4 EFPY
CALVERT CLIFFS 1	230 ⁰ F	3.4 EFPY
TMI 1	160 ⁰ F	10.4 EFPY
OCONEE 1	170 ⁰ F	13.3 EFPY


NUMBER OF PLANTS WITH RT_{NDT} ABOVE 200°F

RANGE OF RT_{NDT} (°F)


	<u>200-220</u>	<u>220-240</u>	<u>240-260</u>	<u>260-280</u>	<u>280-300</u>
VESSELS HAVING LONGITUDINAL WELDS	2	2	1	1	2
VESSELS HAVING CIRCUMFERENTIAL WELDS	2	1	1	0	2

10 CFR 50 APPENDIX G PARAGRAPH IV

"REACTOR VESSELS FOR WHICH THE PREDICTED VALUE OF ADJUSTED
REFERENCE TEMPERATURE EXCEEDS 200°F SHALL BE DESIGNED TO PERMIT
A THERMAL ANNEALING TREATMENT TO RECOVER MATERIAL TOUGHNESS
PROPERTIES OF FERRITIC MATERIALS OF THE REACTOR VESSEL
BELTING."




EXAMPLE OF ANNEALING TO MEET RT_{NDT} LIMITS



EXAMPLE OF ANNEALING TO MEET RT_{NDT} LIMITS

FOLLOWED BY FUEL REMOVAL TO REDUCE FLUX BY FACTOR OF 3



V. STAFF CONCLUSIONS

STAFF CONCLUSIONS

- PRESSURIZED THERMAL SHOCK IS A SAFETY CONCERN FOR OLDER PWR VESSELS HAVING HIGH COPPER CONTENT MATERIAL.
- IMMEDIATE CORRECTIVE ACTION IS NOT NECESSARY, BUT SUBSTANTIAL WORK IS NEEDED BY THE INDUSTRY DURING COMING YEAR
- SOME CORRECTIVE ACTIONS WILL LIKELY BE REQUIRED FOR SOME PLANTS WITHIN A YEAR FROM NOW
- BASES FOR STAFF CONCLUSIONS THAT NO CORRECTIVE ACTIONS ARE REQUIRED NOW:
 - A) CHANCES OF A SEVERE OVERCOOLING TRANSIENT IN OLDER PWR PLANT DURING COMING YEAR IS ABOUT 1 IN 100
 - B) EVEN IF A TRANSIENT AS SEVERE AS RANCHO SECO WERE TO OCCUR, VESSEL FAILURE WOULD NOT BE PREDICTED USING NOMINAL MATERIAL PROPERTIES
 - C) ANALYSES INCLUDE A NUMBER OF CONSERVATISMS

STAFF ACTIONS

- INDEPENDENT ANALYSES OF TRANSIENTS, FLUENCE AND FRACTURE MECHANICS CALCULATIONS
- REVIEW LICENSEE ANALYSES
 - 60 DAY REPLIES
 - 150 DAY REPLIES
 - GENERIC REPORTS
- GENERIC RESOLUTION BY STAFF (DRAFT NUREG BY SUMMER 1982)
 - POSSIBLE OPERATOR GUIDELINES
 - POSSIBLE LIMITS ON RT_{NDT}

REFERENCE TEMPERATURE, RT_{NDT}
FOR PWR OPERATING PLANTS
AT VESSEL INSIDE SURFACE
AS OF MAY 1, 1981

DEFINITION:

RT_{NDT} = REFERENCE TEMPERATURE NIL-DUCTILITY TRANSITION

RT_{NDT} = INITIAL RT_{NDT} + ΔRT_{NDT}

INITIAL RT_{NDT} IS DETERMINED BY FOLLOWING ASME
CODE PROCEDURES, "NB-2331

ΔRT_{NDT} IS THE TEMPERATURE SHIFT IN THE CHARPY
TRANSITION CAUSED BY IRRADIATION. VALUES USED
IN THE ATTACHED TABLES ARE FROM REG. GUIDE 1.99,
REV. 1.

BABCOCK AND WILCOX PLANTS

Plant	Vessel Fabricator	Effective Full Power Years	Fluence Per EFY		Percent Copper		Reference Temperature, RTNDT Deg. Fahr.		
			Cir. Wlds	Long. Wlds	Cir. Wlds	Long. Wlds	Plate	Cir. Wlds	Long. Wlds
			$\times 10^{18}$ n/cm ²	$\times 10^{18}$ n/cm ²					
Oconee 1	B&W	4.89	0.54	0.46	0.26	0.31	150		170
Three Mile Is. 1	B&W	3.45	0.60	0.60	0.35	0.31	180		160
Rancho Seco	B&W	3.25	0.66	0.58	0.31	0.31	160		150
Arkansas 1	B&W	3.85	0.61	0.45	0.31	0.31	170		150
Crystal River 3	B&W	2.18	0.58	0.55	0.35	0.31	150		130
Oconee 2	B&W	4.26	0.61	Forgings	0.35	Forgings	200		Forgings
Oconee 3	B&W	4.3	0.61	Forgings	0.24	Forgings	140		Forgings
Davis Besse	B&W	1.26	0.66	Forgings	0.24	Forgings	60		Forgings

COMBUSTION ENGINEERING PLANTS

Plant	Vessel Fabricator	Effective Full Power Years	Fluence Per EFY		Percent Copper		Reference Temperature, RTNDT Deg. Fahr.		
			Cir. Welds	Long. Welds	Cir. Welds	Long. Welds	Plate	Cir. Welds	Long. Welds
			$\times 10^{18} \text{ n/cm}^2$	$\times 10^{18} \text{ n/cm}^2$					
Fort Calhoun	CE	4.76	1.72	1.72	0.35	0.35		280	280
Maine Yankee	CE	5.50	0.85	0.85	0.36	0.36		240	240
Calvert Cliffs 1	CE	4.10	1.47	1.47	0.30	0.30		230	230
Calvert Cliffs 2	CE	3.03	1.47	1.47	0.23	0.30		150	200
Palisades	CE	3.92	1.16	1.16	0.25	0.25		190	190
Millstone 2	CE	3.37	0.56	0.56	0.37	0.37		160	160
St. Lucie	CE	3.31	0.63	0.63	0.31	0.30		140	140
Arkansas 2	CE	0.69							

WESTINGHOUSE PLANTS

Page 1 of 2

Plant	Vessel Fabricator	Effective Full Power Years	Fluence Per EFPY		Percent Copper		Reference Temperature, RTNDT Deg. Fahr.		
			Cir. Welds	Long. Welds	Cir. Welds	Long. Welds	Plate	Cir. Welds	Long. Welds
			$\times 10^{18} \text{ n/cm}^2$	$\times 10^{18} \text{ n/cm}^2$					
Robinson 2	CE	6.80	1.72	1.59	0.34	0.34	290		290
San Onofre	CE	8.82	1.74	1.74	0.19	0.19	270		270
Haddam Neck	CE	10.42	1.31	1.09	0.22	0.22	230		220
Point Beach 1	B&W	7.69	1.24	0.91	0.24	0.24	220		210
Surry 2	B&W/RDM	4.34	1.56	0.34	0.19	0.31	140		110
Zion 2	B&W	4.16	0.63	0.20	0.26	0.35	120		100
Zion 1	B&W	4.32	0.63	0.20	0.35	0.31	170		90
Farley	CE	1.86	1.69	0.38	0.24	0.27	120		70
Surry 1	B&W	4.51	1.56	0.34	0.25	0.18	190		60
Beaver Valley	CE	1.33	1.69	0.25	0.37	0.36	160		60
Cook 1	CE	4.15	0.63	0.34	0.40	0.13	170		50
Cook 2	CB&I	2.00							
Sequoyah 1	RDM	0.20							
Yankee Rowe	B&W	14.14	0.78 Plate		0.20 Plate		200	No weld data	
Indian Point 2	CE	3.97	0.50 Plate		0.25 Plate		140	No weld data	

WESTINGHOUSE PLANTS

Plant	Vessel Fabricator	Effective Full Power Years	Fluence Per EFY		Percent Copper		Reference Temperature, RTNDT Deg. Fahr.		
			Cir.	Long.	Cir.	Long.	Plate	Cir. Welds	Long. Welds
			Welds	Welds	Welds	Welds			
			$\times 10^{18} \text{ n/cm}^2$	$\times 10^{18} \text{ n/cm}^2$					
Indian Point 3	CE	2.67	0.56	Plate	0.24	Plate	120	Plate is controlling	
Salem 1	CE	1.76	1.16	Plate	0.24	Plate	90	Plate is controlling	
Trojan	CB&I	2.57	0.69	Plate	0.15	Plate	60	Plate is controlling	
Turkey Point 3	B&W	5.67	1.97		0.31		290	Forgings	
Turkey Point 4	B&W	5.16	1.97		0.30		280	Forgings	
Point Beach 2	B&W/CE	6.96	1.24		0.25		240	Forgings	
Ginna	B&W	7.66	1.16		0.25		220	Forgings	
Kewaunee	CE	5.32	1.34		0.20		150	Forgings	
Prairie Is. 2	SFAC	5.11	1.34		0.19		140	Forgings	
Prairie Is. 1	SFAC	5.36	1.34		0.14		100	Forgings	
North Anna 1	RDM	1.90	1.78		0.14		110	Forgings	
North Anna 2	RDM	0.35	1.78		0.13		90	Forgings	

OAK RIDGE NATIONAL LABORATORY

OPERATED BY
UNION CARBIDE CORPORATION
NUCLEAR DIVISION



POST OFFICE BOX X
OAK RIDGE, TENNESSEE 37830

August 24, 1981

Mr. Warren Hazelton
Engineering Branch
Division of Operating Reactors
Mail Stop 440
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Hazelton:

I visited the Oconee nuclear reactor site on July 21-23, 1981 and again on August 10-12, 1981. The purpose of these two visits was to observe and evaluate the ten-year in-service ultrasonic inspection of the welds in the unit 1 reactor vessel. The pressurized-water reactor is owned and operated by the Duke Power Company. The in-service ultrasonic inspections were performed by Babcock and Wilcox (B&W) personnel. A preliminary meeting discussing these inspections was held in Bethesda on March 24, 1981. My comments on that meeting were presented to you in Letter No. 0401-16-81, dated April 1, 1981. The following is a summary of the two visits to Oconee.

On July 21-23, 1981, John Gleim, John Gleske, and I visited the Oconee reactor site. On the first day (July 21) we attended the radiation/safety course (7:00 am to 3:00 pm) and obtained body counts. On the second day (July 22) we picked up dosimeters and emergency kit and met with Nick Economos (NRC representative from Region II). A copy of the Babcock and Wilcox proposed ultrasonic test procedure and a copy of the published issue of the NRC Regulatory Guide 1.150 (June 1981) were made available by Mr. Economos. We reviewed these documents briefly and discussed their compatibility. An unofficial report was received about noon that water had leaked into the electronics of the B&W Automated Reactor Inspection System (ARIS) as it was lowered into the reactor vessel and that the system would require some repair. After lunch we suited up and went into the reactor to examine the scanning fixture and the inspection site. We found the ARIS fixture isolated with no one around to discuss its status. When we got out of containment (about 4:00 pm) we learned that the ARIS fixture had been more severely damaged than earlier estimated and that the repair would take about five days. A meeting was arranged with B&W personnel to

Mr. Warren Hazelton
Page Two
August 24, 1981

discuss the ultrasonic test procedure, but the meeting was not scheduled until 8:30 am the following day. We were allowed to make copies of the B&W test procedure (treating them as proprietary information). We each took a copy of the test procedure back to the motel and studied it individually for a couple of hours, then met during dinner to discuss the procedure as a group. This did not accomplish much because the procedure is written in general language and few details are given discussing how some of the steps are to be performed. In summary, one cannot determine merely by reading the test procedure whether or not the ultrasonic inspection of the welds in the reactor vessel will be performed in accordance with Regulatory Guide 1.150.

On Wednesday, July 23, we met with Jim Brackett (Duke Power) and Mike Hacker and Bert Chism (B&W) to discuss and clarify the ultrasonic test procedure, and the following is a summary of that discussion:

We learned that B&W planned to inspect the near-surface region using shear waves and a refracted angle of 70° . One-half-inch diameter transducers are used and they mount two transducers diagonally side by side to increase the area inspected on a single scan. The ARIS scanning arm has been modified to accommodate five transducers (it was originally designed to operate with three). The sensitivity of the 70° inspection was determined at the B&W laboratories using notches and side-drilled holes. We were told they planned to calibrate for the inspection using a T/4 hole (side-drilled hole located at a depth of one-fourth of the sample thickness). The sensitivity of the 70° inspection was established in the laboratory using corner notches. Since corner notches typically reflect more sound energy, the sensitivity to notches located in the center of the specimen would normally be reduced. No information was available as to how much the sensitivity would be reduced. This may be an item that needs to be investigated at our laboratory. Most of the remaining details discussed were routine and the general appearance was that the ultrasonic inspection would be carried out in accordance with Regulatory Guide 1.150. We left Coconee with plans to return and witness actual testing when the ARIS fixture was repaired.

On Monday, August 10, Nick Economos and I returned to the Coconee plant site. After completing the routine details of body counts, dosimeters, and security badges, we met with Jim Brackett, Mike Hacker, and Bob Micheleski (B&W) to discuss the status of testing to date. We learned that the inspection of the three beltline welds had been completed. On B&W inspection sequence number 4 approximately 16 indications were obtained from one of the beltline welds during the 70° inspection. Most of the indications occurred in a 60° segment on the circumference of the weld, and most occurred at the top of the

Mr. Warren Hazelton
Page Three
August 24, 1981

weld. Preliminary indications showed the depths of the indications to fall in the range of about 0.3 to 0.9 in. with lengths of 0.1 to 0.75 in. The amplitudes of the signals varied from 50 to 150% of the distance amplitude correction (DAC) curve. A couple of the signals were also observed at the 60° inspection angle. No other significant indications had been obtained. We learned that B&W planned to reinspect these indications for confirmation and to obtain additional measurements. We asked to be present during these reexaminations.

There is no good way to compare these data with previous baseline ultrasonic inspection results. The 70° refracted angle inspection has never been performed before and the baseline inspection was performed using contact ultrasonic techniques whereas the in-service inspection was performed using immersion techniques. (This seems to be typical of most reactor sites that I visit. The so-called baseline inspection is usually performed by a different method than the in-service inspection.)

Nick Economos and I spent the afternoon in the B&W trailer that houses the ultrasonic instrumentation, video displays, and computer control system for the ARIS test fixture. The trailer was located in the security area, but outside of containment. We observed the calibration of the ultrasonic test system and learned more about the test procedure.

The ultrasonic inspection was performed as follows: the ARIS system was calibrated manually. The calibration blocks were mounted on the ARIS fixture and were physically located in the reactor pool. The computer was used to place the transducers in the general vicinity of the calibration blocks, then the transducer arm was manipulated manually using push-button motorized controls to obtain peak signals from the reflectors in the calibration blocks. The scanning and detection portions of the inspection were performed automatically using computer control. A rectangular zig-zag scanning pattern (similar to a sewing machine pattern) was employed. The scanning pattern was performed in both transverse and longitudinal directions on each side of the weld. Scanning was performed at a gain 6 dB higher than the calibration setting. When indications were obtained the computer was stopped and the reflectors were evaluated manually by obtaining peak signals using the push-button motorized controls.

The calibration for the 70° inspection was performed in a manner slightly different from that discussed at our previous meeting on July 23. The beltline weld where the indications were obtained is approximately 9 in. thick. In this area the DAC curve was produced as follows: the reflected signal from a 0.2-in.-deep EDM (corner) notch located just below the cladding was adjusted to 80% full-scale height. A straight line was drawn from the left edge of the screen to this point. The signal from a T/4 hole (in the 9-in.-thick calibration block) occurred further in time and had an amplitude of about 40-50%.

Mr. Warren Hazelton

Page Four

August 24, 1981

A straight line was drawn from the 80% signal peak to this peak. The resulting lines produced the DAC curve. The signal from the 0.2-in.-deep notch and the T/4 hole were sharp and distinct and both had good signal-to-noise ratios.

The 0, 45, 60, and 70° (two transducers) inspections were performed simultaneously. The output signals from the 0, 45, 60, and one of the 70° transducers were fed to a Krautkramer KB-600 ultrasonic instrument and were displayed as four separate traces on a single oscilloscope. The fifth transducer (70° angle) was not displayed visually but was connected to an audible alarm module. A single audible alarm system was available for the four channels on the KB-6000 but it was continuously triggered by standing signals (multiples) that could not be eliminated, therefore it was disabled. To summarize: four transducers were displayed visually with no audible alarm and one transducer was connected to an audible alarm but was not displayed visually. During the performance of the ultrasonic examination one man monitored all five transducers and the technicians worked 12-h shifts. The technicians did not have to observe the oscilloscope continuously during the 12-h shifts but the time still seems a little long to me. This particular area (possible technician fatigue) is not covered in the Regulatory Guide.

On the following day we observed more testing and went into the containment area to observe the test fixture. (The ARIS system performs quite well when it is working.) Around 5:00 pm we learned that BSW planned to reinspect the 70° indications that night and we left word to call us at the motel. We received the call about 10:30 pm (does this sound familiar) and we were at the site by 11:30 pm.

The reinspection and evaluation process progressed rather slowly because of the additional requirements to evaluate each indication at 50 and 20% of DAC. The main reason for the increased inspection time, in my opinion, was not the requirement for additional data but was due to the fact that the technicians performing the evaluation were not familiar with 20% DAC or with the new Regulatory Guide. Also the data form had not been modified to have specific slots available to record the required information. The reinspection therefore was a training exercise as well as an evaluation process. Based on my observations for this inspection the evaluation time to obtain the additional data required by the new Regulatory Guide should increase the old evaluation time by a factor of 1.5 to 2.0 per indication. This should amount to roughly 30 min per indication at most. Compared to the overall inspection time (approximately 21 days) this is almost insignificant.

I requested and was allowed to observe the oscilloscope while one of the indications obtained at 70° was scanned in the normal manner. The indication on the screen was distinct and readily detectable but it only occurred on two or three scans and it could have easily been missed if the operator did not apply his full attention to the scope.

Mr. Warren Hazelton

Page Five


August 24, 1981

It is my opinion that individual audible alarms should be provided for each recorded channel during an ultrasonic inspection. The audible alarms are even more important when multiple channels are being observed simultaneously.

Compared with contemporary inspections that I have observed, the ultrasonic inspection of the welds in the unit 1 reactor vessel at Oconee were conducted in a competent manner. Test sensitivity and repeatability both appeared to be good. The addition of the 70° angle inspection provided coverage for the near-surface area and additional data required by the Regulatory Guide were recorded. I got the impression that B&W personnel were trying to follow the new Regulatory Guide and I know of no cases where they did not comply in the performance of the examination. The technicians could have been more familiar with the Regulatory Guide but competent personnel were on hand to direct them. I would suggest the use of individual audible alarms as well as video displays for each channel of data recorded but this is not required by either ASME Code or the Regulatory Guide. I will also mention that we were treated cordially by both Duke and B&W personnel. Our questions were answered and we were allowed to freely visit the inspection areas.

I am including a copy of the preliminary test results for inspection sequence number 4. No other significant indications were obtained during my visit.

Sincerely yours,



J. H. Smith
Nondestructive Testing Group
Metals and Ceramics Division

JHS:jlb

Enclosure

cc/enc: N. Economos, NRC
J. Gieske, Sandia
J. Gleim, NRC
A. R. Herdt, NRC
M. R. Hum, NRC
A. L. Lotts
R. W. McClung
G. M. Slaughter
J. H. Smith/File

FOR INFORMATION ONLY

Sub: Wilcox

EXAMINATION SUMMARY

SEQUENCE NO.: 4
FIGURE NO.: B/L.3

NUMBER OF RECORDABLE INDICATIONS			
0	45	60	70
9	0	3	16

NUMBER OF INDICATIONS EXCEEDING SECTION XI			
0	45	60	70
0	0	0	0

COMMENTS:

- ① All of the 0 degree indications are laminar reflectors of acceptable size.
- ② All of the 60 and 70 degree indications are reflectors of acceptable size.
- ③ No limited examination was encountered on this weld.

Preliminary

FIGURE NO: 61.13

SUR <i>a</i>	SUB <i>2a</i>	<i>l</i>	<i>a/l</i>	<i>a/t</i> %	ALLOWABLE <i>a/t</i> %	EXCEEDS SECTION 51		EXCEEDS NOMOGRAPH	
						YES	NO	YES	NO
00	<i>inverted near the hole</i>	.50	.448	.50	2.77		✓		✓
01		.375	1.492	.12	2.08		✓		✓
02		.375	.746	.25	2.08		✓		✓
000	.225	.597	.37	2.5	3.5		✓		✓
001	.15	.298	.25	0.83	3.7		✓		✓
002	.225	.298	.50	2.5	3.5		✓		✓
003	.10	.10	.50	0.55	6.5		✓		✓
004	.30	.298	.50	3.3	3.5		✓		✓
005	.15	.298	.25	0.83	3.7		✓		✓
006	.10	.10	.50	0.55	6.5		✓		✓
007	.225	.298	.50	2.5	3.5		✓		✓
008	.30	.30	.50	1.67	6.5		✓		✓
009	.10	.10	.50	1.1	6.5		✓		✓
010	.10	.10	.50	0.55	6.5		✓		✓
011	.187	1.64	.11	2.08	2.24		✓		✓
012	.225	.149	.50	2.5	3.5		✓		✓
013	.15	1.343	.11	1.66	2.24		✓		✓
014	.15	.298	.25	0.83	3.7		✓		✓
015	.15	.448	.16	0.83	2.76		✓		✓

*The above are preliminary results
pending final review.*

*M. J. Harker
Howard Stappelman*

FOR INFORMATION ONLY

Beck & Wilcox

EXAMINATION SUMMARY

SEQUENCE NO.: 4
FIGURE NO.: B1.1.3

NUMBER OF RECORDABLE INDICATIONS			
0	45	60	70
9	0	3	16

NUMBER OF INDICATIONS EXCEEDING SECTION XI			
0	45	60	70
0	0	0	0

COMMENTS:

- ① All of the 0 degree indications are laminar reflectors of acceptable size.
- ② All of the 60 and 70 degree indications are reflectors of acceptable size.
- ③ No limited examination was encountered on this weld.

FIGURE NO: 5/1.3

SUR Q	SUB 2Q	L	a/l	a/t %	ALLOWABLE a/t %	EXCEEDS SECTION 31		EXCEEDS NOMOGRAPH	
						YES	NO	YES	N.
0		.50	.448	.50	2.77	6.5	✓		✓
01		.375	1.492	.12	2.08	2.72	✓		✓
02		.375	.746	.25	2.08	3.7	✓		✓
00	.225	.597	.37	2.5	3.5		✓		✓
01	.15	.298	.25	0.83	3.7		✓		✓
02	.225	.298	.50	2.5	3.5		✓		✓
03	.10	.10	.50	0.55	6.5		✓		✓
04	.30	.298	.50	3.3	3.5		✓		✓
05	.15	.298	.25	0.83	3.7		✓		✓
06	.10	.10	.50	0.55	6.5		✓		✓
07	.225	.298	.50	2.5	3.5		✓		✓
08	.30	.30	.50	1.67	6.5		✓		✓
09	.10	.10	.50	1.1	6.5		✓		✓
10	.10	.10	.50	0.55	6.5		✓		✓
11	.187	1.64	.11	2.08	2.24		✓		✓
12	.225	.149	.50	2.5	3.5		✓		✓
13	.15	1.543	.11	1.66	2.24		✓		✓
14	.15	.298	.25	0.83	3.7		✓		✓
15	.15	.448	.16	0.83	2.76		✓		✓

The above are preliminary results
pending final review.

M. J. Nelson
Howard Stappelman

	%Cu	INITIAL RTNOT	FLUENCE WHERE CRACK INITIATION COULD OCCUR (10^{19} neut/cm ²)	CURRENT FLUENCE (neut/cm ²)	FLUENCE/EFPY (10^{19} neut/cm ²)	No. OF EFPY OF CONTINUED OPERATION	JOB #
EEL 1	.31	30	1.0×10^{19} .75 no arrest	0.225	0.046		4H138-4X
TMI 1	.31	30	1.0×10^{19} "	0.207	0.060		4H138-4X
RANCHO SECO	.31	30	1.0×10^{19} "	0.189	0.058		4H138-4X
ARKANSAS 1	.31	30	1.0×10^{19} "	0.173	0.045		4H138-4X
CRYSTAL RIVER 3	.31	30	1.0×10^{19} "	0.119	0.055		4H138-4X
OCONEE 2 * F	.35	30	1.8×10^{19} 1-1.25 a 5.5"	0.259	0.061		4G-44
OCONEE 3 * F	.24	30	2.2×10^{19} 1-0 a 3.5"	0.262	0.061		4G-45
DAVIS BESSE * F	.24	30	2.2×10^{19} 1-0 a 3.5"	0.083	0.066		4G-45
D KING FORGING S							

S.	OFRE	%Cu	IN. RINO	PLACE WHERE INITIATION COULD OCCUR (10 ¹⁹ neut/cm ²)	CURRENT FLUENCE (10 ¹⁹ neut/cm ²)	FLUENCE/EPHY (10 ¹⁹ neut/cm ²)	NO. OF EPHY OF CONTINUED OPERATION	J. 11
		.19	60	2.2 X 10 ¹⁹ .5-1.0 no arrest	1.535	0.174		4T-1V
ROBINSON 2		.34	0	1.7 X 10 ¹⁹ 1.0 no arrest	1.081	0.159		4U-1W
TURKEY PT. 3*		.31	0	2.9 X 10 ¹⁹ 1.0 a 4.5"	1.116	0.197		4R-1
POINT BEACH 1		.24	0	2.1 X 10 ¹⁹ .5-.75 no arrest	0.699	0.091		4L-4V
SURRY 1		.18	0	3.8 X 10 ¹⁹ .5-.75 no arrest	0.153	0.034		4M-4W
ELION 1		.31	30	1.0 X 10 ¹⁹ .75 no arrest	0.086	0.020		4O-4Y
IP-2		.25	60	1.3 X 10 ¹⁹ .5-1.0 no arrest	0.199	0.050		4R-4-7
YANKEE ROWE		.20	10	2.9 X 10 ¹⁹ .5-.75 no arrest	1.103	0.078		4T-45
RING FORGINGS + PLATE DATA								
mean K _{IC}								

[illegible]

PLANT	%Cu	IN. RING?	PLACE WHERE INITIATION COULD OCCUR (10^{19} neut/cm ²)	CURRENT FLUENCE (10^{19} neut/cm ²)	FLUENCE/EFPY (10^{19} neut/cm ²)	No. OF EFPY OF CONTINUED OPERATION	
SAN ONOFRE	.19	60	1.6×10^{14} .75-1.0 no arrest	1.535	0.174		✓ SF
ROBINSON 2	.34	0	0.9×10^{19} 1.0-1.25 no arrest	1.081	0.159		✓ SG
TURKEY PT. 3*	.31	0	1.70×10^{19} 1-1.25 a 3.25	1.116	0.197	1	✓ (X) SW
POINT BEACH I	.24	0	1.7×10^{12} .5-1.0 no arrest	0.699	0.091		✓ SI
SURRY 1	.18	0	3.0×10^{14} .5-1.0 no arrest	0.153	0.034		✓ SJ
ZION 1	.31	30	0.8×10^{19} .5-.75 no arrest	0.086	0.020		✓ SL
IP-2**	.25	60	0.9×10^{14} .75-1 no arrest	0.199	0.050		63 SM
YANKEE ROWE**	.20	10	2.2×10^{19} .5- a-3	1.103	0.078		7B SH
* RING FORGINGS							
** PLATE DATA							

Code Kic

PLANT	%Cu	INITIAL RTNOT	FLUENCE WHERE CRACK INITIATION COULD OCCUR (10^{19} neut/cm 2)	CURRENT FLUENCE (10^{19} neut/cm 2)	FLUENCE/EFPY (10^{19} neut/cm 2)	No. OF EFPY or CONTINUED OPERATIONS
* FT. CARBON	.35	30	$.6 \times 10^{19} .75$ $a .3.5$	0.819	0.172	7D SQ.
MAINE YANKEE	.36	10	$0.7 \times 10^{19} .75$ no arrest	0.468	0.085	7N SR
PALISADES	.25	0	$1.5 \times 10^{19} .5-.75$ $a .3.5"$	0.455	0.116	7V ST
CALVERT CLIFFS I	.30			0.603	0.147	
Code KTC						

PLANT	%Cu	INITIAL RTNOT	FLUENCE WHERE CRACK INITIATION COULD OCCUR (10^{19} neut/cm ²)	CURRENT FLUENCE (10^{19} neut/cm ²)	FLUENCE/ETPY (10^{19} neut/cm ²)	NO. OF ETPT OF CONTINUED OPERATION	JOB #
OCONEE 1	.31	30	0.8×10^{19} ^{0.5-1.0} no arrest	0.225	0.046		5149
TMI 1	.31	30	0.8×10^{19} "	0.207	0.060		5149
RANCHO SECO	.31	30	0.8×10^{19} "	0.189	0.058		5149
ARKANSAS 1	.31	30	0.8×10^{19} "	0.173	0.045		5149
CRYSTAL RIVER 3	.31	30	0.8×10^{19} "	0.119	0.055		5149
OCONEE 2 * F	.35	30	0.8×10^{19} ^{1.0} a 2.75	0.259	0.061		7550
OCONEE 3 * F	.24	30	1.7×10^{19} ^{1.5-1.5} a 1.75	0.262	0.061		5V
DAVIS BESSE * F	.24	30	1.7×10^{19}	0.083	0.066		5V
* RING FORGINGS							

Code KIC