

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9201200589 DDCI DATE: 82/01/18 NOTARIZED: NO DOCKET #:
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern California 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern California 05000362
 AUTH. NAME: BASKIN, K. P. AUTHOR AFFILIATION: Southern California Edison Co.
 RECIP. NAME: MIRAGLIA, F. RECIPIENT AFFILIATION: Licensing Branch 3

SUBJECT: Discusses NRCI concerns re effects of input voltage faults on plant protection sys matrix relay circuit. No effects described would prevent normal tripping action of sys under fault conditions.

DISTRIBUTION CODE: 3001S COPIES RECEIVED: LITR 1 ENCL 0 SIZE: 2
 TITLE: PSAR/FSAR AMDTS and Related Correspondence

NOTES: L Chandler: all FSAR & ER amends. 1 cy: J Hanchett (Region V). 05000361
 D Scaletti: 1 cy all enviro info.
 L Chandler: all FSAR & ER amends. 1 cy: J Hanchett (Region V). 05000362
 D Scaletti: 1 cy all enviro info.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES		
	ID CODE/NAME	LITR	ENCL		ID CODE/NAME	LITR	ENCL
ACTION:	A/D LICENSING	1		LICI BR #3 BCI	1		
	LICI BR #3 LIA	1		ROOD, H.	01		
INTERNAL:	ELD	1		IE	06	3	
	IE/DEP/EPOB 35	1		IE/DEP/EPLB 36	3	3	
	MPA	1		NRR/DE/CEB 11	1	1	
	NRR/DE/EQB 13	3		NRR/DE/GB 28	2	2	
	NRR/DE/HGB 30	2		NRR/DE/MEB 18	1	1	
	NRR/DE/MTEB 17	1		NRR/DE/QAB 21	1	1	
	NRR/DE/SAB 24	1		NRR/DE/SEB 25	1	1	
	NRR/DHFS/HFEB 40	1		NRR/DHFS/LQB 32	1	1	
	NRR/DHFS/OLB 34	1		NRR/DHFS/PTB 20	1	1	
	NRR/DSI/AEB 26	1		NRR/DSI/ASB 27	1	1	
	NRR/DSI/CPB 10	1		NRR/DSI/CSB 09	1	1	
	NRR/DSI/EITB 12	1		NRR/DSI/ICSB 16	1	1	
	NRR/DSI/PSB 19	1		NRR/DSI/RAB 22	1	1	
	NRR/DSI/RSB 23	1		NRR/DST/LGB 33	1	1	
	REG FILE	04	1				
	EXTERNAL:	ACRS 41	15	1	BNLICAMDTS ONLY	1	
		FEMA-REP DIV 39	1		LPDR 03	1	
NRCI POR 02		1		NSIC 05	1		
NTIS		1					

TOTAL NUMBER OF COPIES REQUIRED: LITR

64
 63 ENCL 5

Southern California Edison Company

SCE

P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

K. P. BASKIN
MANAGER OF NUCLEAR ENGINEERING,
SAFETY, AND LICENSING


January 18, 1982

TELEPHONE
(213) 572-1401

Director, Office of Nuclear Reactor Regulation
Attention: Mr. Frank Miraglia, Branch Chief
Licensing Branch No. 3
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station
Units 2 and 3



During recent telephone conversations between the NRC (Mr. R. Stevens) and SCE (Mr. F. R. Nandy), the NRC expressed concerns regarding the effects of input voltage faults on the Plant Protection System — (PPS) matrix relay circuit. Specifically the concern postulated the possibility of the PPS bistable relay contacts welding shut due to a surge or high voltage fault on the input of one of the matrix power supplies with one PPS channel in a bypassed condition, thereby rendering the PPS inoperable.

SCE's response to NRC question 032.11 discussed input surge and fault testing and referenced tests previously performed on the Arkansas Nuclear One - Unit 2 (ANO-2) (Docket 50-368) PPS matrix power supplies. Briefly, the PPS matrix is powered by two Power Mate PXS-B-12V power supplies which are paralleled using auctioneering diodes. During the following input surge and fault tests, the matrix circuit was simulated using load resistors:

1. With 120 volts AC on the AC input of one power supply, 140 volts DC was applied on the AC input of the other power supply for 30 seconds.
2. With 120 volts AC on the AC input of one power supply, 508 volts AC was applied on the AC input of the other power supply for 30 seconds.
3. With 120 volts AC on the AC inputs of both power supplies, surge wave form was applied to one power supply using common-mode configuration.
4. With 120 volts AC on the AC inputs of both power supplies, surge wave form was applied to one power supply using transverse-mode configuration.

The surge waveform used during the testing was in accordance with Section 2 of IEEE 472-1974 with amplitude reduced. The adequacy of this reduced amplitude surge was previously discussed in the response to NRC Question 032.32.

3001
s
1/0

8201200589 820118
PDR ADOCK 05000361
A PDR

The following were observed as a result of the input surge and fault testing which was performed:

1. There were no effects observed on the test load with either surge wave forms or with the 140 volt DC fault applied to the test circuit.
2. With the 508 volt AC fault applied to the test circuit, the wave form across the test lead was observed to be a spike train superimposed on the nominal 12 volt DC level. The peak amplitude of the spike train followed an exponential envelope which rushed to a maximum value of 41 volts DC and subsequently decayed to a steady state value of 12 volts DC.

Based upon the results summarized above as documented in the referenced test report, an analysis was performed to assess the effects of applying the surge and fault voltages to the PPS matrix circuit. The analysis was performed with 41 volts DC applied continuously to the matrix circuit to conservatively model the circuit under fault conditions. This configuration is considered conservative because the voltage applied to the circuit during the fault test was periodic with short duration spikes whose average values were approximately 15 volts DC. The analysis showed that with the higher DC voltages applied to the circuit, the current values in the circuit would increase proportionately due to the resistive nature of the load. The results of the analysis are available at the Combustion Engineering Offices in Windsor, Connecticut for inspection by the NRC.

This increase in the current level is below that which is required to weld the bistable relay contacts shut. The increase in the base current to the relay driver transistors would place these transistors well into saturation but the resulting load line would be well within the safe operating area specified for these transistors and consequently, they would not be expected to fail due to excessive thermal dissipation or secondary breakdown. The increase in current through the matrix relay coil windings may open circuit the windings if the fault is sustained for a long period of time.

In conclusion, none of the above stated effects would prevent normal tripping action of the PPS under fault conditions. The possible matrix relay coil failure would trip the circuit and is not detrimental to the normal operation of the PPS.

If you have any questions or comments concerning this information, please contact me.

Very truly yours,

VP Bushman