

Rulemaking1CEm Resource

From: RulemakingComments Resource
Sent: Wednesday, January 08, 2014 12:40 PM
To: Rulemaking1CEm Resource
Cc: RulemakingComments Resource
Subject: PR-51 Waste Confidence
Attachments: Comment of Carol Overland from Minnetonka Meeting.pdf

**DOCKETED BY USNRC—OFFICE OF THE SECRETARY
SECY-067**

PR#: PR-51
FRN#: 78FR56775
NRC DOCKET#: NRC-2012-0246
SECY DOCKET DATE: 12/20/13
TITLE: Waste Confidence—Continued Storage of Spent Nuclear Fuel
COMMENT#: 00902

Hearing Identifier: Secy_RuleMaking_comments_Public
Email Number: 947

Mail Envelope Properties (377CB97DD54F0F4FAAC7E9FD88BCA6D0014435D73752)

Subject: PR-51 Waste Confidence
Sent Date: 1/8/2014 12:40:21 PM
Received Date: 1/8/2014 12:40:25 PM
From: RulemakingComments Resource

Created By: RulemakingComments.Resource@nrc.gov

Recipients:

"RulemakingComments Resource" <RulemakingComments.Resource@nrc.gov>

Tracking Status: None

"Rulemaking1CEM Resource" <Rulemaking1CEM.Resource@nrc.gov>

Tracking Status: None

Post Office: HQCLSTR01.nrc.gov

Files	Size	Date & Time
MESSAGE	254	1/8/2014 12:40:25 PM
Comment of Carol Overland from Minnetonka Meeting.pdf		1756085

Options

Priority: Standard
Return Notification: No
Reply Requested: No
Sensitivity: Normal
Expiration Date:
Recipients Received:

Dates

Carol Overland
Legalelectric.org

CONF-950787-56

PNL-SA-25969

SPENT FUEL INTEGRITY DURING DRY STORAGE

DISCLAIMER

M. A. McKinnon

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

July 1995

Presented at the
Institute of Nuclear Materials Management 36th
Annual Meeting
July 9-12, 1995
Palm Desert, California

Prepared for
the U.S. Department of Energy
under Contract DE-AC06-76RLO 1830

Pacific Northwest Laboratory
Richland, Washington 99352

RECEIVED
AUG 29 1995
OSTI

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED DT

DISCLAIMER

**Portions of this document may be illegible
in electronic image products. Images are
produced from the best available original
document.**

SPENT FUEL INTEGRITY DURING DRY STORAGE

Mikal A. McKinnon

Pacific Northwest Laboratory
Richland, WA 99352 USA

ABSTRACT

Information on spent fuel integrity is of interest in evaluating the impact of long-term dry storage on the behavior of spent fuel rods. Spent fuel used during cask performance tests at the Idaho National Engineering Laboratory (INEL) offers significant opportunities for confirmation of the benign nature of long-term dry storage. The cask performance tests conducted at INEL included visual observation and ultrasonic examination of the condition of the cladding, fuel rods, and fuel assembly hardware before dry storage and consolidation of the fuel; and a qualitative determination of the effect of dry storage and fuel consolidation on fission gas release from the spent fuel rods. A variety of cover gases and cask orientations were used during the cask performance tests. Cover gases included vacuum, nitrogen, and helium. The nitrogen and helium backfills were sampled and analyzed to detect leaking spent fuel rods. At the conclusion of each performance test, periodic gas sampling was conducted on each cask as part of a surveillance and monitoring activity. Continued surveillance and monitoring activities are being conducted for intact fuel in a CASTOR V/21 cask and for consolidated fuel in a VSC-17 cask. The results of the gas sampling activities are reported in this paper.

INTRODUCTION

In response to the Nuclear Waste Policy Act of 1982 (NWPA), a Solicitation for Cooperative Agreement Proposal (SCAP) was issued in May 1983 by the DOE-Richland Operations Office (DOE-RL) to help the private sector with their spent fuel storage problems, and proposals were received in August 1983. Virginia Power (VP) proposed that pressurized water reactor (PWR) spent fuel storage cask performance testing be conducted at a federal site in support of its at-reactor license demonstration. VP and DOE signed a Cooperative Agreement in March 1984, and VP signed a separate agreement with the Electric Power Research Institute (EPRI), essentially establishing a three-party cooperative agreement.

The scope of the Cooperative Agreement included performance tests of three different metal storage casks loaded with unconsolidated spent nuclear fuel. The tests were conducted at INEL. After cask performance testing with unconsolidated fuel was completed in the VP/DOE cooperative program, a decision was made by DOE and EPRI to extend the performance testing to include consolidated fuel in the Transnuclear, Inc., TN-24P cask. Dry rod consolidation was conducted at INEL as a separate DOE-only funded program.

Prior to testing, the Surry PWR spent fuel assemblies used in the cask performance tests were characterized using in-basin ultrasonic examinations and video scans. Cask internal cover gas samples were taken during testing. After testing, selected fuel assemblies were videotaped and photographed. Then fuel assemblies used in the TN-24P and MC-10 cask performance tests, along with a few Turkey Point reactor spent fuel assemblies, were consolidated and loaded into the TN-24P cask for a DOE-funded performance test. Later, a cooperative agreement was established with Sierra Nuclear Corporation (SNC), and 17 of the consolidated fuel canisters from the TN-24P cask were used in a performance test of SNC's ventilated concrete cask.

Performance test runs involved a combination of cover gases and cask orientations. The backfill environments used were vacuum, nitrogen, and helium; nitrogen and helium were sampled and analyzed to detect leaking spent fuel rods. The integrity of the fuel assemblies was determined from cover gas sampling (Creer 1986; McKinnon 1986, 1987a, 1987b, 1989, 1992, 1993). At the conclusion of each performance test, periodic gas sampling was conducted on each cask as part of a cask surveillance and monitoring activity.

This report combines the gas sampling information from the cask performance tests and cask monitoring activities. It documents the condition of the fuel from the Surry reactor prior to testing and the effect of testing on fuel integrity as ascertained through gas sampling during cask performance tests at INEL using

(a) Performance test using consolidated fuel in the cask.

Visual, Video, and Photographic Examinations

The PWR fuel assemblies were examined visually to establish their general condition after shipment from VP, handling at the INEL hot shop, cask performance testing, and during consolidation. Similar exams were made of the Cooper BWR fuel during the REA 2023 performance tests at GE-Morris. Two kinds of visual examinations were used: black-and-white videos and color photography of selected fuel assemblies.

The black-and-white videos taken at GE-Morris, VP, and INEL did not provide sufficient detail to characterize the crud or very small features on the fuel rods. They did not reveal any indication of significant variations in the fuel rods after shipment, handling, and performance testing. The resolution of the videotapes did not provide enough information to adequately determine the integrity and condition of the fuel and fuel cladding. Examination of the video scans showed that all the fuel assemblies and fuel rods look basically the same when viewed from outside the assemblies. There was some discoloration of the fuel rod cladding in the area of the grid spacers, which was expected.

Color photographs showed that a typical orange/reddish crud (probably Fe_2O_3) was evenly deposited on all of the Zircaloy 2 cladding and fuel assembly hardware. There were no noticeable changes in the characteristics or adherence of the crud during handling operations involving the spent fuel assemblies at GE-Morris or INEL. Some scratches and worn spots were apparent on the spacer grids and some fuel rods, but these features did not change as a result of examination or handling operations. In general, the fuel rods were in excellent condition, with a very adherent crud layer.

Additional visual examinations of the fuel were conducted during the dry rod consolidation program. According to Vinjamuri (1988a, 1988b):

No noticeable cladding defects in the rod surfaces were observed for any of the fuel processed. The oxide layer on the surface of the fuel rods appears to be intact and firmly attached to the cladding. The oxide layer does not appear to be loose, thick, soft, or powdery. However, the oxide layer and some of the zirconium cladding was scraped from the rod surface by the spacer grids as the rod was pulled during fuel consolidation. Very little crud buildup on the surfaces of the rods was observed. The surfaces of the rods displayed only a thin

oxide layer, which had the appearance of surface discoloration rather than any rough or loose material. The rod surfaces are discolored near the spacer grids. The discoloration has an appearance of a dark mottling of the surface and is progressively more predominant from the middle of the rod length toward the rod bottom. The rods are generally clean, with limited amounts of clad discoloration and oxidation . . . The evidence of fuel rod growth since fabrication was visually obvious during the consolidation process.... Length variation between rods appears to be as much as 2 cm (0.8 inch). The rods that grew longer than others appeared to be randomly located within the fuel assembly.

CASK COVER GAS SAMPLING The cask cover gas was sampled several times during each cask performance test to evaluate the integrity of the spent fuel rods. Each sample was collected in a separate 500-cc stainless steel cylinder that had been leak-tested before sampling. Initially, during the CASTOR-V/21 cask performance test, the cylinders were equipped only with quick-disconnect fittings and no bellows-sealed valves as part of the closure. During the early sampling efforts with the CASTOR-V/21 cask, the cover gas samples in the cylinders were diluted with ambient air from the vicinity of the sampling apparatus, air that leaked into the cylinder during shipment, and argon introduced at Lawrence Livermore National Laboratory (LLNL). In many cases, this dilution was made more severe by the collection of small amounts of cask cover gas, presumably due to short equilibration times between the cask and the sample bottle during the actual cask cover gas collection procedure. The end effect of small, diluted samples on the cask cover gas analyses was to increase detection limits, increase measurement uncertainties, and introduce questions of sample validity. Once bellows-sealed valves were added to the sampling cylinders, the problem of air leakage into the sampling cylinders was eliminated.

Gas sample analysis included mass spectroscopy and radiochemical gamma analysis. Mass spectra were analyzed for all common fixed gases with masses less than 100 to verify the purity of backfill gas composition. Only N_2 , O_2 , He, Ar, and CO_2 concentrations above 0.01% are detected in any of the samples. The integrity of the fuel rods was assessed from the radionuclide concentration based on gamma spectroscopy.

However, the relatively low amounts of ^{85}Kr detected indicate that no leaking fuel rods were present in the GNS CASTOR-V/21 and MC-10 casks during performance testing with unconsolidated fuel and up to about a year after testing. At this time, gas sampling in these casks was discontinued. The final gas sample from the CASTOR-V/21 cask during this period was taken in December 1986. In September 1994, the CASTOR cask was opened and backfilled with a fresh charge of helium gas. The pre- and post-test backfills were checked for purity. Gas samples taken in March 1995, after six months of gas residence in the cask, did not contain detectable amounts of krypton-85, which indicates no leaks from fuel rods during that storage period. This is particularly significant, because the first few assemblies loaded in the CASTOR-V/21 cask were exposed to air for approximately 200 hours during incremental loading of the cask and fuel assembly/basket inspections at a reduced temperature. In addition, after testing was completed and long-term surveillance started, all the fuel assemblies were in a 70% He and 30% air environment for approximately four months, because a quick disconnect fitting on the CASTOR-V/21 cask lid had not sealed properly.

Two casks loaded with intact fuel have shown krypton gas concentrations indicative of a leaking fuel rod. During the performance test of the REA-2023 cask, krypton gas was detected after the cask was rotated from a vertical to a horizontal orientation. The accumulated amount of krypton gas released to the cask was consistent with the release from a single fuel rod (Barner 1985; Guenther 1988). The cladding defect was assumed to be very small since the release rate was essentially linear during 2.5 months of testing. There was no confirmation of a leaking fuel rod either by visual inspection or sipping of the fuel assemblies after the cask test. The gas analyses provided the only indication of a leaking fuel rod. The leaking fuel rod had no impact on the basin operation or handling of the fuel assemblies subsequent to the cask test.

The other cask loaded with intact fuel that showed krypton levels indicative of a leaking fuel rod was the TN-24P cask. In this performance test, the cumulative amount of ^{85}Kr detected just after the cask was rotated from a vertical to a horizontal orientation indicated that a fuel rod had leaked during this portion of the test. The decay in the leak rate, as indicated by subsequent gas samples, indicates that the leak was small. It took several days to vent the gas from the fuel rod.

In May 1987, 36 of the 48 intact fuel assemblies in the TN-24P and MC-10 casks, plus 12 intact

assemblies that had been in the Turkey Point Reactor, were consolidated into 24 consolidated fuel canisters as part of INEL's Dry Rod Consolidation Technology Project. The consolidated fuel canisters were then used in performance tests of the TN-24P and VSC-17 casks. During the fuel rod consolidation process, the exhaust gases from the consolidation area were monitored to detect the release of radioactive gases from the fuel that would indicate a cladding failure. In the consolidation reports (Vinjamuri 1988a, 1988b), one of the conclusions reached was that all fuel rods from the 48 assemblies were pulled and canisterized without rod failures.

Later, during the performance test of the TN-24P cask using consolidated fuel, ^{85}Kr was released to the cask. Based on a combination of ORIGEN2 predictions and experimental measurements (Barner 1985; Guenther 1988), it was estimated that four or more fuel rods may have developed leaks between the end of cask loading and the beginning of cask performance testing, three or more fuel rods during cask performance testing, and another five fuel rods in the six-month period following testing. The rate of ^{85}Kr release was observed to decrease with time from cask loading. Shortly after the last gas sample was taken from the fully loaded TN-24P cask, 17 canisters of consolidated fuel were removed from the TN-24P cask and loaded into the VSC-17 cask. The performance tests for the VSC-17 cask showed a nominal ^{85}Kr but not enough to indicate a new leaking fuel rod. Since the end of the VSC-17 performance testing in early 1991, until September 1994, the VSC-17 has been undisturbed. Recent gas samples, taken since September 1994, indicate that the atmosphere in the VSC-17 has not changed significantly. There has been a small amount of ^{85}Kr release, below the quantity expected for a single rod release, and there has been buildup of hydrogen in the cask. The amount of hydrogen is consistent with off-gassing of the RX277 neutron shield material in the lid. Similar amounts of hydrogen were observed during cask performance testing.

The amount of ^{85}Kr released during and after the TN-24P cask performance test with consolidated fuel is significantly higher than was released in previous cask testing with unconsolidated fuel. ~~Before this test, four cask performance tests of similar duration and scope had been performed; only two indications of ^{85}Kr release were observed.~~ The magnitude of the releases in the previous tests and surveillance periods indicated that each was limited to a single rod cladding breach. The previous tests involved about 16,700 spent fuel rods, whereas this test involved about 9800 rods. It is

hypothesized that the greater magnitude of ^{85}Kr released in this test and post-test surveillance is due to additional cladding leaks caused by enlargement of incipient cladding flaws during pulling and flexing of the fuel rods in the consolidation process. The enlarged cladding flaws, combined with cladding creep during cask testing and surveillance periods, allowed leak paths to develop. The leakage has not affected operations.

SUMMARY

Radiochemical gamma analysis of gas samples from cask performance tests and subsequent cask surveillance and monitoring activities provides an indication of spent fuel integrity during dry storage. The gas sampling analysis indicates that dry storage of spent fuel in an inert atmosphere is benign. In general, fuel handling activities have a more significant impact on fuel rods than does extended dry storage in an inert atmosphere.

REFERENCES

- Barner, J. O., 1985, *Characterization of LWR Spent Fuel MCC - Approved Testing Material - ATM-101*, PNL-5109, Pacific Northwest Laboratory, Richland, Washington.
- Creer, J. M., R. A. McCann, M. A. McKinnon, J. E. Tanner, E. R. Gilbert, R. L. Goodman, D. H. Schoonen, M. Jensen, C. Mullen, D. Dziadosz, and E. V. Moore, 1986, *CASTOR-V/21 PWR Spent Fuel Storage Cask Performance Testing and Analysis*, PNL-5917/EPRI NP-4887, Electric Power Research Institute, Palo Alto, California.
- Guenther, R. J., D. E. Blahnik, T. K. Campbell, U. P. Jenquin, J. E. Mendel, L. E. Thomas, and C. K. Thornhill, 1988, *Characterization of Spent Fuel Approved Testing Material--ATM-103*, PNL-5109-103, Pacific Northwest Laboratory, Richland, Washington.
- McKinnon, M. A., J. W. Doman, J. E. Tanner, R. J. Guenther, J. M. Creer and C. E. King, 1986, *Cask Handling Experience and Decay Heat, Heat Transfer, and Shielding Data*, PNL-5777 Vol. 1, Pacific Northwest Laboratory, Richland, Washington.
- McKinnon, M. A., J. M. Creer, T. E. Michener, J. E. Tanner, E. R. Gilbert, R. L. Goodman, D. H. Schoonen, M. Jensen, C. Mullen, D. Dziadosz, and E. V. Moore, 1987a, *TN-24P PWR Spent Fuel Storage Cask Performance Testing and Analysis*, PNL-6054/EPRI NP-5128, Electric Power Research Institute, Palo Alto, California.
- McKinnon, M. A., J. M. Creer, T. E. Michener, J. E. Tanner, E. R. Gilbert, R. L. Goodman, D. H. Schoonen, M. Jensen, C. Mullen, D. Dziadosz, and E. V. Moore, 1987b, *MC-10 PWR Spent Fuel Storage Cask Performance Testing and Analysis*, PNL-6139/EPRI NP-5268, Electric Power Research Institute, Palo Alto, California.
- McKinnon, M. A., T. E. Michener, M. F. Jensen, and G. R. Rodman, 1989, *Performance Testing and Analyses of the TN-24P PWR Spent-Fuel Dry Storage Cask Loaded with Consolidated Fuel*, PNL-6631/EPRI NP-6191, Electric Power Research Institute, Palo Alto, California.
- McKinnon, M. A., R. E. Dodge, R. C. Schmitt, L. E. Eslinger, and G. Dineen, 1992, *Performance Testing and Analyses of the VSC-17 Ventilated Concrete Cask Loaded with Consolidated Fuel*, EPRI TR-100305/PNL-7839, Electric Power Research Institute, Palo Alto, California.
- McKinnon, M. A., and V. A. Deloach, 1993, *Spent Nuclear Fuel Storage - Performance Tests and Demonstrations*, PNL-8451, Pacific Northwest Laboratory, Richland, Washington.
- Vinjamuri, K., E. M. Feldman, C. K. Mullen, A. E. Arave, B. L. Griebenow, J. H. Browder, P. E. Randolph, and W. J. Mings, 1988a, *Dry Rod Consolidation Technology Project Quick-Look Report*, EGG-WM-7852, EG&G Idaho, Idaho Falls, Idaho.
- Vinjamuri, K., E. M. Feldman, C. K. Mullen, B. L. Griebenow, A. E. Arave, and R. C. Hill, 1988b, *Dry Rod Consolidation Technology Project at the Idaho National Engineering Laboratory*, EGG-WM-8059, EG&G Idaho, Idaho Falls, Idaho.

ACKNOWLEDGMENT

This work was supported by the U.S. Department of Energy under Contract DE-AC06-76RLO 1830. Pacific Northwest Laboratory is operated by Battelle Memorial Institute.

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF NUCLEAR MATERIAL
SAFETY AND SAFEGUARDS
WASHINGTON, DC 20555-0001

April 18, 2013

NRC INFORMATION NOTICE 2013-07: PREMATURE DEGRADATION OF SPENT FUEL
STORAGE CASK STRUCTURES AND
COMPONENTS FROM ENVIRONMENTAL
MOISTURE

ADDRESSEES

All holders of, applicants for, and registered users of spent fuel storage system certificates of compliance (CoCs) as well as all holders of and applicants for an independent spent fuel storage installation (ISFSI) license under Title 10 of the *Code of Federal Regulations* (10 CFR) Part 72, "Licensing Requirements for the Independent Storage of Spent Nuclear Fuel, High-Level Radioactive Waste, and Reactor-Related Greater Than Class C Waste."

PURPOSE

The U.S. Nuclear Regulatory Commission (NRC) is issuing this information notice (IN) to inform addressees of recent operating experience on environmental moisture causing premature degradation of structures and components important to safety during spent nuclear fuel storage operations. The NRC expects recipients to review the information for applicability to their facilities and consider actions, as appropriate, to avoid similar problems. However, suggestions contained in this IN are not NRC requirements; therefore, no specific action or written response is required.

DESCRIPTION OF CIRCUMSTANCES

Peach Bottom Atomic Power Station ISFSI

On October 11, 2010, a cask seal pressure monitoring system low pressure alarm was received for Cask TN-68-01 during storage at the Peach Bottom Atomic Power Station ISFSI. Cask TN-68-01 is a bolted closure cask system with a double mechanical O-ring seal (cask lid seal) that provides confinement between the lid and cask interface. The cask had been in service at Peach Bottom since June 2000. Figure 1 shows a cross sectional view of the lid region for a TN-68 cask. A protective cover was installed on the lid region to protect the system from external weathering. During disassembly and removal of the protective cover, the licensee found streaks of rust on the underside of the cover, a pronounced pattern of rust directly under the access plate, and water or signs of moisture around most of the bolt lid holes and bolts. The licensee found the elastomer O-ring seal on the bottom of the protective cover to be completely intact and sealed against the top of the cask lid. After performing a sequence of helium leak tests, the licensee identified that the outer sealing surface of the main cask lid seal was leaking at a rate greater than allowed by the CoC technical specifications. The licensee returned the

ML12320A697

spent fuel assemblies to the spent fuel pool to perform additional inspections on the cask lid and seals. The initial evaluation revealed corrosion of the outer portion of the cask lid seal, lower than expected torque on some of the main lid bolts, and corrosion on the threads of the lid bolts. The inner portion of the cask lid seal remained intact; therefore, the cask's primary confinement was not compromised.

A root cause evaluation concluded that the seal leakage was caused by corrosion of the outer portion of the cask lid seal from water infiltration through the access plate in the protective cover. The water infiltration caused galvanic corrosion of the outer portion of the cask lid seal due to the presence of moisture at the interface of the aluminum-clad cask lid seal and the stainless steel clad cask body sealing surface. The presence of the moisture at the interface of the two dissimilar metals set up a galvanic cell that caused the aluminum to corrode and allowed helium to leak through the outer portion of the cask lid seal. The root cause evaluation further stated that the helium leak was attributed to inadequate sealing of the access plate in the protective cover and a lack of any verification of the integrity of the water-tight cover. The primary corrective actions developed by the cask vendor and the licensee involved improving the access plate design and developing a method for verifying protective cover seal integrity. Additional corrective actions, which were incorporated into operating procedures immediately after the event, included a change to the lid bolt torquing process and ensuring access plate gaskets and O-rings were inspected at installation.




Figure 1

Additional information is available in "Peach Bottom Atomic Power Station—NRC Inspection Report 05000277/12010010," dated July 8, 2011 (Agencywide Documents Access and Management System (ADAMS) Accession No. ML111890441).

Three Mile Island, Unit 2 ISFSI at the Idaho National Laboratory Site

The Three Mile Island, Unit 2 ISFSI uses NUHOMS-12T horizontal storage modules (HSMs). The HSMs were delivered to the Idaho National Laboratory site in 1999 as precast concrete

components. The storage system consists of an external rectangular reinforced concrete vault (i.e., HSM) with a storage canister resting horizontally on internal rails inside the HSM. The prefabricated modules consist of a body and a roof joined together by anchor bolts. All sections were a minimum of 0.6-meters (2-feet) thick. In 2000, the licensee noted cracks in the HSMs, and concluded they were cosmetic and insignificant. However, in 2007, the licensee observed continued cracking, crazing and spalling as well as increased efflorescence on the HSM surfaces. The efflorescence was a solid, whitish crystalline material which was determined through sampling and analysis to be calcium carbonate. The licensee performed an evaluation in 2007, during which it determined that the HSMs were capable of performing their design basic functions. In 2008, the licensee noted that 28 of the 30 HSMs had cracks, mostly emanating from the anchor bolt breakout holes with widths up to 0.95 centimeters (0.38 inches). At that time, the licensee determined that the HSMs appeared to be prematurely deteriorating and that continued crack growth could impact the ability of the HSMs to fulfill their originally planned 50-year design service life. Subsequent evaluations by the licensee initiated the development of an annual inspection plan for the HSMs and base mat as well as an examination of the inside of the HSMs. The evaluation also recommended that the licensee retain the services of a company experienced and qualified in testing and evaluating concrete to determine the degradation mechanism and make recommendations both for repairs and to prevent further degradation. Although the cracking was discussed with the storage system vendor, the licensee chose an independent vendor to perform an evaluation of the HSMs and base mat concrete in 2009. The evaluation included a field investigation and laboratory analysis to evaluate the concrete material quality, strength, and long-term durability potential. The conclusion reached was that water had entered the anchor bolt breakout holes on the roof of the HSMs. Subsequent freeze and thaw cycles initiated the crack formation. Repetition of the process resulted in both continued crack growth and the efflorescence growth identified in 2007. In addition to identifying the root cause of the cracking, the report also suggested repairs (injecting resin into the cracks), preventative actions (e.g., installing caps over the anchor bolt breakout holes), and monitoring (use of crack gauges). The licensee incorporated the suggested corrective actions.

Additional information is available in "Three Mile Island, Unit 2, ISFSI—NRC Inspection of the Independent Spent Fuel Storage Installation—Inspection Report 07200020/2012-001," dated August 14, 2012 (ADAMS Accession No. ML12228A457).

DISCUSSION

The instances described above illustrate how the intrusion of water can potentially decrease the effective life of both the structures and components of a spent fuel storage system. In one instance, the presence of water not only caused chemical degradation through oxidation of one metal, but it also facilitated the formation of a galvanic cell between two dissimilar metals that contributed to the degradation of the secondary confinement barrier of the storage system. In another instance, water contributed to an accelerated aging process of concrete structures of the spent fuel storage system. Water entered cracks and crevices around the anchor bolt breakout holes in the concrete structure, and when subjected to freezing temperatures, generated mechanical forces that produced cracks in the concrete. These cracks provided additional and larger pathways for water to enter the interior of the concrete which resulted in larger cracks from subsequent freezing temperatures and promoted efflorescence. If remedial actions had not been taken, this accelerated aging process could have inhibited the ability of the concrete structure to perform its design function of protecting the canister system containing the

radioactive material, as well as protecting personnel from ionizing radiation, during normal and accident conditions.

The effects of weathering and environmental moisture may lead to degradation of structures, systems, and components. Several phenomena are discussed in NUREG-1536, "Standard Review Plan for Spent Fuel Dry Storage Systems at a General License Facility," NUREG-1567, "Standard Review Plan for Spent Fuel Dry Storage Facilities," and Table D-1 of NUREG-1927, "Standard Review Plan for Renewal of Spent Fuel Dry-Cask Storage System Licenses and Certificates of Compliance" (ADAMS Accession Nos. ML101040620, ML003686776, and ML111020115, respectively). Identifying potential moisture entry points, such as cracks, crevices and joints in both vertical and horizontal storage systems, can facilitate the incorporation of gaskets and sealing materials into both the design of and maintenance of spent nuclear fuel storage systems to minimize premature degradation of structures and components important to safety. Adequate drainage of the base mat (i.e., ISESI pad) may also prove advantageous for the following reasons. First, pooled water may cause premature degradation of the base mat. Second, since humidity and deliquescence have been shown to contribute to stress corrosion cracking in marine environments (see Information Notice IN2012-20, ADAMS Accession Nos. ML12139A440), the combination of pooled water and heat from canisters containing irradiated spent nuclear fuel could produce humid conditions within the storage system.

These examples show the importance of periodically monitoring the physical condition of a spent nuclear fuel storage system. By obtaining baseline measurements and performing periodic evaluations, accelerated degradation can be detected before the structures and components of a storage system are unable to perform their intended function, and corrective actions can be implemented. Such information may prove useful in assessing aging management in license renewal applications.

CONTACT

This IN requires no specific action or written response. Please direct any questions about this matter to the technical contacts listed below or to the appropriate Spent Fuel Storage and Transportation (SFST) project manager.

/RA/

Mark Lombard, Director
Division of Spent Fuel Storage
and Transportation
Office of Nuclear Material Safety
and Safeguards

Technical Contacts: Chris Allen, NMSS/SFST
301-492-3148
E-mail: william.allen@nrc.gov

John Nicholson, R-I/DNMS
610-337-5236
E-mail: john.nicholson@nrc.gov

817-200-1549
E-mail: lee.brookhart@nrc.gov

Note: NRC generic communications may be found on the NRC public Web site, <http://www.nrc.gov>, under NRC Library.

CONTACT

This IN requires no specific action or written response. Please direct any questions about this matter to the technical contacts listed below or to the appropriate Spent Fuel Storage and Transportation (SFST) project manager.

/RA/

Mark Lombard, Director
Division of Spent Fuel Storage
and Transportation
Office of Nuclear Material Safety
and Safeguards

Technical Contacts: Chris Allen, NMSS/SFST
301-492-3148
E-mail: william.allen@nrc.gov

John Nicholson, R-I/DNMS
610-337-5236
E-mail: john.nicholson@nrc.gov

Lee Brookhart, R-IV/DNMS
817-200-1549
E-mail: lee.brookhart@nrc.gov

Note: NRC generic communications may be found on the NRC public Web site,
<http://www.nrc.gov>

ADAMS Accession No. **ML12220A607**

OFC:	SFST	Technical Editor	BC:RIV/NMSS/RSFS	BC:RI/NMSS/Dec
NAME:	WAllen	KAzariah-Kribbs via e-mail	BSpitzberg via e-mail	MFerdas via e-mail
DATE:	11/9/12	11/14/12	1/18/13	2/14/13
OFC:	BC:SFST/RIO	BC:SFST/LB	D:SFST	
NAME:	EBenner	MSampson	MLombard	
DATE:	3/4/13	3/22/13	4/10/13, 4/16/2013	

OFFICIAL RECORD COPY

ENTER

1. The contractor is to be responsible for the design, construction, and testing of the test cell.

2. The contractor is to be responsible for the design, construction, and testing of the test cell.

3. The contractor is to be responsible for the design, construction, and testing of the test cell.

4. The contractor is to be responsible for the design, construction, and testing of the test cell.

ENTER

Doc: 1005

October 12, 1973

1005
Doc

Please note that the experiences noted are with the consolidated canisters which are dimensionally a tighter fit than with normal spent fuel assemblies. D. L. Schmitt

1. The contractor is to be responsible for the design, construction, and testing of the test cell.

2. The contractor is to be responsible for the design, construction, and testing of the test cell.

3. The contractor is to be responsible for the design, construction, and testing of the test cell.

4. The contractor is to be responsible for the design, construction, and testing of the test cell.

5. The contractor is to be responsible for the design, construction, and testing of the test cell.

1005
Doc

1005
Doc

1005
Doc

1005-12

2-17 and
to the DOE account

same with
the 7-24 in
said report
of delays were
for
in 34

to projections
in the transform
ation
action
to form as

7

THE UNIVERSITY OF CHICAGO

25

On October 7, 1987, with further review of the lift test results, it was determined that the need for a new load cell in accordance with the instructions contained in the "Rigging Manual." Discussion with Westinghouse Electric Company's suppliers of the fixture confirmed that the fixture serial number was based on a 4000-lb design load. Subsequently, the fixture was load tested to 6000 lb in conformance with the requirement of IEEE Std Test Code that a 4000-lb lift could be performed.

DISCOVERED BY THE FBI PERSONNEL; IS USUALLY A REPORTED CANDIDATE IN
THE ELECTIONS. THE FBI HAS BEEN ADVISED THAT THE INFORMATION IS
CONFIDENTIAL.

[illegible][illegible]

1. 1990年12月25日，在“九七”香港回归前夕，香港各界人士纷纷发表文章，就香港前途问题提出自己的看法。其中，香港各界人士对香港前途的展望，以及对香港回归后的信心，成为当时舆论的焦点。

The equipment is being used at the cost of its life, nevertheless, it is more the inability to replace the equipment than the lack of funds which has caused the situation.

Secretary Kelly has been informed by the Department of Defense that the Navy will be providing the equipment for the next year.

[illegible]

	7-21-69	CARRIER	BORGES
	RECEIVED	MAY 20 1969	EFT-8, 1128
A1		12	2180
A2		21	3020
A4		18	3020
A5		24	3250
A6		9	3002
B1		10	3010
B2		13	3331
B3		18	3110*
B5		17	3350
B6		9	3030
C1		11	3020
C2		15	3028
C3		6	3049
C6		2	3090
D1		13	3230
D3		4	3050**
D5		23	3350
D5		3	3060

After each run the wire was heated approximately 7 inches, pull force started to increase until the maximum force of 4000 was reached.

The container number 4 was used as a spare for container 13.



Idaho Civilian Record
Idaho County
Idaho State
Idaho State

OPTIONAL: 500
OPERATIONS.

30

the following
regarding the
cask pressure

Order of 15

PLEASE RECALL
VSC-17 CASE
FROM THE IN

increased

canisters &
\$2.95.00
rest of line

Four sides.

can not be
so detestable
if not fear

35

2



Acc: J. G. Green, MS 9109
E. Ellinger, MS 9109
W. A. Frank, MS 9206
L. O. Frank, MS 9940
R. C. Frank, MS 9900
R. C. Schmidt, MS 9900
Central files

[illegible]

THE
JOURNAL OF THE
ROYAL ANTHROPOLOGICAL INSTITUTE

EVALUATION OF OPTIONS, ASSOCIATED RISKS, AND RECOMMENDATIONS FOR:
(A) THE STUCK-FUEL CANISTER IN THE TN-28 CASK, (B) RELATED CASK MOVE
OPERATIONS, AND (C) RESOLUTION OF PLUT-77 PRESSURE BEHAVIOR. AEC-111-50

Chlorine

The following provides an assessment of options, costs, and recommendations regarding the 1980-1 fuel assembly, related cask operations, and the VSC-17 cask pressure indicator.

Review of Stock Field Activity Logs

please recall that during transfer of fuel from the N-24 cask to the VSC-1 cask, computerized canister number 1 was withdrawn about 12 inches from the N-24 basket at which time the 4,000 lb lifting limit of the lifting fixture and the canister lifting tray was reached. Subsequently, the canister was returned to its rated position and in alternation, canister #2 was withdrawn from the VSC-1. The lifting limit had been increased from the 4,000 lbs of previous operations to 6,000 lbs to overcome the difficulty encountered and was subsequently increased in the amount of 4,000 lbs. After 14 years of routine maintenance, the increase to 4,000 lbs lifting limit was derived during this redesign and load test of the lifting fixture of 6,000 lbs and the load test of the canister at 4,000 lbs.

[illegible]

canisters?

SECRET

This activity currently ongoing as of 11/9/92.

2000

2000
 2001
 2002
 2003
 2004
 2005
 2006
 2007
 2008
 2009
 2010
 2011
 2012
 2013
 2014
 2015
 2016
 2017
 2018
 2019
 2020
 2021
 2022
 2023
 2024
 2025
 2026
 2027
 2028
 2029
 2030

[illegible]

Costs for Addis

One possibility is simply to apply the same rule to the stock be incurred.

of the same
Rigging Manual
Engineering to
at the same
conservation

1500 25th Ave
Albany, N.Y. 12206
Tel: 518/534-1111

A second part, assuming that the place of the more common VSC-T and III

Additionaly,
be completed

ADOLPH
12202 OF 12202
Another issue

be installed, estimate to find fact that if installing and procedural the

include a letter on bottling),
issue of 1944.

[illegible]

五、

may be irreversible, it is also possible that cancer number 10 is no longer a direct because of formal collecting of the data for following the recent and treatment in the VSC in case of 17 lung cancers.

Costs for additional employees and operations for the Stock Assembly

One possibility for removing critical number 18 from the T-28P task is simply to assign more life. The major risk is that the assembly might become stuck in a partially withdrawn position or that cylinder damage might be incurred. To assist applying more life involves reanalyzing the design of the cylinder and obtaining position exceptions to exceed 600. Holding and timing manual test/cycling. This risk is analyzed in Exhibit of [redacted] concerning to analyze the [redacted] and cylinder design and determine [redacted].

Secondly, to remove the risk of cylinder. The alternative includes conservatism based on the uncertainty involved and, unfortunately, there is no assurance of a result. The CTR has independently prepared an assessment of the task and believes that the estimate from engineering is about a factor of two too large. Accordingly, [redacted] is expected to be more realistic. Cost could be less if a "dead end" is encountered early.

Second part of the problem would involve the N-2AP. One solution would be to attempt success in extracting the N-2AP. One solution would be to place it in the T-2AP where the catalyst ports are dimensionally replaced (more accurately). This requires a number of operations: removal of the VSC-17 and TN-2AP lids, removal of a catalyst from the VSC-17 and placement in the TN-2AP, removal of catalyst 18 from the TN-2AP and placement in the VSC-17, removal of 165, 166 and backfill of both vessels, and etc. Additionally, partial lifts of the other six catalysts in the TN-2AP would be completed to assure removability. Our estimate for these operations is about 1000 hours.

FILE # 100-114674-219

Anchor 1333 is the hot shop inventory (or request) for the permanent 165 to be installed on the TR-29 when it is returned to the hot line time-schedule. Estimate to price the permanent 161 on the TR-29 is \$200, which includes the fact that 14 placement fixtures need to be designed and fabricated, special shielding and/or remote handling capabilities are required, and numerous procedural changes are necessary [please recall that the permanent 165 include a thin inner lid where shielding is inadequate for personnel to work on bolting].

SECRET

The final issue is the unusual positive behavior observed in the V8-17 cars, particularly during the initial starting and early test runs. The issues includes your request to evaluate the possibility of laboratory scale testing to reproduce the cause of the pressure behavior. It is the project's

2000

laboratory testing for the evaluation of the data acceptable for testing. Obtaining data on the evaluation is not possible without the help and efforts of the end users. Your consideration of the accordingly are requested.

CC-BY-NC-SA

The
inches
the
ently.
had been
overcome
val) of
increase
nd load
canister
on all
the
mechanisms
stability
casket
into the
isters

Number 18 is no longer following the removal and

Stick Assembly

The TN-24P cask is the assembly might at canister damage might reanalyzing the design. extend DOE Housing and an estimate of the cost design and determine. Unfortunately, there independently prepared an from Engineering is is expected to be more encountered early.

to with the canister One solution would be the dimensionally relaxed items: removal of the the VSC-17 and placement IP and placement in the of both casks, and etc. ers in the TN-24P would for these operations is

that the permanent lids we had this time. Our which includes the and fabricated, special required, and numerous the permanent lids site for personnel to work

23 served in the VSC-17 only test runs. The ility of laboratory seals for it is the project's

M. J. Fink
November 28, 1990
RCS-11-190
Page 4

VSC-17 Pressure Behavior The project recommends no-action regarding laboratory testing for evaluating the VSC-17 cask pressure behavior unless the evaluation of the data obtained during testing of the VSC-17 cask proves unacceptable for identifying the observed behavior. Since we are still obtaining data as of November 28, 1990, a completion schedule for the evaluation is not projected at this time. The evaluation includes the efforts of DOE and others not in the project.

Your consideration of the above recommendations and your directions accordingly are requested.

Sincerely,

R. C. Schmitt
R. C. Schmitt, Manager
Cask Transport and Testing Project

cc: D. Nixon, DOE-10, MS 1110
DOE Project Engineer

UNION
EDITION
12

Nov
UNION

U. S.
Docur
Wash

Gen

THIN
1992
diac
The

Nine
prop

STATE

Dur
Sept
Ident
Poll
10 C

Tech
proc
cover
of Re
Item
equa
Depa
Conf
requ

CON
and
Joch
This

9211230
PDR AT