

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | S | C | H | B | R | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
 01 | L | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 1 | 7 | 1 | 1 | 1 | 2 | 7 | 9 | 8 | 1 | 2 | 1 | 2 | 7 | 9 | 9
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 | On November 12, 1979, a review of maintenance trouble tickets by Plant QA Personnel
 03 | revealed that on July 31, 1979, with the plant at 100% power, a Safeguard Test Switch
 04 | had been replaced in "B" train without an approved Operating Work Procedure. This
 05 | resulted in unknowingly defeating the "B" Steam Line High Delta P SI input to "B"
 06 | Safeguard Train for 1½ hours resulting in operation in a reduced degree of redundancy.
 07 | This is reportable under Section 6.9.2.b.3 of the Technical Specifications. "A"
 08 | Safeguard Train was fully operational during the event so there was no threat to the
 7 8 9 health and welfare of the public.

09 | S | H | 11 | D | 12 | Z | 13 | I | N | S | T | R | U | 14 | S | 15 | Z | 16 |
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 17 | 7 | 9 | 0 | 4 | 2 | 0 | 3 | L | 0 |
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
 A | 18 | G | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | Y | 23 | Y | 24 | N | 25 | R | 1 | 3 | 9 | 26
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 | The cause of this event was that the defective Safeguard Test Switch was found while
 11 | performing the monthly Periodic Test on Safeguards. A trouble ticket was initiated
 12 | and the repair made immediately. Operating and Maintenance personnel were working
 13 | closely together and the need for an Operating Work Procedure (OWP) was not
 14 | recognized. An OWP is being implemented to control future maintenance of this type.
 7 8 9

15 | E | 28 | 1 | 0 | 0 | 29 | NA | A | 31 | Plant QA Review
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
 16 | Z | 33 | Z | 34 | NA | NA | NA |
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
 17 | 0 | 0 | 0 | 37 | Z | 38 | NA |
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
 18 | 0 | 0 | 0 | 40 | NA |
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 PERSONNEL INJURIES NUMBER DESCRIPTION
 19 | Z | 42 | NA |
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
 20 | N | 44 | NA |
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARER R. B. Starkey, Jr. PHONE: (803) 383-4524
 7912140451 NRC USE ONLY
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32