

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

5PO 817-826

SUPPLEMENTARY INFORMATION FOR REPORTABLE OCCURRENCE 80-05

I. Cause Description and Analysis

During cold shutdown on 3/20/80 at 0615 hours, component cooling water containment isolation valve 626, reactor coolant pump thermal barrier outlet, failed to close while performing periodic test CPL-PT-42.0. This event is contrary to Technical Specification 3.6.3 and is reportable pursuant to Technical Specification 6.9.2.b.(2). At no time was there any threat to public health or safety due to the event. The failure of the valve to close was attributed to the loosening of the operator locknut, allowing the operator shaft to rotate freely and unattached to the valve stem. Valve CCW-626 is one of the containment isolation valves required to close as part of phase B containment isolation.

II. Corrective Action

The locknut was tightened and staked and the valve was operated electrically and returned to service on 3/22/80 at 0280 hours.

III. Corrective Action to Prevent Further Occurrences

Various Limitorque SMB valve operators had maintenance performed on them during the cycle VI-VII refueling outage as follow-up to IE Circular 79-04. The operator-to-valve stem locknut for valve 626 was staked on 5/7/79. The locknut backed over the stake resulting in the failure of the valve to close. The locknut was staked again and the repair is considered adequate.

As additional action, a representative sample of the total locknuts staked during the 1979 refueling outage will be checked to verify similar problems are not occurring on the other valve operators. Additional corrective action will then be taken if the results of these inspections indicate it is necessary. These inspections and any required corrective action will be completed prior to the end of the 1980 refueling outage.