

Letter to N. C. Moseley from Carolina Power and Light Company dated February 26, 1975.

DISTRIBUTION:

50-261

H. D. Thornburg, IE

IE:HQS (5)

Office of Standards Development

Central Files

Division of Reactor Licensing (13)

PDR

Local PDR

NSIC

TIC

STATE

AO
(4)

✓



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANTS
Post Office Box 790
Hartsville, South Carolina

February 26, 1975

Robinson File No. 2-0-4-a-1

Mr. Norman C. Moseley, Director
Directorate of Regulatory Operations
U. S. Nuclear Regulatory Commission
Region II, Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

Mr. Donald Knuth, Director
Directorate of Regulatory Operations
U. S. Nuclear Regulatory Commission
Washington, D. C. 20545

Dear Sirs:


In accordance with Section 6.6.2 of the Technical Specification the following abnormal occurrence is reported.

At 0853, February 25, 1975, Boric Acid Pump "B", which was recirculating the Boron Injection Tank with Boric Acid Tank "B", was noted to have "off" indication at the RTGB. This was due to activation of the high temperature cutout switch. The pump was known to be running at 0844. Boric Acid Pump "A" had been running, also, during this time and was thus proven operable. The pump was disassembled and inspected, and no problem could be identified. The pump was reinstalled and returned to service at 1632.

At 0758, February 26, 1975, while the same pump was recirculating Boric Acid Tank "B", it was again deenergized by the high temperature cutout switch. Boric Acid Pump "A" was operating at this time. Investigation is in progress on the cause of this failure.

These pump failures constitute an Abnormal Occurrence as defined in Technical Specification 1.8.d and were reported to Mr. Neal Bender of DRU on site on February 25 and 26, 1975.

Yours very truly,


Jack B. McGirt, Manager
H. B. Robinson SEG Plant

ACT:gg

Recd Via Facsimile
2/26/75 3:05 PM TML