

H. B. ROBINSON STEAM ELECTRIC PLANT  
Post Office Box 790  
Hartsville, South Carolina 29550

November 23, 1977

Robinson File No. 2-0-4-a-1

261

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II, Suite 1217  
230 Peachtree Street, N.W.  
Atlanta, Georgia 30303

Dr. Ernst Volgenau, Director  
U. S. Nuclear Regulatory Commission  
Directorate of Regulatory Operations  
Washington, D. C. 20555


Dear Sirs:

In accordance with Section 6.9.2.a.2 of the Technical Specifications, the following Reportable Occurrence is submitted:

On November 23, 1977 while heating the primary system from cold shutdown conditions to hot shutdown, it was discovered that the breakers for all safety injection pumps and containment spray pumps were racked out. This disabled the above pumps. Primary temperature was 320° F at the point of discovery. The limiting condition for operation as stated in Technical Specification Sections 3.3.1.3 and 3.3.2.3 were not satisfied.

The breakers were promptly racked-in and the pumps returned to service. This was reported to Mr. Harold Banks of Carolina Power and Light Company and Mr. Darrell Hinkley on November 23, 1977.

Very truly yours,



R. B. Starkey, Jr., Manager  
H. B. Robinson SEG Plant

RHC/ld

cc: H. R. Banks