

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9310210196 DOC. DATE: 93/10/15 NOTARIZED: NO DOCKET #
FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light Co 05000261
AUTH. NAME AUTHOR AFFILIATION
PEARSON, M.P. Carolina Power & Light Co.
RECIP. NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Submits rept re inservice insp steam generator tube plug on
931005. No mechanical damage or degradation of tube
detected.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-1 LA	1 0	PD2-1 PD	1 1
MOZAFARI, B	2 2		
INTERNAL: AEOD/DSP/ROAB	1 1	NRR/DE/EMEB	1 1
NRR/EMCB	1 1	NUDOCS-ABSTRACT	1 1
OC/LFDCB	1 0	OGC/HDS2	1 0
<u>REG FILE</u> 01	1 1	RES/DSIR/EIB	1 1
EXTERNAL: EG&G BROWN, B	1 1	EG&G RANSOME, C	1 1
NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL 13 0



Carolina Power & Light Company
Robinson Nuclear Plant
PO Box 790
Hartsville SC 29550

October 15, 1993

Robinson File No.: 13510, 3005

Serial: RNP/93-2601

United States Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
INSERVICE INSPECTION: STEAM GENERATOR TUBE PLUG

Gentlemen:

In accordance with Technical Specification 4.2.1.3-1, Carolina Power and Light Company hereby provides this report concerning Steam Generator Tube Plugging:

Steam Generator Inspection Date: October 5, 1993

Number of Tubes Plugged: One

Location: "A" Steam Generator, Row 2, Column 6

Reason for Plug:

During Steam Generator Inservice Inspection conducted as required by Technical Specification 4.2.1.1.1, the Eddy Current probe could not pass through the tube in the U-bend region. Review of the September, 1984, baseline data revealed an area of blockage in the tube, existing from original manufacturer which prevented the probe from passing through the tube. No mechanical damage or degradation of the tube was detected. The tube was plugged as a precautionary measure only.

210048

9310210196 931015
PDR ADOCK 05000261
Q PDR


Highway 151 and SC 23 Hartsville SC

A047
110

October 15, 1993

Should you have any questions regarding this matter, please contact Mr. D. B. Waters at (803) 383-1802.

Very truly yours,



Marc P. Pearson
General Manager

RDC:lst

c: Mr. S. D. Ebnetter
Mr. W. T. Orders
INPO