

# ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9307220251 DOC. DATE: 93/07/14 NOTARIZED: NO DOCKET #  
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261  
 AUTH. NAME AUTHOR AFFILIATION  
 BAUR, D.H. Carolina Power & Light Co.  
 FLANAGAN, W.J. Carolina Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 93-004-00: on 930512, while operating at 100% power, primary plant leakage rate increased to 11.2 gpm & unusual event declared. Due to vibration, causing valve setpoint adjustment to change. Lock nuts tightened. W/930714 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

## NOTES:

RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
	LTTR	ENCL		LTTR	ENCL
PD2-1 LA	1	1	PD2-1 PD	1	1
MOZAFARI, B	1	1			
INTERNAL: ACNW	2	2	AEOD/DOA	1	1
AEOD/DSP/TPAB	1	1	AEOD/ROAB/DSP	2	2
NRR/DE/EELB	1	1	NRR/DE/EMEB	1	1
NRR/DORS/OEAB	1	1	NRR/DRCH/HHFB	1	1
NRR/DRCH/HICB	1	1	NRR/DRCH/HOLB	1	1
NRR/DRIL/RPEB	1	1	NRR/DRSS/PRPB	2	2
NRR/DSSA/SPLB	1	1	NRR/DSSA/SRXB	1	1
REG FILE 02	1	1	RES/DSIR/EIB	1	1
RGN2 FILE 01	1	1			
EXTERNAL: EG&G BRYCE, J.H	2	2	L ST LOBBY WARD	1	1
NRC PDR	1	1	NSIC MURPHY, G.A	1	1
NSIC POORE, W.	1	1	NUDOCS FULL TXT	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 30 ENCL 30



Carolina Power & Light Company

ROBINSON NUCLEAR PLANT  
POST OFFICE BOX 790  
HARTSVILLE, SOUTH CAROLINA 29550

JUL 14 1993

Robinson File No: 13510C

Serial: RNP/93-1584

United States Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
LICENSEE EVENT REPORT NO. 93-004-00

Gentlemen:

The enclosed Licensee Event Report (LER), is submitted in accordance with 10CFR50.73 and NUREG 1022 including Supplements No. 1 and 2.

Very truly yours,

W. J. Flanagan, Jr.  
Acting Plant General Manager  
Robinson Nuclear Plant

DHB:lst

Enclosure

cc: Mr. S. D. Ebnetter  
Mr. W. T. Orders  
INPO

9307220251 930714  
PDR ADOCK 05000261  
S PDR

IF 22  
11

NRC FORM 366  
(5-92)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104  
EXPIRES 5/31/95

## LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2

DOCKET NUMBER (2)  
05000 261PAGE (3)  
1 OF 4

TITLE (4)

## Unusual Event Caused By Reactor Coolant System Leakage

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
05	12	93	93	-- 004 --	00	07	14	93	FACILITY NAME	DOCKET NUMBER 05000
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)							
N			20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)	
POWER LEVEL (10)			20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)	
100			20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		X OTHER	
			20.405(a)(1)(iii)		50.73(a)(2)(i)		50.73(a)(2)(viii)(A)		(Specify in Abstract below and in Text, NRC Form 366A)	
			20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)			
			20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)			

## LICENSEE CONTACT FOR THIS LER (12)

NAME  
David H. Baur - Regulatory ComplianceTELEPHONE NUMBER (Include Area Code)  
(803) 383-1296

## COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
X	CB	RV	C710	Y					

## SUPPLEMENTAL REPORT EXPECTED (14)

YES  
(If yes, complete EXPECTED SUBMISSION DATE).

X NO

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

## ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

This is a voluntary LER and is being submitted to follow-up on Emergency Notifications made to the NRC Operations Center on May 12, 1993.

At approximately 1725 hours on May 12, 1993, with the H. B. Robinson Unit No. 2<sup>1</sup> operating at 100 percent power, the unit entered AOP-016, Excessive Primary Plant Leakage, and a 12-hour to hot shutdown Limiting Condition for Operation (LC0) required by Technical Specifications. The actual leakage rate at 1725 hours was 3.6 gallons per minute (gpm) and at 1812 hours on May 12, 1993, had increased to 11.2 gpm, which required declaration of an Unusual Event due to leakage greater than 10 gpm. At 2113 hours, the leakage was identified as coming from a positive displacement Charging Pump Suction Relief Valve. With the Charging Pump isolated, RCS leakage decreased to less than 1 gpm. The leakage through the 3/4-inch Crosby JRAK-B Relief Valve has been attributed to vibration causing the valve setpoint adjustment to change. Corrective actions will provide additional guidance for tightening the adjusting bolt lock nut.

<sup>1</sup>H. B. Robinson Unit No. 2 is a Pressurized Water Reactor in commercial operation since March, 1971.

NRC FORM 366A  
(5-92)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104  
EXPIRES 5/31/95

## LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
H. B. Robinson Steam Electric Plant, Unit No. 2	05000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 4
		93	-- 004 --	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

I. DESCRIPTION OF EVENT

At approximately 1725 hours on May 12, 1993, with the H. B. Robinson Unit No. 2 operating at 100 percent power, the unit entered AOP-016, Excessive Primary Plant Leakage, and a 12-hour to hot shutdown LCO required by Technical Specifications 3.1.5.1 due to leakage greater than 1 gallon per minute (gpm) with source unknown. The actual leakage rate at 1725 hours was 3.6 gpm and at 1812 hours on May 12, 1993, had increased to 11.2 gpm, which required declaration of an Unusual Event due to leakage greater than 10 gpm. The Emergency Response Organization was contacted and the Technical Support Center (TSC) was activated at 1958 hours on May 12, 1993. The leakage was identified as going to the No. 1 Sump Tank in the Auxiliary Building, but the actual source was unknown. Sections of systems were systematically isolated to identify the source of the leak. At 2113 hours, the leakage was identified as coming from a positive displacement Charging Pump Suction Relief Valve. With the Charging Pump isolated, RCS leakage decreased to less than 1 gpm. The Unusual Event was terminated and the TSC deactivated at 2236 hours on May 12, 1993. The Robinson Plant continued to operate at 100 percent power through the emergency.

II. CAUSE OF EVENT

The cause of the Unusual Event is the Charging Pump Relief Valve lifted at about ten (10) pounds and allowed Volume Control Tank (VCT) water to flow to the No. 1 Sump Tank.

The leakage through the Relief Valve has been attributed to Charging Pump induced vibration causing the adjusting bolt lock nut, and subsequently, the adjusting bolt, to back off allowing the valve setpoint to drift to a setpoint of zero (0) to ten (10) pounds per square inch (psi) while the normal setpoint is 76 ± 2 psi. The relief valve in question is a 3/4-inch Crosby JRAK-B Valve.

NRC FORM 366A  
(5-92)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104  
EXPIRES 5/31/95

## LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
H. B. Robinson Steam Electric Plant, Unit No. 2	05000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 4
		93	-- 004 --	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

## III. ANALYSIS OF EVENT

This is a voluntary LER and is being submitted to follow-up on Emergency Notifications made to the NRC Operations Center on May 12, 1993.

There have been no recorded past failures of this type in these relief valves in this application either at H. B. Robinson or at other Pressurized Water Reactors plants.

The Robinson Plant design is such that there was more than sufficient makeup capability to ensure that a loss of Reactor Coolant inventory would not occur at the leakage rate present. However, because the leak originated at one of the Charging Pumps and was directed to the No. 1 Sump, totally outside the Containment Vessel, a measurable release did occur. However, the release was less than 1 mrem for whole body and child thyroid at the site boundary and at no time was the health and safety of the general public in jeopardy.

A contributing factor to the valve failure could have been that the lock nut may not have been tight enough. Plant Corrective Maintenance Procedures did not provide a torque value for this lock nut. However, it could not be determined whether the lock nut had been tightened sufficiently and vendor maintenance procedures provide no specific guidance beyond obtaining metal to metal contact.

## IV. CORRECTIVE ACTIONS

The relief valve was removed from the system and tested to determine the as-found setpoint. The valve was disassembled and inspected and parts were repaired or replaced as necessary. The valve was reassembled and satisfactorily tested. The valve was reinstalled in the system and the charging pump returned to service.

Due to the relatively high vibration inherent to positive displacement, Charging Pumps Procedure, CM-102, Nozzle Relief Valve Maintenance, will be revised to provide additional guidance for tightening the adjusting bolt lock nut for valves in this application to prevent recurrence of this event. The method of capture will be applied to Valves CVC-2080, CVC-2081, and CVC-2082 prior to the end of Refueling Outage No. 15.

NRC FORM 366A  
(5-92)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104  
EXPIRES 5/31/95

## LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
H. B. Robinson Steam Electric Plant, Unit No. 2	05000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 4
		93	-- 004 --	00	

TEXT (If more space is required, use additional copies of NRC Form 366A)

V. ADDITIONAL INFORMATION

1. Failed Component Identification  
Relief Valve - 3/4-inch Crosby JRAK-B Valve
2. Previous Similar Events  
None