

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9503210150 DOC. DATE: 95/03/16 NOTARIZED: NO DOCKET # 05000261
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light Co
 AUTH. NAME AUTHOR AFFILIATION
 JURY, K.R. Carolina Power & Light Co.
 YOUNG, D.E. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 95-001-00: on 950214, SI sys was declared inoperable to perform scheduled operations surveillance test. Caused by SI sys configuration required for check valve testing. Review of test configurations has been initiated. W/950316 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-1 PD	1 1	MOZAFARI, B	1 1
INTERNAL: AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	1 1
FILE CENTER 02	1 1	NRR/DE/ECGB	1 1
NRR/DE/EELB	1 1	NRR/DE/EMEB	1 1
NRR/DISP/PIPB	1 1	NRR/DOPS/OECB	1 1
NRR/DRCH/HHFB	1 1	NRR/DRCH/HICB	1 1
NRR/DRCH/HOLB	1 1	NRR/DRSS/PRPB	2 2
NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL: L ST LOBBY WARD	1 1	LITCO BRYCE, J H	2 2
NOAC MURPHY, G.A	1 1	NOAC POORE, W.	1 1
NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 27 ENCL 27

Ady

P
R
I
C
R
I
T
Y

1

C
C
U
M
E
N
T



10 CFR 50.73

Carolina Power & Light Company
Robinson Nuclear Plant
3581 West Entrance Road
Hartsville SC 29550

Robinson File No.: 13510C
Serial: RNP-RA/95-0030

MAR 16 1995

United States Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
LICENSEE EVENT REPORT NO. 95-001-00

Gentlemen:

The enclosed Licensee Event Report (LER), is submitted in accordance with 10 CFR 50.73.

Very truly yours,

D. E. Young
Plant General Manager

RDC:rdc
Enclosure

c: Mr. S. D. Ebner, Regional Administrator, USNRC, Region II
Ms. B. L. Mozafari, USNRC Project Manager, HBRSEP
Mr. W. T. Orders, USNRC Senior Resident Inspector, HBRSEP

210097

9503210150 950316
PDR ADOCK 05000261
S PDR

Highway 151 and SC 23 Hartsville SC

NRC FORM 366 (5-92)			U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95				
LICENSEE EVENT REPORT (LER)										
FACILITY NAME (1) H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2						DOCKET NUMBER (2) 050-261		PAGE (3) 1 OF 3		
TITLE (4) SAFETY INJECTION PUMP TESTING REQUIRES TS 3.0 ENTRY										
EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
02	14	95	95	-- 001 --	00	03	16	95	FACILITY NAME	05000
OPERATING MODE (9) N			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)							
POWER LEVEL (10) 100			20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)	
			20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)	
			20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		OTHER	
			20.405(a)(1)(iii)		X 50.73(a)(2)(i)		50.73(a)(2)(viii)(A)		(Specify in Abstract below and in Text, NRC Form 366A)	
			20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)			
			20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)			
LICENSEE CONTACT FOR THIS LER (12)										
NAME K. R. Jury: Manager - Licensing/Regulatory Programs								TELEPHONE NUMBER (Include Area Code) (803) 857-1363		
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
SUPPLEMENTAL REPORT EXPECTED (14)										
YES (If yes, complete EXPECTED SUBMISSION DATE).					X NO		EXPECTED SUBMISSION DATE (15)		MONTH	DAY
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)										
<p>On February 14, 1994, with H. B. Robinson Steam Electric Plant (HBRSEP), Unit No. 2 operating at 100 percent power, the Safety Injection (SI) system was declared inoperable to perform a scheduled Operations Surveillance Test (OST) procedure. To accomplish a portion of the test, SI flow must be directed through the SI test line, which is not normally aligned for flow. Although specific confirming calculations have not been completed, this testing apparently places the SI system in a configuration where adequate flow to the reactor core cannot be assured during all design bases accidents. Since there are no Technical Specifications (TS) provisions for this test configuration, conducting this portion of the test places the system in a condition prohibited by the TS. Accordingly, TS Section 3.0, which requires that the unit be placed in hot shutdown within eight hours and in cold shutdown within the next thirty hours, was entered on three occasions between February 14, and 17, 1994, when the SI system was declared inoperable to accommodate this testing.</p> <p>A review of the test configuration has been initiated to determine if the SI system is operable in this configuration. Whether the check valve testing frequency can be changed to allow testing on a Cold Shutdown interval is under investigation.</p> <p>This report is submitted in accordance with 10 CFR 50.73(a)(2)(i)(B) as a condition prohibited by TS.</p>										

NRC FORM 366A
(5-92)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104
EXPIRES 5/31/95

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2	050-261	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 3
		95	001	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

I. DESCRIPTION OF EVENT

On February 14, 1994, H. B. Robinson Steam Electric Plant (HBRSEP), Unit No. 2 was operating at 100 percent power. At 0144 hours, the Safety Injection system (EIS Code: BQ) was declared inoperable to perform portions of the scheduled Operations Surveillance Test (OST) procedure OST-151, "Safety Injection (SI) System Component Test." This test, which is performed in accordance with Section XI of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel (B&PV) Code, and to satisfy the requirements Technical Specifications (TS) Section 4.0.1.a, is conducted on a quarterly basis to assure SI system components are capable of performing their required functions. This OST includes forward flow testing of valves SI-879A, B, and C (i.e., SI pump discharge check valves), and SI-839 (i.e., SI test line check valve) (EIS Code: V). To accomplish this portion of the test, SI flow must be directed to the Refueling Water Storage Tank (RWST) (EIS Code: TK) through the SI test line, which is not normally aligned for flow. Although specific confirming calculations have not been completed, with flow aligned to the RWST to perform check valve testing, the SI system is apparently in a configuration where adequate flow to the reactor core cannot be assured during all design bases accidents. Since there are no TS provisions for this test configuration, conducting this portion of the test places the system in a condition prohibited by the TS. Accordingly, TS Section 3.0, which requires that the unit be placed in hot shutdown within eight hours and in cold shutdown within the next thirty hours, was entered on three occasions between February 14, and 17, 1994, when the SI system was declared inoperable to accommodate this testing.

II. CAUSE OF EVENT

This condition is caused by an SI system configuration that is required for check valve testing, but results in the possibility for inadequate flow to the reactor core during a design basis accident.

Previous interpretations of TS assumed the requirement to test the SI system allowed the actions necessary to perform the required surveillance testing. Re-interpretation of these TS requirements and the testing configuration has resulted in the conclusion that the affects of this testing on overall system operability must be addressed as part of routine surveillance testing. As a result, a condition prohibited by TS was determined to exist while the system flowpath was aligned to accomplish the required check valve testing.

NRC FORM 366A
(5-92)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104
EXPIRES 5/31/95LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2	050-261	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 3
		95	001	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

III. ANALYSIS OF EVENT

With flow aligned to the RWST to perform check valve testing, the SI system is potentially in a configuration where adequate flow to the reactor core cannot be assured during all design bases accidents. However, a continuous action step is provided within Procedure OST-151, directing the operator to take immediate action to isolate this flowpath if an SI actuation occurs while the system is out of its normal alignment. Although credit cannot be taken for the pump being tested, based on engineering judgement, adequate flow to the core would exist with an operable SI pump when the other pump is in the test configuration, if the pump being tested operates as designed upon receipt of an SI signal. Therefore, the safety significance of this configuration is considered to be minimal.

Since the SI system configuration that is established for required check valve testing does not have an action required by TS, this configuration is considered a condition prohibited by the TS; therefore, this report is submitted in accordance with 10 CFR 50.73(a)(2)(i)(B).

IV. CORRECTIVE ACTIONS

A review of the test configuration has been initiated to determine if the SI system is operable in this configuration.

Whether the check valve testing frequency can be changed under the applicable ASME B&PV Code requirements to allow testing on a Cold Shutdown interval is under investigation.

V. ADDITIONAL INFORMATION

A. Failed Component Information

None

B. Previous Similar Events

LER 94-018