

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912130586 DOC. DATE: 79/11/02 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261
 50-324 Brunswick Steam Electric Plant, Unit 2, Carolina Power 05000324
 50-325 Brunswick Steam Electric Plant, Unit 1, Carolina Power 05000325
 AUTH. NAME: AUTHOR AFFILIATION
 CHIANGI, N. J. Carolina Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director

SUBJECT: Notifies NRC that final rept re deficiencies in the procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads will be completed on 791231. Delays caused by extensive rework.

DISTRIBUTION CODE: B019B COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTT ENCL	RECIPIENT ID CODE/NAME	COPIES LTTT ENCL
ACTION:	14 PM J. NEIGHBORS, 1	1	15 BC ORB #1, ORB #3	1
	20 LA P. KREUTZER, 1	1	21 AD D. EISENHUT, 1	1
	ORB #3		B. GRIMES	
INTERNAL:	01 REG FILE	1	02 NRC PDR	1
	05 I&E	2	07 EDO & STAFF	1
	08 MPA	1	09 DEPY DIR DPM	1
	10 QAB	1	11 STANDRDS DEV	1
	12 JORDAN, E/IE	1	13 FIELD COOR/IE	1
	16 AD FOR ENGR	1	17 AD PLANT SYS	1
	17 AD REAC SFTY	1	22 DIR DPM	1
	23 OELD	1	AD/SITE TECH	1
	DIRECTOR DSE	1	GEOSCIENCES BR	1
	I&C SYS BR	1	MATL ENG BR	1
	MECH ENG BR	1	POWER SYS BR	1
	S HANAUER	1	STRUCT ENG BR	1
EXTERNAL:	03 LPDR	1	04 NSIC	1
	24 ACRS	16		1

Ltr

MOORE

EPB # 2 BC

DEC 17 1979 P. LEECH

EPB # 2 LA

TOTAL NUMBER OF COPIES REQUIRED: LTTT

55
47

ENCL

0
47

ma
cup



Carolina Power & Light Company

November 2, 1979

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest
Atlanta, Georgia 30303

NOV 7 1979 8:55

DEFICIENCIES IN THE PROCUREMENT, FABRICATION, AND INSPECTION
OF ENGINEERED PLATES FOR CONCRETE EMBEDMENT AND SUPPORT OF
SAFETY-RELATED LOADS

Dear Mr. O'Reilly:

In accordance with 10CFR50.55(e), the Region II office (Mr. J. Bryant) was officially notified of the subject deficiency as being a "potentially reportable" item on July 6, 1979. On August 6, 1979, the Region II office (Mr. R. Bradley) was officially notified that the subject deficiency was considered reportable under the provisions of 10CFR50.55(e). On September 5, 1979, CP&L provided you with an interim report on the subject deficiency indicating that the final report will be submitted by November 2, 1979. The intent of this letter is to inform you that the final report will not be submitted by the previously indicated November 2, 1979 date because all corrective action has not been completed due to the extensive nature of the rework and the extreme caution being applied to the rework because of the critical nature of the plates. The current status of corrective action on the subject deficiency is as follows:

- a) Evaluation/resolution of individual engineered plates embedded in concrete continues by the Architect Engineer (Ebasco).
- b) Final resolution requires any corrective action required and revision of all affected drawings.
- c) A number of plates (approximately 65) remain on QA hold pending repair and/or NDT examination. To date repair and inspection has been performed on over 150 plates.
- d) Corrective action to minimize chances of recurrence has been implemented.

At this time we cannot determine a final completion date for corrective action. It is estimated that all corrective action will be completed on or about

7912130586


8019
SE
1/0

790297

December 31, 1979. Upon completion of corrective action, the final report will be submitted. We will routinely keep you appraised of our progress during your site inspection visits.

If you have any questions regarding this matter, please do not hesitate to contact me.

Yours very truly,



N. J. Chiangi - Manager
Engineering & Construction
Quality Assurance

KVH/bd (427/517)

cc: Mr. V. Stello (2)