

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9205210003 DOC. DATE: 92/05/11 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
 AUTH. NAME AUTHOR AFFILIATION
 CHAMBERS, R.H. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Submits SG tube plugging rept conducted during inservice
 insp on 920428. One tube plugged in Steam Generator A, Row 1,
 Column 29 based on failure of probe to pass through tube at
 sixth hot leg tube support plate.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	PD2-1 LA	1	0	PD2-1 PD	1	1
	LO, R	2	2			
INTERNAL:	NRR/DET/ECMB 9H	1	1	NRR/DET/EMEB 7E	1	1
	NUDOCS-ABSTRACT	1	1	OC/LFMB	1	0
	OGC/HDS2	1	0	<u>REG FILE</u> 01	1	1
	RES MILLMAN, G	1	1	RES/DSIR/EIB	1	1
EXTERNAL:	EG&G BROWN, B	1	1	EG&G RANSOME, C	1	1
	NRC PDR	1	1	NSIC	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL ~~13~~ 0

R
I
D
S
/
A
D
S
/
A
D
D
S

MA-4
dhp



Carolina Power & Light Company

ROBINSON NUCLEAR PROJECT DEPARTMENT
POST OFFICE BOX 790
HARTSVILLE, SOUTH CAROLINA 29550

MAY 11 1992

Robinson File No.: 13510
3005

Serial: RNPDP/92-1374

United States Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
INSERVICE INSPECTION: STEAM GENERATOR TUBE PLUG

Gentlemen:

In accordance with Technical Specification 4.2.1.3-1, Carolina Power and Light Company hereby provides this report concerning Steam Generator Tube Plugging.

Steam Generator Inspection Date: April 28, 1992

Number of Tubes Plugged: One

Location: "A" Steam Generator, Row 1, Column 29

Reason for Plug:

During Steam Generator Inservice Inspection conducted as required by Technical Specification 4.2.1.1.1, the Eddy Current probe could not pass through the tube at the 6th hot leg tube support plate. Review of the September, 1984 baseline data revealed an indentation in the tube, existing from original manufacturer, which prevented the probe from passing through the tube. No mechanical damage or degradation of the tube was detected. The tube was plugged as a precautionary measure only.

9205210003 920511
PDR ADDCK 05000261
Q PDR

A047
110

Letter to U. S. Nuclear Regulatory Commssion

Serial: RNPD/92-1374

Page 2

Should you have any questions regarding this matter, please contact
Mr. J. L. Harrison at (803) 383-1433.

Very truly yours,



R. H. Chambers
General Manager

Robinson Nuclear Project Department

RDC:sgk

cc: S. D. Ebnetter
L. W. Garner
INPO