

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8011170444 DOC.DATE: 80/11/13 NOTARIZED: NO DOCKET #
 FACIL:50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Ligh 05000261
 AUTH.NAME AUTHOR AFFILIATION
 STARKEY,R.B. Carolina Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Region 2, Atlanta, Office of the Director

SUBJECT: LER 80-026/01T-0: on 801030, valve SI-892A found shut. Caused
 by normally locked-open spray additive tank educator feed
 isolation valve mistaken for valve on operating work
 procedure & inadvertently closed. Procedure will be revised.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME		COPIES	
			LTTR	ENCL			LTTR	ENCL
	VARGA, S.	04	3	3				
INTERNAL:	A/D COMP&STRU06		1	1	A/D ENV TECH 07		1	1
	A/D MATL & QU08		1	1	A/D OP REACT009		1	1
	A/D PLANT SYS10		1	1	A/D RAD PROT 11		1	1
	A/D SFTY ASSE12		1	1	A/D TECHNOLOG13		1	1
	ACC EVAL BR 14		1	1	AEOD		2	2
	ASLBP/J.HARD		1	1	AUX SYS BR 15		1	1
	CHEM ENG BR 16		1	1	CONT SYS BR 17		1	1
	CORE PERF BR 18		1	1	D/DIR,HUM FAC19		1	1
	DIR,ENGINEERI20		1	1	DIR,HUM FAC S21		1	1
	DIR,SYS INTEG22		1	1	EFF TR SYS BR23		1	1
	EQUIP QUAL BR25		1	1	GEOSCIENCES 26		1	1
	I&C SYS BR 29		1	1	I&E 05		2	2
	JORDAN,E./IE		1	1	LIC GUID BR 30		1	1
	LIC QUAL BR 31		1	1	MATL ENG BR 32		1	1
	MECH ENG BR 33		1	1	MPA		3	3
	NRC PDR 02		1	1	OP EX EVAL BR34		3	3
	OR ASSESS BR 35		1	1	POWER SYS BR 36		1	1
	RAD ASSESS BR39		1	1	REACT SYS BR 40		1	1
	REG FILE 01		1	1	REL & RISK A 41		1	1
	SFTY PROG EVA42		1	1	STRUCT ENG BR44		1	1
	SYS INTERAC B45		1	1				
EXTERNAL:	ACRS	46	16	16	LPDR	03	1	1
	NSIC	05	1	1	TERA:DOUG MAY		1	1

NOV 19 1980

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	S	C	H	B	R	2	2	0	0	-	0	0	0	0	0	0	3	4	1	1	1	1	4		5									
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33									
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE										57 CAT 58	

0	1	L	6	0	5	0	0	0	2	6	1	7	1	0	3	0	8	0	8	1	1	1	3	8	0	9							
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33							
CON'T		REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 2004 hours on October 30, 1980, while returning "B" containment spray pump to

0 3 normal lineup per Operating Work Procedure (OWP-CS-2), valve SI-892A was found shut.

0 4 Valve SI-892A is the common isolation valve for the sodium hydroxide addition line.

0 5 The plant was operating at 68% power and isolation of the sodium hydroxide system,

0 6 under this plant condition, is contrary to Technical Specification 3.3.2.1.e which is

0 7 reportable pursuant to 6.9.2.a(2).

0	9	S	B	11	A	12	A	13	V	A	L	V	E	X	14	F	15	D	16								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	
LER/RO REPORT NUMBER		EVENT YEAR		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE		VALVE SUBCODE		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
17		8 0		11		12		13								15		16		24		28		30		32	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER											
18		19		20		21		22		23		24		25		26											
E		G		Z		Z		0 0 0 0		Y		N		N		E 0 9 0											
33		34		35		36		37		41		42		43		44											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 During the isolation of containment spray pump "B", the normally locked open spray

1 1 additive tank educator feed isolation valve SI-892A was mistaken for a valve on the

1 2 OWP and inadvertently closed. This discrepancy was identified and corrected at 2004

1 3 hours on October 30, 1980. The procedure will be revised to incorporate double

1 4 valve lineups.

1	5	C	28	0	6	8	29	NA	30	B	31	Operator Observation	32													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION																		
15		28		29		30		32																		
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE																				
16		33		34		35		36																		
Z		Z		NA		NA																				
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION																				
17		37		38		39																				
0 0 0		Z		NA																						
PERSONNEL INJURIES		NUMBER		DESCRIPTION																						
18		40		41																						
0 0 0		NA																								
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION																						
19		42		43																						
Z		NA																								
PUBLICITY		ISSUED		DESCRIPTION																						
20		44		45																						
N		NA																								

8011170 444

NAME OF PREPARER: R. B. Starkey, Jr.

PHONE: (803) 383-4524

NRC USE ONLY

GPO 917-926

SUPPLEMENTAL INFORMATION

FOR

LICENSEE EVENT REPORT 80-026

1. Cause Description and Analysis: On October 30, 1980 at 2004 hours while returning containment spray pump "B" to normal lineup as per Operating Work Procedure, OWP-CS-2, valve SI-892A was found to be shut. This closed valve caused isolation of the Sodium Hydroxide Addition Tank which is contrary to Technical Specification 3.3.2.1.e and is reportable pursuant to 6.9.2.a(2). The plant was operating at 68% power and startup physics testing following refueling was in progress.

"B" containment spray pump had been declared inoperable and isolated for repair using OWP-CS-2 at 0420 hours on October 30, 1980. This procedure requires the normally locked open containment spray pump "B" educator suction valve SI-892G to be closed. However, the normally locked open spray additive tank feed isolation valve SI-892A (common to both pumps) was inadvertently closed instead of SI-892G. This resulted in the isolation of the Sodium Hydroxide Spray Additive Tank from the operable "A" containment spray pump for fifteen hours and forty-four minutes. These two valves are similar two inch globe valves located in close proximity to one another. No adverse consequences resulted from this misalignment and the system was restored to full operability when valve SI-892A was reopened at 2004 hours on October 30, 1980.

2. Corrective Action: When SI-892A was found shut, it was reopened, thereby regaining automatic sodium hydroxide addition to "A" containment spray pump.
3. Corrective Action to Prevent Recurrence: The plant procedures will be revised to require double valve lineup verification on all Operating Work Procedures associated with safety systems. This redundancy should provide for immediate identification of this type of event. The appropriate revisions to the applicable procedures will be implemented by January 31, 1981.

In addition, the operator involved in this error has been admonished and the circumstances surrounding this incident and the lessons to be learned have been reviewed in detail with all operations personnel as further action to preclude recurrence.