

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8012090462 DOC. DATE: 80/12/05 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261
 AUTH. NAME: AUTHOR AFFILIATION
 STARKEY, R.B. Carolina Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION
 Region 2, Atlanta, Office of the Director

SUBJECT: LER 80-027/01T-0: on 801122, reactor protection relay RT-9 in reactor protection train A failed. Caused by de-energized relay coil resulting in continuous reactor trip signal. Relay replaced.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTTR 1 ENCL 1 SIZE: 112
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME		COPIES	
			LTTR	ENCL			LTTR	ENCL
	VARGA, S.	04	3	3				
INTERNAL:	A/D COMP&STRU06		1	1	A/D ENV TECH 07		1	1
	A/D MATL & QU08		1	1	A/D OP REACT009		1	1
	A/D PLANT SYS10		1	1	A/D RAD PROT 11		1	1
	A/D SFTY ASSE12		1	1	A/D TECHNOLOG13		1	1
	ACC EVALI BR 14		1	1	AEDD		2	2
	ASLBP/J. HARD		1	1	AUX SYS BR 15		1	1
	CHEM ENG BR 16		1	1	CONT SYS BR 17		1	1
	CORE PERF BR 18		1	1	D/DIR, HUM FAC19		1	1
	DIR, ENGINEERI20		1	1	DIR, HUM FACI S21		1	1
	DIR, SYS INTEG22		1	1	EFF TR SYS BR23		1	1
	EQUIP QUALI BR25		1	1	GEOSCIENCES 26		1	1
	I&C SYS BR 29		1	1	I&E 05		2	2
	JORDAN, E./IE		1	1	LIC GUID BR 30		1	1
	LIC QUALI BR 31		1	1	MATL ENG BR 32		1	1
	MECH ENG BR 33		1	1	MPA		3	3
	NRC PDR 02		1	1	OP EX EVALI BR34		3	3
	OR ASSESS BR 35		1	1	POWER SYS BR 36		1	1
	RAD ASSESS BR39		1	1	REACT SYS BR 40		1	1
	REG FILE 01		1	1	RELI & RISK A 41		1	1
	SFTY PROG EVA42		1	1	STRUCT ENG BR44		1	1
	SYS INTERACI B45		1	1				
EXTERNAL:	ACRS	46	16	16	LPDR	03	1	1
	NSIC	05	1	1	TERA: DOUG MAY		1	1

VP

DEC 10 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR 69 ENCL 69

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	S	C	H	B	R	2	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5																				
2	8	9						14						15										25										26					30					57					58	
		LICENSEE CODE																LICENSE NUMBER															LICENSE TYPE																	

CON'T

REPORT SOURCE L 6 0 5 0 0 0 2 6 1 7 1 1 2 2 8 0 8 1 2 0 5 8 0 9

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At approximately 1000 hours on November 22, 1980, Reactor Protection Relay RT-9 in

0 3 | Reactor Protection Train "A" failed. This failure occurred during the periodic test

0 4 | of the Reactor Protection Logic. This constitutes a reportable occurrence per

0 5 | Technical Specification Section 6.9.2.a.9. The relay had failed in the safe

0 6 | configuration. Thus, no increase in risk to the health and safety of the public

0 7 | resulted.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
		I	A	B		B		R	E	L	A	Y	X	A	
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
23	24	25	26	27	28	29	30	31	32	33	34				
		8	0	0	2	7	0	1	T	0					
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED					
35	36	37	38	39	40	41	42	43	44	45	46				
C	C	Z		Z		0	0	0	0	Y					
NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER											
47	48	49	50	51	52										
Y		N		W	1										

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The failed and replacement relays are Westinghouse Model NBFD-31 S, style 5072A49G03

1 1 with 125 to 130 volt coils. The relay coil was found de-energized which caused a

1 2 continuous reactor trip signal. The relay was replaced with an identical unit and

1 2 tested satisfactorily.

1 4

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) 1 5 E

% POWER 1 0 0 (29)

OTHER STATUS (30) NA

METHOD OF DISCOVERY (31) B

DISCOVERY DESCRIPTION (32) Periodic Test

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) Z (34) NA

7 8 9 10 11 44

LOCATION OF RELEASE (36)

NA

45 8

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION (39)				
1	7	0	0	0	(37)	(38)	NA		

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	40	NA

		LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE		DESCRIPTION		
1	9	Z	(42)	NA

PUBLICATION		ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	(44)	NA			

NRC USE ONLY

8012090462#

R. B. Starkey, Jr. *R. B. Starkey, Jr.*

PHONE: (803) 383-4524

Supplemental Information

for

Licensee Event Report 80-027

1. Cause Description and Analysis: On November 22, 1980, at approximately 1000 hours, with the plant at 100% power, Reactor Protection Relay RT-9 in Reactor Protection Train "A" failed to re-energize during the periodic test of the Reactor Protection Logic. The relays are installed in a fail safe configuration (normally energized); therefore, no loss of safety function resulted or would have resulted from their failure to re-energize.

The failure appears to be the result of a shorting condition where the lead wires connect to the coil wires. This has been confirmed by a manufacturer investigation of the coil failures.

This is the same condition as reported previously on LER 80-006, LER 80-015, and LER 80-025.

2. Corrective Action: The failed relay was replaced with an identical unit and the Periodic Test was completed satisfactorily.
3. Corrective Action to Prevent Further Occurrence: An investigation by the manufacturer of the failed relay coils has confirmed the failures to be caused by an insulation breakdown at the point where the lead wire is soldered to the coil wire. Sharp edges left on this connection during the manufacturing process contribute to the failure which apparently occurs when the voltage to the relay coil is interrupted. The collapsing electrical field under this condition generates an instantaneous reverse voltage of more than 2000 volts. CP&L was told that the manufacturing process on these relays will be changed to better insulate these coil connections.

Due to the number of failures at the Robinson Plant and the apparent lack at other facilities, it appears that a particular Robinson Plant order of NBFD-31 S relays was a defective batch. Therefore, new relays manufactured under the improved process will be obtained and installed in the Reactor Protection System as soon as practicable. Until such time that they are replaced, current periodic surveillance and the fail-safe application of these relays is sufficient to maintain safe operation of the plant. When a schedule for replacement of these relays is determined, a supplement to this LER will be submitted.