

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8012300415 DOC. DATE: 80/12/24 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261
 AUTH. NAME: STARKEY, R. B. AUTHOR AFFILIATION: Carolina Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Region 2, Atlanta, Office of the Director

SUBJECT: LER 80-029/01T-0: on 801212, leak calculated to be between 8 to 16 gpm developed in RHR pump suction isolation valve RHR-750. Caused by normal wear. Leak stopped & repair made.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME		COPIES	
			LTTR	ENCL			LTTR	ENCL
	VARGA, S.	04	3	3				
INTERNAL:	A/D COMP&STRU06		1	1	A/D ENV TECH 07		1	1
	A/D MATL & QU08		1	1	A/D OP REACT009		1	1
	A/D PLANT SYS10		1	1	A/D RAD PROT 11		1	1
	A/D SFTY ASSE12		1	1	A/D TECHNOLOG13		1	1
	ACC EVAL BR 14		1	1	AEOD		2	2
	ASLBP/J. HARD		1	1	AUX SYS BR 15		1	1
	CHEM ENG BR 16		1	1	CONT SYS BR 17		1	1
	CORE PERF BR 18		1	1	D/DIR, HUM FAC19		1	1
	DIR, DIV OF LIC		1	1	DIR, ENGINEERI20		1	1
	DIR, HUM FAC S21		1	1	DIR, SYS INTEG22		1	1
	EFF TR SYS BR23		1	1	EQUIP QUAL BR25		1	1
	GEOSCIENCES 26		1	1	I&C SYS BR 29		1	1
	I&E 05		2	2	JORDAN, E./IE		1	1
	LIC GUID BR 30		1	1	LIC QUAL BR 31		1	1
	MATL ENG BR 32		1	1	MECH ENG BR 33		1	1
	MPA		3	3	NRC PDR 02		1	1
	OP EX EVAL BR34		3	3	OR ASSESS BR 35		1	1
	POWER SYS BR 36		1	1	RAD ASSESS BR39		1	1
	REACT SYS BR 40		1	1	REG FILE 01		1	1
	REL & RISK A 41		1	1	SFTY PROG EVA42		1	1
	STRUCT ENG BR44		1	1	SYS INTERAC B45		1	1
EXTERNAL:	ACRS	46	16	16	LPDR 03		1	1
	NSIC	05	1	1	TERA: DOUG MAY		1	1

DEC 31 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR 70 ENCL 70

L.J.

CONTROL BLOCK:

							1
--	--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK:

							1
--	--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES		10
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 4 80

7	8	9	FACILITY STATUS										OTHER STATUS (30)										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION (32)										80	
1	5	E	(28)	% POWER										NA										A										Operator Observation										
1	5	E	(28)	0	8	6	(29)											A	(31)																									
7	8	9		10	11	12	13											44	45	46																								

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 Z (33) Z (34) NA
NA LOCATION OF RELEASE (36)
NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

7	8	9	10	11	12
1 9		Z	LOSS OF OR DAMAGE TO FACILITY (43)		
		(42)	DESCRIPTION		
			NA		

80

NBC USE ONLY

7 8 9 10
 PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 N (44) NA 1801230415
 68 69 80
 NRC USE ONLY

NAME OF PREPARER R. B. Starkey, Jr.

PHONE: (803) 383-4524

Supplemental Information

for

Licensee Event Report 80-029

1. Cause Description and Analysis: On December 12, 1980, at 2002 hours, a Reactor Coolant System primary leak developed. The unit was operating at 86% power. The leak was calculated at between 8 gpm and 16 gpm. This leak rate exceeds Technical Specification 3.1.5.2 and so a unit shutdown was immediately started. The unit was in the hot shutdown condition at 2100.

At approximately 2046 hours, the leak had been identified as a packing leak on valve RHR-750 which is a residual heat removal pump suction isolation valve from the Reactor Coolant System. The unit was cooled down to approximately 350°F and 400 psig at which time the leak was stopped and repair was made. The cause for the packing failure was determined to be normal wearout.

The leakage was contained within the plant's containment vessel and was disposed of normally using the plant's radioactive waste water processing systems. No off-site release occurred.

2. Corrective Action: The leakage on valve RHR-750 was stopped by opening the valve and placing it on its backseat while the unit was at 350°F and 400 psig. The valve was repacked using Q-list packing material and placed back in service following testing per PT-42.0.
3. Corrective Action to Prevent Recurrence: The valve failure was due to normal wear on the the valve packing and so repacking of the valve is deemed sufficient to correct the problem.