

**AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 5838

FILE: A/D

FROM: Northern States Power Company Minneapolis, Minn L. O. Mayer			DATE OF DOC UNDTD	DATE REC'D 6-27-74	LTR X	TWX	RPT	OTHER
TO: J. F. O'Leary			ORIG	CC 40	OTHER	SENT AEC PDR XX SENT LOCAL PDR XX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 40		DOCKET NO: 50-263		
DESCRIPTION: Ltr furn info re abnormal occurrence #AO 263/74-19 of 6-14-74 re crack in a restraining orifice assembly to coupling weld on the #11 reactor feedpump warmup line.....				ENCLOSURES: <div style="text-align: center; font-size: 1.5em; font-weight: bold;"> ACKNOWLEDGED DO NOT REMOVE </div>				
PLANT NAME:								

FOR ACTION/INFORMATION 6-27-74 GMC

BUTLER (L) W/ CYS CLARK (L) W/ CYS BARR (L) W/ CYS KNIEL (L) W/ CYS	SCHWENCER (L) W/ CYS STOLZ (L) W/ CYS VASSALLO (L) W/ CYS PURPLE (L) W/ CYS	✓ ZIEMANN (L) W/ 7 CYS DICKER (E) W/ CYS KNIGHTON (E) W/ CYS YOUNGBLOOD (E) W/ CYS	REGAN (E) W/ CYS W/ CYS W/ CYS W/ CYS
--	--	---	---

INTERNAL DISTRIBUTION

✓ REG FILE ✓ AEC PDR ✓ OGC ✓ MUNTZING/STAFF ✓ CASE GIAMBUSO BOYD MOORE (L)(LWR-2) DEYOUNG (L)(LWR-1) SKOVHOLT (L) ✓ GOLLER (L) P. COLLINS DENISE ✓ REG OPR ✓ FILE & REGION (3) ✓ MORRIS ✓ STEELE	✓ TECH REVIEW ✓ HENDRIE ✓ SCHROEDER ✓ MACCARY ✓ KNIGHT ✓ PAWLICKI ✓ SHAO ✓ STELLO ✓ HOUSTON ✓ NOVAK ✓ ROSS ✓ IPPOLITO ✓ TEDESCO ✓ LONG ✓ LAINAS ✓ BENAROYA ✓ VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT MGR HARLESS	✓ LIC ASST ✓ DIGGS (L) GEARIN (L) GOULBOURNE (L) KREUTZER (E) LEE (L) MAIGRET (L) REED (E) SERVICE (L) SHEPPARD (L) SLATER (E) SMITH (L) TEETS (L) WILLIAMS (E) WILSON (L)	A/T IND BRAITMAN SALTZMAN B. HURT PLANS MCDONALD CHAPMAN DUBE w/input E. COUPE ✓ D. THOMPSON (2) ✓ KLECKER ✓ EISENHUT
--	--	--	--	--

EXTERNAL DISTRIBUTION

✓ 1 - LOCAL PDR MINNEAPOLIS, MINN ✓ 1 - TIC (ABERNATHY) ✓ 1 - NSIC (BUCHANAN) 1 - ASLB ✓ 1 - P. R. DAVIS ✓ 16 - ACRS SENT TO LIC ASST DIGGS 6-27-74	(1)(2)(10)-NATIONAL LABS 1-ASLBP(E/W Bldg, Rm 529) 1-W. PENNINGTON, Rm E-201 GT 1-B&M SWINEBROAD, Rm E-201 GT 1-CONSULTANTS NEWARK/BLUME/AGBABIAN	1-PDR-SAN/LA/NY 1-BROOKHAVEN NAT LAB 1-G. ULRIKSON, ORNL 1-AGMED (RUTH GUSSMAN) Rm B-127 GT 1-RD..MUELLER, Rm F-309 GT
---	--	--



NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401


Mr. J F O'Leary, Director
Directorate of Licensing
Office of Regulation
U S Atomic Energy Commission
Washington, DC 20545



ABNORMAL OCCURRENCE REPORT TO THE AEC

Cracked Weld on Feedwater Pump Warmup Line Orifice

1. Report Number: AO 263/74-19
- 2A. Report Date: June 24, 1974
- 2B. Occurrence Date: June 14, 1974
3. Facility: Monticello Nuclear Generating Plant (DPR-22)
Monticello, Minnesota 55362
4. Identification of Occurrence:



This report concerns a crack in a restraining orifice assembly-to-coupling weld on the #11 reactor feedpump warmup line. This event is being reported as requested by Regulatory Operations personnel on June 21, 1974.

5. Conditions Prior to Occurrence:

Steady State Power - The plant was at 94% of rated power prior to the occurrence.

6. Description of Occurrence:

On June 14, 1974, water was discovered leaking from the #11 reactor feed-pump warmup line. The line was inspected following removal of the insulation and the leak was found to be coming from a 3/16" circumferential crack in one of the warmup line restricting orifice-to-coupling welds (on the high pressure side of the orifice). A plant shutdown was begun immediately and the reactor was placed in a hot standby condition to allow isolation of the feedwater lines and repair of the crack.

7. Designation of Apparent Cause of Occurrence:

Installation/Construction: Inspection revealed that the orifice assembly-to coupling gap (see Figure 1) was less than that specified by the ANSI B.31.1 code. Based on the measurements taken, it is felt that stresses induced due to thermal expansion of the orifice assembly caused the weld to crack.

(over)
REGULATORY DOCKET FILE COPY

5838

NORTHERN STATES POWER COMPANY

8. Analysis of Occurrence:

This occurrence had no effect on the public health and safety. The crack in the weld resulted in a leak of approximately 0.2 gpm from the primary system. The water was collected and processed via the normal turbine building radioactive waste drain system. Even in the event of complete weld failure, the plant could have been shutdown immediately and the line isolated without any significant consequences.

9. Corrective Action:

The orifice assembly-to-coupling weld was ground out. The orifice assembly was rewelded to the coupling leaving a 1/16" gap as outlined in ANSI B.31.1. The repair weld was dye penetrant tested and found to be acceptable. All other orifice assembly-to-coupling welds on both reactor feedpump warmup lines were visually inspected and found to be acceptable.

10. Failure Data:

Coupling Material: Carbon Steel ASTM A-106R2

Orifice Material: Stainless Steel ASTM A-276 Type 347

Manufacturer: The restricting orifice with couplings were supplied by DeLavel Turbine, Inc., as a complete assembly.

LO Mayer / DMU

L O Mayer, PE
Director of Nuclear Support Services

LOM/kn

cc: J G Keppler
G Charnoff
Minnesota Pollution Control Agency
Attn. E A Pryzina

ORIFICE ASSEMBLY

ORIFICE ASSEMBLY TO
COUPLING GAP

(SHOULD BE APPROXIMATELY
1/16 INCH PER ANSI B.31.1)

1-1/2 INCH COUPLING

FIGURE 1

