

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

Mr. Norman C. Moseley

FROM:

Carolina Power & Light Company
Raleigh, North Carolina
H. R. Banks

DATE OF DOCUMENT

8/31/76

DATE RECEIVED

9/3/76

☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
One signed copy

DESCRIPTION

Ltr. trans the following:

ACKNOWLEDGED

DO NOT REMOVE

(1-P) (3-P)

PLANT NAME:

H. B. Robinson #2

ENCLOSURE

Licensee Event Report (RO 50-261/76-15)
on 8/17/76 concerning Auxiliary Feedwater
Pump Discharge Valve V2-16A failing to open
as required while performing Auxiliary
Feedwater PT-22 at 100% power.NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J..COLLINS

FOR ACTION/INFORMATION 9/8/76

RJL

☒ BRANCH CHIEF: Reid
W/3 CYS FOR ACTION
☒ LIC. ASST.: Ingram
W/1 CYS
ACRS 16 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

☒ REG FILE
☒ NRC PDR
☒ I & E (2)
☒ MIPC
☒ SCHROEDER/IPPOLITO
☒ HOUSTON
☒ NOVAK/CHECK
☒ GRIMES
☒ CASE
☒ BUTLER
☒ HANAUER
☒ TEDESCO/MACCARY
☒ EISENHUT
☒ BAER
☒ SHAO
☒ VOLLMER/BUNCH
☒ KREGER/J..COLLINS

EXTERNAL DISTRIBUTION

☒ LPDR: Hartville, S.C.
☒ TIC:
☒ NSIC:

CONTROL NUMBER

8993



Carolina Power & Light Company

August 31, 1976


FILE: NG-3513 (R)

SERIAL: NG-76-1167

Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

Dear Mr. Moseley:

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
LICENSEE EVENT REPORT 76-15



In accordance with Section 6.9.2.a of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the attached Licensee Event Report is submitted. This report fulfills the requirement for a written report within fourteen (14) days of a reportable occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Yours very truly,

H. R. Banks
Manager


Nuclear Generation

CSB:ku

Attachment

cc: Messrs. W. G. McDonald
E. Volgenau

REGULATORY DOCKET FILE COPY



8993

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME			LICENSE NUMBER										LICENSE TYPE					EVENT TYPE					
01	S	C	H	B	R	2	0	0	-	0	0	0	0	-	0	0	4	1	1	1	0	0	1
7	8	9	14			15	25					26	30			31	32						

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE										
01	CONT		T	L	0	5	0	-	0	2	6	1	0	8	1	7	7	6	0	8	3	1	7	6
7	8	57	58	59	60	61	68					69	74					75	80					

EVENT DESCRIPTION

02	While performing Auxiliary Feedwater PT-22 at 100% power, Auxiliary Feedwater Pump																						
03	Discharge Valve V2-16A failed to open as required. The redundant auxiliary feedwater																						
04	pump discharge valve operated properly. Valve appeared to be binding, was eventually																						
05	manually operated then properly electrically operated subsequently. Larger capacity																						
06	motors for valve operators will be installed. (HBR-2 RO 76-15)																						

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07	C	H	B	V	A	L	V	O	P	N	L	2	0	0	Y		
7	8	9	10	11	17					43	47					48	

CAUSE DESCRIPTION

08	Limitorque Valve operator failed to open Auxiliary Feedwater Disch. Valve violating																						
09	Tech Spec 3.4.1.(d). Valve binded to seat. More pull-out torque is required. Valve																						
10	binding temporarily is alleviated. Permanent fix will be to install larger capacity.																						

FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION												
11	E	1	0	0	NA	A	NA															
7	8	9	10	11	12	13	44	45	46	80												

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE											
12	Z	Z	NA						NA											
7	8	9	10	11	44					45	80									

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION										
13	0	0	0	Z	NA									
7	8	9	11	12	13									

PERSONNEL INJURIES

NUMBER		DESCRIPTION											
14	0	0	0	NA									
7	8	9	11	12									

OFFSITE CONSEQUENCES

15	NA																						
7	8	9	80																				

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																				
16	Z	NA																				
7	8	9	10																			

PUBLICITY

17	NA																						
7	8	9	80																				

ADDITIONAL FACTORS

18																							
7	8	9	80																				

19	(Cause Description Cont'd) valve operator motors.																						
7	8	9	80																				

NAME: J. B. McGirt

803-332-1351
PHONE: _____

Supplementary Information For
Reportable Occurrence 76-15

1. Report No: 50-261/76-15
- 2a. Report Date: August 31, 1976
- 2b. Occurrence Date: August 17, 1976
3. Facility: H. B. Robinson Unit No. 2
Hartsville, South Carolina 29550
4. Identification of Occurrence:

At 1805 hours on August 17, 1976, while performing Auxiliary Feedwater PT-22 at 100% power, the Auxiliary Feedwater pump discharge valve V2-16A failed to open as commanded. This is a violation of paragraph 3.4.1.(d) of the Technical Specification and constitutes a reportable occurrence in accordance with Technical Specification paragraph 6.9.2.a.5.

5. Conditions Prior to Occurrence

No unusual conditions prevailed prior to the occurrence. The plant was at steady state and 100% power level. No Auxiliary Feedwater pumps were in operation and the Auxiliary Feedwater pump discharge valves were in their normally closed position.

6. Description of the Occurrence

At 1805 hours on August 17, 1976, the Auxiliary Feedwater pump discharge valve V2-16A failed to open when commanded while performing step 7.1 of Auxiliary Feedwater PT-22. The valve operator motor energized and attempted to open the valve. This attempt provided dual indication of red and green lights energized at the RTGB thus indicating slight movement of the valve's limit switch. However, the valve disc was binding on its seat and there was not enough pull out torque provided by the valve operator motor to overcome the binding friction and lift the valve disc off its seat. Thus, there was no movement of the valve stem when the valve was commanded to open.

An overcurrent condition in the valve operator motor circuit was created by the failed attempt to open the valve. This caused the motor circuit breaker to open. The breaker was reclosed and another attempt was made to open the valve with the same results.

An attempt was then made to open the valve manually. There was too much resistance to handwheel movement to manually open the valve.

At 1827 hours "B" Auxiliary Feedwater Pump was started, and the valve was then partially opened manually. Later the valve was cycled with the pump secured. A large amount of backflow was experienced from "A" Steam Generator when the valve was opened. Subsequently, the valve was cycled two additional times and was declared in service at 1830 hours.

7. Designation of Apparent Cause of Occurrence

The cause of the occurrence can be attributed to insufficient pull out torque developed by Valve V2-16A motor operator. The motor operator did not have enough torque capacity to overcome valve seat friction.

8. Analysis of Occurrence

The occurrence could have been avoided if a larger torque capacity motor were installed on the valve operator.

9. Corrective Action

The existing 10 ft. lb. motors installed on all three of the Auxiliary Feedwater pump discharge valve operators will be replaced by 15 ft. lb. motors. Calculations have been performed by the valve operator manufacturer to substantiate the necessity for installation of the 15 ft. lb. motors.



Carolina Power & Light Company

August 31, 1976

FILE: NG-3513 (R)

SERIAL: NG-76-1167

Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

Dear Mr. Moseley:

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
LICENSEE EVENT REPORT 76-15

In accordance with Section 6.9.2.a of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the attached Licensee Event Report is submitted. This report fulfills the requirement for a written report within fourteen (14) days of a reportable occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Yours very truly,

H. R. Banks
Manager
Nuclear Generation

CSB:ku

Attachment

cc: Messrs. W. G. McDonald
E. Volgenau

CENSEE EVENT REPORT

CONTROL BLOCK:
16

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER														LICENSE TYPE						EVENT TYPE			
01	S	C	H	B	R	2									0	0	-	0	0	0	0	-	0	0	4	1	1	1	0	0	1						
7	8	9				14				15				25				26				30				31				32							

CATEGORY				REPORT TYPE		REPORT SOURCE		DOCKET NUMBER										EVENT DATE						REPORT DATE					
01	CONT					T	L	0	5	0	-	0	2	6	1	0	8	1	7	7	6	0	8	3	1	7	6		
7	8				57	58	59	60	61				68	69				74	75				80				80		

EVENT DESCRIPTION

02	While performing Auxiliary Feedwater PT-22 at 100% power, Auxiliary Feedwater Pump																															80
03	Discharge Valve V2-16A failed to open as required. The redundant auxiliary feedwater																															80
04	pump discharge valve operated properly. Valve appeared to be binding, was eventually																															80
05	manually operated then properly electrically operated subsequently. Larger capacity																															80
06	motors for valve operators will be installed. (HBR-2 RO 76-15)																															80

SYSTEM CODE				CAUSE CODE		COMPONENT CODE										PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER						VIOLATION	
07	C	H		B	V	A	L	V	O	P					N	L	2	0	0			Y			
7	8	9	10	11	12				17	43				44				47			48				

CAUSE DESCRIPTION

08	Limitorque Valve operator failed to open Auxiliary Feedwater Disch. Valve violating																															80
09	Tech Spec 3.4.1.(d). Valve binded to seat. More pull-out torque is required. Valve																															80
10	binding temporarily is alleviated. Permanent fix will be to install larger capacity.																															80

FACILITY STATUS				% POWER				OTHER STATUS						METHOD OF DISCOVERY		DISCOVERY DESCRIPTION															
11	E	1	0	0	NA								A			NA															
7	8	9	10	11	12				13				44	45			46														

FORM OF ACTIVITY RELEASED				CONTENT OF RELEASE				AMOUNT OF ACTIVITY										LOCATION OF RELEASE													
12	Z	Z	NA														NA														
7	8	9	10	11				44	45															80							

PERSONNEL EXPOSURES

NUMBER				TYPE		DESCRIPTION																									
13	0	0	0	Z	NA																										
7	8	9	11	12																											80

PERSONNEL INJURIES

NUMBER				DESCRIPTION																											
14	0	0	0	NA																											
7	8	9	11	12																											80

OFFSITE CONSEQUENCES

15	NA																															80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE				DESCRIPTION																											
16	Z	NA																													
7	8	9	10																											80	

PUBLICITY

17	NA																															80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18																																80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19	(Cause Description Cont'd) valve operator motors.																															80
----	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: J. B. McGirt

PHONE: 803-332-1351

Supplementary Information For
Reportable Occurrence 76-15

1. Report No: 50-261/76-15
- 2a. Report Date: August 31, 1976
- 2b. Occurrence Date: August 17, 1976
3. Facility: H. B. Robinson Unit No. 2
Hartsville, South Carolina 29550
4. Identification of Occurrence:

At 1805 hours on August 17, 1976, while performing Auxiliary Feedwater PT-22 at 100% power, the Auxiliary Feedwater pump discharge valve V2-16A failed to open as commanded. This is a violation of paragraph 3.4.1.(d) of the Technical Specification and constitutes a reportable occurrence in accordance with Technical Specification paragraph 6.9.2.a.5.

5. Conditions Prior to Occurrence

No unusual conditions prevailed prior to the occurrence. The plant was at steady state and 100% power level. No Auxiliary Feedwater pumps were in operation and the Auxiliary Feedwater pump discharge valves were in their normally closed position.

6. Description of the Occurrence

At 1805 hours on August 17, 1976, the Auxiliary Feedwater pump discharge valve V2-16A failed to open when commanded while performing step 7.1 of Auxiliary Feedwater PT-22. The valve operator motor energized and attempted to open the valve. This attempt provided dual indication of red and green lights energized at the RTGB thus indicating slight movement of the valve's limit switch. However, the valve disc was binding on its seat and there was not enough pull out torque provided by the valve operator motor to overcome the binding friction and lift the valve disc off its seat. Thus, there was no movement of the valve stem when the valve was commanded to open.

An overcurrent condition in the valve operator motor circuit was created by the failed attempt to open the valve. This caused the motor circuit breaker to open. The breaker was reclosed and another attempt was made to open the valve with the same results.

An attempt was then made to open the valve manually. There was too much resistance to handwheel movement to manually open the valve.

At 1827 hours "B" Auxiliary Feedwater Pump was started, and the valve was then partially opened manually. Later the valve was cycled with the pump secured. A large amount of backflow was experienced from "A" Steam Generator when the valve was opened. Subsequently, the valve was cycled two additional times and was declared in service at 1830 hours.

7. Designation of Apparent Cause of Occurrence

The cause of the occurrence can be attributed to insufficient pull out torque developed by Valve V2-16A motor operator. The motor operator did not have enough torque capacity to overcome valve seat friction.

8. Analysis of Occurrence

The occurrence could have been avoided if a larger torque capacity motor were installed on the valve operator.

9. Corrective Action

The existing 10 ft. lb. motors installed on all three of the Auxiliary Feedwater pump discharge valve operators will be replaced by 15 ft. lb. motors. Calculations have been performed by the valve operator manufacturer to substantiate the necessity for installation of the 15 ft. lb. motors.

U.S.A.E.C.
REGULATORY OPERATIONS
REGION II
ATLANTA, GA.

SEP 1 1 35 PM '76