

DISTRIBUTION AFTER ISSUANCE OF OPERATING LICENSE

NRC FORM 195
(2-76)

U.S. NUCLEAR REGULATORY COMMISSION

DOCKET NUMBER

50-261

FILE NUMBER

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO:

Mr. Robert W. Reid

FROM:

Carolina Power & Light Company
Raleigh, North Carolina
E. E. Utley

DATE OF DOCUMENT

1/2/78

DATE RECEIVED

1/10/78

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☒ ORIGINAL
☐ COPY☒ UNCLASSIFIED

1 signed

DESCRIPTION

ENCLOSURE

Response to Steam Generator Water Hammer
information request.....

(1-P)

PLANT NAME: H. B. Robinson Unit No. 2
RJL 1/11/78

SAFETY

FOR ACTION/INFORMATION

BRANCH CHIEF: (7)

Reid

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

OELD

HANAUER

CHECK

EISENHUT

SHAO (2)

BAER

BUTLER (2)

GRIMES

J. COLLINS

J. MCGOUGH

BENAROYA (2)

Knight

E. REEVES

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: HARTSVILLE, S.C.

TIC

NSIC

ACRS 16 CYS SENT CATEGORY B

780110113




Carolina Power & Light Company

REGULATORY DOCKET FILE COPY

January 2, 1978

NG 3514 (R)

Office of Nuclear Reactor Regulation
ATTN: Mr. Robert W. Reid, Chief
Operating Reactors Branch No. 4
U. S. Nuclear Regulatory Commission
Washington, DC 20555



GD-78-015

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23

RESPONSE TO STEAM GENERATOR WATER HAMMER INFORMATION REQUEST

Dear Mr. Reid:

This letter is in response to the NRC letter of September 2, 1977, concerning the potential for steam generator water hammer problems at the H. B. Robinson Plant.

This subject was addressed in our response to a May 15, 1975, NRC letter concerning secondary system fluid flow instability. Since there have been no water hammer events at the H. B. Robinson Plant due to uncovering the steam generator feedwater spargers, our July 23, 1975, response is still valid and will satisfactorily answer the questions posed in this most recent letter.

Yours very truly,

E. E. Utley
Senior Vice President
Power Supply

RAD:CSB/mf

780110113