

7 03/05/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL 50-261

REC: OREILLY J P
NRC

ORG: BANKS H R
CAROLINA PWR & LIGHT

DOCDATE: 03/20/78
DATE RCVD: 03/24/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 1 ENCL 1

LICENSEE EVENT REPT (RO 50-261/78-06) ON 03/05/78 CONCERNING INDICATIONS AT
NINE LOCATIONS IN THE INLET AND OUTLET PIPING OF THE BORON INJECTION TANK
WERE FOUND.

PLANT NAME: H B ROBINSON - UNIT 2

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL *PC*

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF SCHWENCER**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL

I & E**W/2 ENCL

SCHROEDER/IPPOLITO**W/ENCL

NOVAK/CHECK**W/ENCL

KNIGHT**W/ENCL

HANAUER**W/ENCL

EISENHUT**W/ENCL

SHAO**W/ENCL

KREGER/J. COLLINS**W/ENCL

K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL

MIPC**W/3 ENCL

HOUSTON**W/ENCL

GRIMES**W/ENCL

BUTLER**W/ENCL

TEDESCO**W/ENCL

BAER**W/ENCL

VOLLMER/BUNCH**W/ENCL

ROSA**W/ENCL

EXTERNAL:

LPDR'S

HARTSVILLE, SC**W/ENCL

TIC**W/ENCL

NSIC**W/ENCL

ACRS CAT B**W/16 ENCL

COPIES NOT SUBMITTED PER
REGULATORY GUIDE 10.1

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P+4P

CONTROL NBR: 750830129

***** THE END *****

CP&L


Carolina Power & Light Company
March 20, 1978

RECEIVED DOCKET FILE COPY

FILE: NG-3516 (R)

SERIAL: GD-78-806

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 1217
230 Peachtree Street, N.W.
Atlanta, Georgia 30303




H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
LICENSEE EVENT REPORT 78-06

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the attached Licensee Event Report is submitted. This report fulfills the requirement for a written report within fourteen (14) days of a reportable occurrence and is in accordance with the format set forth in NUREG-0161, July, 1977.

Yours very truly,


H. R. Banks
Manager
Nuclear Generation

DCS:mvp*

Attachment

cc: Messrs. R. A. Hartfield
E. Volgenau

4002
5/11

780830129

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	S	C	H	B	R	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9						14	15	25										26	30					57	58		
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE						CAT			

REPORT
SOURCE

REPORT SOURCE L 6 0 5 0 0 0 2 6 1 7 0 3 0 5 7 8 8 0 3 2 0 7 8 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On March 5, 1978, while at refueling shutdown conditions, indications were found during ultrasonic examination of the BIT inlet and outlet piping. Examination was being conducted as a followup to the BIT failure (LER 77-25). This constitutes a reportable occurrence per Technical Specifications Paragraph 6.9.2.a.9. (HBR-2 RO-78-06)

SYSTEM CODE I C (11)		CAUSE CODE E (12)		CAUSE SUBCODE D (13)		COMPONENT CODE P I P E X X (14)		COMP. SUBCODE B (15)		VALVE SUBCODE Z (16)							
EVENT YEAR 7 8 (21) (22)		SEQUENTIAL REPORT NO. 0 0 6 (24) (25) (26)		OCCURRENCE CODE 0 1 (28) (29)		REPORT TYPE T (30)		REVISION NO. 0 (32)									
ACTION TAKEN C (18)		FUTURE ACTION X (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22) (23) (24) (25)		ATTACHMENT SUBMITTED Y (26)		NPRD-4 FORM SUB. Y (27)		PRIME COMP. SUPPLIER N (28)		COMPONENT MANUFACTURER S 1 5 2 (29) (30) (31) (32)	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Indications at nine locations in the inlet and outlet piping of the Boron Injection

1 1 Tank were found. The affected portions of piping are being replaced with type 316L

1 2 material during this refueling outage. Metallurgical analysis of the affected piping

1 3 material will be conducted.

1 4

7	8	9	FACILITY STATUS		% POWER		OTHER STATUS		30	METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		32			80
1	5		H	28	0	0	0	29	NA		C	31	Ultrasonic Inspection				
7	8	9	ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		35			LOCATION OF RELEASE		36			80
1	6		Z	33	Z	34			NA				NA				
7	8	9	PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION		39						80
1	7		0	0	0	37	Z	38			NA						
7	8	9	PERSONNEL INJURIES		NUMBER		DESCRIPTION		41								80
1	8		0	0	0	40					NA						
7	8	9	LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION		43								80
1	9		Z	42							NA						
7	8	9	PUBLICITY		ISSUED		DESCRIPTION		45								80
2	0		N	44							NA						
7	8	9													NRC USE ONLY		80

PHONE

803-332-1351

Supplemental Information For Reportable Occurrence 78-06

1. Report No: 50-261/78-06
- 2a. Report Date:
- 2b. Occurrence Date: March 5, 1978
3. Facility: H. B. Robinson Unit No. 2
Hartsville, South Carolina 29550
4. Identification of Occurrence:

On March 5, 1978, while at refueling shutdown conditions, sections of safety injection piping adjacent to the Boron Injection Tank were being ultrasonically examined as a followup to metallurgical analysis of portions of the failed Boron Injection Tank (Re: LER 77-25). Indications were found at nine locations; five on inlet piping and four on outlet piping. The locations were specifically on the pipe side in the heat affected zone (HAZ) of pipe to fitting welds and in the HAZ at pipe to pipe butt welds. This constitutes a Reportable Occurrence per Technical Specifications Paragraph 6.9.2.a.9.

5. Conditions Prior to Occurrence:

The plant was at refueling shutdown conditions during the scheduled 1978 refueling outage. Recent developments in the followup to the October, 1977 failure of the BIT indicated that further examination of the safety injection piping was warranted. Ultrasonic examination of the piping was being conducted at this time.

6. Description of Occurrence:

Referring to the attached isometric drawings of the BIT inlet and outlet piping, the ultrasonic examination revealed indications at pipe to fitting welds BA, BB, BC, BF, BH on the inlet piping and TA, TB, TC on the outlet piping. An indication at pipe to pipe butt weld TD was also discovered.

Ultrasonic investigation was being conducted based on results of the metallurgical investigation conducted on samples of the failed BIT. The conclusions of the BIT study showed intragranular corrosion in the presence of higher than normal concentrations of chloride ions, eg. levels of 600 micrograms per square decimeter present with a Westinghouse recommended maximum of 1.5 micrograms per square decimeter. These figures apply to the analysis of the failed thermowell coupling on the BIT. As a result, further examination of the safety injection system, in those portions subject to the same fluids as the BIT was being conducted. The piping segments associated with the recirculation of boric acid from the Boric Acid Storage Tank to the Boron Injection Tank were the first areas to be investigated. Testing began at the BIT and proceeded outward on the inlet and outlet lines. Testing was terminated when inspection of a reasonable number of welds in a direction away from the BIT revealed no indications.

It should be noted that the indications found were only on the pipe side of heat affected zones of weldments. The heavier bodied fittings of the same material do not show any indications.

7. Description of Apparent Cause of Occurrence:

Metallurgical analysis will be conducted on portions of the affected piping, as soon as the piping is removed, to determine the cause of the indications.

8. Analysis of Occurrence:

Safety implications of this occurrence are minimal in that no radioactive materials were released, no personnel were injured or detrimentally exposed and no plant systems other than the affected piping, were damaged as a result of the event. In fact, this piping had passed a hydrostatic test to 1950 psi on November 21, 1977.


9. Corrective Action:

Immediate action taken was to replace the affected portion of the safety injection system piping. Type 316L stainless steel is being used to replace the type 316 material affected. The 316L material is less susceptible to the type of corrosion cracking found in other plants which has led to these type indications. The attached isometric piping drawings define the portion of the piping system being replaced. Replacement will be completed before the end of 1978 refueling outage and subsequent return to full power conditions.

Future action to be taken will consist of continued examination of the removed safety injection system piping to fully define the method of degradation and its extent. Further corrective action, as required, will be initiated pending results of the metallurgical examinations.

10. Failure Data:


The only similar occurrence was the failure of the Boron Injection Tank (LER 77-25).



BORON INJECTION TANK OUTLET PIPING

TA - TP = INSPECTION POINTS

INDICATIONS ON TA, TB, TC, AND TD



BORON INJECTION TANK INLET PIPING

BA - BP = INSPECTION POINTS

INDICATIONS ON BA, BB, BC, BF, BH