



Entergy Operations, Inc.
River Bend Station
5485 U. S. Highway 61N
St. Francisville, LA 70775
Tel 225 381 4374
Fax 225 381 4872
eolson@entergy.com

Eric W. Olson
Site Vice President

RBG-47522

December 16, 2014

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Subject: Licensee Event Report 50-458 / 2014-002-00
River Bend Station – Unit 1
Docket No. 50-458
License No. NPF-47

RBF1-14-0181

Dear Sir or Madam:

In accordance with 10 CFR 50.73, enclosed is the subject Licensee Event Report. This document contains no commitments. Please note that this report number has been reassigned from a previous report submitted on March 12, 2014, which was subsequently cancelled.

If you have any questions, please contact Mr. Joseph Clark at 225-381-4177.

Sincerely,

A handwritten signature in black ink, appearing to read "Eric Olson".

EWO/dhw

Enclosure

IE22
NRR



Licensee Event Report 50-458 / 2014-002-00

December 16, 2014

RBG-47522

Page 2 of 2

cc: U. S. Nuclear Regulatory Commission
Region IV
1600 East Lamar Blvd.
Arlington, TX 76011-4511

NRC Sr. Resident Inspector
P. O. Box 1050
St. Francisville, LA 70775

INPO
(via ICES reporting)

Central Records Clerk
Public Utility Commission of Texas
1701 N. Congress Ave.
Austin, TX 78711-3326

Department of Environmental Quality
Office of Environmental Compliance
Radiological Emergency Planning and Response Section
Ji Young Wiley
P.O. Box 4312
Baton Rouge, LA 70821-4312



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

River Bend Station - Unit 1

2. DOCKET NUMBER

05000 458

3. PAGE

1 OF 4

4. TITLE

Reactor Scram Due to Average Power Range Monitor High-flux Signal Following a Malfunction of the Main Turbine Electro-hydraulic System

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
10	17	2014	2014	002	00	12	16	2014		05000
										05000

9. OPERATING MODE	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)			
1	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
10. POWER LEVEL	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

12. LICENSEE CONTACT FOR THIS LER

LICENSEE CONTACT: Joseph A. Clark, Manager - Regulatory Assurance
 TELEPHONE NUMBER (Include Area Code): (225) 381-4177

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
n/a	J1	n/a	GE	yes					

14. SUPPLEMENTAL REPORT EXPECTED

YES (If yes, complete 15. EXPECTED SUBMISSION DATE) NO

15. EXPECTED SUBMISSION DATE

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On October 17, 2014, at approximately 3:03 a.m. CDT, a reactor scram occurred in response to a high neutron flux signal from the average power range monitors (APRMs). The plant was operating at 100 percent power at the time. Immediately prior to that signal, an apparent malfunction in the main turbine electro-hydraulic control (EHC) system caused both the main turbine steam bypass valves to fully open, and also commanded all four main turbine control valves to close. The resulting increase in reactor steam pressure caused reactor power to immediately rise to the trip setpoint of the APRMs, at which point the actuation of the reactor protection system (RPS) occurred. After the scram occurred, an operator in the auxiliary control room erroneously removed all the main condensate system demineralizers from service, isolating condensate flow to the suction header of the main feedwater pumps. The running feedwater pump tripped on low suction pressure. The mis-operation of the demineralizer system was promptly corrected, and the main feedwater system was restored to service. The cause of the EHC malfunction has not been determined. Potential failure points were identified, and those circuitry parts were replaced. A human performance error review was conducted regarding the mis-operation of the condensate demineralizers, and appropriate procedure revisions have been made. This event is being reported in accordance with 10CFR50.73(a)(2)(iv) as an automatic actuation of the RPS system.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REV NO.	
River Bend Station - Unit 1	05000 458	2014	- 02	- 00	2 OF 4

NARRATIVE

REPORTED CONDITION

On October 17, 2014, at approximately 3:03 a.m. CDT, a reactor scram occurred in response to a high neutron flux signal from the average power range monitors (APRMs). The plant was operating at 100 percent power at the time. Immediately prior to that signal, an apparent malfunction in the main turbine electro-hydraulic control (EHC) (**JI**) system caused both the main turbine steam bypass valves to fully open, and also commanded all four main turbine control valves to close. The resulting increase in reactor steam pressure caused reactor power to immediately rise to the trip setpoint of the APRMs, at which point the actuation of the reactor protection system (RPS) (**JC**) occurred.

All reactor control rods inserted as designed in response to the RPS actuation, and operators implemented the appropriate response procedures. After the scram occurred, an operator in the auxiliary control room erroneously removed all the main condensate system demineralizers (**SF**) from service, isolating condensate flow to the suction header of the main feedwater pumps (**SJ**). The "C" feedwater pump tripped on low suction pressure; the "A" and "B" feedwater pumps had been previously secured by the operators. The mis-operation of the demineralizer system was promptly recognized and corrected, and the main feedwater system was restored to service within approximately six minutes. In the interim, reactor water level decreased to Level 3, causing a second actuation of the RPS system, but remained well above the point at which actuation of the emergency core cooling systems is required. The Level 3 signal also caused an automatic actuation of the containment isolation valves in the suppression pool cooling system, as designed. Reactor recirculation pump "B" failed to downshift to slow speed, and instead, tripped off. A controlled plant cooldown was commenced, and proceeded into cold shutdown conditions.

This event is being reported in accordance with 10CFR50.73(a)(2)(iv) as an automatic actuation of the RPS system.

INVESTIGATION and IMMEDIATE ACTIONS

1. EHC Malfunction

An investigation team was formed to analyze the operating parameters of the EHC system and determine the source of the malfunction.

Earlier in that same shift, there were two actuations of the main control room alarm indicating that the turbine steam bypass valves were open. At 7:26 p.m., the alarm actuated and immediately cleared. Plant computer data indicated that both bypass valves had opened slightly, while the number 4 turbine control valve closed slightly. No accompanying changes were noted in reactor pressure or in any EHC parameters. At 11:14 p.m., the alarm actuated a second time. Computer data then showed that turbine bypass valve no. 1 had fully opened, and bypass valve no. 2 had opened approximately 20 percent. Turbine control valve no. 4 closed significantly, and there was a slight change in the turbine steam flow reference signal in the EHC system.

Analysis of EHC parameters immediately prior to the scram found that the steam flow reference signal went from 92 percent to negative 41 percent with no corresponding change in total steam flow demand. The error in the steam flow reference signal cleared in approximately five seconds, but the resulting pressure transient had caused the reactor scram by that point. The movements of the bypass valves and turbine control valves were appropriate for the loss of the steam flow reference signal.

A detailed circuit analysis was performed to identify which components within the system could cause the loss of this signal. Efforts to recreate the loss of the signal were unsuccessful. Based on the system response earlier in the shift, and the lack of any apparent fault, it was concluded that an intermittent failure with the steam flow reference signal was occurring.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
River Bend Station - Unit 1	05000 458	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 4
		2014	- 02	- 00	

NARRATIVE

The investigation initially postulated that failure in any of these five EHC circuit cards and their subcomponents could have caused this event:

- pressure load gate amplifier
- control valve amplifier input standby transfer
- load limit set runback analog / logic
- control valve flow reference signal
- load limit and load set runback

All these circuit cards, except one, were replaced and sent to the vendor for analysis. Discussion with the vendor concerning the load limit and load set runback card concluded that its potential role as a source of the failure was extremely low.

If a definite cause of the EHC malfunction is found, that information will be provided in a supplement to this report.

2. Mis-operation of the main feedwater system

When the operators in the auxiliary control room heard the plant announcement of a reactor scram, they began removing main condensate demineralizers from service to maintain proper system parameters for the expected decrease in feedwater flow. However, they inappropriately isolated all the demineralizers, isolating all flow to the main feedwater pump suction header. Main control room operators had already secured two of the three pumps; the last pump tripped on low suction pressure. The error was promptly recognized, and demineralizers were restored to service, allowing the re-start of a feedwater pump.

A human performance error review was conducted, which found the following:

- The auxiliary control room operators did not correctly follow the system operating procedure guidance on maintaining flow through individual demineralizers within specifications as overall system flow decreased. The operators imposed unnecessary haste by focusing on demineralizer channeling effects, and did not demonstrate knowledge of integrated system operation.
- Procedural guidance for the removal of condensate demineralizers from service following a scram was less than adequate, in that it promoted the practice that operators in the field have the authority to determine when they can perform actions without specific direction from the main control room.
- Operations department management had not clearly defined standards and expectations to preclude auxiliary operators from taking actions without direction from main control room operators, or a supervisor, during certain plant conditions. In this event, the condensate demineralizers were removed from service and then returned to service without direction from main control room, with the intent of not distracting those operators from the scram recovery. The system operating procedure promotes this long-standing practice.

CORRECTIVE ACTION TO PREVENT RECURRENCE

1. EHC malfunction

During the upcoming refueling outage in February 2015, an evaluation of a potential replacement of the obsolete card will be completed. A complete replacement with a digital EHC system is planned for the refueling outage to occur in early 2017. These actions are being tracked in the corrective action program.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
River Bend Station - Unit 1	05000 458	YEAR	SEQUENTIAL NUMBER	REV NO.	4 OF 4
		2014	- 02	- 00	

NARRATIVE

2. Mis-operation of the main condensate demineralizer system

The system operating procedure for the main condensate demineralizers has been revised to clarify the precautions regarding how many demineralizers are to remain in service. The scram response procedure has been revised to add a step for the main control room operators to communicate with the auxiliary control room operator regarding system operations.

PREVIOUS OCCURRENCE EVALUATION

No event reported by RBS within the last three years was caused by unexplained, erratic signals originating within the main turbine EHC control circuits.

SAFETY SIGNIFICANCE

At the time of the reactor scram, the reactor core isolation cooling system was out of service for planned maintenance. No plant parameters that would have required its actuation were exceeded. No other engineered safety features were out of service at the time. The plant response to this transient was as designed. Thus, this event was of minimal significance to the health and safety of the public.

(NOTE: Energy Industry System Identification codes are annotated as (**XX**).)