



10 CFR 50.73

NMP1L 3019
April 10, 2015

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Nine Mile Point Nuclear Station, Unit 1
Renewed Facility Operating License No. DPR-63
Docket No. 50-220

Subject: NMP1 Licensee Event Report 2015-001, Secondary Containment Inoperable
Due to Simultaneous Opening of Airlock Doors

In accordance with the reporting requirements contained in 10 CFR 50.73(a)(2)(v)(C), please find enclosed NMP1 Licensee Event Report 2015-001, Secondary Containment Inoperable Due to Simultaneous Opening of Airlock Doors.

There are no regulatory commitments contained in this letter.

Should you have any questions regarding the information in this submittal, please contact Terry Syrell, Acting Manager - Site Regulatory Assurance, at (315) 349-5245.

Respectfully,

A handwritten signature in black ink, appearing to read "William J. Trafton".

William J. Trafton
Plant Manager, Nine Mile Point Nuclear Station

WJT/KJK

Enclosure: NMP1 Licensee Event Report 2015-001, Secondary Containment Inoperable
Due to Simultaneous Opening of Airlock Doors

cc: NRC Regional Administrator, Region I
NRC Resident Inspector
NRC Project Manager

IE22
ARK

Enclosure

NMP1 Licensee Event Report 2015-001

Secondary Containment Inoperable Due to Simultaneous Opening of Airlock Doors

Nine Mile Point Nuclear Station, Unit 1

Renewed Facility Operating License No. DPR-63

**LICENSEE EVENT REPORT (LER)**(See Page 2 for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Nine Mile Point Unit 1

2. DOCKET NUMBER

05000220

3. PAGE

1 OF 5

4. TITLE

Secondary Containment Inoperable Due to Simultaneous Opening of Airlock Doors

| 5. EVENT DATE | | | 6. LER NUMBER | | | 7. REPORT DATE | | | 8. OTHER FACILITIES INVOLVED | |
|---------------|-----|------|---------------|-------------------|---------|----------------|-----|------|------------------------------|---------------|
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REV NO. | MONTH | DAY | YEAR | FACILITY NAME | DOCKET NUMBER |
| 2 | 11 | 2015 | 2015 | 001 | 00 | 4 | 10 | 2015 | N/A | N/A |
| | | | | | | | | | N/A | N/A |

| 9. OPERATING MODE | 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply) | | | |
|-------------------|-----------------------------------------------------------------------------------------------|---------------------------------------------|-------------------------------------------------------|-----------------------------------------------|
| 1 | <input type="checkbox"/> 20.2201(b) | <input type="checkbox"/> 20.2203(a)(3)(i) | <input type="checkbox"/> 50.73(a)(2)(i)(C) | <input type="checkbox"/> 50.73(a)(2)(vii) |
| | <input type="checkbox"/> 20.2201(d) | <input type="checkbox"/> 20.2203(a)(3)(ii) | <input type="checkbox"/> 50.73(a)(2)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(viii)(A) |
| | <input type="checkbox"/> 20.2203(a)(1) | <input type="checkbox"/> 20.2203(a)(4) | <input type="checkbox"/> 50.73(a)(2)(ii)(B) | <input type="checkbox"/> 50.73(a)(2)(viii)(B) |
| | <input type="checkbox"/> 20.2203(a)(2)(i) | <input type="checkbox"/> 50.36(c)(1)(i)(A) | <input type="checkbox"/> 50.73(a)(2)(iii) | <input type="checkbox"/> 50.73(a)(2)(ix)(A) |
| 10. POWER LEVEL | <input type="checkbox"/> 20.2203(a)(2)(ii) | <input type="checkbox"/> 50.36(c)(1)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(iv)(A) | <input type="checkbox"/> 50.73(a)(2)(x) |
| | <input type="checkbox"/> 20.2203(a)(2)(iii) | <input type="checkbox"/> 50.36(c)(2) | <input type="checkbox"/> 50.73(a)(2)(v)(A) | <input type="checkbox"/> 73.71(a)(4) |
| | <input type="checkbox"/> 20.2203(a)(2)(iv) | <input type="checkbox"/> 50.46(a)(3)(ii) | <input type="checkbox"/> 50.73(a)(2)(v)(B) | <input type="checkbox"/> 73.71(a)(5) |
| | <input type="checkbox"/> 20.2203(a)(2)(v) | <input type="checkbox"/> 50.73(a)(2)(i)(A) | <input checked="" type="checkbox"/> 50.73(a)(2)(v)(C) | <input type="checkbox"/> OTHER |
| | <input type="checkbox"/> 20.2203(a)(2)(vi) | <input type="checkbox"/> 50.73(a)(2)(i)(B) | <input type="checkbox"/> 50.73(a)(2)(v)(D) | Specify in Abstract below or in NRC Form 366A |

12. LICENSEE CONTACT FOR THIS LER

LICENSEE CONTACT

Terry Syrell, Acting Manager Site Regulatory Assurance

TELEPHONE NUMBER (Include Area Code)

(315) 349-5245

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

| CAUSE | SYSTEM | COMPONENT | MANU-FACTURER | REPORTABLE TO EPIX | CAUSE | SYSTEM | COMPONENT | MANU-FACTURER | REPORTABLE TO EPIX |
|-------|--------|-----------|---------------|--------------------|-------|--------|-----------|---------------|--------------------|
| A | NG | DR | N/A | N | N/A | N/A | N/A | N/A | N/A |

14. SUPPLEMENTAL REPORT EXPECTED☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO**15. EXPECTED SUBMISSION DATE**

| MONTH | DAY | YEAR |
|-------|-----|------|
| N/A | N/A | N/A |

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On February 11, 2015, at approximately 1935 hours, the secondary containment of the Nine Mile Point Nuclear Station Unit 1 (NMP1) Reactor Building (RB) was breached when station personnel opened both inner and outer airlock doors on RB 340 foot elevation simultaneously while traversing through the airlock. The integrity of the airlock was re-established within 5 seconds when one of the doors was closed and latched. Secondary containment differential pressure was unaffected by this event. The cause of the event is failure to use Human Performance verification tools prior to opening the airlock door. Corrective actions include updating the security training program and subsequent implementation. NMP1 LERs 2014-004, 2014-005 and 2014-006 were provided for similar events that occurred on August 13, October 16, and October 20, 2014, respectively. The three LERs in 2014 occurred at the main airlock into the RB 261 foot elevation. This is the first LER for simultaneous opening of the doors on the RB 340 foot elevation.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

| 1. FACILITY NAME | 2. DOCKET | 6. LER NUMBER | | | 3. PAGE |
|------------------------|-----------|---------------|-------------------|---------|---------|
| | | YEAR | SEQUENTIAL NUMBER | REV NO. | |
| Nine Mile Point Unit 1 | 05000220 | 2015 | - 001 | - 00 | 2 OF 5 |

NARRATIVE**I. DESCRIPTION OF EVENT****A. PRE-EVENT PLANT CONDITIONS:**

Prior to the event, Nine Mile Point Nuclear Station Unit 1 (NMP1) was operating at rated thermal power.

B. EVENT:

On Wednesday February 11th, 2015 at approximately 1935 hours, both Unit 1 Reactor Building Airlock Doors on the 340 foot elevation (Door-056 and Door-057) were opened simultaneously, resulting in a momentary loss of Secondary Containment Operability. Upon identification the doors were immediately closed and operability was restored. NMP1 was operating at rated thermal power. The incident occurred as personnel traversed through the airlock. From review of the Badge Access Transaction Report in addition to personnel statements from the prompt investigation, the following scenario had occurred resulting in the event:

At 1935 hours, a Member of the Security Organization (MSO) was exiting the Refuel Floor via D-057, while at the same time a Radiation Protection (RP) Technician was entering through D-056. These actions resulted in the simultaneous opening of both secondary containment doors. This concurrent opening of both airlock doors resulted in a breach of the secondary containment. One of the doors was immediately closed within 5 seconds re-establishing secondary containment integrity.

Operations review determined that the simultaneous opening of both secondary containment airlock doors constituted a momentary loss of secondary containment per Technical Specification 3.4.3 and NUREG 1022, Revision 3.

Review of the Reactor Building differential pressure as recorded by the plant process computer for the time period of the event indicated that the actual differential pressure remained negative and was unaffected by the brief simultaneous opening of the airlock doors.

This event has been documented in the plant's corrective action program as IR 2451218.

C. INOPERABLE STRUCTURES, COMPONENTS, OR SYSTEMS THAT CONTRIBUTED TO THE EVENT:

No other systems, structures, or components contributed to this event.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

| 1. FACILITY NAME | 2. DOCKET | 6. LER NUMBER | | | 3. PAGE |
|------------------------|-----------|---------------|----------------------|------------|------------------|
| Nine Mile Point Unit 1 | 05000220 | YEAR | SEQUENTIAL NUMBER | REV NO. | 3 OF 5 |
| | | 2015 | - 001 | - 00 | |

NARRATIVE

D. DATES AND APPROXIMATE TIMES OF MAJOR OCCURRENCES:

The dates, times and major occurrences for this event are as follows:

February 11, 2015

1935 Worker inside the airlock was exiting secondary containment through D-056 (outer door)
Secondary containment was breached when D-057 (inner door) was opened simultaneously.
One of the doors was immediately closed
Entered TS action statement 3.4.3, Condition C and exited.

E. OTHER SYSTEMS OR SECONDARY FUNCTIONS AFFECTED:

No other systems or secondary functions were affected beyond the systems discussed in Section I.B.

F. METHOD OF DISCOVERY:

This event was discovered by station personnel reporting the issue.

G. MAJOR OPERATOR ACTION:

NMP1 entered TS action statement 3.4.3, and exited it when the inner door was shut.

H. SAFETY SYSTEM RESPONSES:

The duration of this event was approximately 5 seconds. Review of the Reactor Building differential pressure as recorded by the plant process computer for the time period of the event indicated that the actual differential pressure remained negative and was unaffected by the brief simultaneous opening of the airlock doors. Operators entered the applicable TS action statement then exited it soon afterwards. The event concluded when one of the airlock doors was shut.

II. CAUSE OF EVENT:

The MSO involved failed to adhere to established site protocol and administrative requirements governing the use and operation of airlock doors. While attempting to exit the Refuel Floor the MSO approached the inside door (D-057) and validated that he had received a green indicating light. However, contrary to site expectations and administrative postings on the door, the MSO neglected to observe the cameras for inside and outside the airlock, listen for audible door alarms, and pause for an additional five seconds before proceeding. Had the MSO utilized the redundant barriers afforded him, in addition to human performance verification tools, he likely would have observed the RP Technician who had just entered the airlock and the event would not have occurred.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

| 1. FACILITY NAME | 2. DOCKET | 6. LER NUMBER | | | 3. PAGE |
|------------------------|-----------|---------------|----------------------|------------|---------|
| Nine Mile Point Unit 1 | 05000220 | YEAR | SEQUENTIAL NUMBER | REV NO. | 4 OF 5 |
| | | 2015 | - 001 | - 00 | |

NARRATIVE**III. ANALYSIS OF THE EVENT:**

Simultaneous opening of both reactor building airlock doors is reportable under 10 CFR 50.72(b)(3)(v)(C) and 10 CFR 50.73(a)(2)(v)(C). It is defined under paragraph 10 CFR 50.73(a)(2)(v)(C) as any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to control the release of radioactive material. Secondary Containment differential pressure was unaffected by this event.

One of the accesses to the NMP1 Reactor Building refuel floor is through the airlock doors D-056 and D-057. In response to the event, the station entered the action statement for TS 3.4.3 then promptly exited it when the airlock doors were shut. Computer data identified that secondary containment differential pressure was unaffected by this event. Secondary containment structural integrity, the ability to automatically isolate the non-safety related Reactor Building ventilation system, and the Reactor Building Emergency Ventilation System availability were not impacted. It is concluded that the safety significance of this event is low and the event did not pose a threat to the health and safety of the public or plant personnel. This event does not affect the NRC Regulatory Oversight Process Indicators.

IV. CORRECTIVE ACTIONS:**A. ACTION TAKEN TO RETURN AFFECTED SYSTEMS TO PRE-EVENT NORMAL STATUS:**

The RB 340 foot elevation airlock doors were shut.

B. ACTION TAKEN OR PLANNED TO PREVENT RECURRENCE:

Establish and implement a security training solution relating to secondary containment airlock doors. Training should target both current and perspective members of the security organization. Training should include significance of the doors as they relate to personnel safety, nuclear safety, and regulatory compliance along with site expectations for proper usage.

V. ADDITIONAL INFORMATION:**A. FAILED COMPONENTS:**

There were no other failed components that contributed to this event.

B. PREVIOUS LERs ON SIMILAR EVENTS:

NMP1 LER 2014-004, August 13, 2014.

NMP1 LER 2014-005, October 16, 2014.

NMP1 LER 2014-006, October 20, 2014.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

| 1. FACILITY NAME | 2. DOCKET | 6. LER NUMBER | | | 3. PAGE |
|------------------------|-----------|---------------|----------------------|------------|------------------|
| Nine Mile Point Unit 1 | 05000220 | YEAR | SEQUENTIAL NUMBER | REV NO. | 5 OF 5 |
| | | 2015 | - 001 | - 00 | |

NARRATIVE

For the LERs listed above, the secondary containment of the Nine Mile Point Unit 1 (NMP1) Reactor Building was breached when workers opened both inner (D053) and outer (D052) airlock doors simultaneously while passing through. The integrity of the airlock was re-established approximately 5 seconds when one of the doors was closed and latched. Secondary Containment differential pressure was unaffected by these events.

The three LERs in 2014 occurred at the main airlock into the RB 261 foot elevation. This is the first LER for simultaneous opening of the airlock doors on the RB 340 foot elevation.

C. THE ENERGY INDUSTRY IDENTIFICATION SYSTEM (EIIS) COMPONENT FUNCTION IDENTIFIER AND SYSTEM NAME OF EACH COMPONENT OR SYSTEM REFERRED TO IN THIS LER:

| <u>COMPONENT</u> | <u>IEEE 803 FUNCTION IDENTIFIER</u> | <u>IEEE 805 SYSTEM IDENTIFICATION</u> |
|-------------------------------------|-----------------------------------------|-------------------------------------------|
| Reactor Building (BWR) | N/A | NG |
| Reactor Building Ventilation System | PDIC | VA |
| Airlock Door | DR | NG |

D. SPECIAL COMMENTS:

None