

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9910200230 DOC.DATE: 99/10/13 NOTARIZED: NO DOCKET #
FACIL:50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
AUTH:NAME AUTHOR AFFILIATION
MCCOLLUM,W.R. Duke Power Co.
RECIP.NAME RECIPIENT AFFILIATION
Records Management Branch (Document Control Desk)

SUBJECT: Forwards copy of ISI summary rept for Class MC component exams conducted during end of cycle 18 RFO.Rept includes evaluation of degraded moisture barriers detected during insp,which allowed liner plate to be exposed to moisture.

DISTRIBUTION CODE: A047D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2 + 13
TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	HAWES,C	1 1	LABARGE,D	1 1
INTERNAL:	ACRS	1 1	<u>FILE CENTER 01</u>	1 1
	NUDOCS-ABSTRACT	1 1	OGC/RP	1 0
	RES/DET/ERAB	1 1	RES/DET/MEB	1 1
EXTERNAL:	LITCO ANDERSON	1 1	NOAC	1 1
	NRC PDR	1 1		

MICROFILMED

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 11 ENCL 10



W. R. McCollum, Jr.
Vice President

Duke Power

Oconee Nuclear Site
7800 Rochester Highway
Seneca, SC 29672

(864) 885-3107 OFFICE
(864) 885-3564 FAX

October 13, 1999

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


Subject: Duke Power Company
Oconee Nuclear Station, Unit 1
Docket No. 50-269
Unit 1 EOC 18 Refueling Outage
Inservice Inspection Summary Report for Class MC
Component Examinations

Please find attached a copy of the Inservice Inspection Summary Report for Class MC Component Examinations conducted during Oconee Unit 1 End of Cycle 18 Refueling Outage, which ended July 8, 1999. This report is submitted pursuant to 10 CFR 50.55a (b) (2) (x).

This report includes an evaluation of degraded moisture barriers detected during the inspection, which allowed the liner plate to be exposed to moisture. There was no detectable loss of wall thickness. This report also contains commitments for corrective actions related to repairs and additional inspections to address these moisture barriers. These are the only commitments contained in this report.

If there are any questions you may contact R. P. Todd at (864) 885-3418 or M. J. Ferlisi at (704) 382-3923.

Very truly yours,



W. R. McCollum, Jr.
Site Vice-President

Attachment

9910200230 991013
PDR, ADOCK 05000269
G PDR

A04711

U. S. Nuclear Regulatory Commission

October 13, 1999

Page 2

xc wo/attachment: Mr. Luis A. Reyes
Administrator, Region II
U.S. Nuclear Regulatory Commission
61 Forsyth Street, S. W., Suite 23T85
Atlanta, GA 30303

D. E. LaBarge, Projects Manager
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

D. E. Billings
Acting Senior NRC Resident Inspector
Oconee Nuclear Station

Mr. Virgil Autrey
Division of Radioactive Waste Management
Bureau of Land and Waste Management
SC Dept. of Health & Environmental Control
2600 Bull St.
Columbia, SC 29201