



May 15, 2015

NG-15-0132
10 CFR 50.73

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555-0001

Duane Arnold Energy Center
Docket 50-331
Renewed Op. License No. DPR-49

Licensee Event Report #2015-001

Please find attached the subject report submitted in accordance with 10 CFR 50.73. This letter makes no new commitments or changes to any existing commitments.

A handwritten signature in black ink, appearing to be "T. A. Vehec". The signature is stylized with a large, looped initial "V" and a long, sweeping horizontal stroke extending to the right.

T. A. Vehec
Vice President, Duane Arnold Energy Center
NextEra Energy Duane Arnold, LLC

cc: Administrator, Region III, USNRC
Project Manager, DAEC, USNRC
Resident Inspector, DAEC, USNRC

Handwritten initials in black ink, reading "IE22" above "MFR". The "IE22" is written in a large, bold, sans-serif font, and "MFR" is written in a smaller, all-caps sans-serif font below it.



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Duane Arnold Energy Center

2. DOCKET NUMBER

05000-331

3. PAGE

1 OF 3

4. TITLE

Both Doors in Secondary Containment Airlock Opened Concurrently

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
03	21	2015	2015	001	00	05	15	2015	N/A	N/A
9. OPERATING MODE										
11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)										
1			<input type="checkbox"/> 20.2201(b)			<input type="checkbox"/> 20.2203(a)(3)(i)			<input type="checkbox"/> 50.73(a)(2)(i)(C)	
			<input type="checkbox"/> 20.2201(d)			<input type="checkbox"/> 20.2203(a)(3)(ii)			<input type="checkbox"/> 50.73(a)(2)(ii)(A)	
			<input type="checkbox"/> 20.2203(a)(1)			<input type="checkbox"/> 20.2203(a)(4)			<input type="checkbox"/> 50.73(a)(2)(ii)(B)	
			<input type="checkbox"/> 20.2203(a)(2)(i)			<input type="checkbox"/> 50.36(c)(1)(i)(A)			<input type="checkbox"/> 50.73(a)(2)(iii)	
10. POWER LEVEL			<input type="checkbox"/> 20.2203(a)(2)(ii)			<input type="checkbox"/> 50.36(c)(1)(ii)(A)			<input type="checkbox"/> 50.73(a)(2)(iv)(A)	
			<input type="checkbox"/> 20.2203(a)(2)(iii)			<input type="checkbox"/> 50.36(c)(2)			<input type="checkbox"/> 50.73(a)(2)(v)(A)	
			<input type="checkbox"/> 20.2203(a)(2)(iv)			<input type="checkbox"/> 50.46(a)(3)(ii)			<input type="checkbox"/> 50.73(a)(2)(v)(B)	
			<input type="checkbox"/> 20.2203(a)(2)(v)			<input type="checkbox"/> 50.73(a)(2)(i)(A)			<input checked="" type="checkbox"/> 50.73(a)(2)(v)(C)	
			<input type="checkbox"/> 20.2203(a)(2)(vi)			<input type="checkbox"/> 50.73(a)(2)(i)(B)			<input type="checkbox"/> 50.73(a)(2)(v)(D)	
									<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
									<input type="checkbox"/> 50.73(a)(2)(ix)(A)	
									<input type="checkbox"/> 50.73(a)(2)(x)	
									<input type="checkbox"/> 73.71(a)(4)	
									<input type="checkbox"/> 73.71(a)(5)	
									<input checked="" type="checkbox"/> OTHER	
									Specify in Abstract below or in NRC Form 366A	

12. LICENSEE CONTACT FOR THIS LER

LICENSEE CONTACT

Laura B. Swenzinski, Senior Licensing Engineer

TELEPHONE NUMBER (Include Area Code)

(319) 851-7724

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
X	JM	IEL	Alarm Lock	N	N/A	N/A	N/A	N/A	N/A

14. SUPPLEMENTAL REPORT EXPECTED

☒ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☐ NO

15. EXPECTED SUBMISSION DATE

MONTH	DAY	YEAR
06	30	2015

ABSTRACT (Limit to 1400 spaces. i.e., approximately 15 single-spaced typewritten lines)

On March 21, 2015, while operating at 100% power, workers opened doors concurrently when entering a secondary containment access airlock. The individuals involved each closed their respective doors upon encountering this unexpected condition; however, the result was a brief inoperability of secondary containment integrity. This resulted in an 8 hour reportable event. The Resident Inspector was notified, and an Event Notification was made pursuant to 10 CFR 50.72(b)(3)(v)(C) due to a condition at the time of discovery that prevented the fulfillment of the Secondary Containment safety function (Reference EN#50914).

Following the event, the doors were verified to be functioning properly and no deficiencies were noted on either door. A Root Cause Evaluation is currently being conducted and when completed, a Supplemental Report will be submitted detailing the cause(s) and corrective action(s) for this event.

This event did not result in a safety system functional failure. There were no radiological releases associated with this event.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollections.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Duane Arnold Energy Center	05000-331	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 3
		2015	- 001	- 00	

NARRATIVE**I. Description of Event:**

On March 21, 2015 at 0030, while operating at 100% power, the Control Room Supervisor (CRS) received a call that Door 225 and Door 228, both in Secondary Containment Airlock 216 had been opened concurrently. The doors being open at the same time caused a failure to meet SR 3.6.4.1.2 to verify that either the outer door(s) or the inner door(s) in each Secondary Containment access opening are closed. The identified condition caused Secondary Containment to be considered inoperable per TS LCO 3.6.4.1. The individuals involved immediately closed their respective doors upon encountering this unexpected condition. This action allowed SR 3.6.4.1.2 to be met, and restored Secondary Containment to an operable status.

This resulted in an 8 hour reportable event. The Resident Inspector was notified, and an Event Notification was made pursuant to 10 CFR 50.72(b)(3)(v)(C) due to a condition at the time of discovery that prevented the fulfillment of the Secondary Containment safety function (Reference EN#50914). Secondary containment leak tightness is required to ensure that the release of radioactive materials from the primary containment is restricted to those leakage paths and associated leakage rates assumed in the accident analysis and that fission products entrapped within the secondary containment structure will be treated by the Standby Gas Treatment System prior to discharge to the environment.

The Secondary Containment airlock utilizes an interlock device with an adjustable permanent magnet (mounted on the door), and an electromagnet (on the door frame) arranged in an electrical circuit so that door(s) are held closed and/or are allowed to open. Immediately following the event, the doors were verified to be functioning properly and no deficiencies were noted on either door. On March 22, 2015 at 1619 hours, surveillance testing was performed satisfactorily per Surveillance Test Procedure (STP) 3.6.4.1-02, Secondary Containment Airlock Verification.

There were no radiological releases associated with this event. There were no other structures, systems or components inoperable at the start of this event that contributed to the event.

II. Assessment of Safety Consequences:

There were no actual safety consequences associated with this event; the potential safety consequences were minimal. Both doors on the airlock were open simultaneously for less than 10 seconds, and were able to close immediately upon discovery of the condition.

This event will not be reported as a safety system functional failure since an engineering analysis (Corrective Action ACE1968923-01) determined that the system is capable of performing its safety function during events when the airlock is open for less than 10 seconds. The post-LOCA dose calculation does not credit secondary containment integrity for mitigation of on-site and off-site doses for the first 5 minutes of the event. Therefore, this event is bounded by the existing dose calculation.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Duane Arnold Energy Center	05000-331	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 3
		2015	- 001	- 00	

NARRATIVE

This event did not result in a safety system functional failure. There were no automatically or manually initiated safety system responses.

III. Cause of Event:

A Root Cause Evaluation is currently being conducted and when completed, a Supplemental Report will be submitted detailing the cause(s) and corrective action(s) for this event.

IV. Corrective Actions:

An operational check of the Secondary Containment door interlocks is performed monthly via STP 3.6.4.1-02, Secondary Containment Airlock Verification. A Root Cause Evaluation is currently being conducted and when completed, a Supplemental Report will be submitted detailing the cause(s) and corrective Action(s) for this event.

V. Additional Information:

Previous Similar Occurrences:

A review of DAEC Licensee Event Reports from the past 5 years identified three similar occurrences, reference LER 2013-006, LER 2014-002 and LER 2014-003.

A review of the corrective action program identified additional occurrences of airlock conditions causing momentary secondary containment inoperability - seven additional occurrences in the past two years, with two of those occurring in the last year.

EIIS System and Component Codes:

IEL Interlock

Reporting Requirements:

This event is being reported as an event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to control the release of radioactive material, 10CFR50.73(a)(2)(v)(C).