

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

Title: BRIEFING ON CORE SHROUD ISSUES
PUBLIC MEETING

Location: Rockville, Maryland

Date: Wednesday, February 1, 1995

Pages: 1 - 44

2025 RELEASE UNDER E.O. 14176

ANN RILEY & ASSOCIATES, LTD.
1250 I St., N.W., Suite 300
Washington, D.C. 20005
(202) 842-0034

DISCLAIMER

This is an unofficial transcript of a meeting of the United States Nuclear Regulatory Commission held on February 1, 1995 in the Commission's office at One White Flint North, Rockville, Maryland. The meeting was open to public attendance and observation. This transcript has not been reviewed, corrected or edited, and it may contain inaccuracies.

The transcript is intended solely for general informational purposes. As provided by 10 CFR 9.103, it is not part of the formal or informal record of decision of the matters discussed. Expressions of opinion in this transcript do not necessarily reflect final determination or beliefs. No pleading or other paper may be filed with the Commission in any proceeding as the result of, or addressed to, any statement or argument contained herein, except as the Commission may authorize.

1 UNITED STATES OF AMERICA
2 NUCLEAR REGULATORY COMMISSION

3 ***

4 BRIEFING ON CORE SHROUD ISSUES

5 ***

6 PUBLIC MEETING

7
8 U.S. Nuclear Regulatory Commission
9 One White Flint North
10 Rockville, Maryland
11

12 Wednesday, February 1, 1995
13

14 The Commission met in open session, pursuant to
15 notice, at 2:00 p.m., Ivan Selin, Chairman, presiding.
16

17 COMMISSIONERS PRESENT:

18 IVAN SELIN, Chairman of the Commission
19 KENNETH C. ROGERS, Commissioner
20 E. GAIL de PLANQUE, Commissioner
21
22
23
24
25

ANN RILEY & ASSOCIATES, LTD.
Court Reporters
1250 I Street, N.W., Suite 300
Washington, D.C. 20005
(202) 842-0034

1 STAFF SEATED AT THE COMMISSION TABLE:

2 KAREN CYR, General Counsel

3 JOHN C. HOYLE, Acting Secretary

4 JAMES TAYLOR, Executive Director for Operations

5 WILLIAM RUSSELL, Director, NRR

6 BRIAN SHERON, Director, Division of Engineering,
7 NRR

8 ASHOK THADANI, Associate Director for Inspection
9 and Technical Assessment, NRR

10 EDWIN HACKETT, Senior Materials Engineer, NRR

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

ANN RILEY & ASSOCIATES, LTD.
Court Reporters
1250 I Street, N.W., Suite 300
Washington, D.C. 20005
(202) 842-0034

P R O C E E D I N G S

[2:00 p.m.]

CHAIRMAN SELIN: Good afternoon, ladies and gentlemen.

I'm pleased to welcome members of the staff to brief the Commission on the cracking of boiling water reactor core shrouds and on the more general question of aging of internals of boiling water reactors.

The Commission has the impression that once the staff became aware of these problems in 1993 that they and the industry have, in fact, worked together both smoothly and productive to assess the overall safety significance to bound the problem, to improve the inspection methodologies in order to detect the problem and to move quickly. Instead of hoping that the problem would go away, to move quickly with repair plans to limit the possibility of core shroud separation in case of certain design basis accidents or seismic events.

We're particularly interested in the discussion of the inspections conducted to date by licensees in accordance with our generic letter of last July.

Commissioner Rogers?

Mr. Taylor, would you proceed?

MR. TAYLOR: Good afternoon. With me at the table are Bill Russell, Brian Sheron, Ashok Thadani and Ed

1 Hackett, all from NRR.

2 Mr. Chairman, this will update the Commission on
3 several papers that we've given the Commission, the last one
4 in November of this past year, and we have of course more up
5 to date and additional information from that briefing,
6 particularly on the core shroud examinations and the work
7 that's been going on. Brian Sheron will be the principal
8 briefer.

9 Brian?

10 MR. SHERON: Thank you.

11 Could I have the first slide, please?

12 [Slide.]

13 MR. SHERON: This is just an outline of the topics
14 which I'll touch on during the briefing.

15 Next slide, please.

16 [Slide.]

17 MR. SHERON: This is just to show you a
18 configuration of the core shroud. You'll note that it sits
19 inside the vessel between the -- or just inside the jet
20 pumps which sit between the vessel wall and the shroud.

21 Just to refresh you on your memory on this, the
22 core shroud basically is provided to direct the flow through
23 the core, provide structural support for the core, lateral
24 support for the core, proper control rod insertion geometry
25 and provides a refloodable volume following a loss of

1 coolant accident.

2 Next slide, please.

3 [Slide.]

4 MR. SHERON: This shows again the core shroud.
5 What's of note here is the location of the welds which is of
6 primary concern. This model here, which is a Brunswick
7 shroud, will help you visualize. This is about 1/20th scale
8 actually. The shroud is about 20 feet high. This shows you
9 where the welds are, both the vertical welds as well as the
10 horizontal ones. They're numbered. These are not the same
11 numbering for every shroud, but they're fairly consistent
12 and it's usually at the top, starts at H1 and works its way
13 down.

14 What you see here, these narrow ones are rings
15 which sit in and that's where the top guide and also the
16 core plate would sit on. You'll see that further in some
17 other drawings. You'll note that the jet pumps sit right on
18 the outside of this and are actually attached to the shroud
19 up at the top portion there.

20 Next slide, please.

21 [Slide.]

22 MR. SHERON: Shrouds are made of stainless steel,
23 either 304 or the low carbon stainless steel. As I said
24 before, the height is around 20 feet high. Diameters range
25 from 14 to 17 feet. The walls, which are normally about one

1 and a half to two inches thick, are actually that thick
2 because of concerns for stiffness when they transport it and
3 so forth. If one actually had to look at what is the
4 required thickness to meet the structural demands when it's
5 in operation, my understanding is that you could actually
6 have a shroud that's half an inch thick. So, there is a lot
7 of margin in the structural design of the shrouds.

8 As I said before, it's constructed of welded
9 plates which are these, as you can see, which are rolled and
10 then welded. The rings here can either be welded plates
11 where they're actually cut from a rolled plate and then
12 welded together into a ring or they can be forged. That's
13 of interest when one is looking is stress corrosion cracking
14 and the causes of it. You get stresses in this mostly from
15 the residual stresses from the welds. When you weld
16 something you're heating it up, as it cools it builds up
17 residual stresses in the vicinity of the weld area. It's
18 the weld area in what we call these heat affected zones that
19 is particularly susceptible to the stress corrosion
20 cracking.

21 Next slide, please.

22 [Slide.]

23 MR. SHERON: As I said, this is a model of the
24 Brunswick shroud. Brunswick was actually the first U.S.
25 plant that saw cracking in the shroud. It was discovered

1 during a routine examine as recommended by GE. It occurred
2 at H3, which on this you can see is right up here by the top
3 ring. The extent was 360 degrees around the circumference
4 and the maximum depth was 1.7 inches out of a two inch thick
5 shroud. So, you can see it was fairly deep.

6 Similar cracking in the core plate support ring,
7 which is down -- on this one it's H6. I believe it was H5
8 in Dresden and Quad Cities. This was also seen at -- I'm
9 sorry, Dresden 3 and Quad 1, which we found last spring.
10 I'll be discussing this further.

11 Next slide, please.

12 [Slide.]

13 MR. SHERON: On this slide, this actually shows
14 you where the cracking was seen at Dresden and Quad cities.
15 This shows the actual location of the crack which is on the
16 ring which was right down here. You can see these cracks
17 many times grew from the outside in, although we have seen
18 in other instances where we saw cracking on both sides. So,
19 it's not preferential to one side.

20 Next slide, please.

21 [Slide.]

22 MR. SHERON: The real question obviously is what
23 is the safety significance of all this. Well, first off,
24 the fact that it's cracked is not of immediate concern.
25 What's really of concern is if it's cracked all the way

1 through and can be detached, you might say, so that these
2 rings can be separated. Under normal conditions, if you
3 have a crack in the upper elevation, what will happen is
4 that the flow -- remember on top of this whole thing there's
5 a dome with steam dryers and everything and the flow will
6 actually lift. There's enough force that it will actually
7 lift the upper portion slightly.

8 What happened, since the pressure on the outside
9 is higher than the pressure on the inside, remember the flow
10 is coming in, going down through the jet pumps and up
11 through the core so there's a pressure drop, you will get
12 flow going in, directed in through any cracks that exist.
13 What you would see is a power to flow mismatch and the
14 operators would be able to detect it. If you did have
15 cracks in these lower elevations, however, there's not
16 enough force to lift this thing up. So, what happens is
17 you're not going to see any flow going in and you may not be
18 able to really see it or anything.

19 The accidents that we worry about with this,
20 there's about three that really concern us, the main steam
21 line break, an earthquake or a recirculation line break.
22 With the steam line break, as you know, which the break will
23 be at the top, so the forces, the flow, et cetera, will be
24 trying to go this way through the core. What you're worried
25 about is that if it does lift this -- if you can see on the

1 top here, there's a thing called the top guide where the
2 control rods are held in place. If that lifts too far, what
3 happens is you lose the lateral support of the fuel
4 assemblies and so forth and you may not be able to insert
5 the control rods. You'll get misalignment. So, the concern
6 there is if it lifts too much during a steam line break and
7 the rod is trying to go in, they may not be able to go in.

8 Earthquake, it's the same thing. If you shake
9 this and it's broken here, if it can laterally displace,
10 again you'll have a misalignment problem and the rods may
11 not be able to go in.

12 With the recirculation line break, if you recall
13 the recirculation line comes in low. The flow is directed
14 up through pipes, in through the jet pumps, down and then
15 through the core and up. What will happen is you will blow
16 down through the core, so the forces are going to be going
17 around the vessel, up and out through the break on the
18 recirculation line and you get an asymmetric force on the
19 core shroud. Okay. So, the force on one side is going to
20 be higher than the other. If it's enough, there can be a
21 tendency if this is cracked through at a lower elevation you
22 will tip it over and maybe even laterally displace it. What
23 happens is once the blow down is done, if this thing doesn't
24 come back down in its original place, there's going to be a
25 gap down here. Then when the ECC system comes on and tries

1 to reflood the core, what happens is it will only flood up
2 to the point where there's still a gap and then the water is
3 just going to flow out and go out the break.

4 So, as I said, this is required for the
5 refloodable volume. So, if there's no crack here, you can
6 flood this up and you cover the core and everything is okay.
7 If it's cracked low and it's displaced, you can't reflood
8 the core and you just have to rely on the core sprays, which
9 may not be acceptable for some of the plants.

10 Next slide, please.

11 [Slide.]

12 MR. SHERON: This is just to show you
13 schematically where things have to be flooded up to. This
14 shows the flow paths in relationship to the core shroud.
15 You'll see that you can flood during a LOCA in a recirc line
16 up to the top of the jet pumps. After that, the water will
17 just run down the jet pumps and out through the break.
18 Okay. So you normally will flood these up to two-thirds
19 core height and the steaming from the water that's boiling
20 in the core, coupled with the spray, will keep the core
21 cool.

22 Next slide, please.

23 [Slide.]

24 CHAIRMAN SELIN: I'm sorry. This is assuming that
25 you have scrambled or you haven't scrambled?

1 MR. SHERON: Yes. Normally though, even if you --
2 once you blow the thing down and you void the core during
3 the blow down, actually the reactor will shut down. But you
4 worry about when you reflood whether you get any kind of
5 criticality again.

6 Regulatory actions that have been taken to date.
7 Well, when we saw the cracking at Brunswick, an Information
8 Notice 93-79 was issued. Similarly, when we saw the
9 cracking at Dresden 1 and Quad Cities 3, Information Notice
10 94-42 was issued, as well as a supplement to it. Then, as
11 I'm sure you're aware, on July 25th of last year, we issued
12 Generic Letter 94-03. This, in essence, required the
13 industry or the BWR owners, I should say, to inspect and
14 repair their core shrouds at the next refueling outage.
15 They should provide -- and most importantly, this was the
16 most important part, was provide a safety assessment as to
17 why they believed their plants could continue to operate
18 until they performed that inspection and then to provide us
19 with their inspection and repair plans 30 days prior to the
20 outage.

21 Next slide, please.

22 [Slide.]

23 MR. SHERON: Now, while we did all this, the
24 industry was not sitting on their hands either. GE issued
25 some service information letters with regard to the shroud

1 cracking that had been seen and recommendations, et cetera,
2 for inspection. The owners formed what they called BWR
3 vessel and internals project, which is a special committee.
4 It is made up of senior vice presidents from the utilities,
5 so it has a very high level of visibility within the
6 industry. It is also, besides the main committee, it is
7 compose of five subcommittees. There's an Integration
8 Subcommittee, an Inspection Subcommittee, Assessment
9 Subcommittee, Repair Subcommittee and a Mitigation
10 Subcommittee. You can see that they have three of these
11 subcommittees, the Inspection, Assessment and Repair
12 Subcommittees, have all submitted topical reports so far.
13 So, they have not been just giving us lip service, they've
14 actually, I think, done a very credible job.

15 The inspection topical report gave guidance on
16 doing inspections. The assessment topical report, which was
17 actually the same as the inspection, gave guidance on how to
18 do a structural analysis, and the repair topical gave
19 guidance on the basically guidelines for designing a repair.

20 Next slide, please.

21 [Slide.]

22 MR. SHERON: Now, where are we today with all
23 this? First, we've established what the key -- I mean this
24 thing is all being caused by intergranular stress corrosion
25 cracking of the metal near the welds. One thing we did is

1 we have established what the key factors are relative to
2 where are these plants susceptible to this kind of cracking.
3 We have met with EPRI and a BWR Vessel Internals Project
4 Group to discuss the scope of core shroud inspections. This
5 was an important part. There was a disagreement with the
6 industry. Their initial proposal was to only inspect what I
7 call minimum metal. In other words, they would go in and
8 inspect and if they could demonstrate that there was
9 sufficient ligaments in locations, say, I think a minimum
10 like three inches in every quadrant, that would be
11 sufficient to meet the requirements of the ASME code and
12 therefore they would not inspect anymore at that weld.

13 We were not really in agreement with this. We
14 felt that because of the significance of it that a utility
15 should really go in and do a full inspection, 100 percent of
16 all accessible welds in order to best characterize really
17 the extent of the cracking and degree of the problem.

18 The other thing with regard to the inspections I
19 would mention is that it was interesting that when they
20 actually got in and did inspections, they ran into a myriad
21 of problems, nothing runs smoothly. They have a device by
22 GE called a tracking scanner which I believe sits and runs
23 around here on top of the shroud. What was happening, it
24 was getting jammed up and not working properly. There were
25 some situations where they went in one plant, didn't even

1 have a shroud that was round. Okay. It was out of round.
2 Another one, they found out that the gap between the shroud
3 and the vessel was too small to fit this thing and it was
4 jamming up in there. So, there are a number of problems
5 which really affected the ability to do 100 percent
6 accessible inspections on the first plants that really went
7 in and did this.

8 The problem, really what that manifests itself in
9 is that when they do it and they run into a problem, it
10 affects their critical path. They're in an outage and
11 therefore it was very painful if they had to continue to
12 stay down while they did the inspection. So, there was
13 always an incentive if they couldn't do the full 100 percent
14 accessible weld, they would want to do only what was
15 minimally necessary in order to get back on-line.

16 So, I think we've resolved that. We've had some
17 meetings with EPRI down at the NDE Center in Charlotte and
18 my understanding is that I think we've reached agreement
19 with the industry on the scope of these inspections.

20 We are continuing our analysis of the inspection
21 results from each of these plants as they come down and go
22 in and do the inspection, trying to understand what they've
23 seen, trying to again look at the correlation with regard to
24 the susceptibility factors. We are also reviewing the
25 assessments for the repair acceptability and I'll get to

1 that in a minute. Some of these plants are putting repairs
2 in. We have completed our review of Generic Letter 94-03
3 responses.

4 I'll tell you right now that basically we found
5 all of the responses acceptable in terms of the
6 justification for operating until the scheduled outage that
7 they plan to come down and do the inspection. There were
8 several plants in the higher susceptibility category, which
9 I'll also talk about, which we had a number of questions
10 about their plans and their justification. On several
11 occasions we brought them in for a day long meeting, I
12 believe Pilgrim came in and Dresden 2 and Quad 2 came in, in
13 which they gave us much more extensive presentations, but
14 ultimately we were satisfied that they had a justification,
15 proper justification for continuing the operation.

16 COMMISSIONER de PLANQUE: And you're now satisfied
17 that the scope of the inspection program is adequate?

18 MR. SHERON: Yes, so far.

19 COMMISSIONER de PLANQUE: Okay.

20 MR. SHERON: With regard to Generic Letter 94-03,
21 let me just go through some of the technical bases, why we
22 felt it was acceptable to continue operating until the next
23 inspection. These are more generic reasons. One is that
24 despite the fact we have seen cracking, we have not seen any
25 360 degree through-wall cracking so far. No plants have

1 seen that and there may be a reason for that. That is that
2 if you go back and look at those diagrams at the welds, what
3 you will see is what we think is driving these cracks is the
4 residual stresses from the welding. Once the crack proceeds
5 past the heat affected zone, you run out of residual stress
6 and that there's nothing left to drive the crack. So, they
7 may self-arrest, but we don't know that for sure. But that
8 may be the reason why we're not seeing anything through-
9 wall.

10 We have not seen any symptoms of power to flow
11 mismatch in any plants which would indicate even that even
12 if a plant had not shut down and done an inspection that
13 they were not experiencing any 360 cracks, at least in the
14 upper portions. As I said before, in order for these things
15 to hold together, you just need a very small ligament in the
16 various quadrants. So, you can have like a ligament in only
17 three quadrants or even in two. It was just a small
18 distance, maybe three or four inches. That would be
19 sufficient to hold this whole thing together.

20 The ASME code margins are satisfied based on all
21 the inspections that we've seen, even the ones that have
22 seen some cracking. Dresden and Quad Cities, for example,
23 which, as you know, they came in and justified continuing to
24 operate for 15 months even though they did have some
25 cracking. It wasn't through-wall. The reason was because

1 they did a stress analysis and showed that the ASME code
2 margins were still satisfied, even assuming crack growth
3 rates over the cycle that they would propose to run the
4 plant.

5 Also, there's a low frequency of the initiating
6 event. As I said before, these things -- the real concern
7 is when you have either a steam line break or a
8 recirculation line break. These are relatively low
9 frequency events. We've never seen one or anything. So,
10 the likelihood of getting one of these in the period before
11 they inspect is fairly low. The reason too is it's a short
12 period of operation. Those plants will be inspecting within
13 months of when they got the letter.

14 There are a number of plant-specific factors which
15 we also took into consideration for the higher
16 susceptibility plants. These have to do with things like
17 water chemistry, the low radial stresses on the lower weld,
18 for example, at a non-jet pump plant.

19 COMMISSIONER ROGERS: Just before you leave that.

20 MR. SHERON: Yes, sir.

21 COMMISSIONER ROGERS: Do you recall what those
22 ASME code margins are, how they work?

23 MR. SHERON: Yes. We actually anticipated that
24 question. My understanding is they are for accidents.
25 They're 1.4 times the allowable stresses and they are 2.77

1 times allowable stresses for normal operation.

2 COMMISSIONER ROGERS: And how well are they
3 satisfied here?

4 MR. SHERON: Ed, you looked at that.

5 MR. HACKETT: They're satisfied by quite a degree.
6 As Brian said, 90 percent through-wall is almost what you
7 could satisfy here. So, that means on the shroud you're
8 talking something on the order of a tenth of an inch
9 remaining metal that could satisfy these margins.

10 COMMISSIONER ROGERS: Thank you.

11 MR. SHERON: Then when we looked at Dresden and
12 Quad Cities, for example, what we did is when we looked at
13 how much longer they could operate before they would come
14 down again to inspect, we used conservative crack growth
15 rates. We assumed that these cracks would grow at that
16 maximum rate and still maintain the ASME code margins.

17 DR. THADANI: That was for 15 additional months of
18 operation.

19 COMMISSIONER ROGERS: And that ligament, how big
20 is that that's required?

21 MR. SHERON: I'm sorry?

22 COMMISSIONER ROGERS: How large is the ligament
23 required for adequate structural integrity?

24 MR. HACKETT: That would be what we were referring
25 to just then as the tenth of an inch, for instance.

1 COMMISSIONER ROGERS: Oh, okay, just that. Okay.
2 All right.

3 MR. HACKETT: It comes down to the fact that the
4 steel is that forgiving a material.

5 COMMISSIONER ROGERS: I just viewed this as some
6 kind of a bridging of cracks, but it's just residual
7 material that's left.

8 MR. HACKETT: That would be a ligament left on the
9 inside or the outside of the wall.

10 COMMISSIONER ROGERS: Fine. Fine. Thank you.

11 MR. SHERON: Could I have the next slide, please?
12 [Slide.]

13 MR. SHERON: Let me just talk quickly on the
14 susceptibility criteria for stress corrosion cracking.
15 These are the five elements which seem to have affected the
16 greatest operational time. This is at power. Reactor water
17 chemistry, in essence the conductivity of the water. As I
18 said before, the carbon content of the material, high carbon
19 being more susceptible than a low carbon content steel.
20 Shroud fabrication methods, as I said, some plants, these
21 rings right here are made from rolled plate and then cut and
22 welded together into segments. In others, they're forged.
23 When you have a rolled plate and you cut it, you leave
24 basically an end grain here which is exposed then to the
25 coolant. That seems to be more susceptible than the forged

1 rings. So, a plant that has a forged ring is less
2 susceptible.

3 Then, as I said before, the weld stresses. Again,
4 the residual stresses seem to be what's driving these cracks
5 once they initiate.

6 COMMISSIONER ROGERS: Just on the water chemistry.
7 What are the factors there that are most important? I seem
8 to remember some time ago GE considering addition of zinc
9 for some purposes, I can't remember what it was, probably to
10 reduce crude or something, reduce radioactive background.
11 But I don't remember what it was. But ten years ago or so
12 there was a flurry of activity to consider the addition of
13 zinc, small quantities of zinc. Has anybody looked at the
14 relevance of that to this phenomena?

15 MR. HACKETT: They are looking at those as
16 mitigation methods. Zinc would act as a sacrificial anode,
17 would be the appropriate term electrochemically. What
18 they're looking at now is potentially noble metal coatings
19 and possibly the additions of catalysts to the reactor
20 coolant water. The idea there would be to reduce what's
21 called the electrochemical potential, which is the driving
22 force for stress corrosion. So, that's some of the methods
23 that they have under consideration for mitigation.

24 COMMISSIONER ROGERS: But these are really
25 microscopic, very tiny.

1 MR. RUSSELL: Very small.

2 COMMISSIONER ROGERS: Yes.

3 MR. RUSSELL: They're also looking at hydrogen
4 water chemistry to potentially assist as well. That has the
5 downside of increased radiation source term. So, that's one
6 that's being looked at carefully on a plant by plant basis.

7 COMMISSIONER ROGERS: Well, the question I had in
8 mind was whether there's any connection between any
9 specifics of the water chemistry programs of these reactors
10 that are showing this and any of the proposed -- well, any
11 of the considered treatments, water treatments that have
12 been either used or not used over the last 20 years or so.

13 MR. HACKETT: Really, what it comes down to is to
14 a large degree it's cleanliness. The cleaner the water or
15 the lower the ionic content, the less the conductivity and
16 hence the less the driving force for the reaction. So, over
17 the years they've tried to increase the cleanliness of the
18 water primarily and the EPRI has published guidelines on
19 cleanliness of the BWR water.

20 Then the VIP, as Brian alluded to earlier, has one
21 subcommittee on mitigation that's studying some of these
22 advanced methods. The only one that's employed at the
23 moment is hydrogen water chemistry which was used very
24 effectively for the recirc piping and there's good arguments
25 to be made that it would be very effective for the lower

1 internals but less effective as you go up through the core.

2 COMMISSIONER ROGERS: Yes. My understanding is
3 you have some questions about that, how effective that is
4 over the life of the plant --

5 MR. HACKETT: That's right.

6 COMMISSIONER ROGERS: -- when it might be
7 effective and when it might, in fact, be sort of a negative
8 factor.

9 MR. RUSSELL: We've discussed it in the context of
10 mitigation. I think it's also important to recognize that
11 the history of prior water chemistry, particularly if there
12 had been any excursions, contaminants going in, could be
13 quite significant. That's one of the things that was looked
14 at. Generally, some of the older reactors did not have the
15 same water chemistry treatment early on and have had, even
16 in some cases, some chloride intrusion, so that those may be
17 making it more susceptible than others.

18 COMMISSIONER ROGERS: But so far you haven't been
19 able to connect any of that with this particular phenomenon.
20 Is that right?

21 MR. HACKETT: There is a correlation between --
22 you raised an interesting point. What we'd like to have is
23 a measure of the electrochemical potential for all these
24 plants. We don't have that necessarily as a function of
25 core height. What we do have is the conductivity. Actually

1 there is a very good correlation with the industry tabulated
2 the average over the first five cycles for many of these
3 plants, their average conductivity. We have found that when
4 that average is high we do see a relatively high incidence
5 of cracking. There's been a very strong correlation there.

6 COMMISSIONER ROGERS: Thank you.

7 MR. SHERON: Could I have the next slide, please?

8 [Slide.]

9 MR. SHERON: Picking up on what Ed said on the
10 susceptibility rankings, you will see that water chemistry
11 is one of the key factors here. We've actually categorized
12 the plants, the fleet of BWRs, into three categories with
13 regard to susceptibility to experiencing the stress
14 corrosion cracking. You will see that category A, which is
15 the least susceptible plants, there are eight units that we
16 feel are in that category. The criteria there are that
17 they've been on-line less than eight years. They've had
18 good initial water chemistry and they have low carbon steel
19 in their shrouds.

20 The middle category, Category B, there are six
21 units there. For these plants they would have been on-line
22 more than eight years. They've had good to moderate initial
23 water chemistry and again low carbon steel.

24 Then, where the majority of the units fall, 22,
25 Category C, these would have more than six on-line years for

1 BWRs with shrouds fabricated from the regular 304 stainless
2 and eight years for those constructed using the low carbon.
3 They would have moderate to poor water chemistry.

4 Could I have the next slide, please?

5 [Slide.]

6 MR. SHERON: Now, of the 22 plants in Category C,
7 we looked at those a little bit harder. What we concluded
8 was that of the 22, 11 really had the potential for
9 significant cracking. We felt that when we looked at the
10 conditions at these plants, we felt that they bounded all
11 the other BWRs.

12 What I'm showing here is these 11 plants. They're
13 basically ranked in order of their susceptibility. The
14 other two columns show either if they've inspected or plan
15 to inspect and also whether they have installed a repair yet
16 or when they plan to install a repair.

17 The three plants that have put the repairs in so
18 far are Fitzpatrick. Actually, they're doing it right now
19 as we talk, I think. Oyster Creek has completed their
20 repair. Brunswick 1 and 2 completed a repair but it was not
21 what I will talk to you about, which is the tie rod design.
22 It was these clamps because they only saw cracking at the
23 H2, H3 area here and they put these small clamps on. These
24 are not the kind of repairs that were done at Hatch or at
25 Oyster Creek, but I've got some pictures of those repairs a

1 little bit later.

2 COMMISSIONER ROGERS: Excuse me. On that table,
3 those ones at the top of the list that the repairs have
4 already been done, would they have been at the top of the
5 list if they --

6 MR. SHERON: I'm sorry.

7 MR. RUSSELL: That's when they're scheduled.

8 MR. SHERON: They're not done yet.

9 COMMISSIONER ROGERS: The ones that are completed
10 are the ones at the bottom.

11 COMMISSIONER ROGERS: Oh, yes, they're '95.

12 MR. RUSSELL: This is basically a summary of their
13 commitments to us in response to the generic letter.

14 COMMISSIONER ROGERS: I see. Okay. All right. In
15 other words, the question is really whether this
16 susceptibility list, in fact, tracks the development of
17 these, that those that are most susceptible are, in fact,
18 showing the cracking. Is that --

19 MR. SHERON: Well, we don't know. For example,
20 Pilgrim has not inspected. So, we don't --

21 COMMISSIONER ROGERS: Which ones have actually
22 shown cracks?

23 MR. SHERON: Well, the ones that show the
24 inspection completed, the completed inspections which would
25 be Dresden 3, Quad 1. Fitzpatrick I do not --

1 Did they inspect, Ed?

2 MR. HACKETT: Fitzpatrick did a partial inspection
3 and didn't find much to report in the way of cracking.

4 MR. SHERON: And Oyster Creek did an inspection.
5 They were actually doing very well until they reached the
6 last weld, which was H4, right here. They found a crack
7 from both the inside and the outside on a butt weld. It was
8 never in any of these rings. They got around and they saw
9 -- I think it was -- how much on one side was it and then 55
10 degrees on the other.

11 MR. HACKETT: About 120 on one side.

12 MR. SHERON: And they said, "To heck with it," and
13 they said, "We're going to do a preemptive repair."

14 And then Hatch went in and they did a preemptive
15 repair which several of us went down and observed while they
16 were installing it this fall.

17 Next slide, please.

18 [Slide.]

19 MR. SHERON: This slide basically summarizes the
20 overall inspection results to date. 13 of 22 Category C
21 plants have completed their inspections. We've seen 360
22 degree circumferential cracking in four units. If you
23 recall, these are Brunswick, Dresden 1, Quad Cities 3 and
24 Oyster Creek, if you want to count what they had seen pretty
25 much as a 360 crack. The cracks were primarily found in the

1 core shroud rings. Again, these are the rings here right
2 around H2, H3 and down on this one about H6A and B,
3 although, as I said before, Oyster Creek saw extensive
4 cracking at H4 which is a butt weld. It is not an end grain
5 on a ring.

6 The required structural margins, the ASME code
7 were satisfied for all the identified cracks. In other
8 words, no one was cracked to an unacceptable amount in the
9 sense that we think all of them, even if they were to
10 continue operating, would have still satisfied the ASME
11 code.

12 Two Category B plants have been inspected. These
13 were Susquehanna and LaSalle. There was no cracking
14 identified in those plants.

15 One Category A plant actually did an inspection,
16 Fermi 2, and again they saw no cracking.

17 Most licensees for the Category B and C plants
18 should have their inspections or repairs completed by this
19 coming fall.

20 [Slide.]

21 MR. SHERON: The next slide is merely a bar graph
22 showing the cumulative number of plants that will have
23 inspected or repaired by the spring of '96. You will see
24 that by spring of '96 all the plants will have completed. I
25 hope your viewgraph shows the distinction here. The

1 Category B is the short one and the Category C is the longer
2 one. I think the Xerox didn't do too good a job here.

3 Next slide, please.

4 [Slide.]

5 MR. SHERON: Let me talk a little bit about the
6 repairs that are being proposed. First off, if a licensee
7 goes in and does an inspection, they have sort of two
8 options if they see cracking. One is they could follow the
9 course like Commonwealth Edison did on Dresden 3 and Quad
10 Cities 1 and evaluate analytically the acceptability of
11 leaving the shroud in place with the cracks by demonstrating
12 that over the next operating cycle or however long they plan
13 to operate it, assuming conservative things like initial
14 crack depth, crack growth rate, that they would still
15 satisfy the ASME margins at the end of that operating cycle.
16 That's what led to the staff allowing those plants to go on
17 for another 15 months.

18 The other thing they could do is install a repair
19 option, which I'll talk about in a second. What we're
20 finding is that economic factors really come into play here.
21 The reason is that an inspection of these welds is not a
22 cheap thing to do. It can run anywhere from half-a-million
23 to a million dollars and if they run into problems during
24 the inspection, if a machine breaks, it gets jammed or
25 something, then they've got all sorts of grief. So, many

1 licensees have decided it is cheaper to install a repair
2 than it is to go in and keep doing inspections all the time
3 because the repair can be done for several million dollars
4 and once it's done, that's it, they don't have to go back
5 and inspect all of these horizontal welds.

6 What the repair does, this tie rod repair, and
7 I've got some pictures I'll show you, is it functionally
8 replaces all these circumferential welds. You're basically
9 clamping this thing together on the outside. There have
10 been two designs that have been approved to date, although
11 my understanding is there are several other vendors that
12 have actually developed designs and are trying to market
13 them. So, there's a number of designs out there. Two have
14 been contracted with and installed to date. One is with GE
15 and the other is MPR Associates.

16 The repair ensures that one maintain structural
17 integrity under all design conditions. As I said before,
18 the plants that have used the tie rod type design to date
19 are Hatch 1, Oyster Creek, and Fitzpatrick, with Brunswick
20 using these small clamps just to take care of the H2, H3
21 weld.

22 Next slide, please.

23 [Slide.]

24 MR. SHERON: This is what I will characterize as a
25 generic repair. It does not represent any actual repair

1 that went into a plant. It's similar, but the designs have
2 been refined, so they look a little bit different. But as
3 you can see, what you're doing is you're basically hooking
4 onto the bottom where the jet pumps sit on that lower plate
5 and clamping onto the top of the shroud. Then they tension
6 those down and that essentially clamps it together.

7 The next slide, please.

8 [Slide.]

9 MR. SHERON: These are not in your package. These
10 are some photographs. I hope you can see these. I've got
11 some actual pictures here. I'd like to pass these around.
12 These were taken at Plant Hatch when we were visiting there.
13 These will just give you an idea of the size of these tie
14 rods. The one you saw in the slide here had ten tie rods.
15 The GE design uses four and these are one of the GE designs.

16 Can I see the next slide, please?

17 [Slide.]

18 MR. SHERON: The piece you see there, that clevis
19 piece, is actually -- what that does is on the bottom where
20 you see the gusset plates, down where the jet pump is, what
21 they actually do is they drill a hole through the gusset
22 plate, put a clevis pin in there and that thing comes down
23 and grabs onto it. But that will give you an idea of the
24 size of these things.

25 Could I have the next slide, please?

1 [Slide.]

2 MR. SHERON: I've talked now about the core
3 shroud, but obviously other internals in the BWRs are
4 susceptible to stress corrosion cracking. Let me talk a
5 little bit about that.

6 When a licensee goes in to inspect the internals,
7 they just don't look at the shroud, they look at a number of
8 different components. They look at jet pump hold-down
9 beams, the driers, the manway covers, et cetera. So, it's
10 not that we've only been looking at shrouds. The shrouds
11 have been the most significant cracking that we've seen, but
12 there have been cracks seen in other components for some
13 time now, jet pump hold-down, beam cracking and so forth.

14 One is that the utilities have been doing these
15 inspections and when they find this cracking they have to
16 evaluate it and either determine whether a repair is
17 necessary or whether again it can be operated safely.
18 Nevertheless, we have asked the BWR Vessel Internals
19 Project, once they've gotten over this hump with the
20 shrouds, to develop comprehensive plan that would address
21 potential cracking at all of the internals. My
22 understanding is they are well along on that. They have
23 sent this in a letter recently that said they will send a
24 detailed plan in by March, next month. My understanding is
25 we will have their assessment in sometime this summer, I

1 believe around June or July.

2 COMMISSIONER ROGERS: What is the biggest safety
3 problem with any internals cracking? You've told us --

4 MR. SHERON: Well, there's a number. One is
5 manway covers in which -- and the other would be loose parts
6 that are generated, obviously if you have small pieces that
7 break off or something. Then there's a question too of if
8 you have one piece that is cracked and another piece that
9 happens to break loose, is there any synergistic effect.

10 MR. RUSSELL: The issue -- if you go back to slide
11 4.

12 [Slide.]

13 MR. RUSSELL: If you look between the two jet
14 pumps, right around where the symbol for the H8 weld is,
15 you'll see a manway cover. There are typically two of
16 these, one on each side. We have seen cracking in the weld.
17 The manway cover basically sits on the top and then it's a
18 fillet weld going around the sides. We've seen that at a
19 number of facilities, at Peach Bottom, at Browns Ferry and
20 others. This would have the potential for losing the
21 ability to reflood the volume because it's part of that
22 boundary for reflooding up to two-thirds core height. This
23 only becomes an issue if you have recirc line break. For a
24 steam line break you can still reflood and would also not
25 impact your core sprays because a failure down here is not

1 moving the shroud where you would be impacting the piping up
2 at the top of the vessel, either the lines that are going in
3 where you could shear those. So, it would still have the
4 spray effectiveness where the shroud lifting or moving could
5 cause you to lose spray as well as have a flow path. So,
6 the shroud issue, from a safety standpoint, is the more
7 significant.

8 Probably the next is associated with the manway
9 covers. The hold-down beams, if they come loose, they could
10 potentially damage piping, potentially impact your core
11 spray, but it's essentially a loose part inside and it's not
12 of the same order of magnitude as the other components.

13 So, we have prioritized these issues to address
14 the shroud first. We have been addressing the manway covers
15 as they have come up and inspection techniques have been
16 developed to look at those and also the hold-down beams.
17 Again, these are relatively simple devices to replace. So,
18 from an economic standpoint, they may be better off just
19 replacing them rather than spending time inspecting, et
20 cetera.

21 It really is going to be driven by economics
22 because if you have a manway cover that cracks or come
23 loose, if you have problems with that, or you have a hold-
24 down beam that comes loose and damages internal components,
25 the facility is going to be down for some time. This is

1 critical path time on outages. You've got to go into
2 refueling and lift the head. So, there are a number of
3 economic incentives. So, we believe that we're addressing
4 the more significant safety ones first and that's
5 appropriate from an overall priority standpoint.

6 MR. SHERON: And the last bullet on that slide
7 obviously is we have asked our Office of Research, Nuclear
8 Regulatory Research, to perform research looking into the
9 ability to understand and perhaps predict not only the
10 growth and the initiation of the stress corrosion cracks but
11 also the arrest mechanism. As I said before, we could
12 demonstrate conclusive that once these things go outside of
13 the heat affected zone they stop. I think that would give
14 us a lot more assurance that we didn't have in terms of the
15 degree of the problem.

16 Also, we have asked them to look at the cracking
17 of multiple internals. Again, it's a synergistic effect to
18 look at what are the important ones and if I had two things
19 crack, is there a synergistic effect that I'm not aware of?
20 We don't think there are any right now that we haven't seen,
21 but nevertheless it's, I think, a good confirmatory thing to
22 do.

23 DR. THADANI: Brian, if I may add, in terms of the
24 other internals, we have raised the same issues with the
25 industry. I think at this stage it does appear that the

1 industry is taking a very serious look trying to evaluate
2 and understand, for example, the synergistic effects that
3 Brian talked about. They have also shared with us the level
4 of effort they are putting into this activity. It has gone
5 up by more than an order of magnitude, which to me is a
6 clear indication of how seriously they seem to be taking it.
7 It's a lot of money they're putting in this program.

8 They owe us details. That means milestones,
9 schedules and specific activities that they are undertaking
10 as to when they will complete them, in March. To me, that's
11 a very important time period. We're very anxious to see the
12 details.

13 COMMISSIONER de PLANQUE: Going back to the growth
14 of the cracks, given the inspections that you've seen so
15 far, how well would what you have predicted compare with
16 what's actually been found and how conservative were your
17 estimates of how deep the cracks are, how wide --

18 MR. SHERON: One of the problems is that you
19 really don't know when they initiated.

20 COMMISSIONER de PLANQUE: Right.

21 MR. SHERON: Okay. That's the big problem. If
22 you knew when they initiated, then you would be able --

23 COMMISSIONER de PLANQUE: Then the curves are
24 easy.

25 MR. SHERON: Yes, that makes it real easy.

1 COMMISSIONER de PLANQUE: Right.

2 MR. SHERON: Right now we use a conservative bound
3 on that.

4 I don't know, Ed, maybe you want to add a little
5 bit to --

6 MR. HACKETT: The one foreign plant that we have
7 data where they have tracked a crack from -- I guess it's
8 over two cycles now is growing very much slower than the
9 conservative value we're forcing the industry to use. So,
10 that's something, we're looking at trying to accumulate that
11 kind of data. On the other hand, a lot of the plants are
12 putting in these repairs. So, we're not likely to be
13 getting a whole lot more field data here. That's the one
14 data point that we have and that shows that it's pretty
15 conservative.

16 COMMISSIONER de PLANQUE: Okay. And in terms of
17 the factors that you plug in, the water chemistry, et
18 cetera, do they seem to be fairly in line with what your
19 thinking is in terms of effect or can't you really tell from
20 the data available?

21 MR. HACKETT: That's a much tougher question
22 because you're asking, I guess, about --

23 COMMISSIONER de PLANQUE: The second order.

24 MR. HACKETT: -- another level of synergism here
25 between the water chemistry, the material and so on. So

1 far, as we were talking about earlier, the strongest
2 correlation we seem to have is with the conductivity over
3 the early operating years for the plants. In other areas,
4 like the residual stress level that Brian was referring to,
5 we don't have that quantified anywhere near as well. So,
6 it's difficult to say. The strongest correlation is with
7 the conductivity at this point.

8 COMMISSIONER de PLANQUE: Okay.

9 MR. SHERON: And could I have the last slide,
10 please?

11 [Slide.]

12 MR. SHERON: Where are we going from here? Well,
13 first off, we will continue to review the inspection
14 results. Plants will still come down and do inspections.
15 Even though some will come in and do preemptive repair,
16 there may be reasons why they don't want to do the repair at
17 this time. So, if a plant chooses to do an inspection
18 again, we want to be on top of it. We will be reviewing it.

19 We also want to look at the inspection plans
20 before a plant goes into an outage so we don't get into one
21 of these last minute arguing about how much they should
22 inspect and so forth. We'd like to get that all sorted out
23 way before they ever bring the plant down and go in, so they
24 know what they're going to do when they go in, they know
25 what they're going to do when they find certain cracking and

1 so forth.

2 The other thing we want to do is we would like to
3 issue a summary report, NUREG report on this whole issue.
4 So, if somebody wanted to get a real comprehensive
5 assessment of this whole issue of BWR shroud cracking and so
6 forth, they can go to this NUREG and it would kind of lay
7 out the whole history for them.

8 We are also doing a comprehensive assessment, as I
9 said before, as Ashok said, of all of the BWR internals.
10 Okay. The shroud again was the most important, but we need
11 to look further at all the internals to make sure we
12 understand where the most susceptible ones are, what the
13 consequences of that kind of cracking is and to make sure
14 there's nothing out there that we're not aware of.

15 Lastly, we will be reviewing the repairs. These
16 repairs are not ASME code repairs in the sense that they are
17 not restoring it to its original condition and that requires
18 the licensee to make a submittal to the staff under
19 50.55(a). So, we will be doing reviews of repairs and then
20 writing the safety evaluations on those.

21 Lastly, which is not on here, obviously once you
22 put a repair in, you can't ignore it forever. Now the
23 question is we have to inspect the repairs. The question is
24 what needs to be inspected and how often and we are right
25 now working, developing a plan for that.

1 That concludes my presentation. If there are any
2 questions, we'll try to answer them.

3 CHAIRMAN SELIN: Is the cause of the cracking all
4 ancient chemistry or is there still corrosion going on? In
5 the current plants, in the current chemistry, do we still
6 see contributions of corrosion or is this the residue of
7 poor chemistry and a longer time?

8 MR. SHERON: I think this is just -- you know,
9 there's really nothing there from the erosion. It's mostly
10 just from the water chemistry, the cracking.

11 Is that your understanding?

12 MR. HACKETT: That's correct. It's probably too
13 early to tell, if your question is aimed at some of the
14 newer plants. For instance, on water chemistry, any level
15 of conductivity in the water is enough to cause this
16 phenomenon. You probably can get it, it will just take an
17 awful lot more time. Certainly there's the correlation with
18 the high conductivity that seems to cause the initiation
19 very early, but at this point we don't know for the other
20 plants where they're going to go. That's why it's very
21 important I think at this point to emphasize mitigation
22 efforts for those plants.

23 CHAIRMAN SELIN: I'm not sure everybody in the
24 industry, including us, too this really quite as seriously
25 as it might have been taken in the beginning.

1 MR. TAYLOR: We did meet with the owners. I can't
2 recall the date of that meeting, and we called that as soon
3 as we felt we were ready and that was a very productive
4 meeting which I think caused the owners to universally get
5 behind this project.

6 CHAIRMAN SELIN: So there's not a catching
7 people's attention problem?

8 MR. TAYLOR: I think we have their attention.

9 MR. RUSSELL: I think the industry was surprised
10 when they saw the extensive of the cracking at Dresden and
11 Quad Cities and they may have thought that Brunswick was an
12 outlier for some reason. But once you started to see it at
13 more facilities and the interaction back and forth with the
14 staff that first time around to justify and review, for the
15 licensee to provide the justification and us to review, why
16 it was okay to continue operation with this extensive
17 cracking when the consequences of being incorrect could be
18 quite significant was a very long and involved process.
19 There was quite a bit of dialogue back and forth with senior
20 managers of Commonwealth Edison and senior utility managers
21 to make sure that this was, in fact, focused upon. I think
22 they have done a good job of it. They recognize that this
23 was an issue that the owners needed to get together and
24 address and not just leave to a particular vendor to
25 address.

1 CHAIRMAN SELIN: If you talked to the people
2 overseas that run boilers and have seen this, do you get any
3 different picture from the one that was presented today?

4 MR. RUSSELL: I've had discussion with the
5 regulators in one country that has been monitoring the
6 cracking for some time and that cracking is less significant
7 than what we've seen. They are, in fact, mapping it and
8 monitoring it and the growth rates appear to be less than
9 what we would see. Based upon analysis we've done, I have
10 no reason to question their conclusion about why it's
11 acceptable and continue to operate without installing a
12 repair. The issue becomes one at some point it's going to
13 cost them more to continue to inspect than it would be to do
14 a preemptive repair and not continue to inspect.

15 DR. THADANI: And yet there's another country,
16 they have seen a fair amount of cracking and their
17 inclination, as I understand now, seems to be to actually
18 replace the shroud. It's a different design. It's bolted
19 down instead of being welded at the bottom. The utility --
20 right now there seems to be some question as to what the
21 utility is actually going to do because one source indicated
22 to us -- when I was there actually and spoke with the
23 regulators, they said the utility was planning to replace
24 the shroud. There seems to be some question about that now,
25 but nevertheless there is another example.

1 CHAIRMAN SELIN: Commissioner Rogers?

2 COMMISSIONER ROGERS: Yes. Have you come to an
3 agreement with the licensees on what constitutes an
4 acceptable inspection program for this? Do you have to
5 thrash this out with each individual licensee or have you
6 been able to come to some general agreement?

7 MR. SHERON: I think we have general agreement,
8 but I would not guarantee that there would not be
9 circumstances in which they would like to negotiate some
10 more on it. Again, it's a matter of they really don't know
11 what they're going to find until they open up the vessel and
12 go in and look. That's when they run into problems with
13 either the equipment breaking down or they find out, like I
14 said, the shroud is not round or they forgot the fact that
15 the gap between the shroud and the vessel is too narrow for
16 the equipment to fit and stuff. Then you've got to get into
17 these discussions.

18 But right now, our going imposition is we think
19 they should do 100 percent of the accessible welds. I use
20 the word "accessible" because you have to remember if you
21 look at these pictures, there's a lot of garbage sitting
22 around these welds. Okay?

23 MR. RUSSELL: Important safety-related --

24 MR. TAYLOR: Not garbage, Brian.

25 MR. SHERON: Wrong term. But there is a lot of

1 stuff sitting there that they cannot really get a good
2 picture of these welds. Some of them even have bands around
3 them, as I understand, and so forth. So, you can only see
4 one side. Core spray piping is up there that you can't get
5 behind to see some of them. So, when we say accessible,
6 it's not necessarily the whole weld, it's just the part of
7 it that can be seen.

8 MR. RUSSELL: Early on we had a lot of dialogue
9 back and forth on scope of inspection. That's why it's
10 important for them to describe to us what their actual
11 inspection plans are 30 days prior to and resolve those
12 issues before you get into a critical path situation. So,
13 they have learned and we have learned from that process and
14 I think it's fairly well understood now that our expectation
15 is that that which can be inspected you should inspect
16 unless you're going in to do a preemptive repair and we
17 review and approve the repair.

18 COMMISSIONER ROGERS: Well, it sounds like you've
19 gotten on top of the problem and it seems to be well in
20 hand. Very good. Thank you.

21 COMMISSIONER de PLANQUE: You've answered my
22 questions. Thank you.

23 CHAIRMAN SELIN: Thank you very much for a timely
24 report.

25 [Whereupon, at 3:01 p.m., the meeting was

1 concluded.]

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

ANN RILEY & ASSOCIATES, LTD.
Court Reporters
1250 I Street, N.W., Suite 300
Washington, D.C. 20005
(202) 842-0034

CERTIFICATE

This is to certify that the attached description of a meeting of the U.S. Nuclear Regulatory Commission entitled:

TITLE OF MEETING: BRIEFING ON CORE SHROUD ISSUES -
PUBLIC MEETING

PLACE OF MEETING: Rockville, Maryland

DATE OF MEETING: Wednesday, February 1, 1995

was held as herein appears, is a true and accurate record of the meeting, and that this is the original transcript thereof taken stenographically by me, thereafter reduced to typewriting by me or under the direction of the court reporting company

Transcriber: Carol Lynch

Reporter: Peter Lynch



INTERGRANULAR STRESS CORROSION CRACKING OF BOILING WATER REACTOR CORE SHROUDS (GENERIC LETTER 94-03)

February 1, 1995


**Brian W. Sheron, Director
Division of Engineering, Office of Nuclear Reactor Regulation**

**Lead Technical Contacts:
E. Hackett, NRR, 504-2751
K. Kavanagh, NRR, 504-3743**


STRESS CORROSION CRACKING OF BWR CORE SHROUDS

- **Background (Commission Papers - 1/3/94, 11/10/94)**
- **Initial Observations of Shroud Cracking in U.S. Plants**
- **Safety Significance**
- **Regulatory and Industry Actions**
- **Current Status**
- **Stress Corrosion Cracking Susceptibility Criteria**
- **Susceptibility Ranking of BWRs**
- **Inspection Experience**
- **Core Shroud Repairs**
- **Comprehensive Assessment of BWR Internals Cracking**
- **Future Actions**

CORE SHROUD STRUCTURAL CONFIGURATION



CORE SHROUD WELD LOCATIONS



SUPPORT CONFIGURATION VARIES DEPENDING ON BWR SERIES


BACKGROUND - CORE SHROUD FABRICATION

- **Shroud Material is 304 or 304L Stainless Steel**
- **Typical Dimensions**
 - **14 to 17 Feet in Diameter**
 - **Wall Thickness (1.5 to 2 Inches)**
- **Construction**
 - **Welded Plates**
 - **Welded Plates + Ring Forgings**
- **Fabrication Involves Both Circumferential and Axial Welds**
- **Residual Stresses are Present from Welding**
- **Weld Heat Affected Zones Particularly Susceptible to IGSCC**

INITIAL OBSERVATIONS OF SHROUD CRACKING IN U.S. PLANTS

- **Significant Shroud Cracking First Observed at Brunswick Unit 1**
- **Discovered During GE-Recommended Visual Examination of Internals**
- **Cracking at Weld H3 on the Inside of the Top Guide Support Ring**
- **Extent of Cracking was 360°, with a Maximum Depth of 1.7 Inches**
- **Similar Cracking in the Core Plate Support Ring Subsequently Observed at Dresden Unit 3 and Quad Cities Unit 1**


SHROUD CRACKING IN CORE PLATE RING



SAFETY SIGNIFICANCE

- **Only a Concern if Cracking is 360° Through-Wall**
 - **Potential for Shroud Separation**
- **Normal Operating Conditions**
 - **Through-Wall Cracks at Upper Elevation Detectable By Core Flow/Power Mismatch**
 - **Through-Wall Cracks at Lower Elevation May Not be Detectable**
- **Accidents of Concern are Main Steam Line Break, Recirculation Line Break and Safe Shutdown Earthquake**
 - **Uplift of Top Guide**
 - **Interference with Control Rod Insertion**

REACTOR VESSEL FLOW PATHS



REGULATORY ACTIONS

- **Information Notice 93-79 (September 30, 1993)**
- **Information Notice 94-42 and Supplement 1 (June 7/July 19, 1994)**
- **Generic Letter 94-03 (July 25, 1994)**
 - **Inspect/Repair Shroud at Next Refueling Outage**
 - **Provide Safety Assessment Justifying Operation Until Inspection/Repair**
 - **Provide Inspection/Repair Plans 30 Days Prior to the Outage**

INDUSTRY ACTIONS

- **GE Service Information Letters**
- **Formation of BWR Vessel and Internals Project (BWRVIP)**
- **BWRVIP Subcommittees:**
 - **Integration**
 - **Inspection - Topical Report (9/2/94)**
 - **Assessment - Topical Report (9/2/94)**
 - **Repair - Topical Report (8/18/94)**
 - **Mitigation**

CURRENT STATUS

- **Key Factors Affecting Relative IGSCC Susceptibility for BWRs Established**
- **Staff Met with EPRI and BWRVIP to Discuss Scope of Core Shroud Inspections**
- **Analysis of Inspection Results Continuing**
- **Staff Continues Plant-Specific Assessments for Repair Acceptability**
- **NRR Review of Generic Letter 94-03 Responses Completed**

GL 94-03 CONCLUSIONS/BASES FOR CONTINUED OPERATION

- **No 360° Through-Wall Cracking to Date**
- **No Symptoms (Power to Flow Mismatch) of Through-Wall Cracking Have Been Identified During Power Operation**
- **Small Ligament Required for Adequate Structural Integrity**
- **ASME Code Margins Satisfied**
- **Low Frequency of Initiating Event**
- **Short Period of Operation Until Inspection can be Performed**
- **Plant-Specific Factors (Four Highest Susceptibility Plants)**

STRESS CORROSION CRACKING SUSCEPTIBILITY CRITERIA

- **Operational Time**
- **Reactor Water Chemistry (Conductivity)**
- **Materials (Carbon Content)**
- **Shroud Fabrication Methods**
- **Weld Stresses**

SUSCEPTIBILITY RANKINGS

- **Category “A” BWRs (8 Units)**
 - **Less Than 8 On-line Years of Operation**
 - **Good Initial Water Chemistry**
 - **Low Carbon Materials (304L)**
- **Category “B” BWRs (6 Units)**
 - **More Than 8 On-line Years of Operation**
 - **Good to Moderate Initial Water Chemistry**
 - **Low Carbon Materials (304L)**
- **Category “C” BWRs (22 Units)**
 - **More Than 6 On-line Years for BWRs with Shrouds Fabricated from 304 SS; 8 Years for Those Constructed using 304L**
 - **Moderate to Poor Water Chemistry**

MOST SUSCEPTIBLE PLANTS

- The Staff Concluded that 11 of the 22 Category C BWRs had the Potential for Containing Significant Cracking
- Conditions at These Plants Bounded All Other BWRs


Plant	Inspection	Repair
Pilgrim		4/95
Dresden 2		5/95
Quad Cities 2		4/95
NMP-1	2/95	2/95
Dresden 3	Complete, 4/94	3/96
Quad Cities 1	Complete, 4/94	9/95
FitzPatrick	Complete, 1/95	Complete, 2/95
Oyster Creek	Complete, 10/94	Complete, 11/94
Brunswick 1	Complete, 10/93	Complete, 1/94
Brunswick 2	Complete, 5/94	Complete, 6/94
Hatch 1		Complete, 10/94

OVERALL INSPECTION RESULTS TO DATE

- **13 of 22 Category C Plants Inspected**
 - **360° Circumferential Cracking at Four Units**
 - **No 360° Through-wall Cracks Identified**
 - **Cracks Primarily Found in Core Shroud Rings**
 - **The Required Structural Margins of the ASME Code were Satisfied for all Identified Cracks**
- **2 Category B Plants Inspected**
 - **No Cracking Identified**
- **1 Category A plant inspected (Fermi 2)**
 - **No Cracking Identified**
- **Most licensees of Category B and C BWRs will Complete an Inspection or Repair by Fall 1995**

CORE SHROUD INSPECTIONS/REPAIRS

Category B and C Plants



Total Category C = 22 plants*


Total Category B = 6 plants

* - Browns Ferry 1 is not operating and is not reflected in the graph

CORE SHROUD REPAIRS

- **If Cracking is Identified Licensees May:**
 - **Evaluate Analytically to Demonstrate Structural Margin**
 - **Install Repair Option**
- **Considering Economic Factors in Addition to Susceptibility, Some Licensees Have Decided to Initiate a Preemptive Repair**
- **Repair Functionally Replaces Shroud Circumferential Welds**
- **Several Tie Rod Restraint Systems Have Been Developed, Two Designs Have Been Approved to Date**
- **Repair Ensures Structural Integrity for All Design Conditions**
- **U.S. Plants Repaired to Date Using Tie Rods:**
 - **Hatch 1**
 - **Oyster Creek**
 - **FitzPatrick**

NUCLEAR POWER PLANT PROPOSED REPAIR TO REACTOR SHROUD



Photograph - Plant Hatch Repair (Tie Rod)

Photograph - Plant Hatch Repair (Lower Clevis Forging)

COMPREHENSIVE ASSESSMENT OF CRACKING IN BWR INTERNALS

- **Other BWR Internals Are Susceptible to IGSCC**
- **Inspections and Evaluations of These Components Have Been and Are Continuing to be Conducted**
- **Staff has Requested the BWRVIP to Develop a Comprehensive Plan Addressing Potential Cracking in All BWR Internals**
- **January 1995 Commitment Letter Received from BWRVIP, Detailed Plan to be Submitted in March 1995**
- **NRR User's Request to Office of Research (December 1994)**
 - **Growth/Arrest of IGSCC Cracks**
 - **Effects of Cracking in Multiple Internal Components**

FUTURE ACTIONS

- **Continue Review of Inspection Results**
- **Review Licensee Inspection Plans Before Plant Outages**
- **Issue Summary NUREG Report**
- **Comprehensive Assessment of all BWR Reactor Vessel Internals**
- **Review Repairs**