



Monticello Nuclear Generating Plant  
2807 W County Road 75  
Monticello, MN 55362

June 29, 2015

L-MT-15-033  
10 CFR 50.73

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

Monticello Nuclear Generating Plant  
Docket 50-263  
Renewed Facility Operating License No. DPR-22

LER 2015-002-00 "Loss of Shutdown Cooling Due to Improperly Landed Jumper Wire"

Enclosed, is the Monticello Nuclear Generating Plant (MNGP) Licensee Event Report (LER) 2015-002-00 regarding a loss of shutdown cooling. This condition is reportable to the NRC in accordance with 10 CFR 50.73(a)(2)(v)(B), as an Event or Condition that Could have Prevented the Fulfillment of the Safety Function of Structures or Systems that are Needed to Remove Residual Heat.

Summary of Commitments

This letter contains no new commitments and no revisions to existing commitments.

A handwritten signature in blue ink, appearing to read 'P. Gardner'.

Peter A. Gardner  
Site Vice President, Monticello Nuclear Generating Plant  
Northern States Power Company – Minnesota

Enclosure

cc: Regional Administrator, Region III, USNRC  
Project Manager, MNGP, USNRC  
Resident Inspector, MNGP, USNRC

**LICENSEE EVENT REPORT (LER)**(See Page 2 for required number of  
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

**1. FACILITY NAME**

Monticello Nuclear Generating Plant

**2. DOCKET NUMBER**

05000-263

**3. PAGE**

1 OF 3

**4. TITLE**

Loss of Shutdown Cooling Due to Improperly Landed Jumper Wire

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
05	02	2015	2015	002	00	06	29	2015	FACILITY NAME	05000
									FACILITY NAME	05000
<b>9. OPERATING MODE</b>			<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)</b>							
5			<input type="checkbox"/> 20.2201(b)		<input type="checkbox"/> 20.2203(a)(3)(i)		<input type="checkbox"/> 50.73(a)(2)(i)(C)		<input type="checkbox"/> 50.73(a)(2)(vii)	
			<input type="checkbox"/> 20.2201(d)		<input type="checkbox"/> 20.2203(a)(3)(ii)		<input type="checkbox"/> 50.73(a)(2)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(viii)(A)	
			<input type="checkbox"/> 20.2203(a)(1)		<input type="checkbox"/> 20.2203(a)(4)		<input type="checkbox"/> 50.73(a)(2)(ii)(B)		<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
			<input type="checkbox"/> 20.2203(a)(2)(i)		<input type="checkbox"/> 50.36(c)(1)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(iii)		<input type="checkbox"/> 50.73(a)(2)(ix)(A)	
10. POWER LEVEL  0%			<input type="checkbox"/> 20.2203(a)(2)(ii)		<input type="checkbox"/> 50.36(c)(1)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(iv)(A)		<input type="checkbox"/> 50.73(a)(2)(x)	
			<input type="checkbox"/> 20.2203(a)(2)(iii)		<input type="checkbox"/> 50.36(c)(2)		<input type="checkbox"/> 50.73(a)(2)(v)(A)		<input type="checkbox"/> 73.71(a)(4)	
			<input type="checkbox"/> 20.2203(a)(2)(iv)		<input type="checkbox"/> 50.46(a)(3)(ii)		<input checked="" type="checkbox"/> 50.73(a)(2)(v)(B)		<input type="checkbox"/> 73.71(a)(5)	
			<input type="checkbox"/> 20.2203(a)(2)(v)		<input type="checkbox"/> 50.73(a)(2)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(v)(C)		<input type="checkbox"/> OTHER	
			<input type="checkbox"/> 20.2203(a)(2)(vi)		<input type="checkbox"/> 50.73(a)(2)(i)(B)		<input type="checkbox"/> 50.73(a)(2)(v)(D)		Specify in Abstract below or in NRC Form 366A	

**12. LICENSEE CONTACT FOR THIS LER**

## LICENSEE CONTACT

Steve Sollom, Licensing Engineer

## TELEPHONE NUMBER (Include Area Code)

(763) – 295 – 1611

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

**14. SUPPLEMENTAL REPORT EXPECTED**☒ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☐ NO**15. EXPECTED SUBMISSION DATE**

MONTH	DAY	YEAR
09	01	2015

**ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)**

On May 2, 2015, the Monticello Nuclear Generating Plant (MNGP) was in Mode 5 for a refueling outage. During performance of surveillances of the non-credited 4kV essential Bus, MNGP experienced a loss of the 4kV Bus and essential Load Center due to an improperly landed jumper wire. Loss of the Load Center de-energized the valve position indication on the shutdown cooling inboard isolation valve, causing a subsequent trip of the Residual Heat Removal pump operating in shutdown cooling on a pump suction interlock and a loss of normal shutdown cooling. Control Room operators entered the appropriate abnormal procedures and verified alternate decay heat removal was in service until shutdown cooling could be restored.

Immediate corrective actions included suspension of all work pending approval of the shift manager to ensure outage activities did not further degrade plant conditions and electrical work was limited to protect shutdown cooling. The essential Load Centers were cross tied to restore normal shutdown cooling. This Licensee Event Report is expected to be supplemented to address the root cause evaluation and corrective actions resulting from this event.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REV NO.	
Monticello Nuclear Generating Plant	05000-263	2015	- 002	- 00	2 OF 3

**NARRATIVE****EVENT DESCRIPTION**

On May 2, 2015 the Monticello Nuclear Generating Plant (MNGP) was in Mode 5 (Refueling) at 0% thermal rated power with the vessel [RPV] cavity flooded. Shutdown cooling (SDC) was being provided by the 12-Residual Heat Removal (RHR) Pump [P] and the 12-RHR Service Water (SW) System [BI] powered by Bus-16 (Division 2-4kV Essential Bus) [BU].

At 1246 hours the MNGP experienced a loss of power to Bus-15 (Division 1-4kV Essential Bus) and LC-103 (Division 1-480V Essential Load Center) during calibration of Bus-15 relays [RLY]. A human performance error occurred during the surveillance when a jumper wire was installed across the incorrect terminals.

The loss of LC-103 resulted in a loss of power to MCC-133A (Division 1-480V Essential Motor Control Center) [MCC] which powers the position indication for the RHR SDC Inboard Isolation Valve [ISV]. The valve position indication was de-energized, resulting in 12-RHR pump control logic to interpret the loss of position indication as a closed valve. Loss of detection of a viable suction flow path by 12-RHR pump control logic caused a subsequent trip of the 12-RHR pump and a loss of SDC, even though the pump was powered by Bus-16. Immediately following the event, abnormal procedures were entered and all work suspended pending approval of the shift manager.

At 1300 hours the Fuel Pool Cooling and Cleanup (FPCC) System [DA] and natural circulation were verified as an alternate decay heat removal source and hourly reactor coolant temperature monitoring was initiated per required actions of Technical Specification (TS) Limiting Condition for Operation (LCO) 3.9.7, "Residual Heat Removal (RHR) – High Water Level."

At 1500 hours power was restored to LC-103 when it was cross-tied with LC-104 (Division 2-480V Essential Load Center), restoring power to the RHR SDC Inboard Isolation Valve.

At 1602 hours 12-RHR Pump was placed back into service restoring normal SDC. The 12-RHR Pump was unavailable for approximately 196 minutes causing the RHR Heat Exchanger [HX] inlet temperature to increase approximately 10 degrees F to 91.1 degrees F. Reactor Pressure Vessel (RPV) water temperature was maintained within the allowable temperature band throughout the duration of the event.

**EVENT ANALYSIS**

At the time of the event, decay heat was being removed by the 12-RHR pump and the 12-RHR SW System. The vessel cavity was fully flooded above the top of the RPV flange with the Spent Fuel Pool gates [GATE] removed. Since the RHR SDC Inboard Isolation Valve provides common suction to all RHR pumps, loss of position indication of the valve caused all trains of RHR to be unavailable for decay heat removal function. Reactor Water Cleanup (RWCU) System [CE] was also unavailable due to planned maintenance activities. Therefore, following the loss of normal SDC, decay heat removal function was supported by a single FPCC pump.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Monticello Nuclear Generating Plant	05000-263	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 3
		2015	- 002	- 00	

**NARRATIVE**

The event was determined to be reportable in accordance with 10 CFR 50.73(a)(2)(v)(B) as an Event or Condition that Could have Prevented the Fulfillment of the Safety Function of Structures or Systems that are Needed to Remove Residual Heat. This event is considered a Safety System Functional Failure per NEI 99-02 Revision 7.

**SAFETY SIGNIFICANCE**

With the unit in Mode 5, the RHR SDC System is not required to mitigate any events or accidents evaluated in the safety analyses. The RHR SDC System is required for removing decay heat to maintain the temperature of the reactor coolant.

Residual heat removal was supported by a single FPCC pump and reactor coolant temperature was maintained less than the 125 degrees F required for maintaining safe shutdown of the plant. Heat up calculations were performed and determined RPV maximum coolant temperatures would remain less than 115 degrees F after 55 hours while the single FPCC Pump provided decay heat removal. The safety significance of this event was minimal and there were no consequences that affected public health and safety.

**CAUSE**

Direct cause was determined shortly after the event occurred. During surveillances that were performed on Bus-15 relays, a technician improperly landed a jumper wire across the incorrect terminals and caused a "no voltage" signal to trip the breaker. The direct cause of the human performance error was inadequate use of concurrent verification techniques. The physical environment created an error precursor as the terminal strip was located in a tight space that complicated the concurrent verification process. The verifier failed to recognize the performer miscounted down the terminal strip to the inappropriate terminal. This Licensee Event Report (LER) will be supplemented upon completion of a root cause evaluation.

**CORRECTIVE ACTION**

Immediate corrective actions included suspension of all work pending approval of the shift manager to ensure outage activities did not further degrade plant conditions and electrical work was limited to protect SDC. SDC was restored by cross tying LC-103 to LC-104 using approved plant procedures. This LER will be supplemented upon completion of a root cause evaluation to include all corrective actions implemented to preclude reoccurrence of this event.

**PREVIOUS SIMILAR EVENTS**

There was one previous similar event in the past three years captured in LER 2013-004, "Loss of Normal Off-Site Power as a Result of Switchgear Fault," where shutdown cooling was lost. This event was not caused by a human performance error; therefore corrective actions as a result of this event would not have prevented loss of shutdown cooling reported in this LER.

**ADDITIONAL INFORMATION**

The Institute of Electrical and Electronics Engineer codes for equipment are denoted by [XX].